

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO CLEAN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☒ OIL WELL ☐ GAS WELL ☐ OTHER

2. Name of Operator
Gulf Oil Corporation

3. Address of Operator
Box 670, Hobbs, New Mexico 88240

4. Location of Well
UNIT LETTER **F**, **1980** FEET FROM THE **North** LINE AND **1650** FEET FROM
THE **West** LINE, SECTION **6** TOWNSHIP **22-S** RANGE **37-E** NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
3457' GL

7. Unit Agreement Name
8. Form or Lease Name H. T. Mattern (NCT-D)
9. Well No. 11
10. Field and Pool, or Wildcat Drinkard
12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER Acidized and installed pumping equipment. <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.

6735' PB.

Fumped 3000 gallons of 15% NE FE acid down tubing over 5-1/2" casing perforations 6506' to 6643'. Flushed with 100 barrels of oil. Maximum pressure 2600#, ISIP 950#, after 3 minutes 0#. AIR 4.5 BPM. Swabbed and cleaned up. Ran rods and pump. Installed pumping equipment and returned well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u><i>D.F. Berlin</i></u>	TITLE <u>Area Engineer</u>	DATE <u>May 21, 1976</u>
APPROVED BY <u><i>Larry Berlin</i></u>	TITLE <u></u>	DATE <u>MAY 24 1976</u>
CONDITIONS OF APPROVAL, IF ANY:		