





**APPROVED** HOBBS OFFICE COPY

Budget Bureau No. 42-R358.4.  
Form Approved.


JUN 10 1963

(SUBMIT IN TRIPLICATE)

Land Office Las Cruces

Lease No. LC-065880-A

J. L. GORDON UNITED STATES  
ACTING DISTRICT ENGINEER DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY



APR 24 1963

# SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL	SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT	X
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

April 22, 1963

Gulf Federal Littlefield

Well No. 1 is located 1880 ft. from [N] line and 660 ft. from [E] line of sec. 29

SE/4 NE/4 Sec. 29  
(1/4 Sec. and Sec. No.)

26S  
(Twp.)

33EE  
(Range)

NMPM  
(Meridian)

Wildcat  
(Field)

Lea County  
(County or Subdivision)

New Mexico  
(State or Territory)

The elevation of the derrick floor above sea level is 3188.7 ft.

## DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

The 4" marker has been set. Pits have been backfilled and location cleaned as prescribed. Set 333' of 8-5/8" surface casing @ 323'. Cemented with 100 sx plug 8% gel and 50 sx plug 2% CaCl<sub>2</sub>. Drilled to TD of 4991'. Cored from 4886' to 4986'. Dry Hole. Set cement plugs as follows:

34 sxs 100'	4600' - 4700'
34 sxs 100'	1000' - 1100'
34 sxs 100'	700' - 800'
17 sxs 50'	300' - 350'

Cement circulated.

6' plug @ surface.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company Curtis Hankamer

Address 1421 Bank of the Southwest Bldg.

Houston 2, Texas

By Phil C. Hankamer  
Title Engineer