

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1940, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 3002512409
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Buffington
8. Well No. 1
9. Pool name or Wildcat Langlie Mattox 7 Rvs Qn Grbg.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>
2. Name of Operator Mack Energy Corporation
3. Address of Operator P.O. Box 960, Artesia, NM 88211
4. Well Location Unit Lease L : 1980 Feet From The South Line and 990 Feet From The West Line Section 19 Township 25S Range 38E N.M.P.M. Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

<p>NOTICE OF INTENTION TO:</p> <p>PERFORM REMEDIAL WORK <input type="checkbox"/></p> <p>TEMPORARILY ABANDON <input type="checkbox"/></p> <p>PULL OR ALTER CASING <input type="checkbox"/></p> <p>OTHER: <input type="checkbox"/></p>	<p>SUBSEQUENT REPORT OF:</p> <p>PLUG AND ABANDON <input type="checkbox"/></p> <p>CHANGE PLANS <input type="checkbox"/></p> <p>OTHER: <input type="checkbox"/></p>	<p>REMEDIAL WORK <input type="checkbox"/></p> <p>COMMENCE DRILLING OPNS. <input type="checkbox"/></p> <p>CASING TEST AND CEMENT JOB <input type="checkbox"/></p> <p>OTHER: <input type="checkbox"/></p>	<p>ALTERING CASING <input type="checkbox"/></p> <p>PLUG AND ABANDONMENT <input checked="" type="checkbox"/></p> <p>OTHER: <input type="checkbox"/></p>
--	---	---	--

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-07-02 MIRU plugging unit.
Spot 25 sx cmt. 3170-3070'.

11-08-02 WOC & tag @ 2952'. Mud up hole, spot 25 sx 2395-2295'. Perf @ 1165', sqz. 35 sx 1165-1065' & tag @ 1050'. Perf @ 293', sqz. 35 sx, WOC until next day.

11-11-02 Tag plug @ 185', RIH @ 60', spot 10 sx cmt. to surface.
RDMO. Cut off wellhead, install dry hole marker, clean location.

Approved as to plugging of the Well Bore.
Liability under bond is retained until surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jerry W. Sherrell TITLE Production Clerk DATE 11/19/2002

TYPE OR PRINT NAME Jerry W. Sherrell TELEPHONE NO 505-748-1288

(This space for State Use)

APPROVED BY GARY W. WINK TITLE OC FIELD REPRESENTATIVE II / STAFF MANAGER DATE FEB 25 2003

CONDITIONS OF APPROVAL, IF ANY: