## HM389 OFFICE OF

## (SUBMIT IN TRIPLICATE)

## **UNITED STATES**

## DEPARTMENT OF THE INTERIOR **GEOLOGICAL SURVEY**

L.	Office	New	Mexico
			0889
Unit	<b>-  -</b> -		

			D REI OF	RTS ON W	ELLS	
NOTICE OF INTE	NTION TO DRILL		CHRSEAUENT DED	ORT OF WATER SHUT-O	er.	X
l l	NTION TO CHANGE PLANS		ıl	ORT OF WATER SHOT-C		
1	NTION TO TEST WATER SHE		1	ORT OF ALTERING CAS		
1	NTION TO RE-DRILL OR RE	1	li .	ORT OF REDRILLING O		
1	NTION TO SHOOT OR ACIDI	1	<b>!</b>			1 1
i	NTION TO SHOOT OR ACTER	1	il.			1 1
ł .	NTION TO ABANDON WELL.		H			
NOTICE OF THE						
	(INDICATE ABOV	VE BY CHECK MARK NAT	ure of Report, No	TICE, OR OTHER DATA)		
		•		(g -	2	., 19
Well No1-	Self is located	660 ft. from	S line and	660 ft. from (1	tine of sec	6
SW/4	d Sec. No.)	. 26S 3	8E	NMP		
			KDge)		Mexico	
	sld)	Les. (County or St				
(		(County of Be	10414181011)	(State	e or Territory)	
		ng points, and all other  P.M. June 14	1950, 703	d work)	5L# casin	g was
nell was	151 with 500 ekg	i cemeni, circ				3 4 Pakis
set @ 70 June 26 bailed o	051 with 500 sks, 1950. After identify and tested in 5 hrs.	or 2 hrs. Te	Plug was te ested OK, pl	sted on June ug was drill	28, 1950. ed, hole ba	Hole Ailed
set @ 70 June 26 bailed o dry & te	)5: with 500 sks , 1950. After i dry and tested i	or 2 hrs. Te	Plug was te ested OK, pl	sted on June ug was drill	28, 1950. ed, hole ba	Hole Ailed
set @ 70 June 26 bailed o dry & te	)5: with 500 sks , 1950. After i dry and tested i	. WOC. For 2 hrs. Te	Plug was te ested OK, pl ne complete	sted on June ug was drill shut off was	28, 1950. ed, hole ba indicated	Hole Ailed •
set @ 70 June 26 bailed o dry & te	051 with 500 sks , 1950. After T dry and tested i ested for 5 hrs.	. WOC. For 2 hrs. Te	Plug was te ested OK, pl ne complete	sted on June ug was drill shut off was	28, 1950. ed, hole ba indicated	Hole Ailed •
set @ 76 June 26 bailed c dry & te	051 with 500 sks, 1950. After 1 dry and tested 1 ested for 5 hrs.	. WOC. For 2 hrs. Te	Plug was te ested OK, pl ne complete	sted on June ug was drill shut off was	28, 1950. ed, hole ba indicated	Hole Ailed •
set @ 76 June 26 bailed o dry & te	951 with 500 sks, 1950. After 1 dry and tested 1 ested for 5 hrs.  That this plan of work must Ralph Lowe.	. WOC. For 2 hrs. Te	Plug was te ested OK, pl ne complete	sted on June ug was drill shut off was	28, 1950. ed, hole be indicated	Hole Ailed •
set @ 76 June 26 bailed o dry & te	951 with 500 sks, 1950. After 1 dry and tested 1 ested for 5 hrs.  Matthiaplan of work must  Ralph Lowe  Box 832	. WOC. For 2 hrs. Te	Plug was te ested OK, pl ne complete	sted on June ug was drill shut off was	28, 1950. ed, hole be indicated	Hole Ailed •