

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPlicate
(Other instructions
reverse side)Form approved.
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

LC-061374-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐		7. UNIT AGREEMENT NAME <i>Bell Lake</i>
2. NAME OF OPERATOR <i>Continental Oil Company</i>		8. FARM OR LEASE NAME <i>Bell Lake Unit 1</i>
3. ADDRESS OF OPERATOR <i>P.O. Box 460, Hobbs, New Mexico 88240</i>		9. WELL NO. <i>14</i>
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface <i>1,650' FNL & 1,650' FWH of Sec. 5</i>		10. FIELD AND POOL, OR WILDCAT <i>Undesignated</i>
14. PERMIT NO.		11. SEC., T., R./M., OR BLK. AND SURVEY OR AREA <i>Sec. 5, T. 24 S., R. 5 E.</i>
15. ELEVATIONS (Show whether DF, RT, GR, etc.) <i>3,600' SR</i>		12. COUNTY OR PARISH <i>Lea</i>
		13. STATE <i>N. Mex.</i>

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON* ☐CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) *Setting Intermediate String* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

REPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT* ☐

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Set 10 3/4" 45.5# casing at 5,190'. Cemented with 2,235 sacks Class 'C' Cement in 3 stages; DV Collars @ 3,425' & 748'. Cemented 1st stage w/650 sacks, circ. & has thru DV tool at 3,425'; Cemented 2nd stage w/1,285 sacks, circ. & has thru DV tool at 748'; Cemented 3rd stage w/300 sacks, circ. approx. 25 sacks to surface. Tested casing with 2,000#, held O.K.

18. I hereby certify that the foregoing is true and correct.

SIGNED

*Robert J. Smith*TITLE *Division Office Manager*DATE *1-7-74*

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

ACCEPTED FOR RECORD

JAN 10 1974

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

*See Instructions on Reverse Side

USGS - Partners-6, File