

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-025-26881
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name FREDERICK H. CURRY WN
8. Well No. 3
9. Pool name or Wildcat LANGLIE MATTIX SRQ GB

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT'
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER
2. Name of Operator ARCO OIL AND GAS COMPANY
3. Address of Operator BOX 1710, HOBBS, NEW MEXICO 88240
4. Well Location Unit Letter <u>0</u> : <u>660</u> Feet From The <u>SOUTH</u> Line and <u>1980</u> Feet From The <u>EAST</u> Line Section <u>1</u> Township <u>24S</u> Range <u>36E</u> NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3344.6' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: TEMPORARILY ABANDON _____ <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 3750'; PBD 3740'; PERFS: 3396-3636'

TA & HOLD WELL BORE FOR FUTURE USE

5/6/92 MIRU. LAY DOWN RODS & PUMP. NU BOP. POOH w/TBG. RU WIRELINE. RUN GAUGE RING & JUNK BASKET TO 3405'. RIH & SET CIBP ON WIRELINE @ 3367'. RD WIRELINE. RIH w/TBG TO CIBP. SDON.

5/7/92 RU KILL TRUCK. CIRCULATE HOLE w/TREATED PACKER FLUID. PRESSURE TEST CIBP TO 320# FOR 30 MIN., OK. POOH & LAY DOWN TBG. ND BOP, NU WELL HEAD w/1 JT 2-7/8" TBG IN WELL HEAD. WELL TEMPORARILY ABANDONED 5/7/92.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE James D. Cogburn TITLE Operations Coordinator DATE 5/12/92

TYPE OR PRINT NAME James D. Cogburn TELEPHONE NO. 391-1600

(This space for State Use)

APPROVED BY JERRY SEXTON TITLE OPERATIONS SUPERVISOR DATE MAY 13 '92

CONDITIONS OF APPROVAL, IF ANY: This Approval of Temporary Abandonment Expires 5-12-97

TD.C.UT