

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE  
(Other instructions on  
reverse side)

Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

**MS-0349780**

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

**Union Federal**

9. WELL NO.

**1**

10. FIELD AND POOL, OR WILDCAT

**Field 1 (Delaware)**

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

**Sec. 13, T-25-S, R-32-E**

12. COUNTY OR PARISH

**Lee**

13. STATE

**New Mexico**

1. OIL WELL  GAS WELL  OTHER  **Dry Hole**

2. NAME OF OPERATOR  
**Petrol Corporation**

3. ADDRESS OF OPERATOR  
**610 Midland Natl Bank Bldg., Midland, Texas 79701**

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

**1980 F-1 & 660 F-1 of Section 13, T-25-S, R-32-E,  
Unit Letter M**

14. PERMIT NO.  
**Approved Sept. 2, 1970**

15. ELEVATIONS (Show whether DF, RT, GR, etc.)  
**3660 LF**

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

**25 sack plug will be bottomed at 4700', above Delaware sand porosity at 4860'.  
25 sack plug will be bottomed at 1130', above top of salt section at 1140'.  
25 sack plug will be bottomed at 830', in top of Rustler at 805'.  
25 sack plug will be bottomed at 390', bottom of surface casing at 366'.  
10 sack plug will be placed in top of surface casing.  
There will be drilling mud in hole below and between plugs.  
TD of well is 4957'.  
Work will begin immediately.**

18. I hereby certify that the foregoing is true and correct

SIGNED \_\_\_\_\_

TITLE **Division Manager**

DATE **September 18, 1970**

(This space for Federal or State Office use)

APPROVED BY \_\_\_\_\_

TITLE \_\_\_\_\_

DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

**APPROVED**  
SEP 17 1970  
ARTHUR R. BROWN  
DISTRICT ENGINEER

\*See Instructions on Reverse Side

## Instructions

**General:** This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

**Item 4:** If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

**Item 17:** Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.