

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(505) 393-6161 Fax:(505) 393-0720
District II
1301 W. Grand Ave., Artesia, NM 88210
Phone:(505) 748-1283 Fax:(505) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

Form C-103
Permit 18916

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NUMBER 30-005-63757
1. Type of Well:G		5. Indicate Type of Lease S
2. Name of Operator YATES PETROLEUM CORPORATION		6. State Oil & Gas Lease No.
3. Address of Operator 105 South Fourth St. , Artesia , NM 88210		7. Lease Name or Unit Agreement Name COMANCHE HILLS VE STATE COM
4. Well Location Unit Letter C : 660 feet from the N line and 1500 feet from the W line Section 36 Township 10S Range 25E NMPM Chaves County		8. Well Number 002
11. Elevation (Show whether DR, KB, BT, GR, etc.) 3689 GR.		9. OGRID Number 25575
10. Pool name or Wildcat See Area 13		
Pit or Below-grade Tank Application ☐ or Closure ☐ Pit Type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ TEMPORARILY ABANDON ☐ CHANGE OF PLANS ☐ PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐ Other:	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTER CASING ☐ COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDON ☐ CASING/CEMENT JOB ☐ Other: Perforations/Tubing ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.
11/4/05 Tested production casing to 1000 psi for 30 min.
11/7/05 Perforate Abo 4220'-4224'(5), 4229'-4230'(3), 4342'-4371'(30), 4382'-4388'(7) and 4448'-4460'(13).
11/8/05 Acidize Abo 4448'-4460' with 500g 7-1/2% IC acid. Acidize Abo 4342'-4388' with 1500g 7-1/2% IC. Acidize Abo 4229'-4330' with 500g 7-1/2%.
11/9/05 Frac Abo with 119,425g 60Q CO2 foam and 316,000# 20/40 Ottawa. Set AS-1 packer with 2.25" on/off tool at 4170'.

Perforations

Pool: WILDCAT GRANITE, 96542 Location: F -36-10S-25E 1650 N 1650 W

TOP	BOT	Open Hole	Shots/ft	Shot Size	Material	Stimulation	Amount
4220	4460		58				

Pool: PECOS SLOPE;ABO (GAS), 82730 Location: F -36-10S-25E 1650 N 1650 W

TOP	BOT	Open Hole	Shots/ft	Shot Size	Material	Stimulation	Amount
4220	4460		58				

Tubing

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Electronically Signed TITLE Regulatory Agent DATE 11/18/2005
Type or print name Debbie Caffall E-mail address debbiec@ypcnm.com Telephone No. 505-748-4376

For State Use Only:
APPROVED BY: Bryan Arrant TITLE Geologist DATE 11/22/2005 8:21:55 AM