

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(505) 393-6161 Fax:(505) 393-0720
District II
1301 W. Grand Ave., Artesia, NM 88210
Phone:(505) 748-1283 Fax:(505) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

Form C-103
Permit 22365

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFRENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well:G 2. Name of Operator YATES PETROLEUM CORPORATION 3. Address of Operator 105 S 4TH ST , ARTESIA , NM 88210 4. Well Location Unit Letter M : 660 feet from the S line and 1050 feet from the W line Section 25 Township 18S Range 24E NMPM Eddy County		WELL API NUMBER 30-015-34173
		5. Indicate Type of Lease S
		6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name STATE JM COM		
8. Well Number 003		
9. OGRID Number 25575		
10. Pool name or Wildcat See Area 13		
11. Elevation (Show whether DR, KB, BT, GR, etc.) 3673 GR.		
Pit or Below-grade Tank Application ☐ or Closure ☐ Pit Type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE OF PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
Other:

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTER CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDON ☐
CASING/CEMENT JOB ☐
Other: **Perforations/Tubing** ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.
1/10/06 Tested production casing to 1000 psi for 30 min.
1/11/06 TOC 1700' Est. Perforate Morrow 8570'-8593'(138). Set AS-1 10K packer at 8252'.
1/16/06 Acidize Morrow with 1500g 7-1/2% Morrow acid.

Perforations

Pool: WILDCAT GRANITE , 96542 Location: M -25-18S-24E 660 S 1050 W

TOP	BOT	Open Hole	Shots/ft	Shot Size	Material	Stimulation	Amount
-----	-----	-----------	----------	-----------	----------	-------------	--------

Pool: PENASCO DRAW;MORROW (GAS), 82770 Location: M -25-18S-24E 660 S 1050 W

TOP	BOT	Open Hole	Shots/ft	Shot Size	Material	Stimulation	Amount
8570	8593		138			Acid	

Tubing

PENASCO DRAW;MORROW (GAS) , 82770

Tubing Size	Type	Depth Set	Packer Set
2.875		8252	8252

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Electronically Signed TITLE Regulatory Agent DATE 1/30/2006

Type or print name Debbie Caffall E-mail address debbiec@ypcnm.com Telephone No. 505-748-4376

For State Use Only:

APPROVED BY: Bryan Arrant TITLE Geologist DATE 2/2/2006 8:54:22 AM