

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(505) 393-6161 Fax:(505) 393-0720
District II
1301 W. Grand Ave., Artesia, NM 88210
Phone:(505) 748-1283 Fax:(505) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

Form C-103
Permit 54427

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NUMBER 30-015-35282
1. Type of Well:G		5. Indicate Type of Lease S
2. Name of Operator MARBOB ENERGY CORP		6. State Oil & Gas Lease No.
3. Address of Operator PO Box 227, Artesia, NM 88211		7. Lease Name or Unit Agreement Name MAN STATE
4. Well Location Unit Letter I : 1780 feet from the S line and 660 feet from the E line Section 32 Township 18S Range 28E NMPM Eddy County		8. Well Number 001
11. Elevation (Show whether DR, KB, BT, GR, etc.) 3528 GR.		9. OGRID Number 14049
Pit or Below-grade Tank Application ☐ or Closure ☐ Pit Type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____		10. Pool name or Wildcat

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE OF PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
Other:

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTER CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDON ☐
CASING/CEMENT JOB ☐
Other: **Drilling/Cement** ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.
SPUD WELL @5:34 PM ON 05/25/07. DRLD 17 1/2" HOLE TO 350' @10:00 PM ON 05/25/07. RAN 8 JTS (349.60') 13 3/8" 48#
STC CSG TO 350'. CMTD W/425 SX P+, PD @9:28 AM ON 05/26/07, CIRC 42 SX TO PIT. WOC 18 HRS, TSTD CSG TO 600#
F/30 MIN - HELD OK.

05/30/07 @9:30 PM, DRLD 12 1/4" HOLE TO 2780'. RAN 70 JTS (2777.17') 8 5/8" 36# KS STC CSG TO 2780.47'. CMTD W/750
SX HLPP, TAILED IN W/250 SX P+, PD @7:27 AM ON 05/31/07, CIRC 146 SX TO PIT. WOC 18 HRS, TSTD CSG TO 1500#
F/30 MIN - HELD OK. 5/25/2007 Spudded well.

Casing and Cement Program

Date	String	Fluid Type	Hole Size	Csg Size	Weight lb/ft	Grade	Est TOC	Dpth Set	Sacks	Yield	Class	1" Dpth	Pres Held	Pres Drop	Open Hole
05/25/07	Surf		17.5	13.375	48	STC	0	350	425		P+		600	0	
05/30/07	Int1		12.25	8.625	36	KS	0	2780	1000		HLPP, P+		1500	0	

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Electronically Signed TITLE Production Analyst DATE 6/1/2007
Type or print name Diana Briggs E-mail address production@marbob.com Telephone No. 505-748-3303

For State Use Only:

APPROVED BY: Bryan Arrant TITLE Geologist DATE 6/7/2007 7:44:41 AM