

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(505) 393-6161 Fax:(505) 393-0720

District II

1301 W. Grand Ave., Artesia, NM 88210
Phone:(505) 748-1283 Fax:(505) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Permit 55288

Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

WELL API NUMBER
30-021-20428

5. Indicate Type of Lease
S

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
WEST BRAVO DOME UNIT

8. Well Number
011E

9. OGRID Number
495

10. Pool name or Wildcat

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: C

2. Name of Operator

HESS CORPORATION

3. Address of Operator

P.O. BOX 840, SEMINOLE, TX 79360

4. Well Location

Unit Letter G : 2310 feet from the N line and 1650 feet from the E line
Section 1 Township 18N Range 29E NMPM Harding County

11. Elevation (Show whether DR, KB, BT, GR, etc.)

4511 GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit Type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE OF PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

Other:

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTER CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDON ☐

CASING/CEMENT JOB ☐

Other: **Drilling/Cement** ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

MIRU Capstar Rig #5. Spud well 6/7/07. Drill to 526'. Surv.=3/4" Drill to 765'. Run 17 jts 8-5/8" csg. Set @ 760'. Centralizer every other jt. starting w/1st jt. RU Halliburton. Pump lead 250sx P+ + add. @ 13.5PPG, yld 1.74CFS. Pump tail 150sx P+ + add. @ 14.8PPG, YLD 1.34CFS. Bump plug w/900psi.Circ. 13sx to pit. WOC 4 hrs. Test BOP 250 -2000 psi. Drill f765'-1324' Surv @ 1294 1". Drill to 1831'. Surv. @ 1800-2". Drill to 2242'. Run 2222.8' 4.5" fiberglass. Cmt 4.5 Lead 75 sks Midcon P+, 11.4 PPG, 2.93 YLD; Tail 300sx MidconII P+ YLD 1.85 13.2 PPG. Cmt in place. 25sx to surf. RDMO 6/12/07 16:30. **6/7/2007** Spudded well.

Casing and Cement Program

Date	String	Fluid Type	Hole Size	Csg Size	Weight lb/ft	Grade	Est TOC	Dpth Set	Sacks	Yield	Class	1" Dpth	Pres Held	Pres Drop	Open Hole
06/08/07	Surf		12.25	8.625	24		0	760	400		PPlus		900		
06/12/07	Prod		7.875	4.5	12.75		0	2223	375		MidconPplu				

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Electronically Signed

TITLE Senior Advisor, Regulatory

DATE 6/27/2007

Type or print name Carol Moore

E-mail address cmoore@hess.com

Telephone No. 432-758-6738

For State Use Only:

APPROVED BY: Ed Martin

TITLE District Supervisor

DATE 6/29/2007 2:12:34 PM