District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(505) 393-6161 Fax:(505) 393-0720

District II

1301 W. Grand Ave., Artesia, NM 88210 Phone:(505) 748-1283 Fax:(505) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

I. Operator and Well:

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico

Energy, Minerals and Natural Resources

Permit 58118 Revised June 10, 2003

Form C-140

Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505 (505) 476-3440

APPLICATION FOR WELL WORKOVER PROJECT

Operator name & address							OGRID Number	
OCCIDENTAL PERMIAN LTD PO Box 4294							157984	
Houston TX 77210								
Contact Party Karen Ellis							Phone 713-366-5161	
Property Name Well Number NORTH HOBBS G/SA UNIT 533							API Number 30-025-35541	
UL - Lot	Section Tow		hip Range	Feet From The	North/South Line	Feet From The	East/West Line	County
J	29	189	38E	2326	S	1902	E	Lea
II. Worke	over:	NO.	20	· · · · · · · · · · · · · · · · · · ·				
Date Workover Commenced: 3/19/2007 Date Workover Completed:			Previous Producing Pool(s) (Prior to Workover): HOBBS;GRAYBURG-SAN ANDRES					
3/22/2007								
 III. Attach a description of the Workover Procedures performed to increase production. IV. Attach a production decline curve or table showing at least twelve months of production prior to the workover and at least three months of production following the workover reflecting a positive production increase. III. Attach a description of the Workover Procedures performed to increase production. 								
V. Signat								
					y knowledge and be		D	
Signature Electronically Signed Title Regulatory Team Leader Date 7/30/2007								
Type or p	rint name <u>E</u> l	izabeth	Bush-Ivie I	E-mail address	Elizabeth_Bush	@oxy.com_Tel	lephone No. 71	.3-366-5303
This A shows	IFICATION O Application is h a positive prod	F APPRO ereby appo luction inc	OVAL: roved and the above rease. By copy here					by verifies the data ent of this Approval and
Signature I	District Sup	ervisor	: Paul Kautz		District	1	Date <u>7/30/200</u>	17

VII. DATE OF NOTIFICATION TO THE SECRETARY OF THE TAXATION AND REVENUE DEPARTMENT: 7/30/2007

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE OIL CONSERVATION DIVISION DISTRICT I WELL API NO. 1220 South St. Francis Dr. 1625 N. French Dr., Hobbs, NM 88240 30-025-35541 Santa Fe, NM 87505 DISTRICT II 5. Indicate Type of Lease 1301 W. Grand Ave, Artesia, NM 88210 STATE X FEE DISTRICT III 6. State Oil & Gas Lease No. 1000 Rio Brazos Rd, Aztec, NM 87410 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A North Hobbs (G/SA) Unit DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.) Section 29 1. Type of Well: 8. Well No. 533 Oil Well X Gas Well Other 2. Name of Operator 9. OGRID No. 157984 Occidental Permian Ltd. 3. Address of Operator 10. Pool name or Wildcat Hobbs (G/SA) HCR I Box 90 Denver City, TX 79323 4. Well Location Unit Letter J : 2326 Feet From The Feet From The South 1902 East Line Section 29 Township 18-S Range 38-E **NMPM** Lea County 11. Elevation (Show whether DF, RKB, RT GR, etc.) 3646' GL Pit or Below-grade Tank Application or Closure Pit Type _____ Depth of Ground Water Distance from nearest fresh water well ______ Distance from nearest surface water Pit Liner Thickness Below-Grade Tank: Volume _____ bbls; Construction Material mil 12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING **TEMPORARILY ABANDON** CHANGE PLANS COMMENCE DRILLING OPNS. PLUG & ABANDONMENT PULL OR ALTER CASING Multiple Completion CASING TEST AND CEMENT JOB OTHER: OTHER: Repair ESP/Acid Treat 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. I. RUPU & RU. Kill well. 2. RU wireline & perforate tubing. RD wireline. 3. NDWH & NUBOP. POOH w/ESP equipment. 4. RIH w/bit & scraper, tag @4375'. 5. RIH w/5-1/2" treating packer set @4080'. 6. RU HES & pump 420 gal of Xylene & acidize perfs 4116-4303' w/2000 gal os 15% PAD acid & 1500# rock salt. RD HES. 7. RU pump truck & pump 200 gal of 6490 mixed w/100 bbl of fresh water. Flush w/500 bbl fresh water. RD pump truck. 8. POOH w/treating packer. 9. RIH w/ESP equipment on 125 jts of 2-7/8" tubing. Intake set @4070' 10. NDBOP & NUWH. 11. RDPU & RU. Clean location. RUPU 03/19/2007 RDPU 03/22/2007 I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan SIGNATURE TITLE Administrative Associate DATE 04/07/2007 TYPE OR PRINT NAME Mendy A. Johnson E-mail address: Mendy_johnson@oxy.com TELEPHONE NO. 806-592-6280 For State Use Only APPROVED BY TITLE DATE

CONDITIONS OF APPROVAL IF ANY: