

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(505) 393-6161 Fax:(505) 393-0720

District II

1301 W. Grand Ave., Artesia, NM 88210
Phone:(505) 748-1283 Fax:(505) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico

Energy, Minerals and Natural Resources

Form C-103
Permit 75945

Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

WELL API NUMBER
30-015-36256

5. Indicate Type of Lease
S

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
FOC B STATE

8. Well Number
012

9. OGRID Number
8041

10. Pool name or Wildcat
See Area 13

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:O

2. Name of Operator

FOREST OIL CORPORATION

3. Address of Operator

707 17TH ST , , SUITE 3600 DENVER , CO 80202

4. Well Location

Unit Letter P : 10 feet from the S line and 110 feet from the E line
Section 16 Township 17S Range 31E NMPM Eddy County

11. Elevation (Show whether DR, KB, BT, GR, etc.)
3838 GR.

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit Type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE OF PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

Other:

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTER CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDON ☐

CASING/CEMENT JOB ☐

Other: **Perforations/Tubing** ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

5-13-08 MIRU NU WH & BOP

5-14-08 /ran GR to PBTD to 3963'. Found green crnt in junk basket. Pulled CBL from PBTD 3970' to surf. TOC @ Surf.PU to 3000'

5-15-08 Perf & Acidized L Jackson. 3895-3924 Acid w/2500 gals 15% acid. Released pkc.RIH & set prk @3710. Acid 3820-3924 w/7900 gals 15% acid.

5-22-08 WO COOp to set Meter.

Perforations

Pool: GRAYBURG JACKSON;SR-Q-G-SA , 28509 Location: P -16-17S-31E 10 S 110 E

TOP	BOT	Open Hole	Shots/ft	Shot Size	Material	Stimulation	Amount
3820	3924		2			Acid	2500
3706	3924		2			Acid	

Tubing

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐ .

SIGNATURE Electronically Signed TITLE Sr. Regulatory Tech DATE 5/30/2008

Type or print name Cindy Bush E-mail address cbush@forestoil.com Telephone No. 303-812-1554

For State Use Only:

APPROVED BY: Tim Gum TITLE District Supervisor DATE 6/2/2008 2:45:19 PM