

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(505) 393-6161 Fax:(505) 393-0720
District II
1301 W. Grand Ave., Artesia, NM 88210
Phone:(505) 748-1283 Fax:(505) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

Form C-103
Permit 86693

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NUMBER 30-025-39198
1. Type of Well:O		5. Indicate Type of Lease S
2. Name of Operator ARENA RESOURCES, INC		6. State Oil & Gas Lease No.
3. Address of Operator 6555 S LEWIS , TULSA , OK 74136		7. Lease Name or Unit Agreement Name EAST HOBBS SAN ANDRES UNIT
4. Well Location Unit Letter N : 220 feet from the S line and 1110 feet from the W line Section 29 Township 18S Range 39E NMPM Lea County		8. Well Number 813
11. Elevation (Show whether DR, KB, BT, GR, etc.) 999 GR		9. OGRID Number 220420
Pit or Below-grade Tank Application ☐ or Closure ☐ Pit Type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____		10. Pool name or Wildcat

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE OF PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
Other:

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTER CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDON ☐
CASING/CEMENT JOB ☐
Other: **Drilling/Cement** ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.
Drill to 238'. WLS @198'=1degree. Drill to 507'. WLS @467'=3/4degree. Drill to 746. WLS @706'=1/2degree. Drill to 987. WLS @947' = 1/4degree. Drill to 1209'. WLS @1169' = 1/2degree. Drill to 1494'. WLS @1454 = 1/4degree. Drill to 1899'. RU casing crew, run 46 jts 8 5/8 24# J55. Set @1899'. Cement with 830sks lead C=4%Salt+.25#SX/CF+3#SX/LCM-1+4%Gel, 200sks tail C+1% CACL. Circ 150sks to pit. WOC 6hrs. Test BOP, blind rams, pipe rams & choke manifold to 1000 psi. Tag cement @1800', plug @1851'. Test shoe to 200#, ok.12/3/2008 Spudded well.

Casing and Cement Program

Date	String	Fluid Type	Hole Size	Csg Size	Weight lb/ft	Grade	Est TOC	Dpth Set	Sacks	Yield	Class	1" Dpth	Pres Held	Pres Drop	Open Hole
	Surf	FreshWater	12.25	8.625	24	J55		1899	1030	1.78	C		1000		

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Electronically Signed TITLE DATE 12/11/2008
Type or print name Anita Adams E-mail address aadams@arenaresourcesinc.com Telephone No. 918-747-6060

For State Use Only:

APPROVED BY: Paul Kautz TITLE Geologist DATE 12/11/2008 2:53:57 PM