

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(505) 393-6161 Fax:(505) 393-0720
District II
1301 W. Grand Ave., Artesia, NM 88210
Phone:(505) 748-1283 Fax:(505) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

Form C-103
Permit 88650

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well:O 2. Name of Operator CHESAPEAKE OPERATING, INC. 3. Address of Operator P. O. BOX 18496 , OKLAHOMA CITY, OK 731540496 4. Well Location Unit Letter D : 330 feet from the N line and 330 feet from the W line Section 16 Township 21S Range 32E NMPM Lea County		WELL API NUMBER 30-025-38907
		5. Indicate Type of Lease S
		6. State Oil & Gas Lease No.
		7. Lease Name or Unit Agreement Name LOST TANK 16 STATE
		8. Well Number 004
		9. OGRID Number 147179
		10. Pool name or Wildcat See Area 13
11. Elevation (Show whether DR, KB, BT, GR, etc.) 3652 GR.		
Pit or Below-grade Tank Application ☐ or Closure ☐ Pit Type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____ Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE OF PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
Other:

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTER CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDON ☐
CASING/CEMENT JOB ☐
Other: **Perforations/Tubing** ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work.) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.
12/29/08-1/13/2009:

Pf w/2 jspf 8504-22 & 8547-54. Azid w/3000 gals 15% NeFe. Frac w/ Borate Fluid, Ottawa Sd & SLC. CIBP@ 8000' Perf w/2 jspf 7032-48 & 7184-98. Azid w/3000 gals NeFe. Frac w/Borate XL Fluid, Ottawa Sd & SLC. CIBP@ 6910'. Perf w/2 jspf 6698-6707. Azid w/ 1500 gal 15% NeFe. Frac w/Borate Fluid, Ottawa Sd & SLC. DO CIBPs. Tubing production set at 6680 on 1/13/2009.

Perforations

Pool: LOST TANK,DELAWARE, 40299 Location: D -16-21S-32E 330 N 330 W

TOP	BOT	Open Hole	Shots/ft	Shot Size	Material	Stimulation	Amount
8504	8554	N	2		Sand	Acid	3000
7032	7198	N	2		Sand	Acid	3000
6698	6707	N	2		Sand	Acid	1500

Tubing

LOST TANK,DELAWARE, 40299

Tubing Size	Type	Depth Set	Packer Set
2.875	N-80	6681	

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐ , a general permit ☐ or an (attached) alternative OCD-approved plan ☐ .

SIGNATURE Electronically Signed TITLE Sr. Regulatory Comp. Spec. DATE 1/19/2009

Type or print name Brenda Coffman E-mail address bcoffman@chkenergy.com Telephone No. 817-556-5825

For State Use Only:

APPROVED BY: Paul Kautz TITLE Geologist DATE 1/22/2009 6:56:27 AM