

3/31/2020

C-145

Form C-145
Revised May 19, 2017

Permit 279420

District I1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720**District II**811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720**District III**1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170**District IV**1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural
Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505
Change of Operator

Previous Operator Information**New Operator Information**

		Effective Date:	Effective on the date of approval by the OCD
OGRID:	7377	OGRID:	329877
Name:	EOG RESOURCES INC	Name:	IACX Production LLC
Address:	P.O. Box 2267	Address:	5001 LBJ Freeway, Suite 300
City, State, Zip:	Midland, TX 79702	City, State, Zip:	Dallas, TX 75244

I hereby certify that the rules of the Oil Conservation Division ("OCD") have been complied with and that the information on this form and the certified list of wells is true to the best of my knowledge and belief.

Additionally, by signing below, IACX Production LLC certifies that it has read and understands the following synopsis of applicable rules.

PREVIOUS OPERATOR certifies that all below-grade tanks constructed and installed prior to June 16, 2008 associated with the selected wells being transferred are either (1) in compliance with 19.15.17 NMAC, (2) have been closed pursuant to 19.15.17.13 NMAC or (3) have been retrofitted to comply with Paragraphs 1 through 4 of 19.15.17.11(l) NMAC.

IACX Production LLC understands that the OCD's approval of this operator change:

1. constitutes approval of the transfer of the permit for any permitted pit, below-grade tank or closed-loop system associated with the selected wells; and
2. constitutes approval of the transfer of any below-grade tanks constructed and installed prior to June 16, 2008 associated with the selected wells, regardless of whether the transferor has disclosed the existence of those below-grade tanks to the transferee or to the OCD, and regardless of whether the below-grade tanks are in compliance with 19.15.17 NMAC.

As the operator of record of wells in New Mexico, IACX Production LLC agrees to the following statements:

1. Initials JS I am responsible for ensuring that the wells and related facilities comply with applicable statutes and rules, and am responsible for all regulatory filings with the OCD. I am responsible for knowing all applicable statutes and rules, not just the rules referenced in this list. I understand that the OCD's rules are available on the OCD website under "Rules," and that the Water Quality Control Commission rules are available on the OCD website on the "Publications" page.
2. Initials JS I understand that if I acquire wells from another operator, the OCD must approve the operator change before I begin operating those wells. See Subsection B of 19.15.9.9 NMAC. I understand that if I acquire wells or facilities subject to a compliance order addressing inactive wells or environmental cleanup, before the OCD will approve the operator change it may require me to enter into an enforceable agreement to return those wells to compliance. See Paragraph (2) of Subsection C of 19.15.9.9 NMAC.
3. Initials JS I must file a monthly C-115 report showing production for each non-plugged well completion for which the OCD has approved an allowable and authorization to transport, and injection for each injection well. See 19.15.7.24 NMAC. I understand that the OCD may cancel my authority to transport from or inject into all the wells I operate if I fail to file C-115 reports. See Subsection C of 19.15.7.24 NMAC.
4. Initials JS I understand that New Mexico requires wells that have been inactive for certain time periods to be plugged or placed in approved temporary abandonment. See 19.15.25.8 NMAC. I understand the requirements for plugging and approved temporary abandonment in 19.15.25 NMAC. I understand that I can check my compliance with the basic requirements of 19.15.25.8 NMAC by using the "Inactive Well List" on OCD's website.
5. Initials JS I must keep current with financial assurances for well plugging. I understand that New Mexico requires each state or fee well that has been inactive for more than two years and has not been plugged and released to be covered by a single-well financial assurance or a "blanket plugging financial assurance for wells in temporarily abandoned statuses", even if the well is also covered by a blanket financial assurance and even if the well is on approved temporary abandonment status. See Subsection C of 19.15.8.9 NMAC. I understand that I can check my compliance with the financial assurance requirement by using the "Inactive Well Additional Financial Assurance Report" on the OCD's website.
6. Initials JS I am responsible for reporting and remediating releases pursuant to 19.15.29 NMAC. I understand the OCD will look to me as the operator of record to take corrective action for releases at my wells and related facilities, including releases that occurred before I became operator of record. I am responsible for conducting my own due diligence for any releases that have occurred prior to becoming operator of my wells and related facilities and am responsible for any open releases or unreported releases.
7. Initials JS I have read 19.15.5.9 NMAC, commonly known as "Part 5.9," and understand that to be in compliance with its requirements I must have the appropriate financial assurances in place, comply with orders requiring corrective action, pay penalties assessed by the courts or agreed to by me in a settlement agreement, and not have too many wells out of compliance with the inactive well rule (19.15.25.8 NMAC). If I am in violation of Part 5.9, I may not be allowed to drill, acquire or produce any additional wells, and will not be able to obtain any new injection permits. See 19.15.16.19 NMAC, 19.15.26.8 NMAC, 19.15.9.9 NMAC and 19.15.14.10 NMAC. If I am in violation of Part 5.9 the OCD may, after notice and hearing, revoke my existing injection permits and seek other relief. See 19.15.26.8 NMAC and 19.15.5.10 NMAC.
8. Initials JS For Injection wells, I understand that I must report injection on my monthly C-115 report and must operate my wells in compliance with 19.15.26 NMAC and the terms of my Injection permit. I understand that I must conduct mechanical integrity tests on my injection wells at least once every five years. See 19.15.26.11 NMAC. I understand that when there is a continuous one-year period of non-injection into all wells in an injection or storage project or into a saltwater disposal well or special purpose injection well, authority for that injection automatically terminates. See 19.15.26.12 NMAC. I understand that if I transfer operation of an injection well to another operator, the OCD must approve the transfer of authority to inject, and the OCD may require me to demonstrate the well's mechanical integrity prior to approving that transfer. See 19.15.26.15 NMAC.
9. Initials JS I am responsible for providing the OCD with my current address of record and emergency contact information, and I am responsible for updating that information when it changes. See Subsection C of 19.15.9.8 NMAC. I understand that I can update that information on the OCD's website under "Electronic Permitting."
10. Initials JS If I transfer well operations to another operator, the OCD must approve the change before the new operator can begin operations. See Subsection B of 19.15.9.9 NMAC. I remain responsible for the wells and related facilities and all related regulatory filings until the OCD approves the operator change. I understand that the transfer will not relieve me of responsibility or liability for any act or omission which occurred while I operated the wells and related facilities.
11. Initials JS No person with an interest exceeding 25% in the undersigned company is, or was within the last 5 years, an officer, director, partner or person with a 25% or greater interest in another entity that is not currently in compliance with Subsection A of 19.15.5.9 NMAC.
12. Initials JS NMOC Rule Subsection E and F of 19.15.16.8 NMAC: An operator shall have 90 days from the effective date of an operator name change to change the operator name on the well sign unless the division grants an extension time, for good cause shown, along with a schedule for making the changes. Each sign shall show the (1) well number, (2) property name, (3) operator's name, (4) location by footage, quarter-quarter section, township and range (or unit letter can be substituted for the quarter-quarter section), and (5) API number.


3/31/2020

C-145

I hereby certify I understand the above. The statements I have made are true and correct and a condition precedent to the Oil Conservation Division accepting this Change of Operator.

Previous Operator

Signature:



Printed Name:

Reese Linton

Title:

VP & GM Alaska

Date:

3/31/20 Phone: 817 374 3289

New Operator

Signature:



Printed Name:

JEREMY JORDAN

Title:

MANAGER

Date:

3/31/20 Phone: 972 960 3210

Permit 279420

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural
Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

Wells Selected for Transfer

Permit 279420

431 Wells Selected for Transfer

From:	EOG RESOURCES INC	OGRID:	7377
To:	IACX Production LLC	OGRID:	329877

OCD District: Artesia (431 Wells selected.)

Property	Well	Lease Type	ULSTR	OCD Unit	API	Pool ID	Pool Name	Well Type	Last Prod/Inj	Single Well Bond Required for Inactive Well
323194	ACME #001	P	L-29-08S-26E	L	30-005-60647	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	ACME #002	P	G-29-08S-26E	G	30-005-60894	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	ACME #003	P	J-30-08S-26E	J	30-005-60895	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	ACME #006	P	J-29-08S-26E	J	30-005-61169	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	ACME #008	P	F-29-08S-26E	F	30-005-61171	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323202	AIKMAN BDK STATE COM #001	S	P-36-06S-26E	P	30-005-61804	78320	HAYSTACK; CISCO (GAS)	G	01/20	0
323205	ALBITUS TH FEDERAL #001	F	B-21-07S-25E	B	30-005-61439	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	ALBITUS TH FEDERAL #002	F	E-21-07S-25E	E	30-005-61746	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	ALBITUS TH FEDERAL #003	F	N-21-07S-25E	N	30-005-61747	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	ALBITUS TH FEDERAL #004	F	I-21-07S-25E	I	30-005-61689	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323212	ALLIED AUS STATE COM #001	S	G-33-09S-26E	G	30-005-60275	76750	FOOR RANCH; WOLFCAMP (GAS)	G	01/20	0
	ALLIED AUS STATE COM #002	S	L-33-09S-26E	L	30-005-63287	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
					30-005-63287	76750	FOOR RANCH; WOLFCAMP (GAS)			
323231	ANCHITO AZE FEDERAL COM #001	F	P-26-10S-25E	P	30-005-63742	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323265	AURORA AUR STATE #001	S	I-16-09S-26E	I	30-005-63236	76750	FOOR RANCH; WOLFCAMP (GAS)	G	01/20	0
323269	AVENUE AVU STATE #001	S	I-21-09S-26E	I	30-005-63259	76755	FOOR RANCH; WOLFCAMP, NORTH (GAS)	G	01/20	0
	AVENUE AVU STATE #002	S	K-21-09S-26E	K	30-005-63260	76755	FOOR RANCH; WOLFCAMP, NORTH (GAS)	G	01/20	0
323295	BASIL ANS COM #001	F	A-23-07S-25E	A	30-005-63012	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323298	BASKETBALL BBI FEDERAL #001	F	D-12-12S-26E	D	30-005-62792	96542	WILDCAT; GRANITE	G	01/20	0
					30-005-62792	97361	COYOTE; WOLFCAMP (G)			
323300	BEAN #001	P	M-20-07S-26E	M	30-005-61837	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323301	BEAN COM #002	P	H-20-07S-26E	H	30-005-63136	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0

323302	BEARD QQ FEDERAL #002	F	C-18-07S-26E	C	30-005-61840	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323303	BEARD QQ FEDERAL COM #001	F	4-18-07S-26E	M	30-005-60934	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323307	BEDFORD FEDERAL COM. #001	F	J-31-06S-25E	J	30-005-60791	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323322	BESTWALL ST #002	P	M-20-08S-26E	M	30-005-63229	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323323	BESTWALL ST. COM #001	P	N-20-08S-26E	N	30-005-61573	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323332	BINNION TT FEDERAL #001	F	G-24-07S-25E	G	30-005-61915	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	BINNION TT FEDERAL #002	F	K-24-07S-25E	K	30-005-61916	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	BINNION TT FEDERAL #006	F	I-24-07S-25E	I	30-005-61938	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	BINNION TT FEDERAL #007	F	A-24-07S-25E	A	30-005-63350	82730	PECOS SLOPE; ABO (GAS)	O	01/20	0
					30-005-63350	97150	COYOTE; DRAW; PERMO PENNSYLVANIAN (G)			
323333	BIPLANE BLW STATE COM #006	S	N-16-06S-27E	N	30-005-63979	78320	HAYSTACK; CISCO (GAS)	G	01/20	0
					30-005-63979	97457	WILDCAT PRE-CAMBRIAN			
323337	BITTER LAKE FEDERAL COM #001	F	J-05-09S-25E	J	30-005-61444	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323338	BITTERSWEET AOZ STATE COM #001	F	J-28-09S-26E	J	30-005-62756	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
					30-005-62756	76755	FOOR RANCH; WOLFCAMP, NORTH (GAS)			
323345	BLANCO #002	P	B-12-07S-25E	B	30-005-61249	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323360	BOFFIN BLY STATE COM #002	S	F-16-09S-27E	F	30-005-64061	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
323375	BOSQUE GRANDE SQ FED #002	F	H-17-07S-26E	H	30-005-62264	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323377	BOSQUE GRANDE SQ FEDERAL COM #001	F	A-08-07S-26E	A	30-005-61510	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323387	BOXCAR BCX FEDERAL COM #001	F	P-25-10S-25E	P	30-005-63572	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323412	BUDER ACN FEDERAL #001	F	D-22-06S-26E	D	30-005-62283	82730	PECOS SLOPE; ABO (GAS)	G	01/19	0
	BUDER ACN FEDERAL #002	F	K-22-06S-26E	K	30-005-63513	97263	BOSQUE; PENNSYLVANIAN (G)	G	01/20	0
					30-005-63513	97282	CROCKETT DRAW; WOLFCAMP (G)			
	BUDER ACN FEDERAL #003	F	F-22-06S-26E	F	30-005-63576	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323421	BURTIS COM #002	P	A-11-07S-25E	A	30-005-61230	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323427	BYERS ZV #001	P	N-08-08S-26E	N	30-005-62162	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
					30-005-62162	97179	ROCK SCHOOL HOUSE, NE (G)			
323431	CACTUS FLOWERS AMC STATE #001	S	K-19-08S-27E	K	30-005-62557	70005	ACME; PENN, SOUTH (GAS)	G	01/20	0
323448	CARDDECK BDD STATE COM #001	S	N-16-10S-26E	N	30-005-63608	76750	FOOR RANCH; WOLFCAMP (GAS)	G	01/20	0
					30-005-63608	82730	PECOS SLOPE; ABO (GAS)			
323461	CASINO AXC STATE #001	S	K-02-10S-26E	K	30-005-63403	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
323466	CATTERSON SS FEDERAL #001	F	P-21-07S-26E	P	30-005-61544	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	CATTERSON SS FEDERAL #002	F	K-21-07S-26E	K	30-005-61941	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	CATTERSON SS FEDERAL #003	F	A-07-07S-26E	A	30-005-62758	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0

	CATTERSON SS FEDERAL #004	F	2-07-07S-26E	E	30-005-62721	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	CATTERSON SS FEDERAL #005	F	K-07-07S-26E	K	30-005-62833	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	CATTERSON SS FEDERAL #006	F	O-07-07S-26E	O	30-005-62857	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	CATTERSON SS FEDERAL #007	F	I-21-07S-26E	I	30-005-63033	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	CATTERSON SS FEDERAL #008	F	N-21-07S-26E	N	30-005-63326	80145	LESLIE SPRING; PENN (GAS)	G	12/19	0
323485	CHARLIE ZA FEDERAL #001	F	O-22-08S-26E	O	30-005-62134	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	CHARLIE ZA FEDERAL #002	F	H-22-08S-26E	H	30-005-63499	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	CHARLIE ZA FEDERAL #003	F	L-23-08S-26E	L	30-005-63581	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323487	CHARLOTTE FEDERAL #001	F	1-30-07S-26E	D	30-005-61194	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	CHARLOTTE FEDERAL #003	F	B-30-07S-26E	B	30-005-61304	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323488	CHARLOTTE FEDERAL COM #005	F	E-29-07S-26E	E	30-005-61480	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323524	COFFMAN NY FEDERAL #001	F	E-25-07S-25E	E	30-005-60742	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	COFFMAN NY FEDERAL #002	F	A-25-07S-25E	A	30-005-61421	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	COFFMAN NY FEDERAL #003	F	C-25-07S-25E	C	30-005-63089	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323530	COMANCHE HILLS VE STATE #001	F	B-36-10S-25E	B	30-005-61754	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323531	COMANCHE HILLS VE STATE COM #002	S	F-36-10S-25E	F	30-005-63757	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
					30-005-63757	96542	WILDCAT; GRANITE			
323532	COMANCHE HILLS ZU FEDERAL #001	F	N-25-10S-25E	N	30-005-62168	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323534	COMANCHERO BCZ FEDERAL COM #001	F	E-26-10S-25E	E	30-005-62113	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
					30-005-62113	97347	BITTER LAKES; PENN. (G)			
323540	CONEJO RH STATE #001	S	P-02-07S-25E	P	30-005-61026	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	CONEJO RH STATE #002	S	M-02-07S-25E	M	30-005-61201	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	CONEJO RH STATE #004	S	E-02-07S-25E	E	30-005-61329	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	CONEJO RH STATE #005R	S	F-02-07S-25E	F	30-005-63233	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
					30-005-63233	97129	FIVE MILE DRAW; PENN (G)			
323548	COOKER BCB FEDERAL COM #003	F	J-14-06S-26E	J	30-005-63996	96079	WC; SILURIAN (GAS) DO NOT USE	G	12/19	0
					30-005-63996	96542	WILDCAT; GRANITE			
					30-005-63996	97284	ALKALI DRAW; SILURO-DEVONIAN			
323556	CORNETT TI #001	P	1-03-08S-26E	A	30-005-61575	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323557	CORONET TI #002	P	H-03-08S-26E	H	30-005-63231	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	CORONET TI #003	P	G-03-08S-26E	G	30-005-63369	97110	LESLIE SPRING; WOLFCAMP,SOUTH (G)	G	01/20	0
323562	COTTONWOOD FEDERAL #001	F	I-26-06S-25E	I	30-005-60959	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	COTTONWOOD FEDERAL #002	F	H-26-06S-25E	H	30-005-61136	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	COTTONWOOD FEDERAL #003	F	B-26-06S-25E	B	30-005-62992	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	COTTONWOOD FEDERAL #005	F	J-26-06S-25E	J	30-005-63448	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0

					30-005-63448	97285	CROCKETT DRAW; WOLFCAMP (G)			
323564	COTTONWOOD RANCH MK STATE #002	S	F-36-06S-25E	F	30-005-61471	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	COTTONWOOD RANCH MK STATE #003	S	M-36-06S-25E	M	30-005-61491	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	COTTONWOOD RANCH MK STATE #004	S	O-36-06S-25E	O	30-005-61581	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	COTTONWOOD RANCH MK STATE #005	S	H-36-06S-25E	H	30-005-63148	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	COTTONWOOD RANCH MK STATE #006	S	D-36-06S-25E	D	30-005-63421	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323566	COYOTE FEDERAL #001	F	H-05-07S-25E	H	30-005-60759	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	COYOTE FEDERAL #002	F	H-08-07S-25E	H	30-005-60779	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	COYOTE FEDERAL #004	F	E-20-07S-25E	E	30-005-60818	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	COYOTE FEDERAL #005	F	H-19-07S-25E	H	30-005-60860	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	COYOTE FEDERAL #006	F	I-08-07S-25E	I	30-005-61209	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	COYOTE FEDERAL #008	F	K-20-07S-25E	K	30-005-61217	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	COYOTE FEDERAL #009	F	I-19-07S-25E	I	30-005-61296	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323568	CRANDALL UD #001	P	H-06-07S-26E	H	30-005-61576	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	CRANDALL UD #002	P	2-06-07S-26E	B	30-005-63016	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323569	CRAWFORD FEDERAL COM #001	F	I-30-07S-26E	I	30-005-61579	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	CRAWFORD FEDERAL COM #004	F	3-31-07S-26E	L	30-005-61533	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323574	CROSBY TV FEDERAL #002	F	F-15-08S-25E	F	30-005-63218	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323579	CUMMINGS TO FEDERAL #002	F	G-14-08S-25E	G	30-005-61917	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323586	DALLAS AUE STATE COM #001	S	I-35-09S-26E	I	30-005-63237	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
					30-005-63237	76750	FOOR RANCH; WOLFCAMP (GAS)			
	DALLAS AUE STATE COM #005	S	N-34-09S-26E	N	30-005-63481	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
					30-005-63481	76750	FOOR RANCH; WOLFCAMP (GAS)			
323587	DANDELION AFW FEDERAL COM #001	F	H-10-09S-26E	H	30-005-62708	82730	PECOS SLOPE; ABO (GAS)	G	12/19	0
323588	DATIL BFD STATE COM #001	S	N-02-09S-26E	N	30-005-63689	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
					30-005-63689	76750	FOOR RANCH; WOLFCAMP (GAS)			
					30-005-63689	82730	PECOS SLOPE; ABO (GAS)			
323590	DAVIS #001	P	L-12-07S-25E	L	30-005-60868	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	DAVIS #003	P	D-12-07S-25E	D	30-005-61147	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	DAVIS #004	P	F-12-07S-25E	F	30-005-63122	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	DAVIS #005	P	N-12-07S-25E	N	30-005-63123	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323616	DELHAGEN BAJ COM #001	P	3-06-10S-25E	C	30-005-63508	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0

323619	DESERT ROSE ALS #002	S	P-11-09S-26E	P	30-005-62569	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323620	DESERT ROSE ALS STATE #003	S	F-11-09S-26E	F	30-005-62591	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
323622	DIAMOND A #001	P	G-29-07S-26E	G	30-005-61783	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323624	DICE BHD STATE COM #003	S	D-10-10S-26E	D	30-005-64110	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
					30-005-64110	76750	FOOR RANCH; WOLFCAMP (GAS)			
323644	DOROTHY VO FEDERAL #001	F	M-05-08S-26E	M	30-005-60173	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	DOROTHY VO FEDERAL #002	F	E-14-08S-26E	E	30-005-63376	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323647	DRAGONFLY ARX STATE #001	S	1-30-09S-27E	D	30-005-62566	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323650	DUNCAN LH FEDERAL #001Y	F	3-03-08S-25E	C	30-005-60599	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	DUNCAN LH FEDERAL #002	F	J-03-08S-25E	J	30-005-61939	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	DUNCAN LH FEDERAL #003	F	N-03-08S-25E	N	30-005-61922	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	DUNCAN LH FEDERAL #004	F	F-03-08S-25E	F	30-005-63256	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323691	ELECTROLUX BCE STATE #001	S	D-17-10S-26E	D	30-005-63553	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323696	ENERGY AFY STATE #003	S	P-36-09S-26E	P	30-005-63624	76750	FOOR RANCH; WOLFCAMP (GAS)	G	01/20	0
323699	ENGWALL RL FEDERAL #001	F	P-04-09S-26E	P	30-005-61123	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	ENGWALL RL FEDERAL #002	F	H-04-09S-26E	H	30-005-62576	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	ENGWALL RL FEDERAL #003	F	1-04-09S-26E	A	30-005-63244	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	10/19	0
					30-005-63244	97066	FOOR RANCH; WOLFCAMP, NORTHWEST			
	ENGWALL RL FEDERAL #004	F	J-04-09S-26E	J	30-005-63284	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
					30-005-63284	97066	FOOR RANCH; WOLFCAMP, NORTHWEST			
					30-005-63284	97117	FOOR RANCH; PRE-PERMIAN, NW (G)			
323700	ENRON AEY STATE #001	S	K-25-09S-26E	K	30-005-62595	76750	FOOR RANCH; WOLFCAMP (GAS)	G	01/20	0
323702	ERICKSON KY STATE #001	S	H-02-10S-25E	H	30-005-60564	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	ERICKSON KY STATE #002	S	1-02-10S-25E	A	30-005-62579	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323703	ERMA #001	P	M-01-10S-24E	M	30-005-61739	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323704	ERMA COM #002	P	1-01-10S-24E	1	30-005-63502	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
					30-005-63502	97281	LOST LAKE; WOLFCAMP (G)			
323709	EUBANKS BEN COM #001	S	O-22-09S-24E	O	30-005-63686	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
					30-005-63686	96542	WILDCAT; GRANITE			
323710	EUREKA UK STATE #001	S	D-20-10S-26E	D	30-005-61612	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	EUREKA UK STATE #002	S	I-20-10S-26E	I	30-005-64040	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
	EUREKA UK STATE #003	S	B-20-10S-26E	B	30-005-64124	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
323712	EXACTA AXE STATE #001	S	B-09-10S-26E	B	30-005-63512	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
323713	EXPENDITURE AXY STATE #001	S	D-09-10S-26E	D	30-005-63461	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0

323720	FAXON BFS STATE COM #001	S	3-02-09S-26E	C	30-005-63717	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
323754	FEDERAL HJ #003	F	C-31-06S-26E	C	30-005-61420	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	FEDERAL HJ #004	F	K-31-06S-26E	K	30-005-61484	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	FEDERAL HJ #006	F	A-31-06S-26E	A	30-005-61456	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	FEDERAL HJ #007	F	P-31-06S-26E	P	30-005-61485	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	FEDERAL HJ #008	F	A-19-06S-26E	A	30-005-61486	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	FEDERAL HJ #011	F	G-31-06S-26E	G	30-005-63091	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	FEDERAL HJ #012	F	3-31-06S-26E	L	30-005-63127	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	FEDERAL HJ #013	F	D-31-06S-26E	D	30-005-63495	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
					30-005-63495	97303	LESLIE SPRING; WOLFCAMP, NW (G)			
323756	FEDERAL HY #002	F	O-33-07S-25E	O	30-005-60555	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	FEDERAL HY #005	F	F-34-07S-25E	F	30-005-61860	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	FEDERAL HY #006	F	A-28-07S-25E	A	30-005-61853	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	FEDERAL HY #007	F	A-34-07S-25E	A	30-005-61943	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	FEDERAL HY #008	F	J-34-07S-25E	J	30-005-61957	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	FEDERAL HY #009	F	I-28-07S-25E	I	30-005-62082	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	FEDERAL HY #011	F	A-33-07S-25E	A	30-005-62110	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	FEDERAL HY #012Q	F	C-28-07S-25E	C	30-005-63503	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323757	FEDERAL IX #001	F	L-03-09S-26E	L	30-005-60467	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	FEDERAL IX #002	F	4-03-09S-26E	D	30-005-62063	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323767	FILAREE AEL FEDERAL #001	F	O-33-08S-26E	O	30-005-62486	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	FILAREE AEL FEDERAL #002	F	K-33-08S-26E	K	30-005-62704	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	FILAREE AEL FEDERAL #004	F	M-33-08S-26E	M	30-005-63252	97117	FOOR RANCH; PRE-PERMIAN, NW (G)	G	01/20	0
	FILAREE AEL FEDERAL #006	F	K-26-08S-26E	K	30-005-63988	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
					30-005-63988	82730	PECOS SLOPE; ABO (GAS)			
	FILAREE AEL FEDERAL #007	F	C-26-08S-26E	C	30-005-63665	97066	FOOR RANCH; WOLFCAMP, NORTHWEST	G	01/20	0
	FILAREE AEL FEDERAL #008	F	H-27-08S-26E	H	30-005-63750	97066	FOOR RANCH; WOLFCAMP, NORTHWEST	G	01/20	0
323768	FILAREE AEL FEDERAL COM #003	F	E-33-08S-26E	E	30-005-62913	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323769	FINLEY RV COM #001Y	P	K-34-06S-25E	K	30-005-61325	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	FINLEY RV COM #002	P	H-33-06S-25E	H	30-005-62699	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323779	FOOTBALL BCF FEDERAL #001	F	N-01-12S-26E	N	30-005-63603	97418	SAND DRAW; ABO (G)	G	01/20	0
	FOOTBALL BCF FEDERAL #002H	F	I-01-12S-26E	I	30-005-64020	97361	COYOTE; WOLFCAMP (G)	G	01/20	0
323790	FRANCIS FEDERAL COM. #001	F	F-13-08S-25E	F	30-005-62064	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323156	FRANK SR. COM #001	S	I-15-05S-24E	I	30-005-62744	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0

323799	GALLETTA YT STATE #001	S	L-02-07S-26E	L	30-005-62085	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323812	GEORGE QJ FEDERAL #001	F	A-34-06S-25E	A	30-005-61008	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	GEORGE QJ FEDERAL #003	F	L-25-06S-25E	L	30-005-61263	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	GEORGE QJ FEDERAL #004	F	A-35-06S-25E	A	30-005-61462	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	GEORGE QJ FEDERAL #005	F	C-34-06S-25E	C	30-005-61511	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	GEORGE QJ FEDERAL #006	F	D-26-06S-25E	D	30-005-61546	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	GEORGE QJ FEDERAL #007	F	K-26-06S-25E	K	30-005-61547	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	GEORGE QJ FEDERAL #010	F	N-26-06S-25E	N	30-005-63368	97189	PECOS SLOPE; PENNSYLVANIAN OIL	G	01/20	0
	GEORGE QJ FEDERAL #011	F	F-26-06S-25E	F	30-005-63444	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323813	GEORGE QJ FEDERAL COM #009Q	F	C-35-06S-25E	C	30-005-63435	97189	PECOS SLOPE; PENNSYLVANIAN OIL	G	01/20	0
323814	GEORGE QJ FEDERAL DEEP COM #002Y	F	P-27-06S-25E	P	30-005-61400	97128	COTTONWOOD RANCH; PENNSYLVANIAN (G)	G	01/20	0
323818	GERRY FEDERAL COM #002	F	2-01-08S-25E	B	30-005-61320	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323819	GETTY VQ FEDERAL COM #001	F	H-24-06S-25E	H	30-005-61857	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323830	GODFREY MP FEDERAL #003	F	C-15-07S-25E	C	30-005-60968	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	GODFREY MP FEDERAL #004	F	P-03-07S-25E	P	30-005-61118	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	GODFREY MP FEDERAL #006	F	I-10-07S-25E	I	30-005-61177	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323847	GRID IRON BLI FEDERAL #002	F	6-06-12S-27E	L	30-005-64063	97832	WILDCAT G-02 S122706L; WOLFCAMP	G	01/20	0
	GRID IRON BLI FEDERAL #003	F	7-06-12S-27E	M	30-005-64145	97832	WILDCAT G-02 S122706L; WOLFCAMP	O	01/20	0
323850	GROOMS XB COM #001	P	M-08-07S-26E	M	30-005-62034	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323867	HAHN NH FEDERAL #001	F	I-09-07S-25E	I	30-005-60682	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	HAHN NH FEDERAL #002	F	A-09-07S-25E	A	30-005-60954	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	HAHN NH FEDERAL #003	F	E-09-07S-25E	E	30-005-61036	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	HAHN NH FEDERAL #004	F	K-09-07S-25E	K	30-005-61619	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323870	HANCOCK AHC COM #002	P	C-28-06S-26E	C	30-005-62928	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	HANCOCK AHC COM #003	S	O-20-06S-26E	O	30-005-63010	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323872	HANDICAPPER SWD #001	S	2-03-10S-26E	B	30-005-63307	97180	WC SWD; ORDOVICIAN	S	01/20	0
323877	HARD AS NAILS AMD ST #002	S	A-27-09S-26E	A	30-005-62644	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323878	HARD AS NAILS AMD STATE COM #005	S	C-27-09S-26E	C	30-005-63687	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
					30-005-63687	76750	FOOR RANCH; WOLFCAMP (GAS)			
					30-005-63687	82730	PECOS SLOPE; ABO (GAS)			
323882	HARVEST ABR STATE #001	S	A-36-09S-24E	A	30-005-62236	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	HARVEST ABR STATE #002	S	C-36-09S-24E	C	30-005-63232	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	HARVEST ABR STATE #003	S	J-36-09S-24E	J	30-005-63446	76750	FOOR RANCH; WOLFCAMP (GAS)	G	01/20	0

					30-005-63446	82730	PECOS SLOPE; ABO (GAS)			
	HARVEST ABR STATE #004	S	K-36-09S-24E	K	30-005-63447	76750	FOOR RANCH; WOLFCAMP (GAS)	G	01/20	0
					30-005-63447	82730	PECOS SLOPE; ABO (GAS)			
323889	HELEN FEDERAL COM #001	F	4-01-07S-25E	D	30-005-61280	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323894	HEWITT IM FEDERAL #003	F	L-21-06S-25E	L	30-005-62782	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	HEWITT IM FEDERAL #004	F	M-21-06S-25E	M	30-005-63337	82730	PECOS SLOPE; ABO (GAS)	O	01/20	0
	HEWITT IM FEDERAL #005	F	I-25-06S-25E	I	30-005-63320	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
					30-005-63320	97128	COTTONWOOD RANCH; PENNSYLVANIAN (G)			
323900	HILLTOP NQ STATE #001	S	C-07-07S-25E	C	30-005-60700	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323909	HORN YG FEDERAL #001	F	N-10-08S-26E	N	30-005-62140	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
					30-005-62140	97094	FOOR RANCH; PRE-PERMIAN, N. (G)			
	HORN YG FEDERAL #003	F	C-10-08S-26E	C	30-005-63491	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	HORN YG FEDERAL #004	F	I-07-08S-26E	I	30-005-63680	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
					30-005-63680	96542	WILDCAT; GRANITE			
					30-005-63680	97179	ROCK SCHOOL HOUSE, NE (G)			
323910	HORN YG FEDERAL COM #006	F	H-15-08S-26E	H	30-005-63462	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323914	HOUSTON BDH STATE COM #001	S	4-31-09S-27E	M	30-005-63620	76750	FOOR RANCH; WOLFCAMP (GAS)	G	12/19	0
	HOUSTON BDH STATE COM #002	S	F-31-09S-27E	F	30-005-63630	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	12/19	0
323919	HUCKABAY TJ FEDERAL #001	F	4-18-08S-26E	M	30-005-61631	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	HUCKABAY TJ FEDERAL #002	F	1-19-08S-26E	D	30-005-61744	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	HUCKABAY TJ FEDERAL #003	F	G-19-08S-26E	G	30-005-61863	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	HUCKABAY TJ FEDERAL #004	F	E-20-08S-26E	E	30-005-61918	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	HUCKABAY TJ FEDERAL #006	F	P-23-08S-26E	P	30-005-63467	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323920	HUCKABAY TJ FEDERAL COM #008	F	D-23-08S-26E	D	30-005-63504	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323935	IBIS XU STATE #001	S	A-23-09S-26E	A	30-005-62053	89741	CHAVES UNDESIGNATED; WOLFCAMP (GAS)	G	01/20	0
	IBIS XU STATE #004	S	E-23-09S-26E	E	30-005-63379	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
323936	IBIS XU STATE COMM #002	S	C-25-09S-26E	C	30-005-62582	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
					30-005-62582	76750	FOOR RANCH; WOLFCAMP (GAS)			
323946	INGRAM WY FEDERAL #001	F	A-18-07S-26E	A	30-005-61958	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323965	JASPER ARJ FEDERAL #002	F	B-25-08S-26E	B	30-005-63143	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323966	JASPER ARJ FEDERAL COM #001	F	O-25-08S-26E	O	30-005-63142	82555	PALMA MESA; PENN, SOUTH (GAS)	G	01/20	0
					30-005-63142	82730	PECOS SLOPE; ABO (GAS)			
	JASPER ARJ FEDERAL COM #003	F	H-10-08S-26E	H	30-005-63221	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
					30-005-63221	97094	FOOR RANCH; PRE-PERMIAN, N. (G)			

323972	JERVIS AYB FEDERAL #001	F	E-13-08S-26E	E	30-005-63417	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	JERVIS AYB FEDERAL #006	F	L-01-08S-26E	L	30-005-63765	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
					30-005-63765	97094	FOOR RANCH; PRE-PERMIAN, N. (G)			
323979	JOHNSON IL #002	P	3-30-06S-26E	L	30-005-60741	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	JOHNSON IL #003	P	I-30-06S-26E	I	30-005-62926	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	JOHNSON IL #004	P	K-30-06S-26E	K	30-005-63330	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
					30-005-63330	97128	COTTONWOOD RANCH; PENNSYLVANIAN (G)			
	JOHNSON IL #005	P	O-30-06S-26E	O	30-005-63480	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
323981	JOKERS AWJ STATE #003	S	I-03-10S-26E	I	30-005-63470	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
					30-005-63470	76750	FOOR RANCH; WOLFCAMP (GAS)			
					30-005-63470	82730	PECOS SLOPE; ABO (GAS)			
324000	KAREN FEDERAL #001	F	D-25-09S-24E	D	30-005-61629	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324001	KEEBLER AMJ FEDERAL #001A	F	O-13-09S-25E	O	30-005-63219	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324005	KENO AWK STATE #001	S	2-04-10S-26E	B	30-005-63360	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	KENO AWK STATE #002	S	J-04-10S-26E	J	30-005-63318	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324009	KERSHAW UE #001	P	I-19-08S-26E	I	30-005-61734	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324011	KILGORE SO #001	P	M-24-06S-25E	M	30-005-61342	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	KILGORE SO #002	P	O-24-06S-25E	O	30-005-61553	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	KILGORE SO #003	S	K-24-06S-25E	K	30-005-62986	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324012	KILLER BEE STATE #007	S	M-32-10S-26E	M	30-005-63704	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324015	KING TF #002	P	G-25-06S-25E	G	30-005-61492	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	KING TF #003	P	C-25-06S-25E	C	30-005-63085	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	KING TF #004	P	N-25-06S-25E	N	30-005-63276	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324016	KIRBY BCK FEDERAL COM #001	F	F-21-10S-26E	F	30-005-63573	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
	KIRBY BCK FEDERAL COM #002	F	K-21-10S-26E	K	30-005-63955	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
324037	LACROSSE BJX STATE COM #001	S	D-32-11S-27E	D	30-005-63768	96542	WILDCAT; GRANITE	G	01/20	0
					30-005-63768	97361	COYOTE; WOLFCAMP (G)			
324065	LEEDE UG FEDERAL #001	F	E-11-08S-25E	E	30-005-61809	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324066	LEEMAN OC FEDERAL #001	F	O-18-07S-26E	O	30-005-61023	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	LEEMAN OC FEDERAL #002	F	B-19-07S-26E	B	30-005-61154	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	LEEMAN OC FEDERAL #003	F	O-19-07S-26E	O	30-005-61390	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	LEEMAN OC FEDERAL #004	F	D-20-07S-26E	D	30-005-61651	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324069	LEILA FEDERAL #002	F	J-24-06S-26E	J	30-005-61721	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324139	MARGENE AWM FEDERAL #001	F	H-20-09S-26E	H	30-005-63456	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0

	MARGENE AWM FEDERAL #002Q	F	I-20-09S-26E	I	30-005-63488	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	MARGENE AWM FEDERAL #005Q	F	K-19-09S-26E	K	30-005-62690	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324140	MARIE VU FEDERAL #001	F	I-20-09S-25E	I	30-005-62001	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324143	MARSHALL XG COM #001	F	N-22-08S-26E	N	30-005-61967	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324153	MCCONKEY HX #001	P	D-10-09S-26E	D	30-005-00154	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
					30-005-00154	82730	PECOS SLOPE; ABO (GAS)			
					30-005-00154	97066	FOOR RANCH; WOLFCAMP, NORTHWEST			
	MCCONKEY HX #004	P	L-10-09S-26E	L	30-005-62589	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
					30-005-62589	97066	FOOR RANCH; WOLFCAMP, NORTHWEST			
324154	MCCREA SF COM #001	P	C-14-09S-25E	C	30-005-61273	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324155	MCCREA TU COM #001	P	B-32-08S-26E	B	30-005-61566	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324156	MCDERMETT #001	P	J-19-06S-25E	J	30-005-61113	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324161	MEADOWS COM #001	P	B-13-07S-25E	B	30-005-60911	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	MEADOWS COM #002	P	D-13-07S-25E	D	30-005-61148	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324221	MORTON SZ FEDERAL #001	F	L-10-08S-25E	L	30-005-61441	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	MORTON SZ FEDERAL #002	F	H-10-08S-25E	H	30-005-61653	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	MORTON SZ FEDERAL #003	F	C-10-08S-25E	C	30-005-61874	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	MORTON SZ FEDERAL #004	F	P-10-08S-25E	P	30-005-61799	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	MORTON SZ FEDERAL #005	F	J-10-08S-25E	J	30-005-63242	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
					30-005-63242	97115	MILNER LAKE; PENNSYLVANIAN (G)			
324226	MUDDY COM #001	P	N-29-07S-26E	N	30-005-61379			G	09/19	0
324238	NEVADA AXN STATE #002	S	M-04-10S-26E	M	30-005-63362	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
324244	NICKEY RF FEDERAL #001	F	4-19-07S-26E	M	30-005-61458	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	NICKEY RF FEDERAL #002	F	2-19-07S-26E	E	30-005-61690	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	NICKEY RF FEDERAL #003	F	K-19-07S-26E	K	30-005-63044	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324246	NIGHT OWL AFA STATE COM #001	S	I-22-09S-26E	I	30-005-62581	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	NIGHT OWL AFA STATE COM #002	S	H-22-09S-26E	H	30-005-63395	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
	NIGHT OWL AFA STATE COM #003	S	P-22-09S-26E	P	30-005-63377	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
324247	NIGHT OWL AFG STATE COM #001	S	G-22-09S-26E	G	30-005-62590	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	NIGHT OWL AFG STATE COM #002	S	L-09-09S-26E	L	30-005-63688	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
					30-005-63688	76750	FOOR RANCH; WOLFCAMP (GAS)			
324250	NITRAM AVN FEDERAL #002	F	N-35-08S-26E	N	30-005-63799	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
					30-005-63799	96542	WILDCAT; GRANITE			
324258	NORTEX WN STATE COM #001	S	C-22-09S-26E	C	30-005-62048	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324261	NORTH STURGEON PR FEDERAL #002	F	K-04-07S-26E	K	30-005-61593	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0

324277	OHBERG BCQ COM #001	P	F-23-09S-24E	F	30-005-63575	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324301	PAPALOTE OI STATE #001	S	A-16-07S-25E	A	30-005-60775	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	PAPALOTE OI STATE #003	S	C-16-07S-25E	C	30-005-61429	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	PAPALOTE OI STATE #004	S	I-16-07S-25E	I	30-005-61430	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324322	PAY AYY FEDERAL COM #001	F	D-11-08S-26E	D	30-005-63510	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324327	PEEK WU FEDERAL #001	F	4-06-08S-26E	D	30-005-61972	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324334	PENNZOIL SG STATE COM #001	S	J-32-07S-26E	J	30-005-61224	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
					30-005-61224	97110	LESLIE SPRING; WOLFCAMP,SOUTH (G)			
324338	PERCENTAGE APR #001	P	O-03-08S-26E	O	30-005-63269	97094	FOOR RANCH; PRE-PERMIAN, N. (G)	G	01/20	0
					30-005-63269	97095	WC EIGHTMILE DRAW; PENN. (G)			
324339	PERCH BCP STATE COM #001	S	M-29-09S-27E	M	30-005-63557	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
324363	POWERS OL DEEP FEDERAL #006	F	K-27-06S-25E	K	30-005-61548	97128	COTTONWOOD RANCH; PENNSYLVANIAN (G)	G	07/19	0
324364	POWERS OL FEDERAL #001	F	P-33-06S-25E	P	30-005-60799	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	POWERS OL FEDERAL #002	F	N-33-06S-25E	N	30-005-60800	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	POWERS OL FEDERAL #007	F	G-29-06S-25E	G	30-005-62908	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	POWERS OL FEDERAL #008	F	J-21-06S-25E	J	30-005-62923	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	POWERS OL FEDERAL #010Y	F	F-33-06S-25E	F	30-005-61976	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324365	POWERS OL FEDERAL COM #011	F	B-33-06S-25E	B	30-005-63094	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324372	PROGRAM AXP STATE #001	S	O-05-10S-26E	O	30-005-63365	76750	FOOR RANCH; WOLFCAMP (GAS)	G	01/20	0
	PROGRAM AXP STATE #003	S	I-05-10S-26E	I	30-005-63479	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
324382	QUARTERBACK BQG FEDERAL #001	F	J-06-12S-27E	J	30-005-64138	97832	WILDCAT G-02 S122706L; WOLFCAMP	O	01/20	0
324389	QUINIELA AXQ STATE #003	S	I-05-10S-26E	A	30-005-63618	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
324406	RED ROCK NB FEDERAL #002	F	N-28-06S-25E	N	30-005-62748	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	RED ROCK NB FEDERAL #004	F	C-28-06S-25E	C	30-005-62796	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	RED ROCK NB FEDERAL #006	F	B-28-06S-25E	B	30-005-62858	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	RED ROCK NB FEDERAL #007	F	M-28-06S-25E	M	30-005-63103	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324411	REINAUER RC FEDERAL #001	F	A-29-07S-25E	A	30-005-62570	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	REINAUER RC FEDERAL #002	F	G-20-07S-25E	G	30-005-63216	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324412	REINAUER RC FEDERAL COM #003	F	I-20-07S-25E	I	30-005-63217	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324419	RIC #004	P	O-29-06S-25E	O	30-005-61162	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324433	RITA TZ FEDERAL #001	F	4-04-08S-26E	D	30-005-61564	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	RITA TZ FEDERAL #002	F	F-04-08S-26E	F	30-005-61973	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	RITA TZ FEDERAL #006	F	P-05-08S-26E	P	30-005-63632	97110	LESLIE SPRING; WOLFCAMP,SOUTH (G)	G	01/20	0

324434	RITA TZ FEDERAL COM #003	F	F-04-08S-26E	F	30-005-63243	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324448	ROLLA TC #001	P	O-30-09S-26E	O	30-005-61405	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	ROLLA TC #002	P	G-29-09S-26E	G	30-005-62822	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
					30-005-62822	76755	FOOR RANCH; WOLFCAMP, NORTH (GAS)			
324450	ROOK RK STATE #001	S	H-16-08S-25E	H	30-005-61050	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	ROOK RK STATE #003	S	L-02-08S-25E	L	30-005-61447	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	ROOK RK STATE #004	S	E-02-08S-25E	E	30-005-61488	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324451	ROOMBA BKM #001	P	P-17-10S-26E	P	30-005-64000	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
324456	ROULETTE AXR STATE #001	S	E-08-10S-26E	E	30-005-63410	76750	FOOR RANCH; WOLFCAMP (GAS)	G	01/20	0
					30-005-63410	82730	PECOS SLOPE; ABO (GAS)			
324464	RUBY JO ATY #003	P	L-14-08S-26E	L	30-005-63429	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324472	RUTH XK #001	F	J-01-07S-25E	J	30-005-62067	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324476	SACRA SA #002	P	P-23-06S-25E	P	30-005-61340	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	SACRA SA #004	P	P-35-06S-25E	P	30-005-61449	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	SACRA SA #005	P	A-27-06S-25E	A	30-005-61571	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	SACRA SA #006	P	K-23-06S-25E	K	30-005-62017	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	SACRA SA #007Z	P	P-22-06S-25E	P	30-005-61960	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	SACRA SA #009	F	4-19-06S-26E	M	30-005-61634	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	SACRA SA #014	P	K-19-06S-26E	K	30-005-63323	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	SACRA SA #021	P	K-35-06S-25E	K	30-005-63432	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324477	SACRA SA COM #001	P	E-35-06S-25E	E	30-005-61271	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	SACRA SA COM #011	S	G-35-06S-25E	G	30-005-62987	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	SACRA SA COM #012	P	I-23-06S-25E	I	30-005-63356	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	SACRA SA COM #013	P	J-34-06S-25E	J	30-005-63118	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	SACRA SA COM #015	P	N-23-06S-25E	N	30-005-63322	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	SACRA SA COM #017	P	G-34-06S-25E	G	30-005-63321	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324481	SALEM #002	P	N-03-08S-26E	N	30-005-63439	97094	FOOR RANCH; PRE-PERMIAN, N. (G)	G	12/19	0
	SALEM #003	P	L-03-08S-26E	L	30-005-63554	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324482	SALEM COM #001	P	2-04-08S-26E	B	30-005-61584	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324491	SAND COM #001	P	F-10-07S-26E	F	30-005-61667	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324494	SANDLEWOOD AEW STATE #001	S	N-31-08S-27E	N	30-005-62546	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
	SANDLEWOOD AEW STATE #002	S	2-31-08S-27E	E	30-005-63281	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
					30-005-63281	82730	PECOS SLOPE; ABO (GAS)			
324504	SAVAGE FEDERAL #001	F	H-04-07S-25E	H	30-005-60704	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0

	SAVAGE FEDERAL #002	F	F-04-07S-25E	F	30-005-60756	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	SAVAGE FEDERAL #003	F	I-04-07S-25E	I	30-005-61158	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	SAVAGE FEDERAL #004	F	N-04-07S-25E	N	30-005-61220	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	SAVAGE FEDERAL #005	F	2-04-07S-25E	B	30-005-63144	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324505	SAVAGE NI FEDERAL #002	F	O-19-06S-26E	O	30-005-61531	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	SAVAGE NI FEDERAL #005	F	I-19-06S-26E	I	30-005-63025	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324506	SAVAGE NI FEDERAL COM. #003	F	B-30-06S-26E	B	30-005-61847	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324522	SEINFELD BBK FEDERAL #001	F	M-12-06S-26E	M	30-005-62117	97282	CROCKETT DRAW; WOLFCAMP (G)	G	01/20	0
					30-005-62117	97298	BOSQUE; PENN., N (G)			
324540	SHORT RM DEEP FEDERAL #005	F	I-25-07S-25E	I	30-005-62938	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324541	SHORT RM FEDERAL #001	F	K-25-07S-25E	K	30-005-61620	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	SHORT RM FEDERAL #002	F	O-27-07S-25E	O	30-005-62009	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	SHORT RM FEDERAL #003	F	L-27-07S-25E	L	30-005-62059	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	SHORT RM FEDERAL #004	F	G-27-07S-25E	G	30-005-62909	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324542	SHUFFLE BLS STATE COM #001	S	C-16-10S-26E	C	30-005-64122	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
324549	SKINK SK STATE #003	S	C-32-07S-26E	C	30-005-61611	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	SKINK SK STATE #004	S	F-36-07S-25E	F	30-005-61450	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	SKINK SK STATE #005	S	O-36-07S-25E	O	30-005-63319	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	SKINK SK STATE #006	S	L-36-07S-25E	L	30-005-63370	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324561	SNELL QZ #002	P	F-31-06S-25E	F	30-005-63119	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324569	SORENSEN IB FEDERAL #002	F	4-06-07S-26E	D	30-005-61940	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	SORENSEN IB FEDERAL #003	F	K-06-07S-26E	K	30-005-61985	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	SORENSEN IB FEDERAL #004	F	J-06-07S-26E	J	30-005-62025	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324576	SOUTH DALLAS #002	S	2-02-10S-26E	B	30-005-62746	76750	FOOR RANCH; WOLFCAMP (GAS)	G	01/20	0
324582	SPARROW SP STATE #001	S	C-32-06S-25E	C	30-005-61343	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	SPARROW SP STATE #002	S	H-32-06S-25E	H	30-005-61504	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	SPARROW SP STATE #003	S	M-32-06S-25E	M	30-005-62920	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	SPARROW SP STATE #004	S	E-05-07S-25E	E	30-005-62934	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	SPARROW SP STATE #005	S	N-05-07S-25E	N	30-005-62936	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	SPARROW SP STATE #007	S	O-32-06S-25E	O	30-005-63206	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324583	SPEAR OA FEDERAL #001	F	H-09-09S-26E	H	30-005-60761	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	SPEAR OA FEDERAL #002	F	D-15-09S-26E	D	30-005-61974	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	SPEAR OA FEDERAL #003	F	L-15-09S-26E	L	30-005-62079	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
					30-005-62079	76750	FOOR RANCH; WOLFCAMP (GAS)			
	SPEAR OA FEDERAL #004	F	P-09-09S-26E	P	30-005-62575	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0

	SPEAR OA FEDERAL #006	F	B-09-09S-26E	B	30-005-63392	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
					30-005-63392	76750	FOOR RANCH; WOLFCAMP (GAS)			
					30-005-63392	82730	PECOS SLOPE; ABO (GAS)			
	SPEAR OA FEDERAL #007	F	J-09-09S-26E	J	30-005-63393	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
					30-005-63393	82730	PECOS SLOPE; ABO (GAS)			
					30-005-63393	97066	FOOR RANCH; WOLFCAMP, NORTHWEST			
324584	SPEAR OA FEDERAL COM #010	F	O-05-09S-26E	O	30-005-64123	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
324586	SPOOL SU #008	P	E-23-07S-25E	E	30-005-63124	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324587	SPOOL SU COM #004	P	K-22-07S-25E	K	30-005-61961	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324594	SQUIRREL SL STATE #001	S	K-32-07S-26E	K	30-005-61298	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324598	STARE BEA STATE COM #001	S	D-08-09S-27E	D	30-005-63569	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
324622	STERNE BCS COM #001	P	M-11-06S-26E	M	30-005-63561	97282	CROCKETT DRAW; WOLFCAMP (G)	G	01/20	0
	STERNE BCS COM #002	P	M-13-06S-26E	M	30-005-63562	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
					30-005-63562	97282	CROCKETT DRAW; WOLFCAMP (G)			
324638	STURGEON FEDERAL COM #001	F	D-08-07S-26E	D	30-005-61617	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324658	TAMARACK QF STATE COM #003	S	E-32-06S-26E	E	30-005-62927	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324667	TERRA 35 STATE #001	S	H-35-09S-26E	H	30-005-62653	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	11/19	0
					30-005-62653	76750	FOOR RANCH; WOLFCAMP (GAS)			
324679	THOMAS LN FEDERAL #007	F	D-29-06S-25E	D	30-005-61948	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	THOMAS LN FEDERAL #008	F	F-29-06S-25E	F	30-005-63097	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324680	THORPE MI FEDERAL #003	F	E-03-07S-25E	E	30-005-60939	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	THORPE MI FEDERAL #007	F	G-03-07S-25E	G	30-005-61530	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	THORPE MI FEDERAL #008	F	A-22-07S-25E	A	30-005-61563	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	THORPE MI FEDERAL #009	F	E-22-07S-25E	E	30-005-61858	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	THORPE MI FEDERAL #015	F	C-22-07S-25E	C	30-005-63020	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	THORPE MI FEDERAL #016	F	3-03-07S-25E	C	30-005-63129	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	THORPE MI FEDERAL #017	F	G-22-07S-25E	G	30-005-63130	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324681	THORPE MI FEDERAL COM #002	F	L-03-07S-25E	L	30-005-60740	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	THORPE MI FEDERAL COM #011	F	J-03-07S-25E	J	30-005-63019	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324686	TIDE AXT STATE COM #001	S	P-32-09S-26E	P	30-005-63722	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
324696	TOUCHDOWN BJC FEDERAL #001	F	I-11-12S-26E	I	30-005-63876	97361	COYOTE; WOLFCAMP (G)	O	01/20	0
					30-005-63876	97406	LEA LAKE; PRE-PERMIAN (G)			
	TOUCHDOWN BJC FEDERAL #002	F	A-11-12S-26E	A	30-005-64090	97361	COYOTE; WOLFCAMP (G)	G	01/20	0
324700	TRAVIS FEDERAL COM #001	F	M-20-06S-26E	M	30-005-62061	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0

324719	ULTRA U A STATE #001	S	E-32-09S-26E	E	30-005-61536	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324720	ULTRA UA STATE COM #002	S	H-32-09S-26E	H	30-005-63283	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
324728	UPRIGHT BFU STATE COM #001	S	H-30-10S-26E	H	30-005-63698	97120	COMANCHE; WOLFCAMP (G)	G	01/20	0
324733	VALUE BCV STATE COM #001	S	O-02-08S-26E	O	30-005-63590	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
					30-005-63590	97094	FOOR RANCH; PRE-PERMIAN, N. (G)			
324742	VANILLA AZA STATE #001	S	A-28-09S-26E	A	30-005-63390	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
324744	VEGAS AVT STATE COM #001	S	K-22-09S-26E	K	30-005-62539	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
324745	VERBENA UV FEDERAL #001	F	H-26-07S-25E	H	30-005-61748	97150	COYOTE; DRAW; PERMO PENNSYLVANIAN (G)	G	01/20	0
	VERBENA UV FEDERAL #002	F	D-26-07S-25E	D	30-005-62941	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324751	VISTA AVS STATE #002	S	F-21-09S-26E	F	30-005-63262	76755	FOOR RANCH; WOLFCAMP, NORTH (GAS)	G	12/19	0
324754	WAGER AWG STATE #004	S	D-34-09S-26E	D	30-005-63306	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324755	WAGER AWG STATE COM #003	S	J-34-09S-26E	J	30-005-63297	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
					30-005-63297	76750	FOOR RANCH; WOLFCAMP (GAS)			
324762	WANDA ZT FEDERAL #001	F	2-31-10S-26E	E	30-005-62163	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324783	WESTERN #003	P	N-30-06S-25E	N	30-005-63312	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324784	WESTERN COM #002	P	K-30-06S-25E	K	30-005-61489	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324793	WHITWORTH RU STATE #003	S	M-12-09S-26E	M	30-005-62112	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	WHITWORTH RU STATE #005	S	O-12-09S-26E	O	30-005-62707	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324801	WILLIAMSON LC FEDERAL #002	F	P-09-08S-25E	P	30-005-60847	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	WILLIAMSON LC FEDERAL #003	F	1-04-08S-25E	A	30-005-61459	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	WILLIAMSON LC FEDERAL #006	F	H-09-08S-25E	H	30-005-61461	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	WILLIAMSON LC FEDERAL #009	F	P-04-08S-25E	P	30-005-62116	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324816	WITTER VW FEDERAL #001	F	J-34-07S-26E	J	30-005-61842	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324817	WITZ VN STATE #001	S	D-26-09S-26E	D	30-005-61790	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	WITZ VN STATE #002	S	A-26-09S-26E	A	30-005-62599	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
					30-005-62599	76750	FOOR RANCH; WOLFCAMP (GAS)			
	WITZ VN STATE #003	S	I-26-09S-26E	I	30-005-62626	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
					30-005-62626	76750	FOOR RANCH; WOLFCAMP (GAS)			
	WITZ VN STATE #006	S	D-26-09S-26E	D	30-005-63463	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
					30-005-63463	76750	FOOR RANCH; WOLFCAMP (GAS)			
324831	XANADU AXD FEDERAL #001	F	P-29-09S-26E	P	30-005-63641	76730	FOOR RANCH; PRE PERMIAN (GAS)	G	01/20	0
324835	YANKEE ANK FEDERAL COM #001	F	O-11-07S-25E	O	30-005-63026	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
	YANKEE ANK FEDERAL COM #002	F	F-01-07S-25E	F	30-005-63582	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0
324851	ZANE ABS FEDERAL #001	F	O-15-09S-26E	O	30-005-62257	82730	PECOS SLOPE; ABO (GAS)	G	01/20	0

324852	ZANE ABS FEDERAL COM #003	F	G-15-09S-26E	G	30-005-62577	97111	FOOR RANCH; WOLFCAMP (O)	O	12/19	0
--------	------------------------------	---	--------------	---	--------------	-------	-----------------------------	---	-------	---

Total of Single Well Bonds Required for Inactive Wells										0
--	--	--	--	--	--	--	--	--	--	---

NMOCD ApprovalElectronic Signature(s): Daniel J Sanchez, District 2Date: April 06, 2020

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

Wells Selected for Transfer

Permit 279420

431 Wells Selected for Transfer

From:	EOG RESOURCES INC	OGRID:	7377
To:	IACX Production LLC	OGRID:	329877

OCD District: Artesia (431 Wells selected.)

Property	Well	Lease Type	ULSTR	OCD Unit	API	Pool ID	Pool Name	Well Type
327864	ACME #001	P	L-29-08S-26E	L	30-005-60647	82730	PECOS SLOPE; ABO (GAS)	G
	ACME #002	P	G-29-08S-26E	G	30-005-60894	82730	PECOS SLOPE; ABO (GAS)	G
	ACME #003	P	J-30-08S-26E	J	30-005-60895	82730	PECOS SLOPE; ABO (GAS)	G
	ACME #006	P	J-29-08S-26E	J	30-005-61169	82730	PECOS SLOPE; ABO (GAS)	G
	ACME #008	P	F-29-08S-26E	F	30-005-61171	82730	PECOS SLOPE; ABO (GAS)	G
327865	AIKMAN BDK STATE COM #001	S	P-36-06S-26E	P	30-005-61804	78320	HAYSTACK; CISCO (GAS)	G
327866	ALBITUS TH FEDERAL #001	F	B-21-07S-25E	B	30-005-61439	82730	PECOS SLOPE; ABO (GAS)	G
	ALBITUS TH FEDERAL #002	F	E-21-07S-25E	E	30-005-61746	82730	PECOS SLOPE; ABO (GAS)	G
	ALBITUS TH FEDERAL #003	F	N-21-07S-25E	N	30-005-61747	82730	PECOS SLOPE; ABO (GAS)	G
	ALBITUS TH FEDERAL #004	F	I-21-07S-25E	I	30-005-61689	82730	PECOS SLOPE; ABO (GAS)	G
327867	ALLIED AUS STATE COM #001	S	G-33-09S-26E	G	30-005-60275	76750	FOOR RANCH; WOLFCAMP (GAS)	G
	ALLIED AUS STATE COM #002	S	L-33-09S-26E	L	30-005-63287	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
					30-005-63287	76750	FOOR RANCH; WOLFCAMP (GAS)	
327868	ANCHITO AZE FEDERAL COM #001	F	P-26-10S-25E	P	30-005-63742	82730	PECOS SLOPE; ABO (GAS)	G
327869	AURORA AUR STATE #001	S	I-16-09S-26E	I	30-005-63236	76750	FOOR RANCH; WOLFCAMP (GAS)	G
327870	AVENUE AVU STATE #001	S	I-21-09S-26E	I	30-005-63259	76755	FOOR RANCH; WOLFCAMP, NORTH (GAS)	G
	AVENUE AVU STATE #002	S	K-21-09S-26E	K	30-005-63260	76755	FOOR RANCH; WOLFCAMP, NORTH (GAS)	G
327871	BASIL ANS COM #001	F	A-23-07S-25E	A	30-005-63012	82730	PECOS SLOPE; ABO (GAS)	G
327872	BASKETBALL BBI FEDERAL #001	F	D-12-12S-26E	D	30-005-62792	96542	WILDCAT; GRANITE	G
					30-005-62792	97361	COYOTE; WOLFCAMP (G)	
327873	BEAN #001	P	M-20-07S-26E	M	30-005-61837	82730	PECOS SLOPE; ABO (GAS)	G
327874	BEAN COM #002	P	H-20-07S-26E	H	30-005-63136	82730	PECOS SLOPE; ABO (GAS)	G
327875	BEARD QQ FEDERAL #002	F	C-18-07S-26E	C	30-005-61840	82730	PECOS SLOPE; ABO (GAS)	G
327876	BEARD QQ FEDERAL COM #001	F	4-18-07S-26E	M	30-005-60934	82730	PECOS SLOPE; ABO (GAS)	G
327877	BEDFORD FEDERAL COM. #001	F	J-31-06S-25E	J	30-005-60791	82730	PECOS SLOPE; ABO (GAS)	G
327878	BESTWALL ST #002	P	M-20-08S-26E	M	30-005-63229	82730	PECOS SLOPE; ABO (GAS)	G
327879	BESTWALL ST. COM #001	P	N-20-08S-26E	N	30-005-61573	82730	PECOS SLOPE; ABO (GAS)	G
327880	BINNION TT FEDERAL #001	F	G-24-07S-25E	G	30-005-61915	82730	PECOS SLOPE; ABO (GAS)	G
	BINNION TT FEDERAL #002	F	K-24-07S-25E	K	30-005-61916	82730	PECOS SLOPE; ABO (GAS)	G
	BINNION TT FEDERAL #006	F	I-24-07S-25E	I	30-005-61938	82730	PECOS SLOPE; ABO (GAS)	G
	BINNION TT FEDERAL #007	F	A-24-07S-25E	A	30-005-63350	82730	PECOS SLOPE; ABO (GAS)	O
					30-005-63350	97150	COYOTE; DRAW; PERMO PENNSYLVANIAN (G)	
327881	BIPLANE BLW STATE COM #006	S	N-16-06S-27E	N	30-005-63979	78320	HAYSTACK; CISCO (GAS)	G
					30-005-63979	97457	WILDCAT PRE-CAMBRIAN	
327884	BITTER LAKE FEDERAL COM #001	F	J-05-09S-25E	J	30-005-61444	82730	PECOS SLOPE; ABO (GAS)	G
327885	BITTERSWEET AOZ STATE COM #001	F	J-28-09S-26E	J	30-005-62756	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
					30-005-62756	76755	FOOR RANCH; WOLFCAMP, NORTH (GAS)	
327886	BLANCO #002	P	B-12-07S-25E	B	30-005-61249	82730	PECOS SLOPE; ABO (GAS)	G
327887	BOFFIN BLY STATE COM #002	S	F-16-09S-27E	F	30-005-64061	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
327888	BOSQUE GRANDE SQ FED #002	F	H-17-07S-26E	H	30-005-62264	82730	PECOS SLOPE; ABO (GAS)	G
327889	BOSQUE GRANDE SQ FEDERAL COM #001	F	A-08-07S-26E	A	30-005-61510	82730	PECOS SLOPE; ABO (GAS)	G
327890	BOXCAR BCX FEDERAL COM #001	F	P-25-10S-25E	P	30-005-63572	82730	PECOS SLOPE; ABO (GAS)	G
327891	BUDER ACN FEDERAL #001	F	D-22-06S-26E	D	30-005-62283	82730	PECOS SLOPE; ABO (GAS)	G
	BUDER ACN FEDERAL #002	F	K-22-06S-26E	K	30-005-63513	97263	BOSQUE; PENNSYLVANIAN (G)	G
					30-005-63513	97282	CROCKETT DRAW; WOLFCAMP (G)	
	BUDER ACN FEDERAL #003	F	F-22-06S-26E	F	30-005-63576	82730	PECOS SLOPE; ABO (GAS)	G
327892	BURTIS COM #002	P	A-11-07S-25E	A	30-005-61230	82730	PECOS SLOPE; ABO (GAS)	G
327893	BYERS ZV #001	P	N-08-08S-26E	N	30-005-62162	82730	PECOS SLOPE; ABO (GAS)	G
					30-005-62162	97179	ROCK SCHOOL HOUSE, NE (G)	
327894	CACTUS FLOWERS AMC STATE #001	S	K-19-08S-27E	K	30-005-62557	70005	ACME; PENN, SOUTH (GAS)	G
327895	CARDDECK BDD STATE COM #001	S	N-16-10S-26E	N	30-005-63608	76750	FOOR RANCH; WOLFCAMP (GAS)	G

					30-005-63608	82730	PECOS SLOPE; ABO (GAS)	
327896	CASINO AXC STATE #001	S	K-02-10S-26E	K	30-005-63403	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
327897	CATTERSON SS FEDERAL #001	F	P-21-07S-26E	P	30-005-61544	82730	PECOS SLOPE; ABO (GAS)	G
	CATTERSON SS FEDERAL #002	F	K-21-07S-26E	K	30-005-61941	82730	PECOS SLOPE; ABO (GAS)	G
	CATTERSON SS FEDERAL #003	F	A-07-07S-26E	A	30-005-62758	82730	PECOS SLOPE; ABO (GAS)	G
	CATTERSON SS FEDERAL #004	F	2-07-07S-26E	E	30-005-62721	82730	PECOS SLOPE; ABO (GAS)	G
	CATTERSON SS FEDERAL #005	F	K-07-07S-26E	K	30-005-62833	82730	PECOS SLOPE; ABO (GAS)	G
	CATTERSON SS FEDERAL #006	F	O-07-07S-26E	O	30-005-62857	82730	PECOS SLOPE; ABO (GAS)	G
	CATTERSON SS FEDERAL #007	F	I-21-07S-26E	I	30-005-63033	82730	PECOS SLOPE; ABO (GAS)	G
	CATTERSON SS FEDERAL #008	F	N-21-07S-26E	N	30-005-63326	80145	LESLIE SPRING; PENN (GAS)	G
327898	CHARLIE ZA FEDERAL #001	F	O-22-08S-26E	O	30-005-62134	82730	PECOS SLOPE; ABO (GAS)	G
	CHARLIE ZA FEDERAL #002	F	H-22-08S-26E	H	30-005-63499	82730	PECOS SLOPE; ABO (GAS)	G
	CHARLIE ZA FEDERAL #003	F	L-23-08S-26E	L	30-005-63581	82730	PECOS SLOPE; ABO (GAS)	G
327899	CHARLOTTE FEDERAL #001	F	1-30-07S-26E	D	30-005-61194	82730	PECOS SLOPE; ABO (GAS)	G
	CHARLOTTE FEDERAL #003	F	B-30-07S-26E	B	30-005-61304	82730	PECOS SLOPE; ABO (GAS)	G
327900	CHARLOTTE FEDERAL COM #005	F	E-29-07S-26E	E	30-005-61480	82730	PECOS SLOPE; ABO (GAS)	G
327901	COFFMAN NY FEDERAL #001	F	E-25-07S-25E	E	30-005-60742	82730	PECOS SLOPE; ABO (GAS)	G
	COFFMAN NY FEDERAL #002	F	A-25-07S-25E	A	30-005-61421	82730	PECOS SLOPE; ABO (GAS)	G
	COFFMAN NY FEDERAL #003	F	C-25-07S-25E	C	30-005-63089	82730	PECOS SLOPE; ABO (GAS)	G
327902	COMANCHE HILLS VE STATE #001	F	B-36-10S-25E	B	30-005-61754	82730	PECOS SLOPE; ABO (GAS)	G
327903	COMANCHE HILLS VE STATE COM #002	S	F-36-10S-25E	F	30-005-63757	82730	PECOS SLOPE; ABO (GAS)	G
					30-005-63757	96542	WILDCAT; GRANITE	
327904	COMANCHE HILLS ZU FEDERAL #001	F	N-25-10S-25E	N	30-005-62168	82730	PECOS SLOPE; ABO (GAS)	G
327905	COMANCHERO BCZ FEDERAL COM #001	F	E-26-10S-25E	E	30-005-62113	82730	PECOS SLOPE; ABO (GAS)	G
					30-005-62113	97347	BITTER LAKES; PENN. (G)	
327906	CONEJO RH STATE #001	S	P-02-07S-25E	P	30-005-61026	82730	PECOS SLOPE; ABO (GAS)	G
	CONEJO RH STATE #002	S	M-02-07S-25E	M	30-005-61201	82730	PECOS SLOPE; ABO (GAS)	G
	CONEJO RH STATE #004	S	E-02-07S-25E	E	30-005-61329	82730	PECOS SLOPE; ABO (GAS)	G
	CONEJO RH STATE #005R	S	F-02-07S-25E	F	30-005-63233	82730	PECOS SLOPE; ABO (GAS)	G
					30-005-63233	97129	FIVE MILE DRAW; PENN (G)	
327907	COOKER BCB FEDERAL COM #003	F	J-14-06S-26E	J	30-005-63996	96079	WC; SILURIAN (GAS) DO NOT USE	G
					30-005-63996	96542	WILDCAT; GRANITE	
					30-005-63996	97284	ALKALI DRAW; SILURO-DEVONIAN	
328090	CORNETT TI #001	P	1-03-08S-26E	A	30-005-61575	82730	PECOS SLOPE; ABO (GAS)	G
327908	CORONET TI #002	P	H-03-08S-26E	H	30-005-63231	82730	PECOS SLOPE; ABO (GAS)	G
	CORONET TI #003	P	G-03-08S-26E	G	30-005-63369	97110	LESLIE SPRING; WOLFCAMP, SOUTH (G)	G
327909	COTTONWOOD FEDERAL #001	F	I-26-06S-25E	I	30-005-60959	82730	PECOS SLOPE; ABO (GAS)	G
	COTTONWOOD FEDERAL #002	F	H-26-06S-25E	H	30-005-61136	82730	PECOS SLOPE; ABO (GAS)	G
	COTTONWOOD FEDERAL #003	F	B-26-06S-25E	B	30-005-62992	82730	PECOS SLOPE; ABO (GAS)	G
	COTTONWOOD FEDERAL #005	F	J-26-06S-25E	J	30-005-63448	82730	PECOS SLOPE; ABO (GAS)	G
					30-005-63448	97285	CROCKETT DRAW; WOLFCAMP (G)	
327910	COTTONWOOD RANCH MK STATE #002	S	F-36-06S-25E	F	30-005-61471	82730	PECOS SLOPE; ABO (GAS)	G
	COTTONWOOD RANCH MK STATE #003	S	M-36-06S-25E	M	30-005-61491	82730	PECOS SLOPE; ABO (GAS)	G
	COTTONWOOD RANCH MK STATE #004	S	O-36-06S-25E	O	30-005-61581	82730	PECOS SLOPE; ABO (GAS)	G
	COTTONWOOD RANCH MK STATE #005	S	H-36-06S-25E	H	30-005-63148	82730	PECOS SLOPE; ABO (GAS)	G
	COTTONWOOD RANCH MK STATE #006	S	D-36-06S-25E	D	30-005-63421	82730	PECOS SLOPE; ABO (GAS)	G
327911	COYOTE FEDERAL #001	F	H-05-07S-25E	H	30-005-60759	82730	PECOS SLOPE; ABO (GAS)	G
	COYOTE FEDERAL #002	F	H-08-07S-25E	H	30-005-60779	82730	PECOS SLOPE; ABO (GAS)	G
	COYOTE FEDERAL #004	F	E-20-07S-25E	E	30-005-60818	82730	PECOS SLOPE; ABO (GAS)	G
	COYOTE FEDERAL #005	F	H-19-07S-25E	H	30-005-60860	82730	PECOS SLOPE; ABO (GAS)	G
	COYOTE FEDERAL #006	F	I-08-07S-25E	I	30-005-61209	82730	PECOS SLOPE; ABO (GAS)	G
	COYOTE FEDERAL #008	F	K-20-07S-25E	K	30-005-61217	82730	PECOS SLOPE; ABO (GAS)	G
	COYOTE FEDERAL #009	F	I-19-07S-25E	I	30-005-61296	82730	PECOS SLOPE; ABO (GAS)	G
327912	CRANDALL UD #001	P	H-06-07S-26E	H	30-005-61576	82730	PECOS SLOPE; ABO (GAS)	G
	CRANDALL UD #002	P	2-06-07S-26E	B	30-005-63016	82730	PECOS SLOPE; ABO (GAS)	G
327913	CRAWFORD FEDERAL COM #001	F	I-30-07S-26E	I	30-005-61579	82730	PECOS SLOPE; ABO (GAS)	G
	CRAWFORD FEDERAL COM #004	F	3-31-07S-26E	L	30-005-61533	82730	PECOS SLOPE; ABO (GAS)	G
327914	CROSBY TV FEDERAL #002	F	F-15-08S-25E	F	30-005-63218	82730	PECOS SLOPE; ABO (GAS)	G
327915	CUMMINGS TO FEDERAL #002	F	G-14-08S-25E	G	30-005-61917	82730	PECOS SLOPE; ABO (GAS)	G
327917	DALLAS AUE STATE COM #001	S	I-35-09S-26E	I	30-005-63237	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
					30-005-63237	76750	FOOR RANCH; WOLFCAMP (GAS)	
	DALLAS AUE STATE COM #005	S	N-34-09S-26E	N	30-005-63481	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
					30-005-63481	76750	FOOR RANCH; WOLFCAMP (GAS)	
327918	DANDELION AFW FEDERAL COM #001	F	H-10-09S-26E	H	30-005-62708	82730	PECOS SLOPE; ABO (GAS)	G
327919	DATIL BFD STATE COM #001	S	N-02-09S-26E	N	30-005-63689	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
					30-005-63689	76750	FOOR RANCH; WOLFCAMP (GAS)	
					30-005-63689	82730	PECOS SLOPE; ABO (GAS)	
327920	DAVIS #001	P	L-12-07S-25E	L	30-005-60868	82730	PECOS SLOPE; ABO (GAS)	G
	DAVIS #003	P	D-12-07S-25E	D	30-005-61147	82730	PECOS SLOPE; ABO (GAS)	G
	DAVIS #004	P	F-12-07S-25E	F	30-005-63122	82730	PECOS SLOPE; ABO (GAS)	G
	DAVIS #005	P	N-12-07S-25E	N	30-005-63123	82730	PECOS SLOPE; ABO (GAS)	G
327921	DELHAGEN BAJ COM #001	P	3-06-10S-25E	C	30-005-63508	82730	PECOS SLOPE; ABO (GAS)	G
327922	DESERT ROSE ALS #002	S	P-11-09S-26E	P	30-005-62569	82730	PECOS SLOPE; ABO (GAS)	G
327923	DESERT ROSE ALS STATE #003	S	F-11-09S-26E	F	30-005-62591	76730	FOOR RANCH; PRE PERMIAN (GAS)	G

327924	DIAMOND A #001	P	G-29-07S-26E	G	30-005-61783	82730	PECOS SLOPE; ABO (GAS)	G
327925	DICE BHD STATE COM #003	S	D-10-10S-26E	D	30-005-64110	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
					30-005-64110	76750	FOOR RANCH; WOLFCAMP (GAS)	
327926	DOROTHY VO FEDERAL #001	F	M-05-08S-26E	M	30-005-60173	82730	PECOS SLOPE; ABO (GAS)	G
	DOROTHY VO FEDERAL #002	F	E-14-08S-26E	E	30-005-63376	82730	PECOS SLOPE; ABO (GAS)	G
327927	DRAGONFLY ARX STATE #001	S	1-30-09S-27E	D	30-005-62566	82730	PECOS SLOPE; ABO (GAS)	G
327928	DUNCAN LH FEDERAL #001Y	F	3-03-08S-25E	C	30-005-60599	82730	PECOS SLOPE; ABO (GAS)	G
	DUNCAN LH FEDERAL #002	F	J-03-08S-25E	J	30-005-61939	82730	PECOS SLOPE; ABO (GAS)	G
	DUNCAN LH FEDERAL #003	F	N-03-08S-25E	N	30-005-61922	82730	PECOS SLOPE; ABO (GAS)	G
	DUNCAN LH FEDERAL #004	F	F-03-08S-25E	F	30-005-63256	82730	PECOS SLOPE; ABO (GAS)	G
327929	ELECTROLUX BCE STATE #001	S	D-17-10S-26E	D	30-005-63553	82730	PECOS SLOPE; ABO (GAS)	G
327930	ENERGY AFY STATE #003	S	P-36-09S-26E	P	30-005-63624	76750	FOOR RANCH; WOLFCAMP (GAS)	G
327931	ENGWALL RL FEDERAL #001	F	P-04-09S-26E	P	30-005-61123	82730	PECOS SLOPE; ABO (GAS)	G
	ENGWALL RL FEDERAL #002	F	H-04-09S-26E	H	30-005-62576	82730	PECOS SLOPE; ABO (GAS)	G
	ENGWALL RL FEDERAL #003	F	1-04-09S-26E	A	30-005-63244	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
					30-005-63244	97066	FOOR RANCH; WOLFCAMP, NORTHWEST	
	ENGWALL RL FEDERAL #004	F	J-04-09S-26E	J	30-005-63284	82730	PECOS SLOPE; ABO (GAS)	G
					30-005-63284	97066	FOOR RANCH; WOLFCAMP, NORTHWEST	
					30-005-63284	97117	FOOR RANCH; PRE-PERMIAN, NW (G)	
327932	ENRON AEY STATE #001	S	K-25-09S-26E	K	30-005-62595	76750	FOOR RANCH; WOLFCAMP (GAS)	G
327933	ERICKSON KY STATE #001	S	H-02-10S-25E	H	30-005-60564	82730	PECOS SLOPE; ABO (GAS)	G
	ERICKSON KY STATE #002	S	1-02-10S-25E	A	30-005-62579	82730	PECOS SLOPE; ABO (GAS)	G
327934	ERMA #001	P	M-01-10S-24E	M	30-005-61739	82730	PECOS SLOPE; ABO (GAS)	G
327935	ERMA COM #002	P	1-01-10S-24E	1	30-005-63502	82730	PECOS SLOPE; ABO (GAS)	G
					30-005-63502	97281	LOST LAKE; WOLFCAMP (G)	
327936	EUBANKS BEN COM #001	S	O-22-09S-24E	O	30-005-63686	82730	PECOS SLOPE; ABO (GAS)	G
					30-005-63686	96542	WILDCAT; GRANITE	
327937	EUREKA UK STATE #001	S	D-20-10S-26E	D	30-005-61612	82730	PECOS SLOPE; ABO (GAS)	G
	EUREKA UK STATE #002	S	I-20-10S-26E	I	30-005-64040	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
	EUREKA UK STATE #003	S	B-20-10S-26E	B	30-005-64124	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
327938	EXACTA AXE STATE #001	S	B-09-10S-26E	B	30-005-63512	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
327939	EXPENDITURE AXY STATE #001	S	D-09-10S-26E	D	30-005-63461	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
327940	FAXON BFS STATE COM #001	S	3-02-09S-26E	C	30-005-63717	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
327941	FEDERAL HJ #003	F	C-31-06S-26E	C	30-005-61420	82730	PECOS SLOPE; ABO (GAS)	G
	FEDERAL HJ #004	F	K-31-06S-26E	K	30-005-61484	82730	PECOS SLOPE; ABO (GAS)	G
	FEDERAL HJ #006	F	A-31-06S-26E	A	30-005-61456	82730	PECOS SLOPE; ABO (GAS)	G
	FEDERAL HJ #007	F	P-31-06S-26E	P	30-005-61485	82730	PECOS SLOPE; ABO (GAS)	G
	FEDERAL HJ #008	F	A-19-06S-26E	A	30-005-61486	82730	PECOS SLOPE; ABO (GAS)	G
	FEDERAL HJ #011	F	G-31-06S-26E	G	30-005-63091	82730	PECOS SLOPE; ABO (GAS)	G
	FEDERAL HJ #012	F	3-31-06S-26E	L	30-005-63127	82730	PECOS SLOPE; ABO (GAS)	G
	FEDERAL HJ #013	F	D-31-06S-26E	D	30-005-63495	82730	PECOS SLOPE; ABO (GAS)	G
					30-005-63495	97303	LESLIE SPRING; WOLFCAMP, NW (G)	
327942	FEDERAL HY #002	F	O-33-07S-25E	O	30-005-60555	82730	PECOS SLOPE; ABO (GAS)	G
	FEDERAL HY #005	F	F-34-07S-25E	F	30-005-61860	82730	PECOS SLOPE; ABO (GAS)	G
	FEDERAL HY #006	F	A-28-07S-25E	A	30-005-61853	82730	PECOS SLOPE; ABO (GAS)	G
	FEDERAL HY #007	F	A-34-07S-25E	A	30-005-61943	82730	PECOS SLOPE; ABO (GAS)	G
	FEDERAL HY #008	F	J-34-07S-25E	J	30-005-61957	82730	PECOS SLOPE; ABO (GAS)	G
	FEDERAL HY #009	F	I-28-07S-25E	I	30-005-62082	82730	PECOS SLOPE; ABO (GAS)	G
	FEDERAL HY #011	F	A-33-07S-25E	A	30-005-62110	82730	PECOS SLOPE; ABO (GAS)	G
	FEDERAL HY #012Q	F	C-28-07S-25E	C	30-005-63503	82730	PECOS SLOPE; ABO (GAS)	G
327943	FEDERAL IX #001	F	L-03-09S-26E	L	30-005-60467	82730	PECOS SLOPE; ABO (GAS)	G
	FEDERAL IX #002	F	4-03-09S-26E	D	30-005-62063	82730	PECOS SLOPE; ABO (GAS)	G
327944	FILAREE AEL FEDERAL #001	F	O-33-08S-26E	O	30-005-62486	82730	PECOS SLOPE; ABO (GAS)	G
	FILAREE AEL FEDERAL #002	F	K-33-08S-26E	K	30-005-62704	82730	PECOS SLOPE; ABO (GAS)	G
	FILAREE AEL FEDERAL #004	F	M-33-08S-26E	M	30-005-63252	97117	FOOR RANCH; PRE-PERMIAN, NW (G)	G
	FILAREE AEL FEDERAL #006	F	K-26-08S-26E	K	30-005-63988	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
					30-005-63988	82730	PECOS SLOPE; ABO (GAS)	
	FILAREE AEL FEDERAL #007	F	C-26-08S-26E	C	30-005-63665	97066	FOOR RANCH; WOLFCAMP, NORTHWEST	G
	FILAREE AEL FEDERAL #008	F	H-27-08S-26E	H	30-005-63750	97066	FOOR RANCH; WOLFCAMP, NORTHWEST	G
327945	FILAREE AEL FEDERAL COM #003	F	E-33-08S-26E	E	30-005-62913	82730	PECOS SLOPE; ABO (GAS)	G
327946	FINLEY RV COM #001Y	P	K-34-06S-25E	K	30-005-61325	82730	PECOS SLOPE; ABO (GAS)	G
	FINLEY RV COM #002	P	H-33-06S-25E	H	30-005-62699	82730	PECOS SLOPE; ABO (GAS)	G
327947	FOOTBALL BCF FEDERAL #001	F	N-01-12S-26E	N	30-005-63603	97418	SAND DRAW; ABO (G)	G
	FOOTBALL BCF FEDERAL #002H	F	I-01-12S-26E	I	30-005-64020	97361	COYOTE; WOLFCAMP (G)	G
327948	FRANCIS FEDERAL COM. #001	F	F-13-08S-25E	F	30-005-62064	82730	PECOS SLOPE; ABO (GAS)	G
327949	FRANK SR. COM #001	S	I-15-05S-24E	I	30-005-62744	82730	PECOS SLOPE; ABO (GAS)	G
327950	GALLETTA YT STATE #001	S	L-02-07S-26E	L	30-005-62085	82730	PECOS SLOPE; ABO (GAS)	G
327951	GEORGE QJ FEDERAL #001	F	A-34-06S-25E	A	30-005-61008	82730	PECOS SLOPE; ABO (GAS)	G
	GEORGE QJ FEDERAL #003	F	L-25-06S-25E	L	30-005-61263	82730	PECOS SLOPE; ABO (GAS)	G
	GEORGE QJ FEDERAL #004	F	A-35-06S-25E	A	30-005-61462	82730	PECOS SLOPE; ABO (GAS)	G
	GEORGE QJ FEDERAL #005	F	C-34-06S-25E	C	30-005-61511	82730	PECOS SLOPE; ABO (GAS)	G

	GEORGE QJ FEDERAL #006	F	D-26-06S-25E	D	30-005-61546	82730	PECOS SLOPE; ABO (GAS)	G
	GEORGE QJ FEDERAL #007	F	K-26-06S-25E	K	30-005-61547	82730	PECOS SLOPE; ABO (GAS)	G
	GEORGE QJ FEDERAL #010	F	N-26-06S-25E	N	30-005-63368	97189	PECOS SLOPE; PENNSYLVANIAN OIL	G
	GEORGE QJ FEDERAL #011	F	F-26-06S-25E	F	30-005-63444	82730	PECOS SLOPE; ABO (GAS)	G
327952	GEORGE QJ FEDERAL COM #009Q	F	C-35-06S-25E	C	30-005-63435	97189	PECOS SLOPE; PENNSYLVANIAN OIL	G
327953	GEORGE QJ FEDERAL DEEP COM #002Y	F	P-27-06S-25E	P	30-005-61400	97128	COTTONWOOD RANCH; PENNSYLVANIAN (G)	G
327954	GERRY FEDERAL COM #002	F	2-01-08S-25E	B	30-005-61320	82730	PECOS SLOPE; ABO (GAS)	G
327955	GETTY VQ FEDERAL COM #001	F	H-24-06S-25E	H	30-005-61857	82730	PECOS SLOPE; ABO (GAS)	G
327956	GODFREY MP FEDERAL #003	F	C-15-07S-25E	C	30-005-60968	82730	PECOS SLOPE; ABO (GAS)	G
	GODFREY MP FEDERAL #004	F	P-03-07S-25E	P	30-005-61118	82730	PECOS SLOPE; ABO (GAS)	G
	GODFREY MP FEDERAL #006	F	I-10-07S-25E	I	30-005-61177	82730	PECOS SLOPE; ABO (GAS)	G
327957	GRID IRON BLI FEDERAL #002	F	6-06-12S-27E	L	30-005-64063	97832	WILDCAT G-02 S122706L; WOLFCAMP	G
	GRID IRON BLI FEDERAL #003	F	7-06-12S-27E	M	30-005-64145	97832	WILDCAT G-02 S122706L; WOLFCAMP	O
327958	GROOMS XB COM #001	P	M-08-07S-26E	M	30-005-62034	82730	PECOS SLOPE; ABO (GAS)	G
327959	HAHN NH FEDERAL #001	F	I-09-07S-25E	I	30-005-60682	82730	PECOS SLOPE; ABO (GAS)	G
	HAHN NH FEDERAL #002	F	A-09-07S-25E	A	30-005-60954	82730	PECOS SLOPE; ABO (GAS)	G
	HAHN NH FEDERAL #003	F	E-09-07S-25E	E	30-005-61036	82730	PECOS SLOPE; ABO (GAS)	G
	HAHN NH FEDERAL #004	F	K-09-07S-25E	K	30-005-61619	82730	PECOS SLOPE; ABO (GAS)	G
327960	HANCOCK AHC COM #002	P	C-28-06S-26E	C	30-005-62928	82730	PECOS SLOPE; ABO (GAS)	G
	HANCOCK AHC COM #003	S	O-20-06S-26E	O	30-005-63010	82730	PECOS SLOPE; ABO (GAS)	G
327961	HANDICAPPER SWD #001	S	2-03-10S-26E	B	30-005-63307	97180	WC SWD; ORDOVICIAN	S
327962	HARD AS NAILS AMD ST #002	S	A-27-09S-26E	A	30-005-62644	82730	PECOS SLOPE; ABO (GAS)	G
327963	HARD AS NAILS AMD STATE COM #005	S	C-27-09S-26E	C	30-005-63687	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
					30-005-63687	76750	FOOR RANCH; WOLFCAMP (GAS)	
					30-005-63687	82730	PECOS SLOPE; ABO (GAS)	
327964	HARVEST ABR STATE #001	S	A-36-09S-24E	A	30-005-62236	82730	PECOS SLOPE; ABO (GAS)	G
	HARVEST ABR STATE #002	S	C-36-09S-24E	C	30-005-63232	82730	PECOS SLOPE; ABO (GAS)	G
	HARVEST ABR STATE #003	S	J-36-09S-24E	J	30-005-63446	76750	FOOR RANCH; WOLFCAMP (GAS)	G
					30-005-63446	82730	PECOS SLOPE; ABO (GAS)	
	HARVEST ABR STATE #004	S	K-36-09S-24E	K	30-005-63447	76750	FOOR RANCH; WOLFCAMP (GAS)	G
					30-005-63447	82730	PECOS SLOPE; ABO (GAS)	
327965	HELEN FEDERAL COM #001	F	4-01-07S-25E	D	30-005-61280	82730	PECOS SLOPE; ABO (GAS)	G
327966	HEWITT IM FEDERAL #003	F	L-21-06S-25E	L	30-005-62782	82730	PECOS SLOPE; ABO (GAS)	G
	HEWITT IM FEDERAL #004	F	M-21-06S-25E	M	30-005-63337	82730	PECOS SLOPE; ABO (GAS)	O
	HEWITT IM FEDERAL #005	F	I-25-06S-25E	I	30-005-63320	82730	PECOS SLOPE; ABO (GAS)	G
					30-005-63320	97128	COTTONWOOD RANCH; PENNSYLVANIAN (G)	
327967	HILLTOP NQ STATE #001	S	C-07-07S-25E	C	30-005-60700	82730	PECOS SLOPE; ABO (GAS)	G
327968	HORN YG FEDERAL #001	F	N-10-08S-26E	N	30-005-62140	82730	PECOS SLOPE; ABO (GAS)	G
					30-005-62140	97094	FOOR RANCH; PRE-PERMIAN, N. (G)	
	HORN YG FEDERAL #003	F	C-10-08S-26E	C	30-005-63491	82730	PECOS SLOPE; ABO (GAS)	G
	HORN YG FEDERAL #004	F	I-07-08S-26E	I	30-005-63680	82730	PECOS SLOPE; ABO (GAS)	G
					30-005-63680	96542	WILDCAT; GRANITE	
					30-005-63680	97179	ROCK SCHOOL HOUSE, NE (G)	
327969	HORN YG FEDERAL COM #006	F	H-15-08S-26E	H	30-005-63462	82730	PECOS SLOPE; ABO (GAS)	G
327970	HOUSTON BDH STATE COM #001	S	4-31-09S-27E	M	30-005-63620	76750	FOOR RANCH; WOLFCAMP (GAS)	G
	HOUSTON BDH STATE COM #002	S	F-31-09S-27E	F	30-005-63630	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
327971	HUCKABAY TJ FEDERAL #001	F	4-18-08S-26E	M	30-005-61631	82730	PECOS SLOPE; ABO (GAS)	G
	HUCKABAY TJ FEDERAL #002	F	1-19-08S-26E	D	30-005-61744	82730	PECOS SLOPE; ABO (GAS)	G
	HUCKABAY TJ FEDERAL #003	F	G-19-08S-26E	G	30-005-61863	82730	PECOS SLOPE; ABO (GAS)	G
	HUCKABAY TJ FEDERAL #004	F	E-20-08S-26E	E	30-005-61918	82730	PECOS SLOPE; ABO (GAS)	G
	HUCKABAY TJ FEDERAL #006	F	P-23-08S-26E	P	30-005-63467	82730	PECOS SLOPE; ABO (GAS)	G
327972	HUCKABAY TJ FEDERAL COM #008	F	D-23-08S-26E	D	30-005-63504	82730	PECOS SLOPE; ABO (GAS)	G
327973	IBIS XU STATE #001	S	A-23-09S-26E	A	30-005-62053	89741	CHAVES UNDESIGNATED; WOLFCAMP (GAS)	G
	IBIS XU STATE #004	S	E-23-09S-26E	E	30-005-63379	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
327974	IBIS XU STATE COMM #002	S	C-25-09S-26E	C	30-005-62582	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
					30-005-62582	76750	FOOR RANCH; WOLFCAMP (GAS)	
327975	INGRAM WY FEDERAL #001	F	A-18-07S-26E	A	30-005-61958	82730	PECOS SLOPE; ABO (GAS)	G
327976	JASPER ARJ FEDERAL #002	F	B-25-08S-26E	B	30-005-63143	82730	PECOS SLOPE; ABO (GAS)	G
327977	JASPER ARJ FEDERAL COM #001	F	O-25-08S-26E	O	30-005-63142	82555	PALMA MESA; PENN. SOUTH (GAS)	G
					30-005-63142	82730	PECOS SLOPE; ABO (GAS)	
	JASPER ARJ FEDERAL COM #003	F	H-10-08S-26E	H	30-005-63221	82730	PECOS SLOPE; ABO (GAS)	G
					30-005-63221	97094	FOOR RANCH; PRE-PERMIAN, N. (G)	
327978	JERVIS AYB FEDERAL #001	F	E-13-08S-26E	E	30-005-63417	82730	PECOS SLOPE; ABO (GAS)	G
	JERVIS AYB FEDERAL #006	F	L-01-08S-26E	L	30-005-63765	82730	PECOS SLOPE; ABO (GAS)	G
					30-005-63765	97094	FOOR RANCH; PRE-PERMIAN, N. (G)	
327979	JOHNSON IL #002	P	3-30-06S-26E	L	30-005-60741	82730	PECOS SLOPE; ABO (GAS)	G
	JOHNSON IL #003	P	I-30-06S-26E	I	30-005-62926	82730	PECOS SLOPE; ABO (GAS)	G
	JOHNSON IL #004	P	K-30-06S-26E	K	30-005-63330	82730	PECOS SLOPE; ABO (GAS)	G
					30-005-63330	97128	COTTONWOOD RANCH; PENNSYLVANIAN (G)	
	JOHNSON IL #005	P	O-30-06S-26E	O	30-005-63480	82730	PECOS SLOPE; ABO (GAS)	G
327980	JOKERS AWJ STATE #003	S	I-03-10S-26E	I	30-005-63470	76730	FOOR RANCH; PRE PERMIAN (GAS)	G

					30-005-63470	76750	FOOR RANCH; WOLFCAMP (GAS)	
					30-005-63470	82730	PECOS SLOPE; ABO (GAS)	
327981	KAREN FEDERAL #001	F	D-25-09S-24E	D	30-005-61629	82730	PECOS SLOPE; ABO (GAS)	G
327982	KEEBLER AMJ FEDERAL #001A	F	O-13-09S-25E	O	30-005-63219	82730	PECOS SLOPE; ABO (GAS)	G
327983	KENO AWK STATE #001	S	2-04-10S-26E	B	30-005-63360	82730	PECOS SLOPE; ABO (GAS)	G
	KENO AWK STATE #002	S	J-04-10S-26E	J	30-005-63318	82730	PECOS SLOPE; ABO (GAS)	G
327984	KERSHAW UE #001	P	I-19-08S-26E	I	30-005-61734	82730	PECOS SLOPE; ABO (GAS)	G
327985	KILGORE SO #001	P	M-24-06S-25E	M	30-005-61342	82730	PECOS SLOPE; ABO (GAS)	G
	KILGORE SO #002	P	O-24-06S-25E	O	30-005-61553	82730	PECOS SLOPE; ABO (GAS)	G
	KILGORE SO #003	S	K-24-06S-25E	K	30-005-62986	82730	PECOS SLOPE; ABO (GAS)	G
327986	KILLER BEE STATE #007	S	M-32-10S-26E	M	30-005-63704	82730	PECOS SLOPE; ABO (GAS)	G
327987	KING TF #002	P	G-25-06S-25E	G	30-005-61492	82730	PECOS SLOPE; ABO (GAS)	G
	KING TF #003	P	C-25-06S-25E	C	30-005-63085	82730	PECOS SLOPE; ABO (GAS)	G
	KING TF #004	P	N-25-06S-25E	N	30-005-63276	82730	PECOS SLOPE; ABO (GAS)	G
327988	KIRBY BCK FEDERAL COM #001	F	F-21-10S-26E	F	30-005-63573	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
	KIRBY BCK FEDERAL COM #002	F	K-21-10S-26E	K	30-005-63955	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
327989	LACROSSE BJX STATE COM #001	S	D-32-11S-27E	D	30-005-63768	96542	WILDCAT; GRANITE	G
					30-005-63768	97361	COYOTE; WOLFCAMP (G)	
327990	LEEDE UG FEDERAL #001	F	E-11-08S-25E	E	30-005-61809	82730	PECOS SLOPE; ABO (GAS)	G
327991	LEEMAN OC FEDERAL #001	F	O-18-07S-26E	O	30-005-61023	82730	PECOS SLOPE; ABO (GAS)	G
	LEEMAN OC FEDERAL #002	F	B-19-07S-26E	B	30-005-61154	82730	PECOS SLOPE; ABO (GAS)	G
	LEEMAN OC FEDERAL #003	F	O-19-07S-26E	O	30-005-61390	82730	PECOS SLOPE; ABO (GAS)	G
	LEEMAN OC FEDERAL #004	F	D-20-07S-26E	D	30-005-61651	82730	PECOS SLOPE; ABO (GAS)	G
327992	LEILA FEDERAL #002	F	J-24-06S-26E	J	30-005-61721	82730	PECOS SLOPE; ABO (GAS)	G
327993	MARGENE AWM FEDERAL #001	F	H-20-09S-26E	H	30-005-63456	82730	PECOS SLOPE; ABO (GAS)	G
	MARGENE AWM FEDERAL #002Q	F	I-20-09S-26E	I	30-005-63488	82730	PECOS SLOPE; ABO (GAS)	G
	MARGENE AWM FEDERAL #005Q	F	K-19-09S-26E	K	30-005-62690	82730	PECOS SLOPE; ABO (GAS)	G
327994	MARIE VU FEDERAL #001	F	I-20-09S-25E	I	30-005-62001	82730	PECOS SLOPE; ABO (GAS)	G
327995	MARSHALL XG COM #001	F	N-22-08S-26E	N	30-005-61967	82730	PECOS SLOPE; ABO (GAS)	G
327996	MCCONKEY HX #001	P	D-10-09S-26E	D	30-005-00154	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
					30-005-00154	82730	PECOS SLOPE; ABO (GAS)	
					30-005-00154	97066	FOOR RANCH; WOLFCAMP, NORTHWEST	
	MCCONKEY HX #004	P	L-10-09S-26E	L	30-005-62589	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
					30-005-62589	97066	FOOR RANCH; WOLFCAMP, NORTHWEST	
327997	MCCREA SF COM #001	P	C-14-09S-25E	C	30-005-61273	82730	PECOS SLOPE; ABO (GAS)	G
327998	MCCREA TU COM #001	P	B-32-08S-26E	B	30-005-61566	82730	PECOS SLOPE; ABO (GAS)	G
327999	MCDERMETT #001	P	J-19-06S-25E	J	30-005-61113	82730	PECOS SLOPE; ABO (GAS)	G
328000	MEADOWS COM #001	P	B-13-07S-25E	B	30-005-60911	82730	PECOS SLOPE; ABO (GAS)	G
	MEADOWS COM #002	P	D-13-07S-25E	D	30-005-61148	82730	PECOS SLOPE; ABO (GAS)	G
328001	MORTON SZ FEDERAL #001	F	L-10-08S-25E	L	30-005-61441	82730	PECOS SLOPE; ABO (GAS)	G
	MORTON SZ FEDERAL #002	F	H-10-08S-25E	H	30-005-61653	82730	PECOS SLOPE; ABO (GAS)	G
	MORTON SZ FEDERAL #003	F	C-10-08S-25E	C	30-005-61874	82730	PECOS SLOPE; ABO (GAS)	G
	MORTON SZ FEDERAL #004	F	P-10-08S-25E	P	30-005-61799	82730	PECOS SLOPE; ABO (GAS)	G
	MORTON SZ FEDERAL #005	F	J-10-08S-25E	J	30-005-63242	82730	PECOS SLOPE; ABO (GAS)	G
					30-005-63242	97115	MILNER LAKE; PENNSYLVANIAN (G)	
328002	MUDDY COM #001	P	N-29-07S-26E	N	30-005-61379			G
328003	NEVADA AXN STATE #002	S	M-04-10S-26E	M	30-005-63362	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
328004	NICKEY RF FEDERAL #001	F	4-19-07S-26E	M	30-005-61458	82730	PECOS SLOPE; ABO (GAS)	G
	NICKEY RF FEDERAL #002	F	2-19-07S-26E	E	30-005-61690	82730	PECOS SLOPE; ABO (GAS)	G
	NICKEY RF FEDERAL #003	F	K-19-07S-26E	K	30-005-63044	82730	PECOS SLOPE; ABO (GAS)	G
328005	NIGHT OWL AFA STATE COM #001	S	I-22-09S-26E	I	30-005-62581	82730	PECOS SLOPE; ABO (GAS)	G
	NIGHT OWL AFA STATE COM #002	S	H-22-09S-26E	H	30-005-63395	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
	NIGHT OWL AFA STATE COM #003	S	P-22-09S-26E	P	30-005-63377	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
328006	NIGHT OWL AFG STATE COM #001	S	G-22-09S-26E	G	30-005-62590	82730	PECOS SLOPE; ABO (GAS)	G
	NIGHT OWL AFG STATE COM #002	S	L-09-09S-26E	L	30-005-63688	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
					30-005-63688	76750	FOOR RANCH; WOLFCAMP (GAS)	
328007	NITRAM AVN FEDERAL #002	F	N-35-08S-26E	N	30-005-63799	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
					30-005-63799	96542	WILDCAT; GRANITE	
328008	NORTEX WN STATE COM #001	S	C-22-09S-26E	C	30-005-62048	82730	PECOS SLOPE; ABO (GAS)	G
328009	NORTH STURGEON PR FEDERAL #002	F	K-04-07S-26E	K	30-005-61593	82730	PECOS SLOPE; ABO (GAS)	G
328010	OHBERG BCQ COM #001	P	F-23-09S-24E	F	30-005-63575	82730	PECOS SLOPE; ABO (GAS)	G
328011	PAPALOTE OI STATE #001	S	A-16-07S-25E	A	30-005-60775	82730	PECOS SLOPE; ABO (GAS)	G
	PAPALOTE OI STATE #003	S	C-16-07S-25E	C	30-005-61429	82730	PECOS SLOPE; ABO (GAS)	G
	PAPALOTE OI STATE #004	S	I-16-07S-25E	I	30-005-61430	82730	PECOS SLOPE; ABO (GAS)	G
328013	PAY AYY FEDERAL COM #001	F	D-11-08S-26E	D	30-005-63510	82730	PECOS SLOPE; ABO (GAS)	G
328014	PEEK WU FEDERAL #001	F	4-06-08S-26E	D	30-005-61972	82730	PECOS SLOPE; ABO (GAS)	G
328015	PENNZOIL SG STATE COM #001	S	J-32-07S-26E	J	30-005-61224	82730	PECOS SLOPE; ABO (GAS)	G
					30-005-61224	97110	LESLIE SPRING; WOLFCAMP, SOUTH (G)	
328016	PERCENTAGE APR #001	P	O-03-08S-26E	O	30-005-63269	97094	FOOR RANCH; PRE-PERMIAN, N. (G)	G
					30-005-63269	97095	WC EIGHTMILE DRAW; PENN. (G)	
328017	PERCH BCP STATE COM #001	S	M-29-09S-27E	M	30-005-63557	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
328091	POWERS OL DEEP FEDERAL #006	F	K-27-06S-25E	K	30-005-61548	97128	COTTONWOOD RANCH; PENNSYLVANIAN (G)	G

328019	POWERS OL FEDERAL #001	F	P-33-06S-25E	P	30-005-60799	82730	PECOS SLOPE; ABO (GAS)	G
	POWERS OL FEDERAL #002	F	N-33-06S-25E	N	30-005-60800	82730	PECOS SLOPE; ABO (GAS)	G
	POWERS OL FEDERAL #007	F	G-29-06S-25E	G	30-005-62908	82730	PECOS SLOPE; ABO (GAS)	G
	POWERS OL FEDERAL #008	F	J-21-06S-25E	J	30-005-62923	82730	PECOS SLOPE; ABO (GAS)	G
	POWERS OL FEDERAL #010Y	F	F-33-06S-25E	F	30-005-61976	82730	PECOS SLOPE; ABO (GAS)	G
328020	POWERS OL FEDERAL COM #011	F	B-33-06S-25E	B	30-005-63094	82730	PECOS SLOPE; ABO (GAS)	G
328021	PROGRAM AXP STATE #001	S	O-05-10S-26E	O	30-005-63365	76750	FOOR RANCH; WOLFCAMP (GAS)	G
	PROGRAM AXP STATE #003	S	I-05-10S-26E	I	30-005-63479	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
328022	QUARTERBACK BQG FEDERAL #001	F	J-06-12S-27E	J	30-005-64138	97832	WILDCAT G-02 S122706L; WOLFCAMP	O
328023	QUINIELA AXQ STATE #003	S	1-05-10S-26E	A	30-005-63618	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
328024	RED ROCK NB FEDERAL #002	F	N-28-06S-25E	N	30-005-62748	82730	PECOS SLOPE; ABO (GAS)	G
	RED ROCK NB FEDERAL #004	F	C-28-06S-25E	C	30-005-62796	82730	PECOS SLOPE; ABO (GAS)	G
	RED ROCK NB FEDERAL #006	F	B-28-06S-25E	B	30-005-62858	82730	PECOS SLOPE; ABO (GAS)	G
	RED ROCK NB FEDERAL #007	F	M-28-06S-25E	M	30-005-63103	82730	PECOS SLOPE; ABO (GAS)	G
328025	REINAUER RC FEDERAL #001	F	A-29-07S-25E	A	30-005-62570	82730	PECOS SLOPE; ABO (GAS)	G
	REINAUER RC FEDERAL #002	F	G-20-07S-25E	G	30-005-63216	82730	PECOS SLOPE; ABO (GAS)	G
328026	REINAUER RC FEDERAL COM #003	F	I-20-07S-25E	I	30-005-63217	82730	PECOS SLOPE; ABO (GAS)	G
328027	RIC #004	P	O-29-06S-25E	O	30-005-61162	82730	PECOS SLOPE; ABO (GAS)	G
328028	RITA TZ FEDERAL #001	F	4-04-08S-26E	D	30-005-61564	82730	PECOS SLOPE; ABO (GAS)	G
	RITA TZ FEDERAL #002	F	F-04-08S-26E	F	30-005-61973	82730	PECOS SLOPE; ABO (GAS)	G
	RITA TZ FEDERAL #006	F	P-05-08S-26E	P	30-005-63632	97110	LESLIE SPRING; WOLFCAMP, SOUTH (G)	G
328029	RITA TZ FEDERAL COM #003	F	F-04-08S-26E	F	30-005-63243	82730	PECOS SLOPE; ABO (GAS)	G
328030	ROLLA TC #001	P	O-30-09S-26E	O	30-005-61405	82730	PECOS SLOPE; ABO (GAS)	G
	ROLLA TC #002	P	G-29-09S-26E	G	30-005-62822	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
					30-005-62822	76755	FOOR RANCH; WOLFCAMP, NORTH (GAS)	
328031	ROOK RK STATE #001	S	H-16-08S-25E	H	30-005-61050	82730	PECOS SLOPE; ABO (GAS)	G
	ROOK RK STATE #003	S	L-02-08S-25E	L	30-005-61447	82730	PECOS SLOPE; ABO (GAS)	G
	ROOK RK STATE #004	S	E-02-08S-25E	E	30-005-61488	82730	PECOS SLOPE; ABO (GAS)	G
328032	ROOMBA BKM #001	P	P-17-10S-26E	P	30-005-64000	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
328033	ROULETTE AXR STATE #001	S	E-08-10S-26E	E	30-005-63410	76750	FOOR RANCH; WOLFCAMP (GAS)	G
					30-005-63410	82730	PECOS SLOPE; ABO (GAS)	
328034	RUBY JO ATY #003	P	L-14-08S-26E	L	30-005-63429	82730	PECOS SLOPE; ABO (GAS)	G
328035	RUTH XK #001	F	J-01-07S-25E	J	30-005-62067	82730	PECOS SLOPE; ABO (GAS)	G
328036	SACRA SA #002	P	P-23-06S-25E	P	30-005-61340	82730	PECOS SLOPE; ABO (GAS)	G
	SACRA SA #004	P	P-35-06S-25E	P	30-005-61449	82730	PECOS SLOPE; ABO (GAS)	G
	SACRA SA #005	P	A-27-06S-25E	A	30-005-61571	82730	PECOS SLOPE; ABO (GAS)	G
	SACRA SA #006	P	K-23-06S-25E	K	30-005-62017	82730	PECOS SLOPE; ABO (GAS)	G
	SACRA SA #007Z	P	P-22-06S-25E	P	30-005-61960	82730	PECOS SLOPE; ABO (GAS)	G
	SACRA SA #009	F	4-19-06S-26E	M	30-005-61634	82730	PECOS SLOPE; ABO (GAS)	G
	SACRA SA #014	P	K-19-06S-26E	K	30-005-63323	82730	PECOS SLOPE; ABO (GAS)	G
	SACRA SA #021	P	K-35-06S-25E	K	30-005-63432	82730	PECOS SLOPE; ABO (GAS)	G
328037	SACRA SA COM #001	P	E-35-06S-25E	E	30-005-61271	82730	PECOS SLOPE; ABO (GAS)	G
	SACRA SA COM #011	S	G-35-06S-25E	G	30-005-62987	82730	PECOS SLOPE; ABO (GAS)	G
	SACRA SA COM #012	P	I-23-06S-25E	I	30-005-63356	82730	PECOS SLOPE; ABO (GAS)	G
	SACRA SA COM #013	P	J-34-06S-25E	J	30-005-63118	82730	PECOS SLOPE; ABO (GAS)	G
	SACRA SA COM #015	P	N-23-06S-25E	N	30-005-63322	82730	PECOS SLOPE; ABO (GAS)	G
	SACRA SA COM #017	P	G-34-06S-25E	G	30-005-63321	82730	PECOS SLOPE; ABO (GAS)	G
328038	SALEM #002	P	N-03-08S-26E	N	30-005-63439	97094	FOOR RANCH; PRE-PERMIAN, N. (G)	G
	SALEM #003	P	L-03-08S-26E	L	30-005-63554	82730	PECOS SLOPE; ABO (GAS)	G
328039	SALEM COM #001	P	2-04-08S-26E	B	30-005-61584	82730	PECOS SLOPE; ABO (GAS)	G
328040	SAND COM #001	P	F-10-07S-26E	F	30-005-61667	82730	PECOS SLOPE; ABO (GAS)	G
328041	SANDLEWOOD AEW STATE #001	S	N-31-08S-27E	N	30-005-62546	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
	SANDLEWOOD AEW STATE #002	S	2-31-08S-27E	E	30-005-63281	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
					30-005-63281	82730	PECOS SLOPE; ABO (GAS)	
328042	SAVAGE FEDERAL #001	F	H-04-07S-25E	H	30-005-60704	82730	PECOS SLOPE; ABO (GAS)	G
	SAVAGE FEDERAL #002	F	F-04-07S-25E	F	30-005-60756	82730	PECOS SLOPE; ABO (GAS)	G
	SAVAGE FEDERAL #003	F	I-04-07S-25E	I	30-005-61158	82730	PECOS SLOPE; ABO (GAS)	G
	SAVAGE FEDERAL #004	F	N-04-07S-25E	N	30-005-61220	82730	PECOS SLOPE; ABO (GAS)	G
	SAVAGE FEDERAL #005	F	2-04-07S-25E	B	30-005-63144	82730	PECOS SLOPE; ABO (GAS)	G
328053	SAVAGE NI FEDERAL #002	F	O-19-06S-26E	O	30-005-61531	82730	PECOS SLOPE; ABO (GAS)	G
	SAVAGE NI FEDERAL #005	F	I-19-06S-26E	I	30-005-63025	82730	PECOS SLOPE; ABO (GAS)	G
328054	SAVAGE NI FEDERAL COM. #003	F	B-30-06S-26E	B	30-005-61847	82730	PECOS SLOPE; ABO (GAS)	G
328055	SEINFELD BBK FEDERAL #001	F	M-12-06S-26E	M	30-005-62117	97282	CROCKETT DRAW; WOLFCAMP (G)	G
					30-005-62117	97298	BOSQUE; PENN., N (G)	
328056	SHORT RM DEEP FEDERAL #005	F	I-25-07S-25E	I	30-005-62938	82730	PECOS SLOPE; ABO (GAS)	G
328057	SHORT RM FEDERAL #001	F	K-25-07S-25E	K	30-005-61620	82730	PECOS SLOPE; ABO (GAS)	G
	SHORT RM FEDERAL #002	F	O-27-07S-25E	O	30-005-62009	82730	PECOS SLOPE; ABO (GAS)	G
	SHORT RM FEDERAL #003	F	L-27-07S-25E	L	30-005-62059	82730	PECOS SLOPE; ABO (GAS)	G
	SHORT RM FEDERAL #004	F	G-27-07S-25E	G	30-005-62909	82730	PECOS SLOPE; ABO (GAS)	G
328058	SHUFFLE BLS STATE COM #001	S	C-16-10S-26E	C	30-005-64122	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
328059	SKINK SK STATE #003	S	C-32-07S-26E	C	30-005-61611	82730	PECOS SLOPE; ABO (GAS)	G
	SKINK SK STATE #004	S	F-36-07S-25E	F	30-005-61450	82730	PECOS SLOPE; ABO (GAS)	G
	SKINK SK STATE #005	S	O-36-07S-25E	O	30-005-63319	82730	PECOS SLOPE; ABO (GAS)	G
	SKINK SK STATE #006	S	L-36-07S-25E	L	30-005-63370	82730	PECOS SLOPE; ABO (GAS)	G

328060	SNELL QZ #002	P	F-31-06S-25E	F	30-005-63119	82730	PECOS SLOPE; ABO (GAS)	G
328043	SORENSEN IB FEDERAL #002	F	4-06-07S-26E	D	30-005-61940	82730	PECOS SLOPE; ABO (GAS)	G
	SORENSEN IB FEDERAL #003	F	K-06-07S-26E	K	30-005-61985	82730	PECOS SLOPE; ABO (GAS)	G
	SORENSEN IB FEDERAL #004	F	J-06-07S-26E	J	30-005-62025	82730	PECOS SLOPE; ABO (GAS)	G
328044	SOUTH DALLAS #002	S	2-02-10S-26E	B	30-005-62746	76750	FOOR RANCH; WOLFCAMP (GAS)	G
328045	SPARROW SP STATE #001	S	C-32-06S-25E	C	30-005-61343	82730	PECOS SLOPE; ABO (GAS)	G
	SPARROW SP STATE #002	S	H-32-06S-25E	H	30-005-61504	82730	PECOS SLOPE; ABO (GAS)	G
	SPARROW SP STATE #003	S	M-32-06S-25E	M	30-005-62920	82730	PECOS SLOPE; ABO (GAS)	G
	SPARROW SP STATE #004	S	E-05-07S-25E	E	30-005-62934	82730	PECOS SLOPE; ABO (GAS)	G
	SPARROW SP STATE #005	S	N-05-07S-25E	N	30-005-62936	82730	PECOS SLOPE; ABO (GAS)	G
	SPARROW SP STATE #007	S	O-32-06S-25E	O	30-005-63206	82730	PECOS SLOPE; ABO (GAS)	G
328046	SPEAR OA FEDERAL #001	F	H-09-09S-26E	H	30-005-60761	82730	PECOS SLOPE; ABO (GAS)	G
	SPEAR OA FEDERAL #002	F	D-15-09S-26E	D	30-005-61974	82730	PECOS SLOPE; ABO (GAS)	G
	SPEAR OA FEDERAL #003	F	L-15-09S-26E	L	30-005-62079	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
					30-005-62079	76750	FOOR RANCH; WOLFCAMP (GAS)	
	SPEAR OA FEDERAL #004	F	P-09-09S-26E	P	30-005-62575	82730	PECOS SLOPE; ABO (GAS)	G
	SPEAR OA FEDERAL #006	F	B-09-09S-26E	B	30-005-63392	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
					30-005-63392	76750	FOOR RANCH; WOLFCAMP (GAS)	
					30-005-63392	82730	PECOS SLOPE; ABO (GAS)	
	SPEAR OA FEDERAL #007	F	J-09-09S-26E	J	30-005-63393	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
					30-005-63393	82730	PECOS SLOPE; ABO (GAS)	
					30-005-63393	97066	FOOR RANCH; WOLFCAMP, NORTHWEST	
328047	SPEAR OA FEDERAL COM #010	F	O-05-09S-26E	O	30-005-64123	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
328048	SPOOL SU #008	P	E-23-07S-25E	E	30-005-63124	82730	PECOS SLOPE; ABO (GAS)	G
328049	SPOOL SU COM #004	P	K-22-07S-25E	K	30-005-61961	82730	PECOS SLOPE; ABO (GAS)	G
328050	SQUIRREL SL STATE #001	S	K-32-07S-26E	K	30-005-61298	82730	PECOS SLOPE; ABO (GAS)	G
328051	STARE BEA STATE COM #001	S	D-08-09S-27E	D	30-005-63569	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
328061	STERNE BCS COM #001	P	M-11-06S-26E	M	30-005-63561	97282	CROCKETT DRAW; WOLFCAMP (G)	G
	STERNE BCS COM #002	P	M-13-06S-26E	M	30-005-63562	82730	PECOS SLOPE; ABO (GAS)	G
					30-005-63562	97282	CROCKETT DRAW; WOLFCAMP (G)	
328062	STURGEON FEDERAL COM #001	F	D-08-07S-26E	D	30-005-61617	82730	PECOS SLOPE; ABO (GAS)	G
328063	TAMARACK QF STATE COM #003	S	E-32-06S-26E	E	30-005-62927	82730	PECOS SLOPE; ABO (GAS)	G
328064	TERRA 35 STATE #001	S	H-35-09S-26E	H	30-005-62653	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
					30-005-62653	76750	FOOR RANCH; WOLFCAMP (GAS)	
328065	THOMAS LN FEDERAL #007	F	D-29-06S-25E	D	30-005-61948	82730	PECOS SLOPE; ABO (GAS)	G
	THOMAS LN FEDERAL #008	F	F-29-06S-25E	F	30-005-63097	82730	PECOS SLOPE; ABO (GAS)	G
328066	THORPE MI FEDERAL #003	F	E-03-07S-25E	E	30-005-60939	82730	PECOS SLOPE; ABO (GAS)	G
	THORPE MI FEDERAL #007	F	G-03-07S-25E	G	30-005-61530	82730	PECOS SLOPE; ABO (GAS)	G
	THORPE MI FEDERAL #008	F	A-22-07S-25E	A	30-005-61563	82730	PECOS SLOPE; ABO (GAS)	G
	THORPE MI FEDERAL #009	F	E-22-07S-25E	E	30-005-61858	82730	PECOS SLOPE; ABO (GAS)	G
	THORPE MI FEDERAL #015	F	C-22-07S-25E	C	30-005-63020	82730	PECOS SLOPE; ABO (GAS)	G
	THORPE MI FEDERAL #016	F	3-03-07S-25E	C	30-005-63129	82730	PECOS SLOPE; ABO (GAS)	G
	THORPE MI FEDERAL #017	F	G-22-07S-25E	G	30-005-63130	82730	PECOS SLOPE; ABO (GAS)	G
328067	THORPE MI FEDERAL COM #002	F	L-03-07S-25E	L	30-005-60740	82730	PECOS SLOPE; ABO (GAS)	G
	THORPE MI FEDERAL COM #011	F	J-03-07S-25E	J	30-005-63019	82730	PECOS SLOPE; ABO (GAS)	G
328068	TIDE AXT STATE COM #001	S	P-32-09S-26E	P	30-005-63722	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
328069	TOUCHDOWN BJC FEDERAL #001	F	I-11-12S-26E	I	30-005-63876	97361	COYOTE; WOLFCAMP (G)	O
					30-005-63876	97406	LEA LAKE; PRE-PERMIAN (G)	
	TOUCHDOWN BJC FEDERAL #002	F	A-11-12S-26E	A	30-005-64090	97361	COYOTE; WOLFCAMP (G)	G
328070	TRAVIS FEDERAL COM #001	F	M-20-06S-26E	M	30-005-62061	82730	PECOS SLOPE; ABO (GAS)	G
328071	ULTRA U A STATE #001	S	E-32-09S-26E	E	30-005-61536	82730	PECOS SLOPE; ABO (GAS)	G
328072	ULTRA UA STATE COM #002	S	H-32-09S-26E	H	30-005-63283	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
328073	UPRIGHT BFU STATE COM #001	S	H-30-10S-26E	H	30-005-63698	97120	COMANCHE; WOLFCAMP (G)	G
328074	VALUE BCV STATE COM #001	S	O-02-08S-26E	O	30-005-63590	82730	PECOS SLOPE; ABO (GAS)	G
					30-005-63590	97094	FOOR RANCH; PRE-PERMIAN, N. (G)	
328075	VANILLA AZA STATE #001	S	A-28-09S-26E	A	30-005-63390	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
328076	VEGAS AVT STATE COM #001	S	K-22-09S-26E	K	30-005-62539	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
328077	VERBENA UV FEDERAL #001	F	H-26-07S-25E	H	30-005-61748	97150	COYOTE; DRAW; PERMO PENNSYLVANIAN (G)	G
	VERBENA UV FEDERAL #002	F	D-26-07S-25E	D	30-005-62941	82730	PECOS SLOPE; ABO (GAS)	G
328078	VISTA AVS STATE #002	S	F-21-09S-26E	F	30-005-63262	76755	FOOR RANCH; WOLFCAMP, NORTH (GAS)	G
328079	WAGER AWG STATE #004	S	D-34-09S-26E	D	30-005-63306	82730	PECOS SLOPE; ABO (GAS)	G
328080	WAGER AWG STATE COM #003	S	J-34-09S-26E	J	30-005-63297	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
					30-005-63297	76750	FOOR RANCH; WOLFCAMP (GAS)	
328081	WANDA ZT FEDERAL #001	F	2-31-10S-26E	E	30-005-62163	82730	PECOS SLOPE; ABO (GAS)	G
328082	WESTERN #003	P	N-30-06S-25E	N	30-005-63312	82730	PECOS SLOPE; ABO (GAS)	G
328092	WESTERN COM #002	P	K-30-06S-25E	K	30-005-61489	82730	PECOS SLOPE; ABO (GAS)	G
328083	WHITWORTH RU STATE #003	S	M-12-09S-26E	M	30-005-62112	82730	PECOS SLOPE; ABO (GAS)	G
	WHITWORTH RU STATE #005	S	O-12-09S-26E	O	30-005-62707	82730	PECOS SLOPE; ABO (GAS)	G
328084	WILLIAMSON LC FEDERAL #002	F	P-09-08S-25E	P	30-005-60847	82730	PECOS SLOPE; ABO (GAS)	G
	WILLIAMSON LC FEDERAL #003	F	1-04-08S-25E	A	30-005-61459	82730	PECOS SLOPE; ABO (GAS)	G
	WILLIAMSON LC FEDERAL #006	F	H-09-08S-25E	H	30-005-61461	82730	PECOS SLOPE; ABO (GAS)	G
	WILLIAMSON LC FEDERAL #009	F	P-04-08S-25E	P	30-005-62116	82730	PECOS SLOPE; ABO (GAS)	G

328085	WITTER VW FEDERAL #001	F	J-34-07S-26E	J	30-005-61842	82730	PECOS SLOPE; ABO (GAS)	G
328086	WITZ VN STATE #001	S	D-26-09S-26E	D	30-005-61790	82730	PECOS SLOPE; ABO (GAS)	G
	WITZ VN STATE #002	S	A-26-09S-26E	A	30-005-62599	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
					30-005-62599	76750	FOOR RANCH; WOLFCAMP (GAS)	
	WITZ VN STATE #003	S	I-26-09S-26E	I	30-005-62626	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
					30-005-62626	76750	FOOR RANCH; WOLFCAMP (GAS)	
	WITZ VN STATE #006	S	D-26-09S-26E	D	30-005-63463	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
					30-005-63463	76750	FOOR RANCH; WOLFCAMP (GAS)	
328087	XANADU AXD FEDERAL #001	F	P-29-09S-26E	P	30-005-63641	76730	FOOR RANCH; PRE PERMIAN (GAS)	G
328088	YANKEE ANK FEDERAL COM #001	F	O-11-07S-25E	O	30-005-63026	82730	PECOS SLOPE; ABO (GAS)	G
	YANKEE ANK FEDERAL COM #002	F	F-01-07S-25E	F	30-005-63582	82730	PECOS SLOPE; ABO (GAS)	G
328093	ZANE ABS FEDERAL #001	F	O-15-09S-26E	O	30-005-62257	82730	PECOS SLOPE; ABO (GAS)	G
328089	ZANE ABS FEDERAL COM #003	F	G-15-09S-26E	G	30-005-62577	97111	FOOR RANCH; WOLFCAMP (O)	O

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720
District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720
District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170
District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

Comments

Permit 279420

CHANGEOP COMMENTS

Operator: EOG RESOURCES INC P.O. Box 2267 Midland, TX 79702	OGRID: 7377
	Permit Number: 279420
	Permit Type: ChangeOp

Comments

Created By	Comment	Comment Date
------------	---------	--------------

There are no Comments for this Permit