(June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No. NMSF078212

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit or CA/Agreement, Name and/or No.	
Type of Well Oil Well				8. Well Name and No. ROURKE 1E	
2. Name of Operator Contact: AMANDA WALKER HILCORP ENERGY COMPANY E-Mail: mwalker@hilcorp.com				9. API Well No. 30-045-25892-00-C1	
3a. Address 3b. Phone No. (inclu 1111 TRAVIS STREET Ph: 505-324-512 HOUSTON, TX 77002 Ph: 505-324-512				10. Field and Pool or Exploratory Area BASIN DAKOTA FLORA VISTA	
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)			11. County or Parish,	State
Sec 4 T30N R13W NWNW 10 36.846440 N Lat, 108.215210	SAN JUAN COUNTY, NM				
12. CHECK THE AF	PPROPRIATE BOX(ES)	TO INDICATE NATURE OF	F NOTICE,	REPORT, OR OTH	HER DATA
TYPE OF SUBMISSION		TYPE OF	ACTION		
■ Notice of Intent	☐ Acidize	Deepen	_	ion (Start/Resume)	☐ Water Shut-Off
☐ Subsequent Report	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclama		☐ Well Integrity
☐ Subsequent Report	☐ Casing Repair	☐ New Construction	☐ Recomp		☐ Other
☐ Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon	☐ Tempora	arily Abandon	
	☐ Convert to Injection	☐ Plug Back	☐ Water D	☐ Water Disposal	
13. Describe Proposed or Completed Ope If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab- determined that the site is ready for fi Hilcorp Energy Company requ procedure. The Pre-Disturban re-vegetation plan was attached	ally or recomplete horizontally, will be performed or provide operations. If the operation resonandonment Notices must be file and inspection. The sets permission to complete Site Visit was held on 4	give subsurface locations and measur the Bond No. on file with BLM/BIA. Jults in a multiple completion or record and only after all requirements, including the the P&A on the subject were 4/21/2020 with Bob Switzer/BI	red and true ve Required sub mpletion in a r ing reclamation ell per the at LM. The	rtical depths of all pertin osequent reports must be new interval, a Form 316 n, have been completed a tached	nent markers and zones. filed within 30 days 0-4 must be filed once
14. I hereby certify that the foregoing is	Electronic Submission #5	539074 verified by the BLM Well	I Information	System	

Committed to AFMSS for processing by JOE KILLINS on 12/11/2020 (21JK0059SE) Name (Printed/Typed) AMANDA WALKER Title OPERATIONS/REGULATORY TECH SR. Signature (Electronic Submission) Date 12/02/2020 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Title ENGINEER Date 12/11/2020

Approved By JOE KILLINS Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office Farmington

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)
** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

Revisions to Operator-Submitted EC Data for Sundry Notice #539074

Operator Submitted BLM Revised (AFMSS)

ABD NOI ABD Sundry Type: NOI

NMSF078212 NMSF078212 Lease:

Agreement:

Operator: HILCORP ENERGY HILCORP ENERGY COMPANY

1111 TRAVIS ST. HOUSTON, TX 77002 1111 TRAVIS STREET HOUSTON, TX 77002 Ph: 505-324-5122 Ph: 713.209.2400

AMANDA WALKER OPERATIONS/REGULATORY TECH SR. Admin Contact:

AMANDA WALKER OPERATIONS/REGULATORY TECH SR.

E-Mail: mwalker@hilcorp.com E-Mail: mwalker@hilcorp.com

Ph: 505-324-5122 Ph: 505-324-5122

Tech Contact: AMANDA WALKER AMANDA WALKER

OPERATIONS/REGULATORY TECH SR. OPERATIONS/REGULATORY TECH SR.

E-Mail: mwalker@hilcorp.com E-Mail: mwalker@hilcorp.com

Ph: 505-324-5122 Ph: 505-324-5122

Location:

State: County: NM SAN JUAN NM SAN JUAN

DK / GALLUP **BASIN DAKOTA** Field/Pool: FLORA VISTA

ROURKE 1E ROURKE 1E Well/Facility:

Sec 4 T30N R13W NWNW 1000FNL 1000FWL Sec 4 T30N R13W Mer NMP NWNW 1000FNL 1000FWL

36.846440 N Lat, 108.215210 W Lon



Hilcorp Energy Company ROURKE 1E

P&A - Notice of Intent API # 3004525892

PROCEDURE

1. Hold a pre-job safety meeting prior to beginning all operations or during a change in operational scope or initiation of SIMOPs. Properly document all operations via the JSA process. Insure that all personnel onsight abide by HEC safety protocol, including PPE, housekeeping, and procedures. Verify cathodic protection is off and wellhead instrumentation is properly disconnected from wellhead. Comply with all NMOCD, BLM, and HEC safety and environmental regulations. Verify there is no H2S present prior to beginning operations. If H2S is present, take the necessary actions to insure that the operation is safe prior to beginning operations. Observe and record pressures across all strings daily, prior to beginning operations. Notify NMOCD and BLM 24 hours in advance of beginning operations

NOTE: this procedure is contingent upon P&A sundry approval by both the BLM and the NMOCD. All cement volumes use 100% excess outside pipe and 50' excess inside (unless stated otherwise). All cement will be Class G, mixed at 15.8 ppg with a 1.15 cf/sx yield. 8.3 ppg fluid will be used to balance the well during this operation.

- Drill thru the upper cement plug in the production casing from 29' to ~430'. Tag the top of the Kirtland plug (estimated TOC at 451'). PT the sqz holes from 429-430' to 500 psi.
- 3. Continue drilling thru the top of the Kirtland plug (est TOC at 451') to 625' (top of Kirtland sand at 557'). Note: plug btm at ~650'
- 4. Perforate for sqz at 600' using jet cutter to achieve 360' penetration.

NOTE: if unable to establish communication thru the jet cut, a high density perforating option will be utilized at 600'


- 5. Establish injection rate into the surrounding formation. If unable to establish an injection rate, lay a 10 sx balanced plug w/ micro-fine cement and apply surface pressure to squeeze the cement into the channel
- 6. Bleed off BH pressure and monitor for 30 minutes
- 7. RU cementers, mix and pump a 75 sx plug f/ 550' to surface
- 8. Cut and cap wellhead. Install P&A marker



Hilcorp Energy Company 3004525892

P&A - Notice of Intent API #: 3004525892

WBD - CURRENT






Hilcorp Energy Company 3004525892

P&A - Notice of Intent API #: 3004525892

WBD - PROPOSED

Rourke #1E Proposed P&A

Today's Date: **3/17/20** Spud: **4/19/84** Completed: **5/24/84** Elevation: **5551'** GI Basin Dakota / Gallup 1000' FNL & 1000' FWL, Sec. 4, T30N, R13W San Juan County, NM / API# 30-045-25892



GENERAL REQUIREMENTS FOR PERMANENT ABANDONMENT OF WELLS ON FEDERAL AND INDIAN LEASES FARMINGTON FIELD OFFICE

- 1.0 The approved plugging plans may contain variances from the following <u>minimum general</u> requirements.
 - 1.1 Modification of the approved plugging procedure is allowed only with the prior approval of the Authorized Officer, Farmington Field Office.
 - 1.2 Requirements may be added to address specific well conditions.
- 2.0 Materials used must be accurately measured. (densometer/scales)
- 3.0 A tank or lined pit must be used for containment of any fluids from the wellbore during plugging operations and all pits are to be fenced with woven wire. These pits will be fenced on three sides and once the rig leaves location, the fourth side will be fenced.
 - 3.1 Pits are not to be used for disposal of any hydrocarbons. If hydrocarbons are present in the pit, the fluids must be removed prior to filling in.
- 4.0 All cement plugs are to be placed through a work string. Cement may be bull-headed down the casing with prior approval. Cement caps on top of bridge plugs or cement retainers may be placed by dump bailer.
 - 4.1 The cement shall be as specified in the approved plugging plan.
 - 4.2 All cement plugs placed inside casing shall have sufficient volume to fill a minimum of 100' of the casing, or annular void(s) between casings, plus an excess volume sufficient to provide for 50 linear feet of fill above the plug.
 - 4.3 Surface plugs may be no less than 50' in length.
 - 4.4 All cement plugs placed to fill annular void(s) between casing and the formation shall be of sufficient volume to fill a minimum of 100' of the annular space plus 100% excess, calculated using the bit size, or 100' of annular capacity, determined from a caliper log, plus an excess volume sufficient to provide for 50 linear feet of fill above the plug.
 - 4.5 All cement plugs placed to fill an open hole shall be of sufficient volume to fill a minimum of 100' of hole, as calculated from a caliper log, plus an excess volume sufficient to provide for 50 linear feet of fill above the plug. In the absence of a caliper log, an excess of 100% shall be required.
 - 4.6 A cement bond log or other accepted cement evaluation tool is required to be run if one had not been previously ran or cement did not circulate to surface during the original casing cementing job or subsequent cementing jobs.

2

- 5.0 All cement plugs spotted across, or above, any exposed zone(s), when; the wellbore is not full of fluid or the fluid level will not remain static, and in the case of lost circulation or partial returns during cement placement, shall be tested by tagging with the work string.
 - 5.1 The top of any cement plug verified by tagging must be at or above the depth specified in the approved plan, without regard to any excess.
 - 5.2 Testing will not be required for any cement plug that is mechanically contained by use of a bridge plug and/or cement retainer, if casing integrity has been established.
 - 5.3 Any cement plug which is the only isolating medium, for a fresh water interval or a zone containing a prospectively valuable deposit of minerals, shall be tested by tagging.
 - 5.4 If perforations are required below the surface casing shoe, a 30 minute minimum wait time will be required to determine if gas and/or water flows are present. If flow is present, the well will be shut-in for a minimum of one hour and the pressure recorded. Short or long term venting may be necessary to evacuate trapped gas. If only a water flow occurs with no associated gas, shut well in and record the pressures. Contact the Engineer as it may be necessary to change the cement weight and additives.
- 6.0 Before setting any cement plugs the hole needs to be rolled. All wells are to be controlled by means of a fluid that is to be of a weight and consistency necessary to stabilize the wellbore. This fluid shall be left in place as filler between all plugs.
 - 6.1 Drilling mud may be used as the wellbore fluid in open hole plugging operations.
 - 6.2 The wellbore fluid used in cased holes shall be of sufficient weight to balance known pore pressures in all exposed formations.
- 7.0 A blowout preventer and related equipment (BOPE) shall be installed and tested prior to working in a wellbore with any exposed zone(s); (1) that are over pressured, (2) where the pressures are unknown, or (3) known to contain H_2S .
- 8.0 Within 30 days after plugging work is completed, file a Sundry Notice, Subsequent Report of Abandonment (Form 3160-5), five copies, with the Field Manager, Bureau of Land Management, 6251 College Blvd., Suite A, Farmington, NM 87402. The report should show the manner in which the plugging work was carried out, the extent, by depth(s), of cement plugs placed, and the size and location, by depth(s), of casing left in the well. Show date well was plugged.
- 9.0 All permanently abandoned wells are to be marked with a permanent monument as specified in 43 CFR 3162.6(d). Unless otherwise approved.
- 10.0 If this well is located in a Specially Designated Area (SDA), compliance with the appropriate seasonal closure requirements will be necessary.

All of the above are minimum requirements. Failure to comply with the above conditions of approval may result in an assessment for noncompliance and/or a Shut-in Order being issued pursuant to 43 CFR 3163.1. You are further advised that any instructions, orders or decisions issued by the Bureau of Land Management are subject to administrative review pursuant to 43 CFR 3165.3 and appeal pursuant to 43 CFR 3165.4 and 43 CFR 4.700.

(October 2012 Revision)

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III
1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

COMMENTS

Action 20526

COMMENTS

Operator:			OGRID:	Action Number:	Action Type:
HILCORP ENERGY COMPANY	1111 Travis Street	Houston, TX77002	372171	20526	C-103F

Created By	Comment	Comment Date
kpickford	KP GEO Review 3/12/2021	03/12/2021

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III
1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 20526

CONDITIONS OF APPROVAL

Operator:			OGRID:	Action Number:	Action Type:
HILCORP ENERGY COMPANY	1111 Travis Street	Houston, TX77002	372171	20526	C-103F

OCD Reviewer	Condition
kpickford	None