

U.S. Department of the Interior BUREAU OF LAND MANAGEMENT Sundry Print Repor

Well Name: DOMINATOR 25 Well Location: T25S / R33E / SEC 25 / County or Parish/State: LEA /

FEDERAL COM SWSE / 32.095027 / -103.523824

Well Number: 605H Allottee or Tribe Name: Type of Well: OIL WELL

Lease Number: NMNM121958 Unit or CA Name: DOMINATOR 25 FED Unit or CA Number:

> COM WELLS-WLF NMNM138694

US Well Number: 300254474200S1 Well Status: Producing Oil Well **Operator: COG OPERATING**

Notice of Intent

Type of Action Temporary Abandonment Type of Submission: Notice of Intent

Date Sundry Submitted: 08/27/2021 Time Sundry Submitted: 07:15

Date proposed operation will begin: 10/07/2021

Procedure Description: COG Operating LLC respectfully requests temporary abandonment of the Dominator 25 Federal Com #605H. Three additional wells will be drilled on the same pad as the Dominator 25 Federal Com #605H so it will need to have production tubing pulled and the wellhead reduced to ground level in order to safely execute the drilling and completion of the new wells on this pad. Temporary abandonment operations are expected to begin October 7th,2021. This well is expected to be put back on production in the fourth quarter of 2022. 1.) MIRU pulling unit, ND tree, NU BOP. 2.) POOH w/ production tubing. 3.) RIH w/ CIBP and set +/-75ft above top perforation at 12,730ft. 4.) Spot 25 sacks of Class H cement on top of CIBP. 5.) Tag top of cement and displace wellbore with corrosion inhibited fluid. 6.) Test casing to 500psi for 30min and document with test pressure recording device. 7.) ND BOP and install TA cap. 8.) RDMO. See attachments for current wellbore diagram, proposed wellbore diagram, and perforation depths.

Surface Disturbance

Is any additional surface disturbance proposed?: No

NOI Attachments

Procedure Description

Dominator_25_Federal_Com_605H_Current_WBD_20210827071513.pdf

Dominator_25_Federal_Com_605H_Perf_Summary_20210827071458.pdf

Dominator_25_Federal_Com_605H_Proposed_TA_WBD_20210827071448.pdf

Dominator_25_Federal_Com_605H_TA_Justification_and_Procedure_20210827071434.pdf

Accepted for Record Only

SUBJECT TO LIKE APPROVAL BY BLM

NMOCD 10/8/21

Received by OCD: 9/20/2021 10:51:39 AM

Well Name: DOMINATOR 25

FEDERAL COM SWSE / 32.095027 / -103.523824

Well Location: T25S / R33E / SEC 25 / County or Parish/State: LEA /

NM

Well Number: 605H

Type of Well: OIL WELL

Allottee or Tribe Name:

Lease Number: NMNM121958

Unit or CA Name: DOMINATOR 25 FED Unit or CA Number:

Well Status: Producing Oil Well

COM WELLS-WLF

NMNM138694

US Well Number: 300254474200S1

Operator: COG OPERATING

LLC

Conditions of Approval

Specialist Review

REVISED_TA_PROCEDURE_20210830151707.pdf

Operator Certification

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a submission of Form 3160-5 or a Sundry Notice.

Operator Electronic Signature: MAYTE REYES Signed on: AUG 27, 2021 07:15 AM

Name: COG OPERATING LLC

Title: Regulatory Analyst

Street Address: 925 N ELDRIDGE PARKWAY

City: HOUSTON State: TX

Phone: (281) 293-1000

Email address: MAYTE.X.REYES@CONOCOPHILLIPS.COM

Field Representative

Representative Name: Gerald Herrera Street Address: 2208 West Main Street

City: Artesia State: NM Zip: 88210

Phone: (575)748-6940

Email address: gerald.a.herrera@conocophillips.com

BLM Point of Contact

BLM POC Name: ZOTA M STEVENS

BLM POC Title: Petroleum Engineer

BLM POC Phone: 5752345998 **BLM POC Email Address:** ZSTEVENS@BLM.GOV

Disposition: Approved **Disposition Date:** 08/30/2021

Signature: zota stevens

Page 2 of 2

REVISED TA PROCEDURE

- 1.) MIRU pulling unit, ND tree, NU BOP.
- 2.) POOH w/ production tubing.
- 3.) RIH w/ CIBP and set +/-50ft above top perforation at 12,730ft.
- 4.) Spot 25 sacks of Class H cement on top of CIBP. WOC AND TAG
- 5.) Tag top of cement and displace wellbore with corrosion inhibited fluid.
- 6.) Test casing to 500psi for 30min and document with test pressure recording device.
- 7.) ND BOP and install TA cap.
- 8.) RDMO.

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, **placed with tubing**.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Well Name: <u>DOMINATOR 25 FED COM 605H</u> Submit Subsequent Report and well bore diagram with all Perforations and CIBP with tops of cement. Well may be approved to be TA for a period of <u>6 months or until 04/30/2022</u> after successful MIT and subsequent report is submitted. If well is not brought into production by 04/30/2022, operator shall P&A the well.

Dominator 25 Federal Com 605H

Perfs Summary Sheet

	Cluster 1	Cluster 2	Cluster 3	Cluster 4	Cluster 5	Cluster 6	Cluster 7	Cluster 8
Stage 1	16,890	16868	16845	16823	16801	16778	16756	16734
	1.5=1.1	T	T	1	1	1	1	T 44 1
Stage 2	16711	16689	16667	16644	16622	16600	16577	16555
Stage 3	16533	16511	16488	16466	16444	16421	16399	16377
Stage 3	10333	10311	10400	10400	10444	10421	10399	10377
Stage 4	16354	16332	16310	16287	16265	16243	16220	16198
				-	1			
Stage 5	16176	16153	16131	16109	16086	16064	16042	16019
		_		_	,	,	,	,
Stage 6	15997	15975	15952	15930	15908	15886	15863	15841
Stage 7	15819	15796	15774	15752	15729	15707	15685	15662
Stage /	13019	13/90	13//4	13732	13/29	13/07	13063	13002
Stage 8	15640	15618	15595	15573	15551	15528	15506	15484
		1	1	-		<u> </u>		
Stage 9	15461	15439	15417	15394	15372	15350	15327	15305
- 10		T	T	T	1	T	T	T
Stage 10	15283	15260	15238	15216	15194	15171	15149	15127
Stage 11	15104	15082	15060	15037	15015	14993	14970	14948
Stage 11	13104	13002	13000	13037	13013	14773	14770	14740
Stage 12	14926	14903	14881	14859	14836	14814	14792	14769
Stage 13	14747	14725	14702	14680	14658	14635	14613	14591
Stage 14	14569	14546	14524	14502	14479	14457	14435	14412
Stage 14	14309	14340	14324	14302	144/9	14437	14433	14412
Stage 15	14390	14368	14345	14323	14301	14278	14256	14234
		'		'	•	•		
Stage 16	14211	14189	14167	14144	14122	14100	14077	14055
G. 17	14022	14010	12000	12066	12042	12021	1 12000	12077
Stage 17	14033	14010	13988	13966	13943	13921	13899	13877
Stage 18	13854	13832	13810	13787	13765	13743	13720	13698
<u> </u>								
Stage 19	13676	13653	13631	13609	13586	13564	13542	13519
G: 20	12.405	12455	12452	12420	12400	12205	12272	12241
Stage 20	13497	13475	13452	13430	13408	13385	13363	13341
Stage 21	13318	13296	13274	13252	13229	13207	13185	13162
	12310	10270	1 102/1	10202	1 10 227	10207	10100	-5102
Stage 22	13140	13118	13095	13073	13051	13028	13006	12984
Stage 23	12961	12939	12917	12894	12872	12850	12827	12805

Dominator 25 Federal Com #605H API# 30-025-44742

COG Operating LLC respectfully requests temporary abandonment of the Dominator 25 Federal Com #605H. Three additional wells will be drilled on the same pad as the Dominator 25 Federal Com #605H so it will need to have production tubing pulled and the wellhead reduced to ground level in order to safely execute the drilling and completion of the new wells on this pad. Temporary abandonment operations are expected to begin October 7th,2021. This well is expected to be put back on production in the fourth quarter of 2022.

- 1.) MIRU pulling unit, ND tree, NU BOP.
- 2.) POOH w/ production tubing.
- 3.) RIH w/ CIBP and set +/-75ft above top perforation at 12,730ft.
- 4.) Spot 25 sacks of Class H cement on top of CIBP.
- 5.) Tag top of cement and displace wellbore with corrosion inhibited fluid.
- 6.) Test casing to 500psi for 30min and document with test pressure recording device.
- 7.) ND BOP and install TA cap.
- 8.) RDMO.

See attachments for current wellbore diagram, proposed wellbore diagram, and perforation depths.

REVISED TA PROCEDURE

- 1.) MIRU pulling unit, ND tree, NU BOP.
- 2.) POOH w/ production tubing.
- 3.) RIH w/ CIBP and set +/-50ft above top perforation at 12,730ft.
- 4.) Spot 25 sacks of Class H cement on top of CIBP. WOC AND TAG
- 5.) Tag top of cement and displace wellbore with corrosion inhibited fluid.
- 6.) Test casing to 500psi for 30min and document with test pressure recording device.
- 7.) ND BOP and install TA cap.
- 8.) RDMO.

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, **placed with tubing**.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Well Name: <u>DOMINATOR 25 FED COM 605H</u> Submit Subsequent Report and well bore diagram with all Perforations and CIBP with tops of cement. Well may be approved to be TA for a period of <u>6 months or until 04/30/2022</u> after successful MIT and subsequent report is submitted. If well is not brought into production by 04/30/2022, operator shall P&A the well.

Dominator 25 Federal Com 605H

Perfs Summary Sheet

	Cluster 1	Cluster 2	Cluster 3	Cluster 4	Cluster 5	Cluster 6	Cluster 7	Cluster 8
Stage 1	16,890	16868	16845	16823	16801	16778	16756	16734
	1.5=1.1	T	T	1	1	1	1	T 44 1
Stage 2	16711	16689	16667	16644	16622	16600	16577	16555
Stage 3	16533	16511	16488	16466	16444	16421	16399	16377
Stage 3	10333	10311	10400	10400	10444	10421	10399	10377
Stage 4	16354	16332	16310	16287	16265	16243	16220	16198
				-	1			
Stage 5	16176	16153	16131	16109	16086	16064	16042	16019
		_		_	,	,	,	,
Stage 6	15997	15975	15952	15930	15908	15886	15863	15841
Stage 7	15819	15796	15774	15752	15729	15707	15685	15662
Stage /	13019	13/90	13//4	13732	13/29	13/07	13063	13002
Stage 8	15640	15618	15595	15573	15551	15528	15506	15484
		1	1	-		<u> </u>		
Stage 9	15461	15439	15417	15394	15372	15350	15327	15305
- 10		T	T	T	1	T	T	T
Stage 10	15283	15260	15238	15216	15194	15171	15149	15127
Stage 11	15104	15082	15060	15037	15015	14993	14970	14948
Stage 11	13104	13002	13000	13037	13013	14773	14770	14740
Stage 12	14926	14903	14881	14859	14836	14814	14792	14769
Stage 13	14747	14725	14702	14680	14658	14635	14613	14591
Stage 14	14569	14546	14524	14502	14479	14457	14435	14412
Stage 14	14309	14340	14324	14302	144/9	14437	14433	14412
Stage 15	14390	14368	14345	14323	14301	14278	14256	14234
		'		'	•	•		
Stage 16	14211	14189	14167	14144	14122	14100	14077	14055
G. 17	14022	14010	12000	12066	12042	12021	1 12000	12077
Stage 17	14033	14010	13988	13966	13943	13921	13899	13877
Stage 18	13854	13832	13810	13787	13765	13743	13720	13698
<u> </u>								
Stage 19	13676	13653	13631	13609	13586	13564	13542	13519
G: 20	12.405	12455	12452	12420	12400	12205	12272	12241
Stage 20	13497	13475	13452	13430	13408	13385	13363	13341
Stage 21	13318	13296	13274	13252	13229	13207	13185	13162
	12310	10270	1 102/1	10202	1 10 227	10207	10100	-5102
Stage 22	13140	13118	13095	13073	13051	13028	13006	12984
Stage 23	12961	12939	12917	12894	12872	12850	12827	12805

Dominator 25 Federal Com #605H API# 30-025-44742

COG Operating LLC respectfully requests temporary abandonment of the Dominator 25 Federal Com #605H. Three additional wells will be drilled on the same pad as the Dominator 25 Federal Com #605H so it will need to have production tubing pulled and the wellhead reduced to ground level in order to safely execute the drilling and completion of the new wells on this pad. Temporary abandonment operations are expected to begin October 7th,2021. This well is expected to be put back on production in the fourth quarter of 2022.

- 1.) MIRU pulling unit, ND tree, NU BOP.
- 2.) POOH w/ production tubing.
- 3.) RIH w/ CIBP and set +/-75ft above top perforation at 12,730ft.
- 4.) Spot 25 sacks of Class H cement on top of CIBP.
- 5.) Tag top of cement and displace wellbore with corrosion inhibited fluid.
- 6.) Test casing to 500psi for 30min and document with test pressure recording device.
- 7.) ND BOP and install TA cap.
- 8.) RDMO.

See attachments for current wellbore diagram, proposed wellbore diagram, and perforation depths.

REVISED TA PROCEDURE

- 1.) MIRU pulling unit, ND tree, NU BOP.
- 2.) POOH w/ production tubing.
- 3.) RIH w/ CIBP and set +/-50ft above top perforation at 12,730ft.
- 4.) Spot 25 sacks of Class H cement on top of CIBP. WOC AND TAG
- 5.) Tag top of cement and displace wellbore with corrosion inhibited fluid.
- 6.) Test casing to 500psi for 30min and document with test pressure recording device.
- 7.) ND BOP and install TA cap.
- 8.) RDMO.

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, **placed with tubing**.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Well Name: <u>DOMINATOR 25 FED COM 605H</u> Submit Subsequent Report and well bore diagram with all Perforations and CIBP with tops of cement. Well may be approved to be TA for a period of <u>6 months or until 04/30/2022</u> after successful MIT and subsequent report is submitted. If well is not brought into production by 04/30/2022, operator shall P&A the well.

Dominator 25 Federal Com 605H

Perfs Summary Sheet

	Cluster 1	Cluster 2	Cluster 3	Cluster 4	Cluster 5	Cluster 6	Cluster 7	Cluster 8
Stage 1	16,890	16868	16845	16823	16801	16778	16756	16734
	1.5=1.1	T	T	1	1	1	1	T 44 1
Stage 2	16711	16689	16667	16644	16622	16600	16577	16555
Stage 3	16533	16511	16488	16466	16444	16421	16399	16377
Stage 3	10333	10311	10400	10400	10444	10421	10399	10377
Stage 4	16354	16332	16310	16287	16265	16243	16220	16198
				-	1			
Stage 5	16176	16153	16131	16109	16086	16064	16042	16019
		_		_	,	,	,	,
Stage 6	15997	15975	15952	15930	15908	15886	15863	15841
Stage 7	15819	15796	15774	15752	15729	15707	15685	15662
Stage /	13019	13/90	13//4	13732	13/29	13/07	13063	13002
Stage 8	15640	15618	15595	15573	15551	15528	15506	15484
		1	1	-		<u> </u>		
Stage 9	15461	15439	15417	15394	15372	15350	15327	15305
- 10		T	T	T	1	T	T	T
Stage 10	15283	15260	15238	15216	15194	15171	15149	15127
Stage 11	15104	15082	15060	15037	15015	14993	14970	14948
Stage 11	13104	13002	13000	13037	13013	14773	14770	14740
Stage 12	14926	14903	14881	14859	14836	14814	14792	14769
Stage 13	14747	14725	14702	14680	14658	14635	14613	14591
Stage 14	14569	14546	14524	14502	14479	14457	14435	14412
Stage 14	14309	14340	14324	14302	144/9	14437	14433	14412
Stage 15	14390	14368	14345	14323	14301	14278	14256	14234
		'		'	•	•		
Stage 16	14211	14189	14167	14144	14122	14100	14077	14055
G. 17	14022	14010	12000	12066	12042	12021	1 12000	12077
Stage 17	14033	14010	13988	13966	13943	13921	13899	13877
Stage 18	13854	13832	13810	13787	13765	13743	13720	13698
<u> </u>								
Stage 19	13676	13653	13631	13609	13586	13564	13542	13519
G: 20	12.405	12455	12452	12420	12400	12205	12272	12241
Stage 20	13497	13475	13452	13430	13408	13385	13363	13341
Stage 21	13318	13296	13274	13252	13229	13207	13185	13162
	12310	10270	1 102/1	10202	10227	10207	10100	-5102
Stage 22	13140	13118	13095	13073	13051	13028	13006	12984
Stage 23	12961	12939	12917	12894	12872	12850	12827	12805

Dominator 25 Federal Com #605H API# 30-025-44742

COG Operating LLC respectfully requests temporary abandonment of the Dominator 25 Federal Com #605H. Three additional wells will be drilled on the same pad as the Dominator 25 Federal Com #605H so it will need to have production tubing pulled and the wellhead reduced to ground level in order to safely execute the drilling and completion of the new wells on this pad. Temporary abandonment operations are expected to begin October 7th,2021. This well is expected to be put back on production in the fourth quarter of 2022.

- 1.) MIRU pulling unit, ND tree, NU BOP.
- 2.) POOH w/ production tubing.
- 3.) RIH w/ CIBP and set +/-75ft above top perforation at 12,730ft.
- 4.) Spot 25 sacks of Class H cement on top of CIBP.
- 5.) Tag top of cement and displace wellbore with corrosion inhibited fluid.
- 6.) Test casing to 500psi for 30min and document with test pressure recording device.
- 7.) ND BOP and install TA cap.
- 8.) RDMO.

See attachments for current wellbore diagram, proposed wellbore diagram, and perforation depths.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 50136

CONDITIONS

Operator:	OGRID:
COG OPERATING LLC	229137
600 W Illinois Ave	Action Number:
Midland, TX 79701	50136
	Action Type:
	[C-103] NOI Temporary Abandonment (C-103I)

CONDITIONS

Created By	Condition	Condition Date
kfortner	Requires BLM approval	10/8/2021