

U.S. Department of the Interior BUREAU OF LAND MANAGEMENT

Sundry Print Report

Well Name: LINDRITH UNIT Well Location: T24N / R3W / SEC 21 / County or Parish/State: RIO

SWNW / 36.298599 / -107.168223 ARRIBA / NM

Well Number: 29 Type of Well: CONVENTIONAL GAS Allottee or Tribe Name:

ELL

Lease Number: NMSF078913 Unit or CA Name: LINDRITH UNIT - PC Unit or CA Number:

NMNM78399A

**US Well Number:** 300390538800S1 **Well Status:** Producing Gas Well **Operator:** MORNINGSTAR

PARTNERS LP

## **Notice of Intent**

**Sundry ID: 2667594** 

Type of Submission: Notice of Intent

Type of Action: Plug and Abandonment

Date proposed operation will begin: 05/02/2022

**Procedure Description:** MorningStar requests approval to plug and abandon the Lindrith Unit #29. Attached are the Proposed Procedure, WBDs, and Reclamation Plan.

# **Surface Disturbance**

Is any additional surface disturbance proposed?: No

## **NOI Attachments**

### **Procedure Description**

 $PA\_Procedure \_\_WBDs \_\_Reclamation\_Plan\_Lindrith\_Unit\_29\_20220419095333.pdf$ 

Page 1 of 2

County or Parish/State: RIO eived by OCD: 4/21/2022 9:47:55 AM Well Name: LINDRITH UNIT Well Location: T24N / R3W / SEC 21 /

SWNW / 36.298599 / -107.168223

Well Number: 29 Type of Well: CONVENTIONAL GAS Allottee or Tribe Name:

WELL

Unit or CA Name: LINDRITH UNIT - PC **Unit or CA Number:** 

NMNM78399A

ARRIBA / NM

**US Well Number: 300390538800S1** Well Status: Producing Gas Well **Operator: MORNINGSTAR** 

PARTNERS LP

# **Conditions of Approval**

#### **Additional Reviews**

General\_Requirement\_PxA\_20220420154957.pdf

2667594\_NOIA\_29\_3003905388\_KR\_04202022\_20220420154940.pdf

24N03W21EKpc\_Lindrith\_Unit\_29\_20220420104704.pdf

# **Operator Certification**

Lease Number: NMSF078913

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a submission of Form 3160-5 or a Sundry Notice.

**Operator Electronic Signature: CONNIE BLAYLOCK** Signed on: APR 19, 2022 09:54 AM

Name: MORNINGSTAR PARTNERS LP

Title: Regulatory Technician Street Address: 400 W 7th St.

City: Forth Worth State: TX

Phone: (817) 334-7882

Email address: CBLAYLOCK@MSPARTNERS.COM

## **Field Representative**

Representative Name: Amy Byars

**Street Address:** 

City: State: Zip:

Phone:

Email address: abyars@mspartners.com

## **BLM Point of Contact**

Signature: Kenneth Rennick

**BLM POC Name: KENNETH G RENNICK BLM POC Title:** Petroleum Engineer

**BLM POC Phone:** 5055647742 BLM POC Email Address: krennick@blm.gov

**Disposition:** Approved **Disposition Date:** 04/20/2022

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

AFMSS 2 Sundry ID 2667594

Attachment to notice of Intention to Abandon

Well: Lindrith Unit 29

### **CONDITIONS OF APPROVAL**

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence at (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
  - a. Bring the top of Plug #1 up to 2901' to cover BLM pick for the Fruitland formation top (2951').
  - b. After running the CBL, send data to the BLM (krennick@blm.gov). Plugs may be modified based on the results.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.

K. Rennick 4/20/2022

## BLM FLUID MINERALS P&A Geologic Report

**Date Completed:** 04/20/2022

Well No. Lindrith Unit #29 (AP	Location	1650	FNL	&	800	FWL	
Lease No. NMSF-078913		Sec. 21	T24N			R03W	
Operator MorningStar Operating, LLC		County	Rio Arriba		State	New Mexico	
Total Depth 3187'	PBTD 3151'	Formation	Pictured	Cliffs			
Elevation (GL) 7004'	Elevation (KF	Elevation (KB) 7014'					

<b>Geologic Formations</b>	Est. Top	Est. Bottom	Log Top	Log Bottom	Remarks
San Jose Fm			Surface	1553	Surface/freshwater sands
Nacimiento Fm			1553	2633	Possible freshwater sands
Ojo Alamo Ss			2633	2799	Aquifer (possible freshwater)
Kirtland Shale			2799	2951	
Fruitland Fm			2951	3094	Coal/Gas/Possible water
Pictured Cliffs Ss			3094	PBTD	Gas
Lewis Shale					
Chacra					
Cliff House Ss					
Menefee Fm					
Point Lookout Ss					
Mancos Shale					
Gallup					
Greenhorn					
Graneros Shale					
Dakota Ss					

#### Remarks:

#### P & A

-  $\,$  BLM picks for the Fruitland and Kirtland formation tops vary from Operator.

Bring the top of Plug #1 up to 2901' to cover BLM pick for the Fruitland formation top (2951').

- The plugs proposed in the P&A procedure, with changes recommended above, will adequately protect any freshwater sands in this well bore.
- Pictured Cliffs perfs 3104' 3146'.

Reference Well:
1) Formation Tops
Same

**Prepared by:** Chris Wenman

# GENERAL REQUIREMENTS FOR PERMANENT ABANDONMENT OF WELLS ON FEDERAL AND INDIAN LEASES FARMINGTON FIELD OFFICE

- 1.0 The approved plugging plans may contain variances from the following <u>minimum general</u> requirements.
  - 1.1 Modification of the approved plugging procedure is allowed only with the prior approval of the Authorized Officer, Farmington Field Office.
  - 1.2 Requirements may be added to address specific well conditions.
- 2.0 Materials used must be accurately measured. (densometer/scales)
- 3.0 A tank or lined pit must be used for containment of any fluids from the wellbore during plugging operations and all pits are to be fenced with woven wire. These pits will be fenced on three sides and once the rig leaves location, the fourth side will be fenced.
  - 3.1 Pits are not to be used for disposal of any hydrocarbons. If hydrocarbons are present in the pit, the fluids must be removed prior to filling in.
- 4.0 All cement plugs are to be placed through a work string. Cement may be bull-headed down the casing with prior approval. Cement caps on top of bridge plugs or cement retainers may be placed by dump bailer.
  - 4.1 The cement shall be as specified in the approved plugging plan.
  - 4.2 All cement plugs placed inside casing shall have sufficient volume to fill a minimum of 100' of the casing, or annular void(s) between casings, plus an excess volume sufficient to provide for 50 linear feet of fill above the plug.
  - 4.3 Surface plugs may be no less than 50' in length.
  - 4.4 All cement plugs placed to fill annular void(s) between casing and the formation shall be of sufficient volume to fill a minimum of 100' of the annular space plus 100% excess, calculated using the bit size, or 100' of annular capacity, determined from a caliper log, plus an excess volume sufficient to provide for 50 linear feet of fill above the plug.
  - 4.5 All cement plugs placed to fill an open hole shall be of sufficient volume to fill a minimum of 100' of hole, as calculated from a caliper log, plus an excess volume sufficient to provide for 50 linear feet of fill above the plug. In the absence of a caliper log, an excess of 100% shall be required.
  - 4.6 A cement bond log or other accepted cement evaluation tool is required to be run if one had not been previously ran or cement did not circulate to surface during the original casing cementing job or subsequent cementing jobs.

2

- 5.1 The top of any cement plug verified by tagging must be at or above the depth specified in the approved plan, without regard to any excess.
- 5.2 Testing will not be required for any cement plug that is mechanically contained by use of a bridge plug and/or cement retainer, if casing integrity has been established.
- 5.3 Any cement plug which is the only isolating medium, for a fresh water interval or a zone containing a prospectively valuable deposit of minerals, shall be tested by tagging.
- 5.4 If perforations are required below the surface casing shoe, a 30 minute minimum wait time will be required to determine if gas and/or water flows are present. If flow is present, the well will be shut-in for a minimum of one hour and the pressure recorded. Short or long term venting may be necessary to evacuate trapped gas. If only a water flow occurs with no associated gas, shut well in and record the pressures. Contact the Engineer as it may be necessary to change the cement weight and additives.
- 6.0 Before setting any cement plugs the hole needs to be rolled. All wells are to be controlled by means of a fluid that is to be of a weight and consistency necessary to stabilize the wellbore. This fluid shall be left in place as filler between all plugs.
  - 6.1 Drilling mud may be used as the wellbore fluid in open hole plugging operations.
  - 6.2 The wellbore fluid used in cased holes shall be of sufficient weight to balance known pore pressures in all exposed formations.
- 7.0 A blowout preventer and related equipment (BOPE) shall be installed and tested prior to working in a wellbore with any exposed zone(s); (1) that are over pressured, (2) where the pressures are unknown, or (3) known to contain  $H_2S$ .
- 8.0 Within 30 days after plugging work is completed, file a Sundry Notice, Subsequent Report of Abandonment (Form 3160-5), five copies, with the Field Manager, Bureau of Land Management, 6251 College Blvd., Suite A, Farmington, NM 87402. The report should show the manner in which the plugging work was carried out, the extent, by depth(s), of cement plugs placed, and the size and location, by depth(s), of casing left in the well. Show date well was plugged.
- 9.0 All permanently abandoned wells are to be marked with a permanent monument as specified in 43 CFR 3162.6(d). Unless otherwise approved.
- 10.0 If this well is located in a Specially Designated Area (SDA), compliance with the appropriate seasonal closure requirements will be necessary.

All of the above are minimum requirements. Failure to comply with the above conditions of approval may result in an assessment for noncompliance and/or a Shut-in Order being issued pursuant to 43 CFR 3163.1. You are further advised that any instructions, orders or decisions issued by the Bureau of Land Management are subject to administrative review pursuant to 43 CFR 3165.3 and appeal pursuant to 43 CFR 3165.4 and 43 CFR 4.700.

(October 2012 Revision)

#### PROPOSED P&A PROCEDURE

#### Lindrith 29

- 1. MIRU.
- 2. POOH w/ tubing.
- 3. Run a casing scraper to 3,085'
- 4. Set CICR @ 3,060'
- 5. Spot 25 sx Class B Cement on top of plug. (est'd TOC @ 2,851'). WOC, test casing integrity.
- 6. RU and run CBL.
- 7. Circulate hole with mud laden fluid.
- 8. Spot cement plug from 2,849' 2,533' with 37 sx Class B cement.
- 10. Perforate at 1603', set CICR at 1,553', spot inside/outside balanced cement plug from 1,603' 1,503' with a total of 55 sx Class B cement (which includes 100% excess).
- 11. Perforate at 192', circulate balanced cement plug from 192' to surface with 60 sx Class B cement. Ensure cement at surface on all strings of casing, top off as needed.
- 12. Cut off wellhead below surface casing flange. Install P&A marker.

# MorningStar Operating, **LLC**

#### **Current WBD**

# **Lindrith Unit 29** Rio Arriba County, NM

All depths include KB TD - 3,187'; PBTD - 3,151'

Surface Csg: 4 jts 8-5/8" 32# J-55


Setting Depth: 142'

Cement 60 sx Cement **Cmt circulated** 

Production Csg: 77 jts 5-1/2" 15.5# J-55

Setting Depth: 3,181'

Cement: 72 sx cement **TOC** unknown



Picture Cliffs Perfs (1959):

3,104' - 3,114' (4spf) 3,122' - 3,130' (4spf) 3,137' - 3,146' (4spf)

1-1/4" Tubing to 3,134' - 97 jts

PBTD: 3,151'

Prepared by: J. Marschall

Updated by: JRyza Date: 04/19/2022

KB = 10' GL = 7,004'API# 30-039-05388

Spud Date: 04/04/1959 Date Completed: 04/29/1959

> Nacimiento - 1,553' Ojo Alamo - 2,633' Kirtland - 2,799' Fruitland - 2,951'

Picture Cliffs - 3,094'

KB = 10'GL = 7,004'

# MorningStar Operating, **LLC**

## **Lindrith Unit 29** Rio Arriba County, NM

All depths include KB TD - 3,187'; PBTD - 3,151'

Surface Csg: 4 jts 8-5/8" 32# J-55

Setting Depth: 142'

Cement 60 sx Cement **Cmt circulated** 

Production Csg: 77 jts 5-1/2" 15.5# J-55


Setting Depth: 3,181'

Cement: 72 sx cement **TOC** unknown

#### Picture Cliffs Perfs (1959):

3,104' - 3,114' (4spf) 3,122' - 3,130' (4spf) 3,137' - 3,146' (4spf)

## **Proposed P&A WBD**



60 sx cement 192' - surface

Date Completed: 04/29/1959 Nacimiento – 1,553' Ojo Alamo - 2,633' Kirtland - 2,799' Fruitland - 2,951'

Picture Cliffs - 3,094'

Spud Date: 04/04/1959

Prepared by: J. Marschall

Updated by: JRyza


Date: 04/19/2022

API# 30-039-05388

PLUG 3 (inside/outside) Perf 5 1/2" casing at 1,603', set CICR @ 1,553' Outside 31 sx cmt, 1,503' - 1,603' (100% excess) Inside 24 sx cmt, 1,503' - 1,603' (100% excess)

PLUG 2 (Kirtland, Ojo) 37 sx cement 2,533' - 2,849'

PLUG 1 25 sx cement 2,851' - 3,060' CICR set @ 3,060'



# **P&A RECLAMATION PLAN**

Lindrith Unit #29

API: 30-039-05388 Unit: E Sec: 21 T24N R3W 36.29863°, -107.1676°

## **General Notes:**

- MorningStar Operating LLC will comply with the requirements in accordance with the approved Sundry Notice associated with this submittal.
- Surface equipment and trash, if any, will be removed.
- Underground production piping on the well site will be removed or abandoned-inplace.
- The P&A marker will be permanent and comply with NMOCD regulations.

## **Well Site Reclamation:**

• Per discussions with surface owner's representatives, location will be left in current condition. Any areas disturbed due to the P&A process will be seeded.

## **Access Road Reclamation:**

• Location is directly adjacent to another operator's well location. No access road reclamation is necessary.

#### **Revegetation:**

The planned initial seed mixture and application rates for the <u>Sagebrush/Grass Community</u> identified during the site visit will be as follows. The seed application rates may be adjusted according to various methods of application.

Species	Select		Lbs/acre (PLS)*
Fourwing Saltbush	X	Pick two out	2.0
Antelope Bitterbrush		of three	2.0
Winterfat	X	or timee	2.0
Indian Ricegrass	X		4.0
Blue Grama	X	Diale there are	2.0
Galleta		Pick three out of five	3.0
Sand Dropseed			0.5
Western Wheatgrass	X		4.0
Bottle Brush Squaretail	X	Pick one out	3.0
Siberian Wheatgrass		of two	3.0
Small Burnet	ıll Burnet		2.0
Rocky Mountain Bee Plant		Pick one out of three	0.25
Blue Flax	X	oi inree	0.25

|--|

<sup>\*</sup> Minimum if drill seeded. Double this rate if broadcast or hydroseeded.

- Seeding will be broadcast so the rates will be doubled and a rake or harrow will be used to incorporate the seed into the soil.
- Seed mixtures will be certified weed-free and the seeding records (bag labels) or other official documentation will be available to the BLM prior to seeding, upon request.
- Seeding will occur as soon as reasonably possible following completion of earthwork activities and timed for successful germination.
- The need for soil amendments is not expected or proposed.

#### **Monitoring:**

- MorningStar Operating LLC will submit a Sundry Notice informing the BLM the seeding is completed.
- After completion of the reclamation, MorningStar Operating LLC will meet with the surface owner or representative to acquire a letter of concurrence stating that they are satisfied with the reclamation. This information will be submitted with a Sundry Notice (FAN) requesting approval of the reclaimed location.

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 100530

#### **CONDITIONS**

Operator:	OGRID:
MorningStar Operating LLC	330132
400 W 7th St	Action Number:
Fort Worth, TX 76102	100530
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

#### CONDITIONS

Created By	Condition	Condition Date
kpickford	CBL required	4/25/2022
kpickford	Notify NMOCD 24 Hours Prior to beginning operations	4/25/2022
kpickford	Adhere to BLM approved COAs and plugs. See GEO report.	4/25/2022