Sundry Print Report

U.S. Department of the Interior BUREAU OF LAND MANAGEMENT

Well Number: 19

Well Name: RDX FEDERAL 17 Well Location: T26S / R30E / SEC 17 / County or Parish/State: EDDY /

SWSW /

Type of Well: OIL WELL Allottee or Tribe Name:

Lease Number: NMNM20965 Unit or CA Name: Unit or CA Number:

US Well Number: 3001541249 Well Status: Temporarily Abandoned Operator: WPX ENERGY

PERMIAN LLC

Accepted for record – NMOCD gc 6/7/2022

Notice of Intent

Sundry ID: 2674247

Type of Submission: Notice of Intent

Type of Action: Plug and Abandonment

Date Sundry Submitted: 05/31/2022 Time Sundry Submitted: 02:51

Date proposed operation will begin: 06/07/2022

Procedure Description: Please see the attached proposed P&A procedure and the attached wellbore diagrams.

Surface Disturbance

Is any additional surface disturbance proposed?: No

NOI Attachments

Procedure Description

RDX_FEDERAL_17_19_NOI_P_A_SIGNED_CURRENT___PROPOSED_WELLBORE_20220531145052.pdf

Page 1 of 2

eceived by OCD: 6/6/2022 12:45:18 PM Well Name: RDX FEDERAL 17

Well Location: T26S / R30E / SEC 17 /

SWSW /

County or Parish/State: EDD 200

Zip:

Well Number: 19

Type of Well: OIL WELL

Allottee or Tribe Name:

Lease Number: NMNM20965

Unit or CA Name:

Unit or CA Number:

US Well Number: 3001541249

Well Status: Temporarily Abandoned

Operator: WPX ENERGY

PERMIAN LLC

Conditions of Approval

Specialist Review

RDX_FEDERAL_17_19___2674247___COA_AND_PROCEDURE_20220602162607.pdf

Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: LAUREN WATSON Signed on: MAY 31, 2022 02:51 PM

Name: WPX ENERGY PERMIAN LLC

Title: Regulatory Compliance Professional Street Address: 333 W. SHERIDAN AVE.

City: OKLAHOMA CITY State: OK

Phone: (405) 552-3379

Email address: LAUREN.WATSON@DVN.COM

Field

Representative Name:

Street Address:

City: State:

Phone:

Email address:

BLM Point of Contact

Signature: Keith Immatty

BLM POC Name: KEITH P IMMATTY BLM POC Title: ENGINEER

BLM POC Phone: 5759884722 BLM POC Email Address: KIMMATTY@BLM.GOV

Disposition: Approved Disposition Date: 06/02/2022

Form 3160-5 (August 2007)

UNITED STATES


FORM APPROVED OMB No. 1004-0137


DEI	PARIMENT OF THE	INTERIOR		Ez	cpires: July 31, 2010	
BUR	5. Lease Serial No. NMNM20965	-				
					6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE – Other instructions on page 2.			7. If Unit of CA/Agree	ement, Name and/or No.		
1. Type of Well						
✓ Oil Well Gas V	Vell Other			8. Well Name and No. RDX FEDERAL 17	8. Well Name and No. RDX FEDERAL 17 19	
2. Name of Operator WPX ENERGY PERMIAN, LLC				9. API Well No. 30-015-41249	9. API Well No. 30-015-41249	
3a. Address 333 West Sheridan Avenue, Oklahoma City, Ok	< 73102-5015	3b. Phone No. (include 405-228-3047	e area code)		10. Field and Pool or Exploratory Area BRUSHY DRAW-DELAWARE EAST	
4. Location of Well (Footage, Sec., T., 660 FSL 880 FWL SEC17-T26S-R30E	R.,M., or Survey Description)		11. Country or Parish, EDDY, NM	11. Country or Parish, State EDDY, NM	
12. CHEC	CK THE APPROPRIATE BO	OX(ES) TO INDICATE 1	NATURE OF NOT	TICE, REPORT OR OTH	ER DATA	
TYPE OF SUBMISSION			TYPE OF AC	CTION		
✓ Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat	=	oduction (Start/Resume)	Water Shut-Off Well Integrity	
Subsequent Report	Casing Repair Change Plans	✓ New Construc✓ Plug and Aban	=	complete mporarily Abandon	Other	
Final Abandonment Notice	Convert to Injection	Plug Back	_	ater Disposal		
 13. Describe Proposed or Completed Of the proposal is to deepen direction Attach the Bond under which the vision of the involved testing has been completed. Final determined that the site is ready for the MIRU P&A unit. 2. PILL Top @ 40001. Gira 10th cells of the complete of the proposal testing that the site is ready for the proposal testing testing the proposal tes	ally or recomplete horizontal work will be performed or proved operations. If the operations has also must Abandonment Notices must or final inspection.)	ly, give subsurface location ovide the Bond No. on fi on results in a multiple c	tions and measured alle with BLM/BIA. completion or recon	and true vertical depths of Required subsequent rep appletion in a new interval	of all pertinent markers and zone forts must be filed within 30 day a Form 3160-4 must be filed of	es. ys once
 RIH Tag @ 4900'. Circ 10# salt g Spot 25 sx Cl C from 4900'-4675 Spot 25 sx Cl C from 3580'-3355 Perf @ 1840' Pump 50 sx Cl C from 1840'-169 Perf @ 1030' Pump 305 sx Cl C from 1030' to 9 Cut WH off 3' BGL, Set dry hole in 	'. (Perfs @ 5114') '. WOC & tag (T. Delawar 0'. WOC & tag. (T. Salt @ surface.		484'; B. Salt @ 34	466')		
BLM Note: Plugs OK as pro	posed. Leak test: 500p	osi, 30mins				
		KEIT	TH IMMA		by KEITH IMMATTY 2 16:20:00 -06'00'	
14. I hereby certify that the foregoing is to Name (Printed/Typed) KARSAN SPRAGUE	true and correct.	Title F	Production Engine	eer		
Signature Karsan S	Sprague	Date	05/26/2022			
	THIS SPACE	FOR FEDERAL (OR STATE O	FFICE USE		

Approved by Title Date Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would Office entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)





Sundry ID 2674247

Surface Plug	Sundry ID	2674247					
Shoe Plug	Plug Type	Тор	Bottom	Length	Tag	Sacks	Notes
Top of Salt @ 1767	Surface Plug	0.00	100.00	100.00	Tag/Verify	305.00	Same as Shoe plug
Top of Salt @ 1767	Shoe Plug	920.20	1030.00	109.80	Tag/Verify	305.00	Perf and sgz
Shoe Plug 3399.16 3534.00 134.84 Tag/Verify 25.00 Same as Delaware							
Base of Salt @ 3466 3381.34 3516.00 134.66 Tag/Verify If solid base no need to Tag (CIBP present and/or Mechanic all Integrity Test), If Perf & Sqz then Tag, Leak Test all CIBP if no Open Perforatio Delaware @ 3530 3444.70 3580.00 135.30 ns 25.00 If solid base no need to Tag (CIBP present and/or Mechanic all Integrity Test), If Perf & Sqz then Tag, Leak Test all CIBP present and/or Mechanic all Integrity Test), If Perf & Sqz then Tag, Leak Test all CIBP if no Open Perforation all Integrity Test), If Perf & Sqz then Tag, Leak Test all CIBP if no Open	1 op 01 out @ 1101	1000.00	1017.00	117.07	rag, voiny	00.00	1 on and oq2
If solid base no need to Tag (CIBP present and/or Mechanic al Integrity Test), If Perf & Sqz then Tag, CiBP froo Open Perforatio base no need to Tag (CIBP froo Open Perforatio base no need to Tag (CIBP present and/or Mechanic al Integrity Test), If Perf & Sqz then Tag (CIBP present and/or Mechanic al Integrity Test), If Perf & Sqz then Tag, Leak Test all CIBP if no Open	Shoe Plug	3399.16	3534.00	134.84	Tag/Verify	25.00	Same as Delaware
base no need to Tag (CIBP present and/or Mechanic al Integrity Test), If Perf & Sqz then Tag, Leak Test all CIBP if no Open Perforatio Perforatio 135.30 ns 25.00 Delaware @ 3530 3444.70 3580.00 135.30 ns 25.00 If solid base no need to Tag (CIBP present and/or Mechanic al Integrity Test), If Perf & Sqz then Tag, Leak Test all CIBP if no Open	Base of Salt @ 3466	3381.34	3516.00	134.66	Tag/Verify	25.00	Same as Delaware
base no need to Tag (CIBP present and/or Mechanic al Integrity Test), If Perf & Sqz then Tag, Leak Test all CIBP if no Open	Delaware @ 3530	3444.70	3580.00		base no need to Tag (CIBP present and/or Mechanic al Integrity Test), If Perf & Sqz then Tag, Leak Test all CIBP if no Open Perforatio		
CIBP Plug 4865.00 4900.00 35.00 ns 25.00 500psi, 30mins	CIBP Plug	4865.00	4900 00		base no need to Tag (CIBP present and/or Mechanic al Integrity Test), If Perf & Sqz then Tag, Leak Test all CIBP if no Open Perforatio		Pressure test

No more than 2000' is to be allowed between plugs in open hole, and no more than 3000' between plugs in cased hole.

Class H >7500'

Class C<7500'

Fluid used to mix the cement in R111P shall be saturated with the salts common to the section penetrated, and in suitable proportions, but not more than 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible.

Critical, High Cave Karst: Cave Karst depth to surface

R111P: Solid plug in all annuli - 50' from bottom of salt to surface.

Class C: 1.32 ft^3/sx Class H: 1.06 ft^3/sx

Onshore Order 2.III.G Drilling Abandonment Requirements: "All formations bearing usable-quality water, oil, gas, or geothermal resources, and/or a prospectively valuable deposit of minerals shall be protected.

Shoe @	980.00		
Shoe @	3484.00		
Shoe @	7405.00		
3110e @	7 703.00		
		Perforations	
Perforatons Top @	5114.00	Bottom @	7305.00
DV Tool @	5499.00	CIBP @	4900.00

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 113980

CONDITIONS

Operator:	OGRID:
WPX Energy Permian, LLC	246289
Devon Energy - Regulatory	Action Number:
Oklahoma City, OK 73102	113980
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By	Condition	Condition Date
gcordero	None	6/7/2022