Office <u>District I – (575) 393-6161</u> Energy, Minerals and Natur	kico		Form C-103			
1625 N. French Dr., Hobbs, NM 88240	al Resources	Revised July 18, 2013 WELL API NO.				
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CONSERVATION		30-015-23961				
<u>District III</u> – (505) 334-6178 1220 South St. Fran	5 In	5. Indicate Type of Lease STATE STATE				
1000 Rio Brazos Rd., Aztec, NM 87410         Santa Fe, NM 87           District IV – (505) 476-3460         Santa Fe, NM 87	505 6. St	6. State Oil & Gas Lease No.				
1220 S. St. Francis Dr., Santa Fe, NM 87505	••••••	LG-1198				
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name				
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLU DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FO	2 SUCH	Anderson CS State 8. Well Number				
PROPOSALS.)         1. Type of Well: Oil Well         Gas Well         Other         P&A	2					
2. Name of Operator	9. O	9. OGRID Number				
EOG Resources, Inc.	7377	ool name or Wildcat				
<ol> <li>Address of Operator</li> <li>104 South Fourth Street, Artesia, NM 88210</li> </ol>		sco Draw; Permo Pe	enn			
4. Well Location	I					
Unit Letter <u>J</u> : <u>1650</u> feet from the <u>South</u>	line and 1980	feet from the	<u>East</u> line			
Section 14 Township 18S Ran		M Eddy	County			
11. Elevation (Show whether DR, 3679')	· · · · · · · · · · · · · · · · · · ·					
12. Check Appropriate Box to Indicate Na	ture of Notice, Repor	t or Other Data				
NOTICE OF INTENTION TO:	SUBSEQU	JENT REPOR	Г ОЕ·			
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK					
TEMPORARILY ABANDON	COMMENCE DRILLING		DA 🛛			
PULL OR ALTER CASING MULTIPLE COMPL	CASING/CEMENT JOB					
CLOSED-LOOP SYSTEM	OTHER:					
13. Describe proposed or completed operations. (Clearly state all p	ertinent details, and give p					
of starting any proposed work). SEE RULE 19.15.7.14 NMAC	For Multiple Completio	ns: Attach wellbor	e diagram of			
proposed completion or recompletion.						
2/1(2) MIDIE 1NILDOD DOOLE '4 1 4 (220) T 1000 1	1 1 1 1 1 1	1 1				
3/16/22 – MIRU and NU BOP. POOH with packer at 6339'. Tagged RBP and 3/22/22 – RIH to 8175'. Cement to be pumped on top of 2 <sup>nd</sup> existing packer at			and POOH.			
$3/22/22 - RIH$ to 8175'. Cement to be pumped on top of $2^{nd}$ existing packer at $5/5/22$ - MIRU and NU BOP to plug the well. Spotted a 25 sx Class "H" ceme	8175'. Rigged down and NI nt plug from 8175'-7750', ta	DBOP. gged. Perforated at 70	067'.			
3/22/22 – RIH to 8175'. Cement to be pumped on top of 2 <sup>nd</sup> existing packer at 5/5/22 - MIRU and NU BOP to plug the well. Spotted a 25 sx Class "H" ceme 5/6/22 – Tested perf to 500 psi for 10 min, good. Spotted a 30 sx Class "C" ce	8175'. Rigged down and NI nt plug from 8175'-7750', ta nent plug from 7280'-6905'	) BOP. gged. Perforated at 7( , tagged. Set a CIBP a	067'. t 6337'.			
3/22/22 – RIH to 8175'. Cement to be pumped on top of 2 <sup>nd</sup> existing packer at 5/5/22 - MIRU and NU BOP to plug the well. Spotted a 25 sx Class "H" ceme 5/6/22 – Tested perf to 500 psi for 10 min, good. Spotted a 30 sx Class "C" ce 5/9/22 – Spotted 30 sx Class "C" cement on top of CIBP to 5905', tagged. Set 4570', tagged.	8175'. Rigged down and NI nt plug from 8175'-7750', ta nent plug from 7280'-6905' a CIBP at 4999'. Spotted 30	DBOP. gged. Perforated at 7( , tagged. Set a CIBP a sx Class "C" cement	067'. t 6337'. on top of CIBP at			
3/22/22 – RIH to 8175'. Cement to be pumped on top of 2 <sup>nd</sup> existing packer at 5/5/22 - MIRU and NU BOP to plug the well. Spotted a 25 sx Class "H" ceme 5/6/22 – Tested perf to 500 psi for 10 min, good. Spotted a 30 sx Class "C" ce 5/9/22 – Spotted 30 sx Class "C" cement on top of CIBP to 5905', tagged. Set 4570', tagged. 5/10/22 – Perforated at 3966'. Established circulation up 8-5/8" casing. Squee	8175'. Rigged down and NI nt plug from 8175'-7750', ta nent plug from 7280'-6905' a CIBP at 4999'. Spotted 30 zed with 35 sx Class "C" cer	D BOP. gged. Perforated at 7( , tagged. Set a CIBP a sx Class "C" cement nent from 3966'-3818	067'. t 6337'. on top of CIBP at			
<ul> <li>3/22/22 – RIH to 8175'. Cement to be pumped on top of 2<sup>nd</sup> existing packer at 5/5/22 - MIRU and NU BOP to plug the well. Spotted a 25 sx Class "H" ceme 5/6/22 – Tested perf to 500 psi for 10 min, good. Spotted a 30 sx Class "C" ce 5/9/22 – Spotted 30 sx Class "C" cement on top of CIBP to 5905', tagged. Set 4570', tagged.</li> <li>5/10/22 – Perforated at 3966'. Established circulation up 8-5/8" casing. Squee at 1093'. Established circulation up 8-5/8" casing. Squeezed with 25 sx Class</li> </ul>	8175'. Rigged down and NI nt plug from 8175'-7750', ta nent plug from 7280'-6905' a CIBP at 4999'. Spotted 30 zed with 35 sx Class "C" cer 'C" cement from 1093'-993'	D BOP. gged. Perforated at 7( , tagged. Set a CIBP a sx Class "C" cement ment from 3966'-3818 , tagged.	067'. t 6337'. on top of CIBP at ', tagged. Perforated			
<ul> <li>3/22/22 – RIH to 8175'. Cement to be pumped on top of 2<sup>nd</sup> existing packer at 5/5/22 - MIRU and NU BOP to plug the well. Spotted a 25 sx Class "H" ceme 5/6/22 – Tested perf to 500 psi for 10 min, good. Spotted a 30 sx Class "C" ce 5/9/22 – Spotted 30 sx Class "C" cement on top of CIBP to 5905', tagged. Set 4570', tagged.</li> <li>5/10/22 – Perforated at 3966'. Established circulation up 8-5/8" casing. Squee at 1093'. Established circulation up 8-5/8" casing. Squeezed with 25 sx Class "C" cement from 897'-722', tagged. This Spotted 14 sx Class "C" cement from 608'-396' calc TOC. Squeezed with 100</li> </ul>	8175'. Rigged down and NI nt plug from 8175'-7750', ta nent plug from 7280'-6905' a CIBP at 4999'. Spotted 30 zed with 35 sx Class "C" cer 'C" cement from 1093'-993' s plug will cover hole in casi	D BOP. gged. Perforated at 7( , tagged. Set a CIBP a sx Class "C" cement nent from 3966'-3818 , tagged. ng from 865'-897'. Pe	067'. t 6337'. on top of CIBP at ', tagged. Perforated erforated at 396'.			
<ul> <li>3/22/22 – RIH to 8175'. Cement to be pumped on top of 2<sup>nd</sup> existing packer at 5/5/22 - MIRU and NU BOP to plug the well. Spotted a 25 sx Class "H" ceme 5/6/22 – Tested perf to 500 psi for 10 min, good. Spotted a 30 sx Class "C" ce 5/9/22 – Spotted 30 sx Class "C" cement on top of CIBP to 5905', tagged. Set 4570', tagged.</li> <li>5/10/22 – Perforated at 3966'. Established circulation up 8-5/8" casing. Squee at 1093'. Established circulation up 8-5/8" casing. Squeezed with 25 sx Class "C" cement from 897'-722', tagged. This</li> </ul>	8175'. Rigged down and NI nt plug from 8175'-7750', ta nent plug from 7280'-6905' a CIBP at 4999'. Spotted 30 zed with 35 sx Class "C" cer 'C" cement from 1093'-993' s plug will cover hole in casi	D BOP. gged. Perforated at 7( , tagged. Set a CIBP a sx Class "C" cement nent from 3966'-3818 , tagged. ng from 865'-897'. Pe	067'. t 6337'. on top of CIBP at ', tagged. Perforated erforated at 396'.			
<ul> <li>3/22/22 – RIH to 8175'. Cement to be pumped on top of 2<sup>nd</sup> existing packer at 5/5/22 - MIRU and NU BOP to plug the well. Spotted a 25 sx Class "H" ceme 5/6/22 – Tested perf to 500 psi for 10 min, good. Spotted a 30 sx Class "C" ce 5/9/22 – Spotted 30 sx Class "C" cement on top of CIBP to 5905', tagged. Set 4570', tagged.</li> <li>5/10/22 – Perforated at 3966'. Established circulation up 8-5/8" casing. Squee at 1093'. Established circulation up 8-5/8" casing. Squeezed with 25 sx Class "C" cement from 897'-722', tagged. This Spotted 14 sx Class "C" cement from 608'-396' calc TOC. Squeezed with 100</li> </ul>	8175'. Rigged down and NI nt plug from 8175'-7750', ta nent plug from 7280'-6905' a CIBP at 4999'. Spotted 30 zed with 35 sx Class "C" cer 'C" cement from 1093'-993' s plug will cover hole in casi sx Class "C" cement down	D BOP. gged. Perforated at 7( , tagged. Set a CIBP a sx Class "C" cement ment from 3966'-3818 , tagged. ng from 865'-897'. Pe 4-1/2" casing and up 3	067'. t 6337'. on top of CIBP at ', tagged. Perforated erforated at 396'. 3-5/8" casing from			
3/22/22 – RIH to 8175'. Cement to be pumped on top of 2 <sup>nd</sup> existing packer at 5/5/22 - MIRU and NU BOP to plug the well. Spotted a 25 sx Class "H" ceme 5/6/22 – Tested perf to 500 psi for 10 min, good. Spotted a 30 sx Class "C" ce 5/9/22 – Spotted 30 sx Class "C" cement on top of CIBP to 5905', tagged. Set 4570', tagged. 5/10/22 – Perforated at 3966'. Established circulation up 8-5/8" casing. Squee at 1093'. Established circulation up 8-5/8" casing. Squeezed with 25 sx Class "5/11/22 – Squeezed with 25 sx Class "C" cement from 897'-722', tagged. This Spotted 14 sx Class "C" cement from 608'-396' calc TOC. Squeezed with 100 396' and circulated up to surface.	8175'. Rigged down and NI nt plug from 8175'-7750', ta nent plug from 7280'-6905' a CIBP at 4999'. Spotted 30 zed with 35 sx Class "C" cer 'C" cement from 1093'-993' s plug will cover hole in casi sx Class "C" cement down	D BOP. gged. Perforated at 7( , tagged. Set a CIBP a sx Class "C" cement nent from 3966'-3818 , tagged. ng from 865'-897'. Pe	067'. t 6337'. on top of CIBP at ', tagged. Perforated erforated at 396'. 3-5/8" casing from			
<ul> <li>3/22/22 – RIH to 8175'. Cement to be pumped on top of 2<sup>nd</sup> existing packer at 5/5/22 - MIRU and NU BOP to plug the well. Spotted a 25 sx Class "H" ceme 5/6/22 – Tested perf to 500 psi for 10 min, good. Spotted a 30 sx Class "C" ce 5/9/22 – Spotted 30 sx Class "C" cement on top of CIBP to 5905', tagged. Set 4570', tagged.</li> <li>5/10/22 – Perforated at 3966'. Established circulation up 8-5/8" casing. Squee at 1093'. Established circulation up 8-5/8" casing. Squee at 1093'. Established circulation up 8-5/8" casing. Squeezed with 25 sx Class "C" cement from 897'-722', tagged. This Spotted 14 sx Class "C" cement from 608'-396' calc TOC. Squeezed with 100 396' and circulated up to surface.</li> </ul>	8175'. Rigged down and NI nt plug from 8175'-7750', ta nent plug from 7280'-6905' a CIBP at 4999'. Spotted 30 zed with 35 sx Class "C" cer 'C" cement from 1093'-993' s plug will cover hole in casi sx Class "C" cement down	D BOP. gged. Perforated at 7( , tagged. Set a CIBP a sx Class "C" cement ment from 3966'-3818 , tagged. ng from 865'-897'. Pe 4-1/2" casing and up 3	067'. t 6337'. on top of CIBP at ', tagged. Perforated erforated at 396'. 3-5/8" casing from			
3/22/22 – RIH to 8175'. Cement to be pumped on top of 2 <sup>nd</sup> existing packer at 5/5/22 - MIRU and NU BOP to plug the well. Spotted a 25 sx Class "H" ceme 5/6/22 – Tested perf to 500 psi for 10 min, good. Spotted a 30 sx Class "C" ce 5/9/22 – Spotted 30 sx Class "C" cement on top of CIBP to 5905', tagged. Set 4570', tagged. 5/10/22 – Perforated at 3966'. Established circulation up 8-5/8" casing. Squee at 1093'. Established circulation up 8-5/8" casing. Squeezed with 25 sx Class "5/11/22 – Squeezed with 25 sx Class "C" cement from 897'-722', tagged. This Spotted 14 sx Class "C" cement from 608'-396' calc TOC. Squeezed with 100 396' and circulated up to surface.	8175'. Rigged down and NI nt plug from 8175'-7750', ta nent plug from 7280'-6905' a CIBP at 4999'. Spotted 30 zed with 35 sx Class "C" cer 'C" cement from 1093'-993' s plug will cover hole in casi sx Class "C" cement down	D BOP. gged. Perforated at 7( , tagged. Set a CIBP a sx Class "C" cement ment from 3966'-3818 , tagged. ng from 865'-897'. Pe 4-1/2" casing and up 3	067'. t 6337'. on top of CIBP at ', tagged. Perforated erforated at 396'. 8-5/8" casing from			
<ul> <li>3/22/22 – RIH to 8175'. Cement to be pumped on top of 2<sup>nd</sup> existing packer at 5/5/22 - MIRU and NU BOP to plug the well. Spotted a 25 sx Class "H" ceme 5/6/22 – Tested perf to 500 psi for 10 min, good. Spotted a 30 sx Class "C" ce 5/9/22 – Spotted 30 sx Class "C" cement on top of CIBP to 5905', tagged. Set 4570', tagged.</li> <li>5/10/22 – Perforated at 3966'. Established circulation up 8-5/8" casing. Squee at 1093'. Established circulation up 8-5/8" casing. Squee at 1093'. Established circulation up 8-5/8" casing. Squeezed with 25 sx Class "C" cement from 897'-722', tagged. This Spotted 14 sx Class "C" cement from 608'-396' calc TOC. Squeezed with 100 396' and circulated up to surface.</li> </ul>	8175'. Rigged down and NI nt plug from 8175'-7750', ta nent plug from 7280'-6905' a CIBP at 4999'. Spotted 30 zed with 35 sx Class "C" cer 'C" cement from 1093'-993' s plug will cover hole in casi sx Class "C" cement down	D BOP. gged. Perforated at 7( , tagged. Set a CIBP a sx Class "C" cement ment from 3966'-3818 , tagged. ng from 865'-897'. Pe 4-1/2" casing and up 3	067'. t 6337'. on top of CIBP at ', tagged. Perforated erforated at 396'. 3-5/8" casing from			
3/22/22 – RIH to 8175'. Cement to be pumped on top of 2 <sup>nd</sup> existing packer at 5/5/22 - MIRU and NU BOP to plug the well. Spotted a 25 sx Class "H" ceme 5/6/22 – Tested perf to 500 psi for 10 min, good. Spotted a 30 sx Class "C" ce 5/9/22 – Spotted 30 sx Class "C" cement on top of CIBP to 5905', tagged. Set 4570', tagged.         5/10/22 – Perforated at 3966'. Established circulation up 8-5/8" casing. Squee at 1093'. Established circulation up 8-5/8" casing. Squeezed with 25 sx Class "5/11/22 – Squeezed with 25 sx Class "C" cement from 897'-722', tagged. This Spotted 14 sx Class "C" cement from 608'-396' calc TOC. Squeezed with 100 396' and circulated up to surface.         Approved for plugging of well bore only. Liabili bond is retained pending Location cleanup & r C-103Q (Subsequent Report of Well Plugging) may be found at OCD Web Page, OCD Permitti www.emnrd.state.nm.us	8175'. Rigged down and NI nt plug from 8175'-7750', ta ment plug from 7280'-6905' a CIBP at 4999'. Spotted 30 zed with 35 sx Class "C" cerr 'C" cement from 1093'-993' s plug will cover hole in casi sx Class "C" cement down ty under secept of which ag @	D BOP. gged. Perforated at 7( , tagged. Set a CIBP a sx Class "C" cement nent from 3966'-3818 , tagged. ng from 865'-897'. Pe 4-1/2" casing and up 8 <u>CONTINUED ON N</u>	067'. t 6337'. on top of CIBP at ', tagged. Perforated erforated at 396'. 8-5/8" casing from			
3/22/22 – RIH to 8175'. Cement to be pumped on top of 2 <sup>nd</sup> existing packer at 5/5/22 - MIRU and NU BOP to plug the well. Spotted a 25 sx Class "H" ceme 5/6/22 – Tested perf to 500 psi for 10 min, good. Spotted a 30 sx Class "C" ce 5/9/22 – Spotted 30 sx Class "C" cement on top of CIBP to 5905', tagged. Set 4570', tagged.         5/10/22 – Perforated at 3966'. Established circulation up 8-5/8" casing. Squee at 1093'. Established circulation up 8-5/8" casing. Squeezed with 25 sx Class "C" cement from 897'-722', tagged. This Spotted 14 sx Class "C" cement from 608'-396' calc TOC. Squeezed with 100 396' and circulated up to surface.         Approved for plugging of well bore only. Liabil bond is retained pending Location cleanup & r C-103Q (Subsequent Report of Well Plugging) may be found at OCD Web Page, OCD Permitti www.emnrd.state.nm.us         I hereby certify that the information above is true and complete to the be	8175'. Rigged down and NI nt plug from 8175'-7750', ta nent plug from 7280'-6905' a CIBP at 4999'. Spotted 30 zed with 35 sx Class "C" cer 'C" cement from 1093'-993' plug will cover hole in casi sx Class "C" cement down ty under secipt of which ng @	D BOP. gged. Perforated at 7( , tagged. Set a CIBP a sx Class "C" cement nent from 3966'-3818 , tagged. ng from 865'-897'. Pe 4-1/2" casing and up 8 <u>CONTINUED ON N</u>	067'. t 6337'. on top of CIBP at ', tagged. Perforated erforated at 396'. 3-5/8" casing from			
3/22/22 – RIH to 8175'. Cement to be pumped on top of 2 <sup>nd</sup> existing packer at 5/5/22 - MIRU and NU BOP to plug the well. Spotted a 25 sx Class "H" ceme 5/6/22 – Tested perf to 500 psi for 10 min, good. Spotted a 30 sx Class "C" ce 5/9/22 – Spotted 30 sx Class "C" cement on top of CIBP to 5905', tagged. Set 4570', tagged.         5/10/22 – Perforated at 3966'. Established circulation up 8-5/8" casing. Squee at 1093'. Established circulation up 8-5/8" casing. Squeezed with 25 sx Class "5/11/22 – Squeezed with 25 sx Class "C" cement from 897'-722', tagged. This Spotted 14 sx Class "C" cement from 608'-396' calc TOC. Squeezed with 100 396' and circulated up to surface.         Approved for plugging of well bore only. Liabili bond is retained pending Location cleanup & r C-103Q (Subsequent Report of Well Plugging) may be found at OCD Web Page, OCD Permitti www.emmrd.state.nm.us         I hereby certify that the information above is true and complete to the be SIGNATURE Tina Huerta       TITLE Reg	8175'. Rigged down and NI nt plug from 8175'-7750', ta ment plug from 7280'-6905' a CIBP at 4999'. Spotted 30 zed with 35 sx Class "C" cer 'C" cement from 1093'-993' s plug will cover hole in casi sx Class "C" cement down ty under sector of which ng @	D BOP. gged. Perforated at 7( , tagged. Set a CIBP a sx Class "C" cement nent from 3966'-3818 , tagged. ng from 865'-897'. Pe 4-1/2" casing and up 8 CONTINUED ON N CONTINUED ON N elief. ATE <u>August 4, 20</u>	067'. t 6337'. on top of CIBP at ', tagged. Perforated erforated at 396'. 8-5/8" casing from NEXT PAGE:			
3/22/22 – RIH to 8175'. Cement to be pumped on top of 2 <sup>nd</sup> existing packer at 5/5/22 - MIRU and NU BOP to plug the well. Spotted a 25 sx Class "H" ceme 5/6/22 – Tested perf to 500 psi for 10 min, good. Spotted a 30 sx Class "C" ce 5/9/22 – Spotted 30 sx Class "C" cement on top of CIBP to 5905', tagged. Set 4570', tagged.         5/10/22 – Perforated at 3966'. Established circulation up 8-5/8" casing. Squee at 1093'. Established circulation up 8-5/8" casing. Squeezed with 25 sx Class "5/11/22 – Squeezed with 25 sx Class "C" cement from 897'-722', tagged. This Spotted 14 sx Class "C" cement from 608'-396' calc TOC. Squeezed with 100 396' and circulated up to surface.         Approved for plugging of well bore only. Liabili bond is retained pending Location cleanup & r C-103Q (Subsequent Report of Well Plugging) may be found at OCD Web Page, OCD Permitti www.emmrd.state.nm.us         I hereby certify that the information above is true and complete to the be SIGNATURE Tina Huerta       TITLE Reg	8175'. Rigged down and NI nt plug from 8175'-7750', ta nent plug from 7280'-6905' a CIBP at 4999'. Spotted 30 zed with 35 sx Class "C" cerr 'C" cement from 1093'-993' s plug will cover hole in casi sx Class "C" cement down ty under secipt of which ng @	D BOP. gged. Perforated at 7( , tagged. Set a CIBP a sx Class "C" cement nent from 3966'-3818 , tagged. ng from 865'-897'. Pe 4-1/2" casing and up 8 CONTINUED ON N CONTINUED ON N elief. ATE <u>August 4, 20</u>	067'. t 6337'. on top of CIBP at ', tagged. Perforated erforated at 396'. 3-5/8" casing from			
3/22/22 – RIH to 8175'. Cement to be pumped on top of 2 <sup>nd</sup> existing packer at 5/5/22 - MIRU and NU BOP to plug the well. Spotted a 25 sx Class "H" ceme 5/6/22 – Tested perf to 500 psi for 10 min, good. Spotted a 30 sx Class "C" ce         5/9/22 – Spotted 30 sx Class "C" cement on top of CIBP to 5905', tagged. Set 4570', tagged.         5/10/22 – Perforated at 3966'. Established circulation up 8-5/8" casing. Squee at 1093'. Established circulation up 8-5/8" casing. Squeezed with 25 sx Class "C" cement from 897'-722', tagged. This Spotted 14 sx Class "C" cement from 608'-396' calc TOC. Squeezed with 100 396' and circulated up to surface.         Approved for plugging of well bore only. Liabili bond is retained pending Location cleanup & r C-103Q (Subsequent Report of Well Plugging) may be found at OCD Web Page, OCD Permitti www.emrd.state.nm.us         I hereby certify that the information above is true and complete to the be SIGNATURE Tina Huerta       TITLE Reg         Type or print name       Tina Huerta       E-mail address: tin For State Use Only	8175'. Rigged down and NI nt plug from 8175'-7750', ta ment plug from 7280'-6905' a CIBP at 4999'. Spotted 30 zed with 35 sx Class "C" cer 'C" cement from 1093'-993' s plug will cover hole in casi sx Class "C" cement down ty under sector of which ng @	D BOP. gged. Perforated at 7( , tagged. Set a CIBP a sx Class "C" cement nent from 3966'-3818 , tagged. ng from 865'-897'. Pe 4-1/2" casing and up 8 CONTINUED ON N CONTINUED ON N elief. ATE <u>August 4, 20</u>	067'. t 6337'. on top of CIBP at ', tagged. Perforated erforated at 396'. 8-5/8" casing from NEXT PAGE:			

•

## Released to Imaging: 8/12/2022 1:33:31 PM

Anderson CS State 2 J-14-18S-24E Eddy County, New Mexico Page 2

## Form C-103 Continued:

7/20/22 - Note: The gas on the 8-5/8" casing after initial plugging and the planned remedial operations to correct the issue were discussed with NMOCD prior to beginning remedial operations. Moved in plugging ops equipment. NU BOP. Begin drilling cement at surface down to 478' and circulated hole clean.

7/21/22 – Continue drilling out plugs and cement fell out at 897'. Tagged TOC 993'. Circulated hole clean. Attempted circulation and unable to establish circulation. Established injection rate 1 BPM at 800 psi. Set packer at 483'. Verified injection rate below packer 800 psi and tested good, above packer on backside to 1000 psi and tested good. Squeezed with 130 sx Class "C" cement at 830' with 500 psi, apply 700 psi to 8-5/8" casing.

7/22/22 – Gas bubbling up 8-5/8" casing. Released packer and tagged TOC 780'. Pressured up to 1500 psi with no leak off. Ran CBL with 1000 psi from 780' and up to surface. Determined perf depths. Perforate at 750'. Attempted injection rate, holding 1600 psi. No injection rate established. Perforated at 475'. Set packer at 485'. Established suicide circulation around 4-1/2" at 200 psi.

7/25/22 – POH with packer. Set a cement retainer at 495'. Squeezed with 75 sx Class "C" cement from 750'-325' calc TOC. Pressured up to 1500 psi with 8-5/8" open.

7/26/22 – Gas bubbling LEL's up 8-5/8". Tagged TOC at 480'. Pressured up to 1800 psi with no leak off. Perforated at 440'. Set packer at 450' (between perfs at 475' and 440'). Circulated 25 sx Class "C" cement from 450'-200' calc TOC. Released packer. Pressured up to 1500 psi, good.

7/27/22 – Gas LEL's bubbling up 8-5/8" casing. Monitor gas bubbling. Tagged TOC at 128'. Perforated at 125'. Circulated through perf up 8-5/8", broke down cured cement increasing pump rate, decreasing pump pressure. Squeezed with 75 sx Class "C" cement out into casing void from 125' up to surface. Backfilled with 5 sx Class "C" cement to surface.

7/28/22 – Cut off wellhead and installed above ground dry hole marker. Cut off anchors and cleaned location. WELL IS PLUGGED AND ABANDONED.

Tina Huerta

Regulatory Specialist August 4, 2022

				Sec-TWN-RNG:	14 7400	D24E		A D1-	30-015-23961			
Plug 4	lerson CS State	2		FOOTAGES:			L	GR:	3679.5			
			0.4.01110	DETAIL								
			#	B DETAIL HOLE SIZE	SIZE	WGHT	GRADE	Тор	Bottom	Sx Cmt	Circ/TOC	TOC Met
Plug 3			А	17 1/2	13 3/8	48	J-55	0	396	600	1" to surface	
	A		В	12 1/4	8 5/8	24	K-55	0	1,043	300	Circ	
			C	7 7/8	4 1/2	10.5/11.6	J-55	0	8,276	1000	4310	CBL
ug 2									DV tool @ 7017			
ug 1			FORMA	TION TOPS								
				Formation	Top (MD)		Formation	Top (MD)		Formation	Top (MD)	
				San Andres	556		Atoka	8061				
	в			Abo	3916		Morrow	8276				
ug 6				Wolfcamp	5034							
				Cisco	6259							
				Canyon	7234							
							1					
lug 5			PLUGS									
lug 5			PLUGS #	SX	Class	Тор	Bottom	Tag	Notes			
ug 5					Class H	<b>Top</b> 7750	<b>Bottom</b> 8175	Tag Y	<b>Notes</b> Plug on top of existi	ng packer		
ug 5			#	SX				Y Y	Plug on top of existin Perforated at DV too			
			# 1	<b>SX</b> 25 30 30	H C C	7750 6905 5905	8175 7280 6337	Y Y Y	Plug on top of existin Perforated at DV too CIBP			
DC 4310 CBL			# 1 2 3 4	SX           25           30           30           30	H C C C	7750 6905 5905 4570	8175 7280 6337 4999	Y Y Y Y	Plug on top of existin Perforated at DV too CIBP CIBP			
DC 4310 CBL			# 1 2 3 4 5	<b>SX</b> 25 30 30 30 30 35	H C C C C	7750 6905 5905 4570 3818	8175 7280 6337 4999 3966	Y Y Y Y Y	Plug on top of existii Perforated at DV too CIBP CIBP Perforate			
DC 4310 CBL			# 1 2 3 4 5 6	SX           25           30           30           30           30           25	H C C C C C C	7750 6905 5905 4570 3818 993	8175 7280 6337 4999 3966 1093	Y Y Y Y Y Y	Plug on top of existii Perforated at DV too CIBP CIBP Perforate Perforate			
DC 4310 CBL ug 4 olfcamp perfs 5049-5097			# 1 2 3 4 5 6 7	SX           25           30           30           30           35           25           25	H C C C C C C C	7750 6905 5905 4570 3818 993 722	8175 7280 6337 4999 3966 1093 897	Y Y Y Y Y Y Y	Plug on top of existii Perforated at DV too CIBP CIBP Perforate Perforate Perforate			
DC 4310 CBL ug 4 olfcamp perfs 5049-5097 ug 3			# 1 2 3 4 5 6 7 8	SX           25           30           30           35           25           25           14	H C C C C C C C C C C	7750 6905 5905 4570 3818 993 722 396	8175 7280 6337 4999 3966 1093 897 608	Y Y Y Y Y Y Y N	Plug on top of existii Perforated at DV too CIBP CIBP Perforate Perforate			
DC 4310 CBL ug 4 olfcamp perfs 5049-5097 ug 3			# 1 2 3 4 5 6 7 8 9	SX           25           30           30           35           25           25           14           100	H C C C C C C C	7750 6905 5905 4570 3818 993 722	8175 7280 6337 4999 3966 1093 897	Y Y Y Y Y Y Y	Plug on top of existii Perforated at DV too CIBP CIBP Perforate Perforate Perforate			
DC 4310 CBL lug 4 /olfcamp perfs 5049-5097 lug 3 isco perfs 6387-6792			# 1 2 3 4 5 6 7 8 9 8 8 9 Remedi	SX           25           30           30           35           25           14           100           al Cement Work	H C C C C C C C C C C C C C C C C C C C	7750 6905 5905 4570 3818 993 722 396 0	8175 7280 6337 4999 3966 1093 897 608 396	Y Y Y Y Y Y N N	Plug on top of existii Perforated at DV too CIBP CIBP Perforate Perforate Perforate			
DC 4310 CBL lug 4 /olfcamp perfs 5049-5097 lug 3 isco perfs 6387-6792 lug 2			# 1 2 3 4 5 6 7 8 9 8 8 9 8 Remedi	SX           25           30           30           35           25           14           100           al Cement Work           130	H C C C C C C C C C C C C C C C C C C C	7750 6905 5905 4570 3818 993 722 396 0 780	8175 7280 6337 4999 3966 1093 897 608 396 830	Y Y Y Y Y Y N N Y	Plug on top of existii Perforated at DV too CIBP CIBP Perforate Perforate Perforate Perforate	ol at 7067		
DC 4310 CBL <b>ug 4</b> folfcamp perfs 5049-5097 <b>ug 3</b> sco perfs 6387-6792 <b>ug 2</b>		DV Tool @ 7067	# 1 2 3 4 5 6 7 8 8 9 8 Remedi 1 2	SX           25           30           30           35           25           25           14           100           al Cement Work           130           75	H C C C C C C C C C C C C C C C C C C C	7750 6905 5905 4570 3818 993 722 396 0 780 480	8175 7280 6337 4999 3966 1093 897 608 396 830 750	Y Y Y Y Y Y Y N N Y Y	Plug on top of existii Perforated at DV too CIBP CIBP Perforate Perforate Perforate Perforate Perforate 750', 475',	ol at 7067	ner at 495'	
DC 4310 CBL <b>ug 4</b> olfcamp perfs 5049-5097 <b>ug 3</b> sco perfs 6387-6792 <b>ug 2</b>		DV Tool @ 7067	# 1 2 3 4 5 6 7 8 9 8 8 9 9 Remedi 1 2 3	SX           25           30           30           35           25           25           14           100           al Cement Work           130           75           25	H C C C C C C C C C C C C C C C C C C C	7750 6905 5905 4570 3818 993 722 396 0 780 480 128	8175           7280           6337           4999           3966           1093           897           608           396           830           750           450	Y Y Y Y Y Y N N N Y Y Y	Plug on top of existii Perforated at DV too CIBP CIBP Perforate Perforate Perforate Perforate 750', 475', Perforate 440'	ol at 7067	ner at 495'	
DC 4310 CBL lug 4 /olfcamp perfs 5049-5097 lug 3 isco perfs 6387-6792 lug 2		DV Tool @ 7067	# 1 2 3 4 5 6 7 8 8 9 8 Remedi 1 2	SX           25           30           30           35           25           25           14           100           al Cement Work           130           75	H C C C C C C C C C C C C C C C C C C C	7750 6905 5905 4570 3818 993 722 396 0 780 480	8175 7280 6337 4999 3966 1093 897 608 396 830 750	Y Y Y Y Y Y Y N N Y Y	Plug on top of existii Perforated at DV too CIBP CIBP Perforate Perforate Perforate Perforate Perforate 750', 475',	ol at 7067	ner at 495'	
DC 4310 CBL <b>ug 4</b> olfcamp perfs 5049-5097 <b>ug 3</b> isco perfs 6387-6792 <b>ug 2</b> anyon perfs (sqz'd) 6960-6996			# 1 2 3 4 5 6 7 8 9 8 8 9 9 Remedi 1 2 3	SX           25           30           30           35           25           25           14           100           al Cement Work           130           75           25	H C C C C C C C C C C C C C C C C C C C	7750 6905 5905 4570 3818 993 722 396 0 780 480 128	8175           7280           6337           4999           3966           1093           897           608           396           830           750           450	Y Y Y Y Y Y N N N Y Y Y	Plug on top of existii Perforated at DV too CIBP CIBP Perforate Perforate Perforate Perforate 750', 475', Perforate 440'	ol at 7067	ner at 495'	
DC 4310 CBL <b>ug 4</b> olfcamp perfs 5049-5097 <b>ug 3</b> isco perfs 6387-6792 <b>ug 2</b> anyon perfs (sqz'd) 6960-6996		DV Tool @ 7067	# 1 2 3 4 5 6 7 8 9 8 8 9 9 Remedi 1 2 3	SX           25           30           30           35           25           25           14           100           al Cement Work           130           75           25	H C C C C C C C C C C C C C C C C C C C	7750 6905 5905 4570 3818 993 722 396 0 780 480 128	8175           7280           6337           4999           3966           1093           897           608           396           830           750           450	Y Y Y Y Y Y N N N Y Y Y	Plug on top of existii Perforated at DV too CIBP CIBP Perforate Perforate Perforate Perforate 750', 475', Perforate 440'	ol at 7067	ier at 495'	
DC 4310 CBL lug 4 folfcamp perfs 5049-5097 lug 3 isco perfs 6387-6792 lug 2 anyon perfs (sqz'd) 6960-6996			# 1 2 3 4 5 6 7 8 9 Remedi 1 2 3 4	SX           25           30           30           35           25           25           14           100           al Cement Work           130           75           25           100	Н С С С С С С С С С С С С С С С С С С С	7750 6905 5905 4570 3818 993 722 396 0 780 480 128 0 Bottom	8175         7280         6337         4999         3966         1093         897         608         396         830         750         450         125	Y Y Y Y Y Y N N Y Y N	Plug on top of existii Perforated at DV too CIBP CIBP Perforate Perforate Perforate Perforate 750', 475', Perforate 440' Perforate 125'	ol at 7067	1er at 495'	
DC 4310 CBL ug 4 olfcamp perfs 5049-5097 ug 3 sco perfs 6387-6792 ug 2 anyon perfs (sqz'd) 6960-6996 ug 1			# 1 2 3 4 5 6 7 8 9 Remedi 1 2 3 4	SX           25           30           30           35           25           25           14           100           al Cement Work           130           75           25           100	Н С С С С С С С С С С С С С С С С С С С	7750 6905 5905 4570 3818 993 722 396 0 780 480 128 0 Bottom 6,996	8175 7280 6337 4999 3966 1093 897 608 396 830 750 450 125 125	Y           Y           Y           Y           Y           Y           Y           Y           Y           Y           Y           Y           Y           Y           Y           Y           Y           Y           Y           N           O gals 15% NE :	Plug on top of existii Perforated at DV too CIBP CIBP Perforate Perforate Perforate Perforate 750', 475', Perforate 440' Perforate 125'	ol at 7067		
Plug 5         FOC 4310 CBL         Plug 4         Nolfcamp perfs 5049-5097         Plug 3         Cisco perfs 6387-6792         Plug 2         Canyon perfs (sqz'd) 6960-6996         Plug 1         Atoka Perfs 8218-8242			# 1 2 3 4 5 6 7 8 9 Remedi 1 2 3 4	SX           25           30           30           35           25           25           14           100           al Cement Work           130           75           25           100	Н С С С С С С С С С С С С С С С С С С С	7750 6905 5905 4570 3818 993 722 396 0 780 480 128 0 80 480 128 0 80 6,996 8,242	8175 7280 6337 4999 3966 1093 897 608 396 830 750 450 125 125 Acidized w/250	Y           Y           Y           Y           Y           Y           Y           Y           Y           Y           Y           Y           Y           Y           Y           Y           Y           Y           Y           Sals 15% NE a           gals 15% DS-30	Plug on top of existii Perforated at DV too CIBP CIBP Perforate Perforate Perforate Perforate 750', 475', Perforate 440' Perforate 125'	at 7067 , Cement retain B ball sealers Ils ealers. Frac v		

•

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410

Phone:(505) 334-6178 Fax:(505) 334-6170 District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

## State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
EOG RESOURCES INC	7377
P.O. Box 2267	Action Number:
Midland, TX 79702	131734
	Action Type:
	[C-103] Sub. Plugging (C-103P)
CONDITIONS	

## Created By Condition Condition gcordero None 8/12/2022

Page 4 of 4

.

Action 131734