ceined by Och: App. 7/2022 8:49:57	State of New Me.	xico	Form C-103 <sup>1</sup> of S
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natur	ral Resources	Revised July 18, 2013 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	OH CONCEDUATION	DIVIGION	30-015-31557
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	OIL CONSERVATION		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fran Santa Fe, NM 87		STATE FEE
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	Salita Pe, INIVI 67	303	6. State Oil & Gas Lease No.
SUNDRY NOT	ICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			DURANGO 15 STATE COM
PROPOSALS.)  1. Type of Well: Oil Well Gas Well Other SWD			8. Well Number 1
2. Name of Operator			9. OGRID Number
SPUR ENERGY PARTNERS LLC			328947
3. Address of Operator			10. Pool name or Wildcat
9655 KATY FREEWAY, SUITE 500, HOUSTON, TX 77024  4. Well Location			SWD; CISCO
	660 feet from the NORTH	line and	660 feet from the WEST line
Section 15		nge 29E	NMPM EDDY County
	11. Elevation (Show whether DR,		
	3564' GL		
12 Chack	Appropriate Box to Indicate Na	ature of Notice	Papert or Other Data
12. CHECK	Appropriate Box to indicate Na	ature or Notice,	Report of Other Data
	ITENTION TO:		SEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON   CHANCE DIANS	REMEDIAL WOR	
TEMPORARILY ABANDON   □  PULL OR ALTER CASING	CHANGE PLANS   MULTIPLE COMPL	COMMENCE DR CASING/CEMEN	
DOWNHOLE COMMINGLE		0, 1011 10, 02111211	Notify OCD 24 hrs. prior to any work
CLOSED-LOOP SYSTEM		OTUED	done
OTHER:  13. Describe proposed or comm	bleted operations. (Clearly state all r.	OTHER: ertinent details, an	d give pertinent dates, including estimated date
of starting any proposed we	ork). SEE RULE 19.15.7.14 NMAC		mpletions: Attach wellbore diagram of
proposed completion or rec	•		
	uests to put this well in TA status		• • •
Once we have an app	proved injection order, we plan t	o work the well t	over and bring it back online.
Please find proposed	TA procedure and WBDs attacl	hed for your use	
		A status may be granted after a erformed. Contact the OCD to	a successful MIT test is schedule the test so it may be
	The state of the s	itnessed.	
Spud Date:	Rig Release Da	te:	
L			
T. b	-hi	-+ -f 1 1- 4-	d h-1!£
I hereby certify that the information	above is true and complete to the be	est of my knowledg	ge and belief.
< // <p></p>	7/		
SIGNATURE Sarah (	hapman TITLE REGL	JLATORY DIRE	CTOR DATE 10/07/2022
Type or print name SARAH CHA	PMAN E-mail address	: SCHAPMAN@SPU	RENERGY.COM PHONE: 832-930-8613
For State Use Only	2 man acaress		
ADDDOVED BY:	Trimi r	StallM	ANA CAA. DATE 10/14/22
APPROVED BY: Conditions of Approval (if any):	TITLE	Jan III	anager <sub>DATE</sub> 10/14/22
11 " ( " )/"			

Durango 15 State Com #001


30-015-31557

**Proposed TA Procedure** 


Notify OCD and BLM 24hrs prior to rigging up

Notify OCD and BLM 48hrs prior to MIT test

- 1. Move in, rig up well service unit.
- 2. Nipple down wellhead, nipple up BOP.
- 3. Unset packer, kill well if needed.
- 4. POOH with injection tubing while inspecting. If condition is good, rack back. If condition is bad, LD and order 8rd L80 work string.
- 5. Pick up & run in hole w/ bit & casing scraper. Pull out of hole.
- 6. Run in hole w/ 5.5" CIBP & set at 8,755'.
- 7. Pressure test CIBP to 500 psi for 15 minutes.
- 8. Circulate packer fluid.
- 9. Spot 💥 (.&\black) Class H cmt on top of CIBP. Spot 25 sx cement or DumpBail 35' WOC & Tag
- 10. Pull out of hole laying down workstring.
- 11. Nipple down BOP, nipple up wellhead.
- 12. Rig down, move out well service unit.
- 13. Perform MIT test Notify OCD and BLM 48hrs prior to test pressure test casing to 500 psi for 30 minutes and record chart and fill out all pertinent information.



TD @ 11,185 PBTD @ 9,400



TD @ 11,185 PBTD @ 9,400

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 149543

## **CONDITIONS**

Operator:	OGRID:
Spur Energy Partners LLC	328947
9655 Katy Freeway	Action Number:
Houston, TX 77024	149543
	Action Type:
	[C-103] NOI Temporary Abandonment (C-103I)

## CONDITIONS

Created By	Condition	Condition Date
gcordero	None	10/14/2022