eceined by Och & Appropriate being:2	2 AM State of New Mexico	Form C-103 1 of 5			
Office <u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013			
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283	OH CONGEDUATION DUNGLON	WELL API NO. 30-015-28164			
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.	5. Indicate Type of Lease			
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE FEE (X)  6. State Oil & Gas Lease No.			
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	Sunta 1 C, 14141 07303	6. State Oil & Gas Lease No.			
(DO NOT USE THIS FORM FOR PROPO	TICES AND REPORTS ON WELLS DISALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DISALS TO PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name			
PROPOSALS.)	<u> </u>	LAKEWOOD FARMS SWD 18 8. Well Number			
Type of Well: Oil Well     Name of Operator	Gas Well Other SWD	9. OGRID Number			
<u> </u>	IERGY PARTNERS LLC	328947			
3. Address of Operator	SUITE 500, HOUSTON, TX 77024	10. Pool name or Wildcat SWD; CISCO-CANYON			
4. Well Location		·			
Unit LetterD	feet from theNORTH line and	feet from the <u>WEST</u> line			
Section 18	Township 19S Range 26E				
	11. Elevation (Show whether DR, RKB, RT, GR 3385' GR	, etc.)			
	3305 GR				
12. Check	Appropriate Box to Indicate Nature of Not	tice, Report or Other Data			
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE	PLUG AND ABANDON	E DRILLING OPNS. P AND A			
CLOSED-LOOP SYSTEM  OTHER:	WORKOVER ☒ OTHER:	П			
13. Describe proposed or com	pleted operations. (Clearly state all pertinent detail ork). SEE RULE 19.15.7.14 NMAC. For Multiple	ls, and give pertinent dates, including estimated date e Completions: Attach wellbore diagram of			
Well is showing pressu Please find proposed v	re on casing and will require workover. orkover procedure attached along with the \	WBDs for your review.			
Spud Date:	Rig Release Date:				
I hereby certify that the information	above is true and complete to the best of my know	vledge and belief.			
signature Sarah C	hapman TITLE REGULATORY D	IRECTOR DATE 08/04/2023			
Type or print name _SARAH_CHA	APMAN E-mail address: SCHAPMAN	@SPURENERGY.COMPHONE: 832-930-8613			
APPROVED BY:	TITLE	DATE			
Conditions of Approval (if any):					

#### Lakewood Farms 18 #1 SWD

Eddy County, NM API# 30-015-28164 AFE TBD - TBD

# **Hole in Tubing / Packer Leak**

# Objective

This well has a suspected hole in tubing or packer leak due to pressure on the 7" casing. It is proposed to pull and LD all tubing and replace all tubing with new Polycore tubing from Western Falcon. The tubing that is in the well is from the original completion of this well in 2015.

#### Notes:

ONLY RUN 316 OR HIGHER-GRADE STAINLESS STEEL, PLASTIC COATED, OR NICKEL COATED ACCESSORIES DOWNHOLE – COLLARS, XOs, ON/OFF TOOLS ETC. SS IS PREFERED.

### **Procedure**

- 1. Notification: Contact the OCD at least 24 hours prior to the commencing of any operations.
- 2. Move in rig up pulling unit and laydown machine.
- 3. Ensure well is at 0 psi, 10# or 11.6# brine may be needed to kill the well. Nipple down wellhead. Nipple up BOP.
- 4. Pull and LD 3-1/2" CLS Duo-Lined tubing as follows:

### **Tubing Detail (12/4/2021)**

Current Tubing String									
Tubing Description Production Tubing			Set Depth (ftKB) 7,716.1		Run Date 12/4/2021				
Item Des	Grade	Wt (lb/ft)	OD (in)	ID (in)	Len (ft)	Jts	Cum Len (ft)	Top (ftKB)	Btm (ftKB)
KB Correction				0.00	12.00		7,716.17	-0.1	11.9
Tubing 3 1/2 Duo-Lined				2.50	7,688.12	235	7,704.17	11.9	7,700.1
X/O 3 1/2 - 2 7/8				2.50	0.50	1	16.05	7,700.1	7,700.6
On & Off Tool				2.31	2.00	1	15.55	7,700.6	7,702.6
ASI Arrow Set PKR 7"				2.44	7.00	1	13.55	7,702.6	7,709.6
Pup Joint				2.44	6.05	1	6.55	7,709.6	7,715.6
Pump Out Plug Collar					0.50	1	0.50	7,715.6	7,716.1

- 5. Pick up bit and scraper and 3-1/2" Polycore tubing from Western Falcon. Run in hole to 7,750' and pull out of hole.
- 6. RIH to 975' with test RBP and set. Test to 500 psi to test sqz'd perfs at 400' and DV tool at 922'.
- 7. Once good test is confirmed, POOH
- 8. Run in hole hydrotesting tubing to 5,000 psi below the slips as follows:

### **Proposed Tubing Detail**

~235 jts 3-1/2" std WF Polycore L-80 9.3# EUE tbg

3-1/2" T-2 O/O tool NP w/ profile

7" X 3 1/2" NP AS1X Packer


3-1/2" x 2-7/8" SS XO

2 7/8" NP Pup

2 7/8" SS Landing Nipple

POP w/ WLREG

- 9. Put packer at +/- 7,709' (same depth as before).
- 10. Bull head 150 bbls of packer fluid and set packer; once set, top off the annulus with packer fluid.
- 11. Load and test casing to 500 psi for 30 mins.
- 12. If good test, Nipple down BOP. Nipple up wellhead.
- 13. Rig down pulling unit.
- 14. Notify NMOCD 48hrs in advance to witness MIT; run MIT in accordance to 19.15.26 NMAC.



TD @ 9,550' PBTD @ 8,336'

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 248305

## **CONDITIONS**

Operator:	OGRID:
Spur Energy Partners LLC	328947
9655 Katy Freeway	Action Number:
Houston, TX 77024	248305
	Action Type:
	[C-103] NOI Workover (C-103G)

#### CONDITIONS

Created By		Condition Date
mgebremichael	As it is stipulated in SWD -1544,after the repair, same tube size should be installed. Packer shall be within 100ft of top perforation.	8/9/2023