Received by UCD: S/26/2024 3:24:15 PM U.S. Department of the Interior BUREAU OF LAND MANAGEMENT			Sundry Print Report 06/10/2024
	Well Name: WBR FEDERAL	Well Location: T22S / R32E / SEC 13 / SWSW / 32.3574164 / -104.1085246	County or Parish/State: LEA / NM
	Well Number: 02	Type of Well: OIL WELL	Allottee or Tribe Name:
	Lease Number: NMNM58940	Unit or CA Name:	Unit or CA Number:
	US Well Number: 3002532999	Operator: OXY USA INCORPORATED	

Accepted for record only BLM approval required NMOCD 8/27/24 KF

## Subsequent Report

Sundry ID: 2793830

Type of Submission: Subsequent Report

Date Sundry Submitted: 06/06/2024

Date Operation Actually Began: 04/26/2024

Type of Action: Plug and Abandonment Time Sundry Submitted: 08:06 3

Actual Procedure: THE FINAL WELLBORE AND PA JOB SUMMARY ARE ATTACHED. THE WELLHEAD WAS CUT AND CAPPED ON 5/21/2024.

SR Attachments

## **Actual Procedure**

WBR\_2\_PA\_SR\_SUB\_6.5.2024\_20240606080552.pdf

Received by OCD: 8/26/2024 3:24:15 PM Well Name: WBR FEDERAL	Well Location: T22S / R32E / SEC 13 / SWSW / 32.3574164 / -104.1085246	County or Parish/State: LEA
Well Number: 02	Type of Well: OIL WELL	Allottee or Tribe Name:
Lease Number: NMNM58940	Unit or CA Name:	Unit or CA Number:
US Well Number: 3002532999	Operator: OXY USA INCORPORATED	

### Operator

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

**Operator Electronic Signature: STEPHEN JANACEK** 

Name: OXY USA INCORPORATED

Title: Regulatory Engineer

Street Address: 5 Greenway Plaza, Suite 110

City: Houston

State: TX

Phone: (713) 497-2417

Email address: stephen\_janacek@oxy.com

Field

Representative Name: Street Address: City: Phone: Email address:

State:

Zip:

Signed on: JUN 06, 2024 08:05 AM

## **BLM Point of Contact**

BLM POC Name: JAMES A AMOS BLM POC Phone: 5752345927 Disposition: Accepted Signature: James A Amos

BLM POC Title: Acting Assistant Field Manager BLM POC Email Address: jamos@blm.gov Disposition Date: 06/07/2024

## Received by OCD: 8/26/2024 3:24:15 PM

eceived by OCD. 6/20/202	4 3.24.13 F WI				ruge 5 0j
	UNITED STAT DEPARTMENT OF THE BUREAU OF LAND MAN	INTERIOR	-	0	ORM APPROVED MB No. 1004-0137 ires: October 31, 2021
Do not use t		ORTS ON WELLS to drill or to re-enter an APD) for such proposals		6. If Indian, Allottee of	r Tribe Name
	T IN TRIPLICATE - Other inst	ructions on page 2		7. If Unit of CA/Agree	ement, Name and/or No.
1. Type of Well	Gas Well Other		-	8. Well Name and No.	
2. Name of Operator				9. API Well No.	
3a. Address		3b. Phone No. (include area code)	e)	10. Field and Pool or E	Exploratory Area
4. Location of Well (Footage, Sec	c., T.,R.,M., or Survey Description	)		11. Country or Parish,	State
12.	CHECK THE APPROPRIATE F	BOX(ES) TO INDICATE NATURE	E OF NOTIO	E, REPORT OR OTH	IER DATA
TYPE OF SUBMISSION		TYI	PE OF ACT	ION	
Notice of Intent	Acidize	Deepen Hydraulic Fracturing		ction (Start/Resume) mation	Water Shut-Off Well Integrity
Subsequent Report	Casing Repair Change Plans	New Construction Plug and Abandon		nplete orarily Abandon	Other
Final Abandonment Notice			=	Disposal	
the proposal is to deepen dire- the Bond under which the wo completion of the involved op	ctionally or recomplete horizonta rk will be perfonned or provide the perations. If the operation results	lly, give subsurface locations and m ne Bond No. on file with BLM/BIA in a multiple completion or recompl	neasured and A. Required soletion in a r	d true vertical depths o subsequent reports mus lew interval, a Form 31	rk and approximate duration thereof. If f all pertinent markers and zones. Attach st be filed within 30 days following 60-4 must be filed once testing has been he operator has detennined that the site

14. I hereby certify that the foregoing is true and correct. Name ( <i>Printed/Typed</i> )			
1	Fitle		
Signature I	Date		
THE SPACE FOR FEDE	RAL OR STATE OF	FICE USE	-
Approved by			
	Title	Date	
Conditions of approval, if any, are attached. Approval of this notice does not warrant of certify that the applicant holds legal or equitable title to those rights in the subject leas which would entitle the applicant to conduct operations thereon.			
Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any any false, fictitious or fraudulent statements or representations as to any matter within		Ifully to make to any department or agency of the United S	States

(Instructions on page 2)

#### **GENERAL INSTRUCTIONS**

This form is designed for submitting proposals to perform certain well operations and reports of such operations when completed as indicated on Federal and Indian lands pursuant to applicable Federal law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local area or regional procedures and practices, are either shown below, will be issued by or may be obtained from the local Federal office.

#### SPECIFIC INSTRUCTIONS

*Item 4* - Locations on Federal or Indian land should be described in accordance with Federal requirements. Consult the local Federal office for specific instructions.

*Item 13:* Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by the local Federal office. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to the top of any tubing left in the hole; method of closing top of well and date well site conditioned for final inspection looking for approval of the abandonment. If the proposal will involve **hydraulic fracturing operations**, you must comply with 43 CFR 3162.3-3, including providing information about the protection of usable water. Operators should provide the best available information about all formations containing water and their depths. This information could include data and interpretation of resistivity logs run on nearby wells. Information may also be obtained from state or tribal regulatory agencies and from local BLM offices.

#### NOTICES

The privacy Act of 1974 and the regulation in 43 CFR 2.48(d) provide that you be furnished the following information in connection with information required by this application.

AUTHORITY: 30 U.S.C. 181 et seq., 351 et seq., 25 U.S.C. 396; 43 CFR 3160.

PRINCIPAL PURPOSE: The information is used to: (1) Evaluate, when appropriate, approve applications, and report completion of subsequent well operations, on a Federal or Indian lease; and (2) document for administrative use, information for the management, disposal and use of National Resource lands and resources, such as: (a) evaluating the equipment and procedures to be used during a proposed subsequent well operation and reviewing the completed well operations for compliance with the approved plan; (b) requesting and granting approval to perform those actions covered by 43 CFR 3162.3-2, 3162.3-3, and 3162.3-4; (c) reporting the beginning or resumption of production, as required by 43 CFR 3162.4-1(c)and (d) analyzing future applications to drill or modify operations in light of data obtained and methods used.

ROUTINE USES: Information from the record and/or the record will be transferred to appropriate Federal, State, local or foreign agencies, when relevant to civil, criminal or regulatory investigations or prosecutions in connection with congressional inquiries or to consumer reporting agencies to facilitate collection of debts owed the Government.

EFFECT OF NOT PROVIDING THE INFORMATION: Filing of this notice and report and disclosure of the information is mandatory for those subsequent well operations specified in 43 CFR 3162.3-2, 3162.3-3, 3162.3-4.

The Paperwork Reduction Act of 1995 requires us to inform you that:

The BLM collects this information to evaluate proposed and/or completed subsequent well operations on Federal or Indian oil and gas leases.

Response to this request is mandatory.


The BLM would like you to know that you do not have to respond to this or any other Federal agency-sponsored information collection unless it displays a currently valid OMB control number.

**BURDEN HOURS STATEMENT:** Public reporting burden for this form is estimated to average 8 hours per response, including the time for reviewing instructions, gathering and maintaining data, and completing and reviewing the form. Direct comments regarding the burden estimate or any other aspect of this form to U.S. Department of the Interior, Bureau of Land Management (1004-0137), Bureau Information Collection Clearance Officer (WO-630), 1849 C St., N.W., Mail Stop 401 LS, Washington, D.C. 20240

## **Additional Information**

### Location of Well

0. SHL: SWSW / 330 FSL / 330 FWL / TWSP: 22S / RANGE: 32E / SECTION: 13 / LAT: 32.3574164 / LONG: -104.1085246 (TVD: 0 feet, MD: 0 feet ) BHL: SWSW / 330 FSL / 330 FWL / TWSP: 22S / SECTION: / LAT: 0.0 / LONG: 0.0 (TVD: 0 feet, MD: 0 feet )



TD - 10070'

Remarks
CREW TRAVEL TO LOCATION
HPJSM W/ ALL PERSONAL ON LOCATION, DISCUSSED FIT FOR DUTY, ZERO TOLERANCE, HAND & FINGER SAFETY
CAMPAIGN, STOP WORK AUTHORITY, LOTO, PPE, MEET & GREET, GOOD COMMUNICATION AT ALL TIMES, PINCH
POINTS & HAND PLACEMENT, SUSPENDED LOADS, LINE OF FIRE, ONE TASK AT A TIME, TRIP HAZARDS, H2S,
MUSTER AREA, HOUSE KEEPING, UPDATE JSA AS TASK CHANGES
PERFORMED PRE-TRIP RIG INSPECTION
LOAD P&A EQUIPMENT
DROVE PULLING UNIT & P&A PUMP ASSOCIATED EQUIPMENT FROM THE FEDERAL 10 001 TO THE WBR FEDERAL
UNLOAD SPOTTED P&A PUMP & ASSOCIATED EQUIPMENT, UNLOAD & SPOTTED BASE BEAM
PERFORM LO/TO ON PUMPING UNIT PANEL BOX, MIRU AXIS ENERGY RIG 2141 & P&A ASSOCIATED EQUIPMENT,
SET PIPE RACKS & MI OIL DOG PIPE RENTAL UNLOAD 450 JTS OF 2-3/8" L-80 WS TBG
CHECK PSI ON WELL 2-7/8" TBG = 700 PSI, 5-1/2" PROD CSG = 800 PSI, 8-5/8" INTER CSG = 500 PSI, 13-3/8" SURF
CSG = 0 PSI,
SECURE WELL SDFN
CREW TRAVEL BACK TO MAN CAMP
CREW TRAVEL BACK TO MAN CAMP CREW TRAVEL TO LOCATION
HPJSM WITH ALL PERSONAL ON LOCATION
PERFORMED DAILY START UP RIG INSPECTION
SET CO/FO & FUNCTION TEST
CHECK PSI ON WELL 2-7/8" TBG = 700 PSI, 5-1/2" PROD CSG = 800 PSI, 8-5/8" INTER CSG = 500 PSI, 13-3/8" SURF
RIG UP STEEL LINE TO FLOW BACK TANK, BLEED OFF GAS HEAD F/ ALL STRINGS TO 0 PSI
MIRU PUMP, RU RESTRAINTS ON ALL IRON, HOOK UP TO 5.5" PROD CSG, TEST IRON TO 1500 PSI, PUMP 120 BBLS
DOWN CSG & 80 BBLS DOWN TBG OF 10# BW FOR WELL CONTROL, PUMPING RATE 2.5 BPM @ 0 PSI, ISIP = 0 PSI,
CSG & TBG WENT ON VACUUM MONITOR WELL FOR 15 MINUTES WELL STATIC
OPEN WELL FUNCTION TEST BOP W/ A GOOD TEST
ND 3K X 7-1/16" WH FLANGE
NU 3K X 5K X 7-1/16" SPOOL, NU 5K HYD BOP W/ 5K 2-7/8" & 2-3/8" PIPE RAMS ON TOP AND 5K BLINDS ON
воттом
RU WORK FLOOR W/ 2-7/8" TBG HANDLING TOOLS, SET UP SAFETY EQUIP, CENTER & LEVEL RIG OVER HOLE
PERFORM BOP CLOSING DRILL SECURED WELL, CREW MET @ MUSTER AREA IN 1 MIN
PICK UP ON TBG TO SET TBG SLIPS IN POSITION TBG NEUTRAL WT @ 22 PTS POOH LD 107 – JTS 2-7/8" PROD TBG,
CHANGE OVER EQUIP TO 2-3/8" TBG HANDLING TOOLS
SECURE WELL SDFW
CREW TRAVEL BACK HOME
CREW TRAVEL TO LOCATION
HPJSM WITH ALL PERSONAL ON LOCATION
PERFORMED WEEKLY RIG INSPECTION
SET CO/FO & FUNCTION TEST
CHECK PSI ON WELL 5-1/2" PROD CSG = 300 PSI, 8-5/8" INTER CSG = 50 PSI, 13-3/8" SURF CSG = 0 PSI
SPOT AND RIG UP REVERSE UNIT PUMP ON 5.5" CSG PRESSURE TEST LINES TO 1500 PSI W/ A GOOD TEST, BLEED
OFF GAS HEAD F/ ALL STRINGS TO 0 PSI, PUMP 100 BBLS OF 10# BW DOWN CSG FOR WELL CONTROL, CSG WENT
OFF GAS HEAD F/ ALL STRINGS TO UPSI, PUMP TOUBBLS OF TO# BW DOWN CSG FOR WELL CONTROL. USG WENT

	OPEN WELL MI YELLOW JACKET HOT SHOT UNLOAD DRILL COLLARS, MAKE UP / PICK UP BHA AS FOLLOWS 4-3/4"
4/29/2024	BIT, 3-1/2" BIT SUB, 6 – 3-1/2" DRILL COLLARS, 3-1/2" X 2-3/8" TOP SUB, 4' X 2-3/8" L-80 WS TBG SUB,
	TALLY 134 JTS OF 2-3/8" L-80 WS TBG, RIH W/ 4-3/4" BIT PICKING UP 2-3/8" L-80 WS TBG RUNNING RABBIT ON
	PIPE LEAVE BIT/BHA SWINGING @ 4426' W/ 134 JTS IN THE HOLE INSTALL 2-3/8" TIW VALVE CLOSE BOP
	SECURE WELL SDFN
	CREW TRAVEL BACK HOME
	CREW TRAVEL TO LOCATION
4/30/2024	HPJSM WITH ALL PERSONAL ON LOCATION
4/30/2024	PERFORMED DAILY START UP RIG INSPECTION
4/30/2024	SET CO/FO & FUNCTION TEST
	CHECK PSI ON WELL 2-7/8" TBG = 100 PSI, 5-1/2" PROD CSG = 150 PSI, 8-5/8" INTER CSG = 50 PSI, 13-3/8" SURF
4/30/2024	CSG = 0 PSI
	BLEED OFF GAS HEAD F/ ALL STRINGS TO 0 PSI PUMP 30 BBLS DOWN TBG & 60 BBLS DOWN CSG OF 10# BW FOR
4/30/2024	WELL CONTROL TBG & CSG ON VACUUM
	OPEN WELL TALLY 200 JTS OF 2-3/8" L-80 WS TBG, CONTINUE RIH PICKING UP 2-3/8" L-80 WS TBG RUNNING
	RABBIT ON PIPE TAG FILL W/ 4-3/4" BIT @ 9652' (TMD) W/ 299 JTS IN THE HOLE 6' IN ON JT# 300,
4/30/2024	WE TAG 138' HIGHER FROM FIRST PLUG SETTING DEPTH 9790' LD 2 JTS OF 2-3/8" WS TBG
4/30/2024	TIE BACK RIG TO 6 LINES & RU LINE SCALE, NU 7-1/16" X 3K STRIPPER HEAD
4/30/2024	MIRU POWER SWIVEL ON JT #299 EOBHA @ 9646'
4/30/2024	SECURE WELL SDFN
4/30/2024	CREW TRAVEL BACK HOME
5/1/2024	CREW TRAVEL TO LOCATION
5/1/2024	HPJSM WITH ALL PERSONAL ON LOCATION
5/1/2024	PERFORMED DAILY START UP RIG INSPECTION
5/1/2024	SET CO/FO & FUNCTION TEST
	CHECK PSI ON WELL 2-7/8" TBG = 50 PSI, 5-1/2" PROD CSG = 100 PSI, 8-5/8" INTER CSG = 50 PSI, 13-3/8" SURF CSG
5/1/2024	= 0 PSI

	BLEED OFF GAS HEAD F/ ALL STRINGS TO 0 PSI, PUMP 20 BBLS DOWN TBG OF 10# BW TBG WENT ON VACUUM, MAKE CONNECTION W/ PS ON JT# 300
	ATTEMPT TO BREAK CIRC PUMPING REVERSE PUMP 200 BBLS OF FW PUMPING RATE AT 4 BPM @ 500 PSI W/ NEGATIVE RESULTS WE NEVER GOT RETURNS ON REV PIT,
	CHANGED TO PUMPING CONVENTIONAL PUMP 40 BBLS OF FW BREAK CIRC 2.5 BPM @ 1000 PSI GETTING BACK 1 BPM ON RETURNS (REV PIT)
	RIH TAG FILL @ 9652' (TMD) W/ 6' IN ON JT# 300, BEGIN CLEANING OUT FILL MAKING CONNECTIONS W/ PS, NOTE: WE MAKE ALL PS CONNECTIONS BY HAND W/ PS ENGINE SHUT OFF, CLEAN OUT 5' F/ 9652' – 9657' W/ NO ISSUES,
	TAGGED TIGHT SPOT @ 9657' WORK THROUGH TIGHT SPOT & LOST CIRC AND PRESSURE DROPPED F/ 1000 PSI TO 500 PSI @ 2.5 BPM, PICK UP 1' ATTEMPT TO BREAK CIRC WE PUMP 120 BBLS OF FW PUMPING RATE WAS 2.5 BPM @ 500 PSI W/ NEGATIVE RESULTS NOT ABLE TO BREAK CIRC,
	RBIH THROUGH TIGHT SPOT FELL THRU CONT RIH MAKING CONNECTIONS W/ PS, PUMPING CONVENTIONAL 2.5 BPM @ 500 PSI (W/ NO RETURNS) CLEAN OUT 147' F/ 9657' TO 9804' (TMD) W/ 304 JTS IN THE HOLE, (NOTE: BIT WAS DRAGGING AS WE RIH F/ 9657' TO 9804') (NOTE: NO CIBP @ 9782')
5/1/2024	PUMP 100 BBLS OF FW DOWN TBG, LD 4 JTS OF 2-3/8" WS TBG W/ PS AND WORK 4-3/4" BIT F/ 9646' TO 9677' W/ JT# 300 F/ 15 MIN PUMPING 2.5 BPM @ 500 PSI (BAD SPOT WAS @ 9657')
	RDMO PS
	ND 7-1/16" X 3K STRIPPER HEAD
	POOH W/ 37 STANDS OF 2-3/8" WS TBG EOBHA @ 7335' W/ 226 JTS IN HOLE, CLOSE BOP, INSTALL 2-3/8" TIW
5/1/2024	
	SECURE WELL SDFN
5/1/2024	CREW TRAVEL BACK HOME
5/2/2024	CREW TRAVEL TO LOCATION
5/2/2024	HPJSM WITH ALL PERSONAL ON LOCATION
	PERFORMED DAILY START UP RIG INSPECTION
	SET CO/FO & FUNCTION TEST
5/2/2024	CHECK PSI ON WELL 2-7/8" TBG = 0 PSI, 5-1/2" PROD CSG = 50 PSI, 8-5/8" INTER CSG = 0 PSI, 13-3/8" SURF CSG = 0
5/2/2024	BLEED OFF GAS HEAD F/ ALL STRINGS TO 0 PSI PUMP 30 BBLS DOWN TBG & 60 BBLS DOWN CSG OF 10# BW FOR
5/2/2024	WELL CONTROL TBG & CSG ON VACUUM
	OPEN WELL POOH W/ 226 JTS OF 2-3/8" WS TBG
- 1 1 -	
5/2/2024	LD DRILLING BHA 6 – 3-1/2" DC, 3-1/2" BIT SUB & 4-3/4" ROCK BIT, RD POWERS SWIVEL AND REVERSE UNIT
	MIRU YELLOW JACKET WL, RU PCE MAKE UP & RIH W/ 4.24" OD GR/JB F/ 5.5" CSG TO 9800' (WMD) W/ NO ISSUES POOH W/ GR/JB FOUND FLUID LEVEL @ 5000' F/ SURF,
5/2/2024	MAKE UP 4.24" OD CIBP FOR 5.5" CSG RIH W/ WL SET 1ST CIBP @ 9790' (WMD) W/ NO ISSUES PULL UP HOLE W/ WL 50' RBIH LIGHT TAG CIBP @ 9790' (WMD) CONFIRMED PLUG SET SUCCESSFULLY, POOH W/ WL SETTING TOOL
г /з /зоз <b>4</b>	MAKE UP AND PICK UP 50' X 3.5" WL CMT DUMP BAILER, RIH DUMP BAIL 4 SXS CLASS H CMT = .84 BBL SLURRY,
	PLUG CAP 36'ON TOP OF CIBP F/ 9790' – 9754' POOH W/ WL BREAK DOWN 3.5" CMT DUMP BAILER, RDMO WL
	SECURE WELL SDFN
	CREW TRAVEL BACK HOME CREW TRAVEL TO LOCATION
5/3/2024	

5/3/2024	HPJSM WITH ALL PERSONAL ON LOCATION
5/3/2024	PERFORMED DAILY START UP RIG INSPECTION
5/3/2024	SET CO/FO & FUNCTION TEST
5/3/2024	CHECK PSI ON WELL 5-1/2" PROD CSG = 50 PSI, 8-5/8" INTER CSG = 20 PSI, 13-3/8" SURF CSG = 0 PSI
	BLEED OFF GAS HEAD F/ ALL STRINGS TO 0 PSI, PUMP 100 BBLS OF 10# BW DOWN CSG FOR WELL CONTROL, CSG
5/3/2024	WENT ON VACUUM
	OPEN WELL MIRU YELLOW JACKET WL, RU PCE MAKE UP 4.24" OD CIBP FOR 5.5" CSG RIH W/ WL WENT DOWN
	TAG TOC @ 9750' (WMD) COME UP HOLE SET 2ND CIBP @ 7817' (WMD) W/ NO ISSUES PULL UP HOLE W/ WL 50'
	RBIH LIGHT TAG CIBP @ 7817' (WMD) CONFIRMED PLUG SET SUCCESSFULLY, POOH W/ WL SETTING TOOL,
	MAKE UP AND PICK UP 3.5" X 50' WL CMT DUMP BAILER, RIH DUMP BAIL 4 SXS CLASS H CMT = .84 BBL SLURRY,
	PLUG CAP 36' ON TOP OF CIBP F/ 7817' – 7781' POOH W/ WL BREAK DOWN 3.5" CMT DUMP BAILER, RDMO WL
	PICK UP 4' X 2-3/8" PERF TBG SUB RIH W/ 210 JTS OF 2-3/8" WS TBG
5/5/2024	POOH LD 54 JTS OF 2-3/8" WS TBG EOT @ 4976' (TMD) W/ 156 JTS IN THE HOLE, INSTALL 2-3/8" TIW VALVE CLOSE
5/3/2024	
	SECURE WELL SDFN
	CREW TRAVEL BACK HOME
	CREW TRAVEL BACK HOME CREW TRAVEL TO LOCATION
	HPJSM WITH ALL PERSONAL ON LOCATION
	PERFORMED DAILY START UP RIG INSPECTION
	SET CO/FO & FUNCTION TEST
	CHECK PSI ON WELL ALL STRINGS = 0 PSI
	OPEN WELL RIH W/ 2-3/8" WS TBG TAG TOC @ 7793' (TMD) W/ 246 JTS IN THE HOLE 12' IN ON JT# 247
5/4/2024	RU PUMP ON TBG CIRC HOLE CLEAN W/ 170 BBLS OF FW
F / 4 /202 A	
5/4/2024	POOH LD 40 JTS OF 2-3/8" WS TBG PICK UP 6' X 2-3/8" TBG SUBS EOT @ 6550' (TMD) W/ 207 JTS IN THE HOLE
	MIRU AXIS ENERGY CMT BULK TRK BREAK CIRC W/ 8 BBLS OF FW, 1ST PLUG) BALANCED PLUG F/ 6550' – 6331'
	SPOT 25 SXS CLASS C CMT, 5.87 BBLS SLURRY,14.8# 1.32 YIELD, PLUG CAP 253' DISPLACE TOC TO 6297' DISPLACE
5/4/2024	W/ 24.36 BBLS OF FW
_ / . /	LD 6' X 2-3/8" TBG SUB POOH W/ 20 STANDS LD 7 JTS OF 2-3/8" WS TBG EOT @ 5063' W/ 160 JTS IN THE HOLE,
	WASH UP PUMP & FLOW BACK PIT
	SECURE WELL SDFW
	CREW TRAVEL BACK HOME
	CREW TRAVEL TO LOCATION
	HPJSM WITH ALL PERSONAL ON LOCATION
	PERFORMED WEEKLY RIG INSPECTION
5/6/2024	SET CO/FO & FUNCTION TEST
	CHECK PSI ON WELL 2-3/8" TBG = 0 PSI, 5-1/2" PROD CSG = 0 PSI, 8-5/8" INTER CSG = 20 PSI, 13-3/8" SURF CSG = 0
, ,	PSI, BLEED OFF GAS HEAD F/ ALL STRINGS TO 0 PSI
5/6/2024	OPEN WELL RIH W/ 2-3/8" WS TBG TAG TOC @ 6286' (TMD) W/ 198 JTS IN THE HOLE 6' OUT ON JT# 199
5/6/2024	POOH LD 17 JTS OF 2-3/8" WS TBG EOT @ 5755' (TMD) W/ 182 JTS IN THE HOLE
	RU CMT PUMP ON TBG BREAK CIRC W/ 25 BBLS OF FW 2ND PLUG) BALANCED PLUG F/ 5750' – 5531' SPOT 25 SXS
	CLASS C CMT, W/ (2% CALCIUM CHLORIDE) 5.87 BBLS SLURRY,14.8# 1.32 YIELD, PLUG CAP 253' DISPLACE TOC TO
5/6/2024	5502' DISPLACE W/ 21.29 BBLS OF FW
	POOH W/ 20 STANDS LD 7 JTS OF 2-3/8" WS TBG EOT @ 4266' W/ 135 JTS IN THE HOLE, WASH UP PUMP & FLOW
5/6/2024	
	WOC TO TAG
	RIH W/ 2-3/8" WS TBG TAG TOC @ 5487' (TMD) W/ 173 JTS IN THE HOLE 15' OUT ON JT# 174
5/6/2024	RIH W/ 2-3/8" WS TBG TAG TOC @ 5487' (TMD) W/ 173 JTS IN THE HOLE 15' OUT ON JT# 174 POOH W/ 77 STANDS OF 2-3/8" WS TBG. INSTALL 2-3/8" TIW VALVE CLOSE BOP
5/6/2024 5/6/2024	RIH W/ 2-3/8" WS TBG TAG TOC @ 5487' (TMD) W/ 173 JTS IN THE HOLE 15' OUT ON JT# 174 POOH W/ 77 STANDS OF 2-3/8" WS TBG, INSTALL 2-3/8" TIW VALVE CLOSE BOP SECURE WELL SDFN

	CREW TRAVEL BACK HOME
	CREW TRAVEL TO LOCATION
	HPJSM WITH ALL PERSONAL ON LOCATION
	PERFORMED DAILY START UP RIG INSPECTION
	SET CO/FO & FUNCTION TEST
	CHECK PSI ON WELL ALL STRINGS = 0 PSI
5/7/2024	OPEN WELL POOH LD 20 JTS OF 2-3/8" WS TBG BREAK 4' X 2-3/8" PERF TBG SUB
	MIRU YELLOW JACKET WL, RU PCE MAKE UP 4.24" OD CIBP FOR 5.5" CSG RIH W/ WL WENT DOWN SET 3RD CIBP
	@ 4881' (WMD) W/ NO ISSUES PULL UP HOLE W/ WL 50' RBIH LIGHT TAG CIBP @ 4881' (WMD) CONFIRMED PLUG
5/7/2024	SET SUCCESSFULLY, POOH W/ WL SETTING TOOL RDMO YJ WL,
	PICK UP 4' X 2-3/8" PERF TBG SUB RIH W/ 2-3/8" WS TBG TAG 5.5" CIBP @ 4881' (TMD) W/ 154 JTS IN THE HOLE
5/7/2024	11' IN ON JT# 155, LD 1 JT (#155) PICK UP 10' X 2-3/8" TBG SUB
	RU PUMP ON TBG CIRC WELL CLEAN W/ 115 BBLS OF 10# BW MIX 17 GAL OF FLEX GEL W/ 85 BBLS OF 10# BW,
	PRESSURE TEST CIBP TO 500 PSI HOLD PRESSURE FOR 30 MIN W/ A GOOD TEST BLEED OFF PRESSURE
	BREAK CIRC W/ 8 BBLS OF 10# BW, 3RD PLUG) SET 5.5" CIBP @ 4881' BALANCED PLUG F/ 4881' – 4440' SPOT 55
	SXS CLASS C CMT, W/ (2% CALCIUM CHLORIDE) 12.93 BBLS SLURRY,14.8# 1.32 YIELD, PLUG CAP 557' DISPLACE TOC
5/7/2024	TO 4324' DISPLACE W/ 16.73 BBLS OF 10# BW
	LD 10' X 2-3/8" TBG SUB POOH W/ 15 STANDS LD 17 JTS OF 2-3/8" WS TBG EOT @ 3385' W/ 107 JTS IN THE HOLE,
	WASH UP PUMP & FLOW BACK PIT
	SECURE WELL SDFN
	CREW TRAVEL BACK HOME
	CREW TRAVEL TO LOCATION
	HPJSM WITH ALL PERSONAL ON LOCATION
	PERFORMED DAILY START UP RIG INSPECTION
	SET CO/FO & FUNCTION TEST
5/8/2024	CHECK PSI ON WELL ALL STRINGS = 0 PSI
	OPEN WELL RIH W/ 2-3/8" WS TBG TAG TOC @ 4341' (TMD) W/ 137 JTS IN THE HOLE 12' IN ON JT# 138, NOTE:
	MR. ANTONIO DE LA FUENTE W/ NMBLM, FIELD REP ON LOC, WITNESS TAG & GIVE THE OK TO CONTINUE AS
	PROGRAM
	POOH LD 96 JTS AND STAND BACK 42 JTS OF 2-3/8" WS TBG BREAK 4' X 2-3/8" PERF TBG SUB
	MAKE UP & RIH W/ AD-1 (4.75" OD) 5.5" PKR RIH W/ 2-3/8" WS TBG SET 5.5" AD-1 PKR @ 959' W/ 30 JTS IN THE
	HOLE & 8' X 2-3/8" TBG SUB
	LOAD BACK SIDE W/ 8 BBLS OF 10# BW TEST PKR TO 500 PSI W/ A GOOD TEST
	MIRU YELLOW JACKET WL RU PCE PICK UP 1-3/8" CCL 1-9/16" RTG CARRIER W/ OWEN CORE LAB CHARGES PAC-
	1562-457 CHARGE W/ A SPEC OF .28 ENTRY HOLE AND 5/8"-3/4" OF PENETRATION WENT DOWN TO 1446' SHOT 8
5/8/2024	SQZ HOLES POOH RDMO WL
	RU PUMP ON TBG EST – INJ RATE W/ 10# BW 2.5 BPM @ 250 PSI PUMP 10 BBLS OF 10# BW W/ FULL RETURNS ON
F /0 /2 22 5	SURF ON THE 8-5/8" INTER CSG, KEEP PUMPING BOTTOMS UP TO GET GAS & TRASH OUT, CIRCULATE A TOTAL OF
5/8/2024	55 BBLS OF 10# BW
	PUMP AHEAD 5 BBLS OF 10# BW 4TH PLUG) PERF @ 1446' SQZ 30 SXS CLASS C CMT, W/ (2% CALCIUM CHLORIDE)
F /0 /2024	7.05 BBLS SLURRY,14.8# 1.32 YIELD, PLUG CAP 303' DISPLACE TOC TO 1332' DISPLACE W/ 12.36 BBLS OF 10# BW,
	ISIP = 200 PSI WASH UP PUMP & FLOW BACK PIT
	SECURE WELL SDFN
	CREW TRAVEL BACK HOME
	CREW TRAVEL TO LOCATION
	HPJSM WITH ALL PERSONAL ON LOCATION
	PERFORMED DAILY START UP RIG INSPECTION
	SET CO/FO & FUNCTION TEST
5/9/2024	CHECK PSI ON WELL ALL STRINGS = 0 PSI
F /0 /2024	OPEN WELL UNSEAT 5.5" AD-1 PKR RIH W/ 2-3/8" WS TBG TAG TOC @ 1323' (TMD) W/ 41 JTS IN THE HOLE 15'
5/9/2024	OUT ON JT# 42,

5/9/2024 POOH LD 41 JTS OF 2-3/8" WS TBG
SET 5.5" PKR @ 42' W/ 1 JT IN THE HOLE & 8' X 2-3/8" TBG SUB, LOAD BACK SIDE W/ 1/2 BBL OF 10# BW TEST PKR
5/9/2024 TO 500 PSI W/ A GOOD TEST
MIRU YJ WL RU PCE PICK UP 1.2" X 1-3/8" CCL 1" X 1-3/8" DOUBLE O-RING TEAR DROP 5" X 1-9/16" FIRING HEAD
3' X 1-9/16" GUN LOADED 6 SPF W/GEO 2.7G CHARGES 1.2"X1 9/16" DECENTRALIZER WENT DOWN TO 775' SHOT
5/9/2024 6 SQZ HOLES POOH RDMO WL
RU CMT PUMP ON TBG EST – INJ RATE W/ 10# BW 2.5 BPM @ 150 PSI PUMP 25 BBLS OF 10# BW W/ FULL
5/9/2024 RETURNS ON 8-5/8" INTER CSG
5/9/2024 UNSEAT PKR LD 8' X 2-3/8" TBG SUB & 5.5" AD-1 PKR
5/9/2024 RD WORK FLOOR & ASSOCIATED EQUIP
5/9/2024 ND 5K HYD BOP, ND 5K X 3K X 7-1/16" SPOOL
5/9/2024 NU 3K X 7-1/16" B-1 WH FLANGE
MIRU AXIS ENERGY CMT BULK TRK LOAD BULK TRK W/ 350 SXS CLASS C CMT, RU CMT PUMP ON 5.5" PROD CSG
BREAK CIRC W/ 8 BBLS OF 10# BW 5TH PLUG) PERF @ 775' SQZ 205 SXS CLASS C CMT, 48.19 BBLS SLURRY,14.8#
1.32 YIELD, (PLUG CAP 838' / 19.44 BBLS / 82.69 SXS IN 5.5" PROD CSG) & (PLUG CAP 838' / 28.75 BBLS / 122.31
SXS OUT 8-5/8" INTER CSG) F/ 775' – 0' (SURF) GOT FULL RETURNS ON 8-5/8" INTER CSG CLOSE VALVE AND LEFT
500 PSI ON PROD CSG, WOC TOP OFF HOLE W/ CMT VERIFY CMT AT SURF / RU CMT PUMP ON THE 13-3/8" SURF –
CSG TRY TO PUMP CMT W/ NO LUCK 13-3/8" SURF – CSG PRESSURE UP TO 1000 PSI W/ NO LEAK OFF WASH UP
5/9/2024 PUMP & FLOW BACK PIT
5/9/2024 RDMO PU & P&A PUMP ASSOCIATED EQUIP, CLEAN LOC P&A JOB COMPLETED SDFN

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

# **State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
OXY USA INC	16696
P.O. Box 4294	Action Number:
Houston, TX 772104294	377861
	Action Type:
	[C-103] Sub. Plugging (C-103P)

#### CONDITIONS

Created By	Condition	Condition Date
kfortner	Accepted for record only BLM approval required NMOCD 8/27/24 KF	8/27/2024

CONDITIONS

Page 13 of 13

.

Action 377861