State Of New Mexico Energy, Minerals and Natural Resources Department

24-Oct-25

LONGFELLOW ENERGY, LP

Pre Enforcement Notification

8115 Preston Road Suite 800 Dallas, TX 75225

Dear Operator:

The following inspection indicates that the well, equipment, location or operational status of the well failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date indicated.

Please notify the Compliance Officer copied on this letter, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

[30-015-29260] JENNA COM #001		OGRID: 372210	I-05-17S-29E 2110 FSL 990 FE	-17S-29E 2110 FSL 990 FEL	
Inspection Date 10/23/2025	Type Inspection Routine Inspection	Inspector [RZH] Ronald Heuer	•	Inspection No. iRZH2529633505	
Violation		Title		Corrective Action Due	
cRZH2529735805 19.15.16.8 Sign on Wells Inaccurate Information			1/21/2026		
(FSL foot	age is incorrect. API cannot b	e read from at least 50 feet. U	Init Lot letter is incorrect.)		
cRZH2529735806 19.15.18.16 Tanks, Oil Tanks, Fire Walls and Tank Identification Tank identification missing or needs repaired				1/21/2026	
(TB sign	is unreadable from at least 50	feet.)			

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.