

30-015-42479

JUL 12 2019 PM01:55



United States Department of the Interior

BUREAU OF LAND MANAGEMENT
Wyoming State Office Reservoir Management Group
2987 Prospector Drive
Casper, Wyoming 82604-2968



In Reply Refer To:

3186

(3186.1)

Big Eddy Unit

NMNM68294X

XTO Energy Inc.

Attn: Greg Davis

EMHC.W4.4A.541

22777 Springwoods Village Pkwy

Spring, Texas 77389-1425

JUL 08 2019

Re: Paying Well Determination

Big Eddy Unit No. DI4 270H

SHL: NW $\frac{1}{4}$ NE $\frac{1}{4}$, Sec. 5, T.20S., R.31E. (NMLC68408)

BHL: SW $\frac{1}{4}$ NE $\frac{1}{4}$, Sec. 6, T.20S., R.31E. (NMLC68408)

Big Eddy Unit

Eddy County, New Mexico

Gentlemen:

We have determined that under existing conditions the Big Eddy Unit (BEU) No. DI4 270H well is **not** capable of producing unitized substances from the Bone Spring Formation in unit paying quantities. The well was completed in the Bone Spring Formation on October 30, 2014. Since the well was determined to be a nonpaying unit well, a drilling and spacing unit must be established for the well so that a communitization agreement can be approved by the New Mexico State Office.

If you have any questions, please call Lewis Tromp, Petroleum Engineer at (307) 261-7628.

Sincerely,

/s/ J. David Chase

J. David Chase

Chief, Reservoir Management Group

cc: CFO, Chris Walls
NMSO, James Glover