

**From:** [Kandis Roland](#)  
**To:** [McClure, Dean, EMNRD](#)  
**Cc:** [Mandi Walker](#)  
**Subject:** [EXTERNAL] SJ 29-5 Unit 70 30-039-21050 Fix Oil split  
**Date:** Thursday, May 26, 2022 7:03:01 AM  
**Attachments:** [image001.png](#)

**CAUTION:** This email originated outside of our organization. Exercise caution prior to clicking on links or opening attachments.

Dean,

Please see oil allocation for the SJ 29-5 Unit 70. Historically the DK never produced any oil therefore any oil production will be allocated to the MV.

Formation	Yield (bbl/MM)	Remaining Reserves (MMcf)	% Oil Allocation
DK	0	36	0%
MV	1.10	950	100%

Thanks,

Kandis Roland  
HILCORP ENERGY  
San Juan East/South Regulatory  
713.757.5246  
[kroland@hilcorp.com](mailto:kroland@hilcorp.com)

---

**From:** McClure, Dean, EMNRD <Dean.McClure@state.nm.us>  
**Sent:** Wednesday, May 25, 2022 5:32 PM  
**To:** Kandis Roland <kroland@hilcorp.com>  
**Cc:** Mandi Walker <mwalker@hilcorp.com>  
**Subject:** RE: [EXTERNAL] downhole commingling application DHC-5195

Kandis,

I do see 3 DHC approvals using the format of submittal without the fixed oil percentage clearly depicted in the summary. Within 2 of the 3 applications is included a statement that 100% of the oil would be allocated to a single pool which was sufficient. However, the 3<sup>rd</sup> application is lacking the fixed percent and I had mistakenly approved it. Please calculate and email me a fixed percent for the oil production for DHC-5174 which governs the commingling for San Juan 29 5 Unit #70 (30-039-21050).

For reference, the other 2 DHC approvals which I am referring to are DHC-5172 and DHC-5175 which each include a statement similar to the following within the application:

**Historically the Dakota formation has not produced any oil therefore all oil will be allocated to the Meaverde zone.**

Dean McClure  
Petroleum Engineer, Oil Conservation Division  
New Mexico Energy, Minerals and Natural Resources Department  
(505) 469-8211

above. If you are not an intended recipient or if you have received this message in error, you are hereby notified that any dissemination, distribution, or copy of this email is strictly prohibited. If you have received this email in error, please immediately notify us by return email or telephone if the sender's phone number is listed above, then promptly and permanently delete this message.

While all reasonable care has been taken to avoid the transmission of viruses, it is the responsibility of the recipient to ensure that the onward transmission, opening, or use of this message and any attachments will not adversely affect its systems or data. No responsibility is accepted by the company in this regard and the recipient should carry out such virus and other checks as it considers appropriate.

---