3- DATE IN	7-12 SUSPEN	
		NEW MEXICO OIL CONSERVATION DIVISION - Engineering Bureau - 1220 South St. Francis Drive Santa Eq. NM 87505 - Engineering Bureau -
		- Engineering Bureau - 1220 South St. Francis Drive, Santa Fe, NM 87505
		ADMINISTRATIVE APPLICATION CHECKLIST
	HIS CHECKLIST IS M	MANDATORY FOR ALL ADMINISTRATIVE APPLICATIONS FOR EXCEPTIONS TO DIVISION RULES AND REGULATIONS 656 WHICH REQUIRE PROCESSING AT THE DIVISION LEVEL IN SANTA FE
	[DHC-Dow [PC-Po	andard Location] [NSP-Non-Standard Proration Unit] [SD-Simultaneous Dedication] vnhole Commingling] [CTB-Lease Commingling] [PLC-Pool/Lease Commingling] ool Commingling] [OLS - Off-Lease Storage] [OLM-Off-Lease Measurement] [WFX-Waterflood Expansion] [PMX-Pressure Maintenance Expansion] [SWD-Salt Water Disposal] [IPI-Injection Pressure Increase] alified Enhanced Oil Recovery Certification] [PPR-Positive Production Response]
[1]	TYPE OF AI [A]	PPLICATION - Check Those Which Apply for [A] Location - Spacing Unit - Simultaneous Dedication NSL NSP SD
	Checl [B]	k One Only for [B] or [C] Commingling - Storage - Measurement DHC CTB PLC PC OLS OLM
	[C]	Injection - Disposal - Pressure Increase - Enhanced Oil Recovery
	[C] [D]	
[2]	[D]	🗍 WFX 🗍 PMX 🗍 SWD 🗌 IPI 🗌 EOR 🗍 PPR
[2]	[D] NOTIFICAT	WFX PMX SWD IPI EOR PPR Other: Specify
[2]	[D] NOTIFICAT [A]	WFX PMX SWD IPI EOR PPR Other: Specify
[2]	[D] NOTIFICAT [A] [B]	WFX PMX SWD IPI EOR PPR Other: Specify
[2]	[D] NOTIFICAT [A] [B] [C]	 WFX PMX SWD PMX BOULT IPI BOR PPR Other: Specify CION REQUIRED TO: - Check Those Which Apply, or Does Not Apply Working, Royalty or Overriding Royalty Interest Owners Offset Operators, Leaseholders or Surface Owner Application is One Which Requires Published Legal Notice Notification and/or Concurrent Approval by BLM or SLO

1

[4] **CERTIFICATION:** I hereby certify that the information submitted with this application for administrative approval is **accurate** and **complete** to the best of my knowledge. I also understand that **no action** will be taken on this application until the required information and notifications are submitted to the Division.

Note: Statement must be completed by an individual with managerial and/or supervisory capacity.

Print or Type Name	Signature	Title	Date
r. 195			
		e-mail Address	
	<u>بن</u>		

From:	Leslie Garvis [Igarvis@burnettoil.com]
Sent:	Tuesday, March 06, 2012 2:30 PM
То:	Brooks, David K., EMNRD
Cc:	Mark Jacoby
Subject:	Non Standard Location Exception Request for Gissler B #75 API # 30-015-39363
Attachments:	120306_OCD NSL Letter_ GB75.pdf; GisslerB75 Lease Map.pdf; Gissler B75 OCD C102.pdf

David,

As per our discussion yesterday, attached you will find our letter requesting non standard location approval for Gissler B #75. I have also attached a map showing our lease lines in this area along with our C-102. This well is currently down and will

be ready to go online by this Friday so any help you can give in expediting this approval would be greatly appreciated.

Please let me know if you have any questions or need any additional information.

Attachments: (3)

120306_OCD NSL Letter.pdf GisslerB75 Lease Map.pdf Gissler B75 OCD C102.pdf

Leslie M. Garvis Regulatory Coordinator Burnett Oil Co., Inc. Burnett Plaza-Suite 1500 801 Cherry Street - Unit #9 Fort Worth, TX 76102 Office: 817.332.5108 ext 6326 Fax: 817.332.2438 Email: lgarvis@burnettoil.com

6666

BURNETT OIL CO., INC.

06 March 2012

Mr. David Brooks New Mexico Oil Conservation Division 1220 South Saint Francis Drive Santa Fe, New Mexico 87504

Re: Gissler B #75 | Federal Lease # NMLC074939 Unit L, 1715' FSL, 1050' FWL SEC. 12, T17S, R30E – Eddy County, New Mexico API # 30-015-39363

Mr. Brooks:

Burnett Oil Co., Inc. respectfully requests an exception without notice and hearing to NMOCD Rule 104 for the Gissler B #75 (Cedar Lake Glorieta Yeso 96831).


The original location was moved by the BLM due to sand dunes. This location is only 60 feet unorthodox at the surface and only affects Burnett and no other lease holders. I have attached a map showing the Burnett lease in this area as well as a copy of our C-102.

Please contact me if you have any questions or need any additional information.

Thank you,

Jestie M. Garino

Leslie M. Garvis Regulatory Coordinator



DISTRICT I

DISTRICT IV

.

1625 N. French Dr., Hobbs, NM 88240

DISTRICT II 1301 W. Grand Avenue, Artesia, NM 88210

DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy, Minerals and Natural Resources Department

Form C-102 Revised July 16, 2010

Submit one copy to appropriate District Office


OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, New Mexico 87505


□ AMENDED REPORT WELL LOCATION AND ACREAGE DEDICATION PLAT Pool Name API Number Pool Code 0-015-39363 7.7/ La Cen ' CS () Ta OVIE **Property Code** Well Number Property Name 2389 GISSLER "B' 75 OGRID No. **Operator** Name Elevation 3752' 7080 BURNETT OIL COMPANY, INC. Surface Location UL or lot No. Section Lot Idn Township Range Feet from the North/South line Feet from the East/West line County 17 S 12 30 E 1715 SOUTH 1050 WEST EDDY L Bottom Hole Location If Different From Surface UL or lot No. Range Lot Idn Feet from the North/South line County Section Township Feet from the East/West line


Dedicated Acres	Joint or Infill	Consolidation Code	Order No.	

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

	· · · ·	
	 	 OPERATOR CERTIFICATION I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the location or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.
	 ·	Signature Date
	Ý/A I	Printed Name
a solution		Email Address SURVEYOR CERTIFICATION
	+- 	 I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervison and that the same is true and correct to the boot of my belief.
3746.9 <u>SURFACE_LOCATION</u> Lat - N 32.846383201* Long - W 103.930092467* NMSPCE-N 671845.811 NMSPCE-N 671845.811 E 623852.761 (NAD-27)		 Signeturs & Seal of Professional Supersor Barenson Supersor Barenson Superson Barenson Superson Barenson Barenson Superson Barenson Superson Barenson Superson Barens
		Certificate No. Gary L. Jones 7977 BASIN SURVEYS 24416









GISSLER "B" #75 Located 1715' FSL and 1050' FWL Section 12, Township 17 South, Range 30 East, N.M.P.M., Eddy County, New Mexico.

I Ares	P.O. Box 1786	W.O. Number: KJG 24416
	1120 N. West County Rd. Hobbs, New Mexico 88241	Survey Date: 04-16-201
BUILAGAD	(575) 393-7316 - Office (575) 392-2206 - Fax	Scale: 1" = 2000'
focused on excellence	basinsurveys.com	Date: 05-20-2011








GISSLER "B" #75 Located 1715' FSL and 1050' FWL Section 12, Township 17 South, Range 30 East, N.M.P.M., Eddy County, New Mexico.



P.O. Box 1786	
1120 N. West Coun	ty Rd.
Hobbs, New Mexico	88241
(575) 393-7316 -	Office
(575) 392-2206 -	Fax
basinsurveys.com	

W.O. Number: KJG 24416 Scale: 1" = 2000' YELLOW TINT - USA LAND BLUE TINT - STATE LAND NATURAL COLOR - FEE LAND





From:Brooks, David K., EMNRDSent:Wednesday, March 07, 2012 3:54 PMTo:'Leslie Garvis'Subject:RE: Non Standard Location Exception Request for Gissler B #75 | API # 30-015-39363

Dear Ms. Gravis

In order to determine if notice is required for this application, I need to know if Burnett owns 100% of the working interest in the subject lease, and, if not, if working interest ownership is identical between Units L and M of Section 12-17S-30E.

Sincerely

David K. Brooks

From: Leslie Garvis [mailto:lgarvis@burnettoil.com]
Sent: Tuesday, March 06, 2012 2:30 PM
To: Brooks, David K., EMNRD
Cc: Mark Jacoby
Subject: Non Standard Location Exception Request for Gissler B #75 | API # 30-015-39363

David,

As per our discussion yesterday, attached you will find our letter requesting non standard location approval for Gissler B #75. I have also attached a map showing our lease lines in this area along with our C-102. This well is currently down and will

be ready to go online by this Friday so any help you can give in expediting this approval would be greatly appreciated.

Please let me know if you have any questions or need any additional information.

Attachments: (3)

120306_OCD NSL Letter.pdf GisslerB75 Lease Map.pdf Gissler B75 OCD C102.pdf

Leslie M. Garvis Regulatory Coordinator Burnett Oil Co., Inc. Burnett Plaza-Suite 1500 801 Cherry Street - Unit #9 Fort Worth, TX 76102 Office: 817.332.5108 ext 6326 Fax: 817.332.2438 Email: lgarvis@burnettoil.com

From:Brooks, David K., EMNRDSent:Wednesday, March 07, 2012 3:59 PMTo:'Leslie Garvis'Subject:FW: Non Standard Location Exception Request for Gissler B #75 | API # 30-015-39363

Correction: I should have inquired about working interest ownership of Units K and L. The location does not encroach toward Unit M.

From: Brooks, David K., EMNRD
Sent: Wednesday, March 07, 2012 3:54 PM
To: 'Leslie Garvis'
Subject: RE: Non Standard Location Exception Request for Gissler B #75 | API # 30-015-39363

Dear Ms. Gravis

In order to determine if notice is required for this application, I need to know if Burnett owns 100% of the working interest in the subject lease, and, if not, if working interest ownership is identical between Units L and M of Section 12-17S-30E.

Sincerely

David K. Brooks

From: Leslie Garvis [mailto:lgarvis@burnettoil.com]
Sent: Tuesday, March 06, 2012 2:30 PM
To: Brooks, David K., EMNRD
Cc: Mark Jacoby
Subject: Non Standard Location Exception Request for Gissler B #75 | API # 30-015-39363

David,

As per our discussion yesterday, attached you will find our letter requesting non standard location approval for Gissler B #75. I have also attached a map showing our lease lines in this area along with our C-102. This well is currently down and will

be ready to go online by this Friday so any help you can give in expediting this approval would be greatly appreciated.

Please let me know if you have any questions or need any additional information.

Attachments: (3)

120306_OCD NSL Letter.pdf GisslerB75 Lease Map.pdf Gissler B75 OCD C102.pdf

Leslie M. Garvis Regulatory Coordinator Burnett Oil Co., Inc. Burnett Plaza-Suite 1500 801 Cherry Street - Unit #9 Fort Worth, TX 76102 Office: 817.332.5108 ext 6326 Fax: 817.332.2438 Email: <u>lgarvis@burnettoil.com</u>

.

2

.

.

From: Sent: To: Cc: Subject: Leslie Garvis [Igarvis@burnettoil.com] Thursday, March 08, 2012 2:51 PM Brooks, David K., EMNRD Mark Jacoby RE: Non Standard Location Exception Request for Gissler B #75 | API # 30-015-39363

David,

Burnett does not own 100% but I have confirmed that yes the working interest in Units K & L are identical.

Please let me know if you need any additional information.

Thank you,

Leslie M. Garvis Regulatory Coordinator Burnett Oil Co., Inc. Burnett Plaza-Suite 1500 801 Cherry Street - Unit #9 Fort Worth, TX 76102 Office: 817.332.5108 ext 6326 Fax: 817.332.2438 Email: lgarvis@burnettoil.com

From: Brooks, David K., EMNRD [mailto:david.brooks@state.nm.us]
Sent: Wednesday, March 07, 2012 4:59 PM
To: Leslie Garvis
Subject: FW: Non Standard Location Exception Request for Gissler B #75 | API # 30-015-39363

Correction: I should have inquired about working interest ownership of Units K and L. The location does not encroach toward Unit M.

From: Brooks, David K., EMNRD
Sent: Wednesday, March 07, 2012 3:54 PM
To: 'Leslie Garvis'
Subject: RE: Non Standard Location Exception Request for Gissler B #75 | API # 30-015-39363

Dear Ms. Gravis

In order to determine if notice is required for this application, I need to know if Burnett owns 100% of the working interest in the subject lease, and, if not, if working interest ownership is identical between Units L and M of Section 12-17S-30E.

Sincerely

David K. Brooks

To: Brooks, David K., EMNRD
 Cc: Mark Jacoby
 Subject: Non Standard Location Exception Request for Gissler B #75 | API # 30-015-39363

David,

-

As per our discussion yesterday, attached you will find our letter requesting non standard location approval for Gissler B #75. I have also attached a map showing our lease lines in this area along with our C-102. This well is currently down and will

be ready to go online by this Friday so any help you can give in expediting this approval would be greatly appreciated.

Please let me know if you have any questions or need any additional information.

Attachments: (3)

120306_OCD NSL Letter.pdf GisslerB75 Lease Map.pdf Gissler B75 OCD C102.pdf

Leslie M. Garvis Regulatory Coordinator Burnett Oil Co., Inc. Burnett Plaza-Suite 1500 801 Cherry Street - Unit #9 Fort Worth, TX 76102 Office: 817.332.5108 ext 6326 Fax: 817.332.2438 Email: lgarvis@burnettoil.com