

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

*nJMW1232631225*

Name of Company <b>OXY USA Inc.</b> <i>16696</i>		OPERATOR	<input type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Address <b>1017 W. Stanolind Rd.</b>		Contact <b>Leslie V. Moreno</b>		
Facility Name <b>Sterling Silver 33 #2</b>		Telephone No. <b>(575) 397-8247</b>		
		Facility Type <b>Production Battery</b>		

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	33	23S	31E					Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release <b>Flare</b>	Volume of Release <b>170 MCF</b>	Volume Recovered <b>0</b>
Source of Release <b>Temp. Flare</b>	Date and Hour of Occurrence <b>8/7/11 @ 2400 hrs to 8/11/11 @ 1200 hrs</b>	Date and Hour of Discovery <b>8/7/11 @ 0600 hrs</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Mike Bratcher</b>	
By Whom? <b>Leslie V. Moreno, HES Administrative Assistant</b>	Date and Hour <b>8/12/11 @ 10:57 am</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <b>n/a</b>	

If a Watercourse was Impacted, Describe Fully.\* **n/a**

Describe Cause of Problem and Remedial Action Taken.\* **Oxy began flaring on 8/7/11 due to DCP shut down because their Pure Gold Booster is down for repair, they are changing out the motor.**

**RECEIVED**  
 SEP 29 2011  
**NMOCD ARTESIA**

Describe Area Affected and Cleanup Action Taken.\*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Leslie V. Moreno</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Leslie V. Moreno</b>	Approved by District Supervisor:	<b>Accepted for record NMOCD</b>
Title: <b>HES Administrative Assistant</b>	Approval Date:	Expiration Date:
E-mail Address: <b>Leslie_Moreno@oxy.com</b>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <b>9/25/11</b>	Phone: <b>(575) 397-8247</b>	

\* Attach Additional Sheets If Necessary

*2RP-1411*

**Moreno, Leslie V (Office Team )**

---

**From:** Moreno, Leslie V (Office Team )  
**Sent:** Friday, August 12, 2011 10:57 AM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Summers, Chancey J; Wilson, Dusty L; Moreno, Leslie V (Office Team )  
**Subject:** 8/7/11 Venting

Hello Mr. Bratcher,

We began venting on 8/7/11 due to DCP shut down because their Pure Gold Booster is down for repair, they are changing out the motor. So far, here are the locations & what has been vented:

FNR 26 -1	75 MCF
Patton 18-1	496 MCF
Nimitz 13-1	75 MCF
Palladium 7-1	1200 MCF
Sundance 8-1	425 MCF
Sunrise 8-3	85 MCF
Sterling Silver 3-6	470 MCF
Sterling Silver 34-2	88 MCF
Sterling Silver 33-2	170 MCF
Sterling Silver 33 CTB	1174 MCF
Federal 29-8	1200 MCF
Mobil Federal #1	439 MCF

Thank you,

Leslie V. Moreno  
HES Administrative Assistant  
OXY Permian  
1017 W. Stanolind Rd.  
Office: (575) 397-8247  
Cell: (575) 605-5100  
Fax: (575) 397-8234