<u>District 1</u> 1625 N. French Dr., Hobbs, NM 88240 <u>District 11</u> 1301 W. Grand Avenue, Artesia, NM 88210 Di 10 Di 12

State of New Mexico Energy Minerals and Natural Resources

RECEIVED

Form C-141 Revised October 10, 2003

1

1301 W. Grand Avenue, Artesia, NM 88210 <u>District III</u> 1000 Rio Brazos Road, Aztec, NM 87410 <u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505 Release MMW 1309933732	Notification	vation Div St. France NM 875 and Co OPERAT	vision is Dr. 05 orrective A FOR	NMO			October 10, 2003 es to appropriate ce in accordance ute 116 on back side of form	
			Contact Natalie Gladden Telephone No. 575-390-4186					
Facility Name NB Tween #25			e Production W					
Surface Owner Unknown Mineral Owner S			State Lease No. 30-015-39075					
	LOCATION	N OF REI	LEASE					
Unit Letter Section Township Range Feet from the North/S			South Line Feet from the East/West Line County					
C 25 17S 28E 990' FNL			2120'	FWL		Eddy		
Latitude	<u> </u>	Longitud	e					
	NATURE	OF REL	EASE					
Type of Release Oil and Produced Water						lume Recovered 60		
Source of Release Flowback			Date and Hour of OccurrenceDate and H07/18/1207/18/12			lour of Discovery		
Was Immediate Notice Given?			If YES, To Whom? Mike Bratcher					
By Whom? Natalie Gladden			Date and Hour 07/19/12					
Was a Watercourse Reached?			If YES, Volume Impacting the Watercourse.					
If a Watercourse was Impacted, Describe Fully,*		1					•	
Describe Cause of Problem and Remedial Action Take Well flowed back during a work-over procedure to pul								
Describe Area Affected and Cleanup Action Taken.*					<u></u>			
Once the pulling unit moves off of the location, remedi	_							
I hereby certify that the information given above is true regulations all operators are required to report and/or fi public health or the environment. The acceptance of a should their operations have failed to adequately invest or the environment. In addition, NMOCD acceptance of federal, state, op-local laws and/or regulations.	le certain release no C-141 report by the igate and remediate	otifications ar NMOCD ma e contamination	ad perform correct arked as "Final Ro on that pose a three the operator of r	tive acti eport" d eat to gr responsi	ons for rele oes not reli ound water bility for co	eases which may eve the operator , surface water, ompliance with a	rendanger of liability human health	
			OIL CONSERVATION DIVISION					
Signature: Atalu Stolder			Approved by District Supervisor: Signed By Mile Banance					
Printed Name: Natalic Gladden			District Supervise	or: Sign	ed By 🗡	Vila Bren	and m	
,			YK N 8 201	3	Expiration I	Date:		
E-mail Address: natalie.gladdcu@apachecorp.com		Approval Dat						
	\				8 ,	Attached 🗌		
Date: 07/19/12 Phone: 575-390-4186 * Attach Additional Sheets If Necessary	Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THANK							
	N		AL NO LATER			ZRT-	1600	

Release Notifications

Warren, JeanMarie, EMNRD Sent: Tuesday, March¹ 26, 2013 10:03 AM To: Natalie.Gladden@apachecorp.com Cc: Bratcher, Mike, EMNRD

To whom it may concern,

I am writing to you on behalf of Mike Bratcher. We are attempting to follow up regarding a few release notifications that was given to our office, by you, on: 1/22/2013, 12/10/2012, 10/01/2012, 07/19/2012, 06/14/2012, 05/23/2012

Release Date/Location:

- 1/21/2013, Raven 12 H
- 12/09/2012, Tony Federal #46
- No specific Date, D state Btry (closest well #21).
- 7/18/2012, NB Tween #25
- 6/10/2012; Empire ABO Unit G312
- 5/23/2012, Tony Federal Btry (Tony Federal #10)

We have no record of having received an initial C-141, please advise the status of this release and submit an initial C-141 to Mr. Bratcher.

Thank you for your time.

ł

Respectfully,

Jean-Marie Warren Business Operations Specialist NM-OCD District II, Artesia (575) 748-1283, ext[.] 101 C141 Gladden, Natalie [Natalie.Gladden@apachecorp.com] Sent: Tuesday, March 26, 2013 3:04 PM To: Warren, JeanMarie, EMNRD Cc: Bratcher, Mike, EMNRD Attachments: 20130326155559088.pdf (440 KB)

Here you go. If you need me to put them back in the mail, I can do that also.

Natalie Gladden Apache Corporation Sr. Environmental Tech New Mexico District Cell: 575-390-4186 Office: 575-394-1503 x 1258 Fax: 575-394-2425 Email: natalie.gladden@apachecorp.com

----Original Message-----From: ricoh.service@apachecorp.com [<u>mailto:ricoh.service@apachecorp.com</u>] Sent: Tuesday, March 26, 2013 2:56 PM To: Gladden Natalie

This E-mail was sent from "mideunr33511" (Aficio MP 3351).

Scan Date: 03.26.2013 15:55:58 (-0400) Queries to: ricoh.service@apachecorp.com

Bratcher, Mike, EMNRD

From:	Gladden, Natalie [Natalie.Gladden@apachecorp.com]
Sent:	Thursday, July 19, 2012 6:35 AM
To:	Bratcher, Mike, EMNRD
Subject:	FW: Reportable Release on the NB Tween #25
Attachments:	Internal Incident Report for NB Tween #25 071812.docx

Importance:

High

Attached you will find the information concerning the NB Tween #25 release from yesterday.

30-015-39075 C-25-17S-28E 990' FNL and 2120' FWL

C141 to follow.

Natalie Gladder

Apache Corporation EHS Environmental Tech New Mexico District Cell: 575-390-4186 Office: 575-394-1503 x 1258 Fax: 575-394-2425 Email: <u>natalie.gladden@apachecorp.com</u>

From: Gladden, Natalie
Sent: Wednesday, July 18, 2012 4:23 PM
To: Mills, Clinton; Cox, Rodney; Stockton, Billy; Bruton, Marcus; Carnes, Travis (<u>Travis.Carnes@usa.apachecorp.com</u>)
Cc: Herring, Lawana; Martinez, Xavier; Blackmon, Leland
Subject: Reportable Release on the NB Tween #25
Importance: High

Hobbs/Loco Hills Area Craig Maxwell 07/18/2012 NB Tween #25 Well flowed back during a work-over procedure to pull stuck tubing. 20bbls of oil and 60bbls of produced water was released 15bbls of oil and 45bbls of produced water was recovered Well was killed and fluid was recovered. On and off location Little clearance between wash pipe and the casing, for water to flow down-hole to send the well on vacuum.

Natalie Gladdex

Apache Corporation EHS Environmental Tech New Mexico District Cell: 575-390-4186 Office: 575-394-1503 x 1258 Fax: 575-394-2425 Email: <u>natalie.gladden@apachecorp.com</u>

÷



Internal Incident Report - Spill/Release - Reportable Release

{

Location: NB Tween State #25

Production Area: Hobbs (Loco Hills)

District: Eunice

Date: 07/18/12

Time: 12:19pm

One Line Summary: Well flowed back during a work-over procedure to pull stuck tubing.

Full summary: A pulling unit was on the well trying to pull stuck tubing. Due to a close fit between the casing and the wash pipe, the well did not go on vacuum. The wellhead pressure was 30#, which bled down instantly. 4700' of tubing was pulled out of the hole first thing this morning. When they started picking up the wash pipe, with three joints in, the well started flowing without any warning. They were unable to kill the well with produced water. To close the BOP they dropped the wash pipe in the hole. 20bbls of oil and 60bbls of produced water was released onto the location, with a light spray in the pasture area. Approximately 15bbls of oil and 45bbls of produced water was recovered.

Root cause of incident:

1. Little clearance between wash pipe and the casing, for water to flow down-hole to send the well on a vacuum.

Corrective Actions:

- 1. Pump a good amount of kill fluid before running wash pipe or drill collars.
- 2. Possibly start using a high-drill BOP to close around the pipe.

Reported by: Natalie Gladden

