


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised October 10, 2003

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC

**Release Notification and Corrective Action**

*NAB14237884*

**OPERATOR**

Initial Report  Final Report

Name of Company: Linn Operating <i>219324</i>	Contact: Brian Wall
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: Turner B 42	Facility Type: Injection

Surface Owner: Federal	Mineral Owner:	API No.: 30-015-05278
------------------------	----------------	-----------------------

**LOCATION OF RELEASE**

Unit Letter E	Section 20	Township 17S	Range 31E	Feet from the 1650	North/South Line NORTH	Feet from the 330	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

**Latitude:** 32.8227472670828 **Longitude:** -103.899441688941

**NATURE OF RELEASE**

Type of Release: Produced Water	Volume of Release: 120 bbls	Volume Recovered: 100 bbls
Source of Release: 4" fiber glass pipeline	Date and Hour of Occurrence: 07/31/2014	Date and Hour of Discovery: 07/31/2014 11:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jeff Robertson-BLM / Mike Bratcher- NM OCD	
By Whom? Brian Wall	Date and Hour 08/11/2014 1030 written	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*:

Describe Cause of Problem and Remedial Action Taken.\*: 4" injection trunk line blew out on a 45. Probable cause was possibly from running Quintiplex injection pump. This pump has more pulsation on the lines versus the horizontal pump which has no pulsation effect on the lines.

Describe Area Affected and Cleanup Action Taken.\* :  
Directions to Site: From Loco Hills go east 4.5 miles to cattle guard on north side of road. T/L go 2/10 mile, T/L go 100 ft. to leak on left

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Brian Wall</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Brian Wall	Signed By: <i>Mike Bratcher</i> Approved by District Supervisor.	
Title: Construction Foreman II	Approval Date: <i>8/25/14</i>	Expiration Date: <i>NIA</i>
E-mail Address: bwall@linenergy.com Date: 08/18/2014 Phone: 806-367-0645	Conditions of Approval: Remediation per OCD Rule & Guidelines. <b>SUBMIT REMEDIATION</b> <b>PROPOSAL NO LATER THAN:</b> <i>9/25/14</i>	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

*2RP-2456*

## **Patterson, Heather, EMNRD**

---

**From:** Rebecca Pons <rpons@diversifiedfsi.com>  
**Sent:** Monday, August 25, 2014 9:06 AM  
**To:** Patterson, Heather, EMNRD  
**Subject:** Emailing: Turner B 42 7-31-14  
**Attachments:** Turner B 42 7-31-14.pdf

Good Morning,

Could you check to see if you have this C-141 filed on the NMOCD website? If you have it could you please email the RP number that you have assigned to this location? DFSI has started remediation efforts on the C-141 associated with this spill. Please advise me.

Thank you and have a great Monday!

Rebecca Pons  
Project Scientist  
DFSI Environmental Division  
Phone (575)964-8394

The information contained in this e-mail message is intended only for the personal and confidential use of the recipients(s) named above. If the reader of this message is not the intended recipient or an agent responsible for delivering it to the intended recipient, you are hereby notified that you have received this document in error and that any review, dissemination, distribution, or copying of this message is strictly prohibited. If you have received this communication in error, please notify us immediately by e-mail, and delete the original message.

Your message is ready to be sent with the following file or link attachments:

Turner B 42 7-31-14

Note: To protect against computer viruses, e-mail programs may prevent sending or receiving certain types of file attachments. Check your e-mail security settings to determine how attachments are handled.