Stogner, Michael, EMNRD

From:Mull, Donna, EMNRDTo:Stogner, Michael, EMNRDCc:RE: NSL-5346(SD)Attachments:

Sent: Tue 3/21/2006 9:47 AM

You are correct. I must have looked at the pool map wrong that day. Thanks again. Have a nice day. Donna

From: Stogner, Michael, EMNRD Sent: Thu 3/16/2006 4:20 PM To: Mull, Donna, EMNRD; Williams, Lana Cc: Williams, Chris, EMNRD; Jim Bruce; Kautz, Paul, EMNRD; Williams, Chris, EMNRD Subject: RE: NSL-5346(SD)

Donna:

Has there been a nomenclature change to the San Andres formation in the N/2 of Sec. 4-T22S-R37E that I'm not aware of?

In reviewing Apache Corporation's application and preparing the subject administrative order, I found that: (i) the NE/4 of Sec. 4 is within the Eunice-San Andres Pool (24150) boundary (see Division Nomenclature Order No. R-11818); and (ii) the NW/4 of Section 4 is within the Southwest Eunice-San Andres Pool (24180) boundary (see Division Nomenclature Order No. R-11728).

Instead of the Division correcting Division Administrative Order NSL-5446 (SD). Shouldn't Apache Corporation be amending their APD and C-102 for the Rinewalt Well No. (30-025-37750) showing the correct pool?

cc File: NSL-5446 (SD)

From: Mull, Donna, EMNRD Sent: Wed 3/15/2006 8:07 AM To: Williams, Lana Cc: Stogner, Michael, EMNRD; Williams, Chris, EMNRD Subject: NSL-5346(SD)

Lana, Apache needs to send Mike Stogner, OCD Santa Fe a correction on the NSL-5446(SD). Location of this well will not be in the Southwest Eunice-San Andres (24180). But will be in the Eunice San Andres (24150).

Thank you, Donna