District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

| Release Notification and Corrective Action | | | | | | | | | | | |
|---|--------------|----------------|-------------|--|----------------------------|--|-------------------|----------------|----------------|-------------------------|--------------|
| nabl | 5279. | 24509 | | .30301 | 20 | OPERA? | OR | ∀ : | nitial Report | | Final Report |
| | | | | | Contact Heather Dolphin | | | | | | |
| | | | | | Telephone No. 832-797-1334 | | | | | | |
| Facility Name Loco Hills A Federal No.2 | | | | | Facility Type Well | | | | | | |
| Surface Owner Mineral Owner | | | | API No. 30-015-20536 | | | | | | | |
| LOCATION OF RELEASE | | | | | | | | | | | |
| Unit Letter | Section | Township | Range | Feet from the | North/ | South Line | Feet from the | East/West L | ne County | | |
| N | 10 | 17S | 30E | | | | | | Eddy | | |
| · | - | | Lai | itude 32 8436 | 317 | Longitud | e -103 961998 | } | | | |
| Latitude 32.8436317 Longitude -103.961998 | | | | | | | | | | | |
| Type of Release Produced Water Volume of Release 25bbl Volume Recovered 0bbl | | | | | | | | | | | |
| Source of Re | | eu water | | | | | our of Occurrence | | | | 12:00 pm |
| Was Immedia | | iven? | | | | If YES, To | | 03/20/10000 | and Hour of Di | 300 101 9 | <u> </u> |
| 1 | | | Yes 🗌 | No 🔲 Not Re | quired | | | | | | |
| By Whom? I | Heather Do | olphin | | | | • | our 6/25/15 B: | | | | _ |
| Was a Water | | | | | | If YES, Volume Impacting the Watercourse. | | | | | |
| | | | Yes 🔽 | No | | n/a | | | | | |
| If a Watercou | ırse was Im | pacted, Descri | be Fully.* | • | | • | | | | | |
| n/a | | | | | | | | A 184 OII | CONSERV | ΑΤΙΩΝ | L |
| | | | | | | | | MM OIL | ESIA DISTRIC | T | - |
| Describe Cau | ise of Probl | em and Reme | lial Action | ı Taken * | | | | | T 0 5 2015 | | |
| | | | | on, line is buried | l A' dee | n Renlacer | l line | U |) (() ZOI | , | |
| Infection line | developed | a noic duc | io comos | on, and is build | 14 066 | p. Nepiacec | inte. | | | | |
| | | | | | | | | 1 | RECEIVED | | |
| B. | | and Cleanup A | | | | | | | | | |
| 60' x '1 with 10' pool at end in the pasture. Waiting on clean-up instructions from OCD/ BLM | | | | | | | | | | | |
| | | | | | | | | | | | |
| I harabu carti | for that the | nformation of | uan ahaya | is true and comp | lata to th | a bact of my | knowledge and | inderstand the | murauant to NI | MOCD ** | ulan and |
| | | | | is true and comp id/or file certain r | | | | | | | |
| | | | | | | | | | | | |
| public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health | | | | | | | | | | | |
| or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. | | | | | | | | | | | |
| rederal, state. | or local la | ws and/or regu | nacions. | | 1 | • | OIL CON | SERVATI | ON DIVISI | JAO | |
| 15 | · -4 | <u> </u> | | 1 | 1 | | OIL CON | OLKVAII | / DIVIS |) (*) (*) | |
| Signature. | 7 | -7 \- | | | | | | / | / / | | |
| Printed Name | e: Heather | Dolphin | | • | | Approved by | Environmental S | Specialist: | my | 2 | |
| Title: Sr. Re | enulatory S | Specialist | | | | Approval Da | 10/10/1 | 5 5000 | ation Date: | IIA | |
| | | • | | | | | | - Teyhir | mon Date. | .,,, | |
| E-mail Addre | ess: neathe | er.dolphin@n | nemorialr | o.com | | Conditions o | | صمان | Attach | ed 🗌 | |
| Date: 10/5/15 Phone: 832-797-1334 Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO | | | | | | | | | | | |
| Attach Addi | tional She | ets If Necess | ary | - | | ER THAN | | 15 | NU | 20 | D-3316 |

A the same of the same of the same

• • •

And the second of the second o

Patterson, Heather, EMNRD

From: Heather Dolphin < heather.dolphin@memorialrd.com>

Sent: Monday, October 05, 2015 4:32 PM

To: Arias, Arthur, Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; Tucker, Shelly

Subject: RE: Memorial Burnham Battery Spill

Attachments: Loco Hills Injection Line C-141 25bbls PW 09-25-15.pdf

Please find attached the C-141 for the spill at the Loco Hills #2.

Please note I had the location name incorrect below.

Heather Dolphin

Sr. Regulatory Specialist
Memorial Resource Development Corp.
500 Dallas Street, Suite 1800
Houston, TX 77002
Direct (832) 408-8603
Mobile (832)-797-1334
Main (713) 588-8300
Fax (713) 588-8301
heather.dolphin@memorialrd.com

Click here for Memorial Resource Development's Electronic Mail Disclaimer

From: Arias, Arthur [mailto:aaarias@blm.gov]
Sent: Monday, September 28, 2015 8:16 AM

To: Heather Dolphin <heather.dolphin@memorialrd.com>

Subject: Re: Memorial Burnham Battery Spill

Thank you,, also all spills can go directly to <u>stucker@blm.gov</u> she is the primary contact for spills in our office but they can b e-mail to me as well. thanks for keep us updated....

Arthur Arias
aaarias@blm.gov
Environmental Protection Specialist
Bureau Of Land Management, Carlsbad Field Office
575-234-6230 Cell 575-499-3378

On Fri, Sep 25, 2015 at 7:36 PM, Heather Dolphin < heather.dolphin@memorialrd.com > wrote:

Memorial had a hole in the injection line coming from the Burnham Battery to the KLM well. Approx 10bbls PW spilled in the pasture, about 90yards x 2' soaked into the sand immediately. I will follow-up with a C-141 on Monday.

• · (Heather Dolphin
Sr. Regulatory Specialist
Memorial Resource Development Corp.
500 Dallas Street, Suite 1800
Houston, TX 77002
Direct (832) 408-8603
Mobile (832)-797-1334
Main (713) 588-8300
Fax (713) 588-8301
heather.dolphin@memorialrd.com

| | | | • | |
|---|--|--|---|---|
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| · | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | • | |
| | | | | |
| | | | | • |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |

Patterson, Heather, EMNRD

From: Heather Dolphin <heather.dolphin@memorialrd.com>

Sent: Friday, September 25, 2015 7:36 PM **To:** Patterson, Heather, EMNRD; Art Arias

Subject: Memorial Burnham Battery Spill

Memorial had a hole in the injection line coming from the Burnham Battery to the KLM well. Approx 10bbls PW spilled in the pasture, about 90yards x 2' soaked into the sand immediately. I will follow-up with a C-141 on Monday.

Heather Dolphin
Sr. Regulatory Specialist
Memorial Resource Development Corp.
500 Dallas Street, Suite 1800
Houston, TX 77002
Direct (832) 408-8603
Mobile (832)-797-1334
Main (713) 588-8300
Fax (713) 588-8301
heather.dolphin@memorialrd.com

| • | | |
|---|--|--|
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |