

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141  
Revised August 8, 2011

DEC 31 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NABIL00557588 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Cedar Canyon 28 Federal #6	Facility Type	New drill pad

Surface Owner	BLM	Mineral Owner		API No.	30-015-43234
---------------	-----	---------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	28	24S	29E					Eddy County, NM

Latitude N 32.18604° Longitude W 103.98119°

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	215 bbls	Volume Recovered	117 bbls
Source of Release	Manhole cover on rental frac tank was left untightened	Date and Hour of Occurrence	12/20/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson-NMOCD; Shelly Tucker-BLM		
By Whom?	Kathy Purvis @ BBC International	Date and Hour	12/21/2015 @ 1:02 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The manhole cover on a rental frac tank was left untightened spilling 215 bbls of oil onto the ground. A vacuum truck recovered 117 bbls of oil and the manhole cover was tightened.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 200' x 200' on location. Remediation will be completed in accordance with a remediation plan approved by both NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Casey Summers</u>	OIL CONSERVATION DIVISION	
Printed Name: Casey Summers	Approved by Environmental Specialist: <u>[Signature]</u>	
Title: NM Environmental Advisor	Approval Date: <u>1/5/16</u>	Expiration Date: <u>NA</u>
E-mail Address: <u>Casey.Summers@oxy.com</u>	Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> <b>SUBMIT REMEDIATION PROPOSAL NO LATER THAN: <u>2/15/16</u></b>	
Date: <u>12/30/15</u> Phone: (575) 513-8289		

\* Attach Additional Sheets If Necessary

2RP-3472

**Patterson, Heather, EMNRD**

---

**From:** Kathy Purvis <kathy@bbcinternational.com>  
**Sent:** Wednesday, December 30, 2015 4:43 PM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; stucker@blm.gov  
**Cc:** Casey\_Summers@oxy.com; dusty\_wilson@oxy.com; Jennifer\_duarte@oxy.com;  
frank\_barnett@oxy.com; cbrunson@bbcinternational.com;  
kswinney@bbcinternational.com; jgilkey@bbcinternational.com  
**Subject:** Initial C-141s for McKittrick Hills CTB and Cedar Canyon 28 Federal #6  
**Attachments:** Initial C-141, McKittrick Hills CTB.pdf; Initial C-141, Cedar Canyon 28 Federal #6.pdf

Attached are the initial C-141s for two leaks occurring at the McKittrick Hills CTB on 12/09/2015 and the Cedar Canyon 28 Federal #6 on 12/20/2015 in Eddy County, NM. Receipt notification via email is greatly appreciated.

*Kathy Purvis*

BBC International, Inc.  
1324 W. Marland  
Hobbs, NM 88240  
Phone: (575) 397-6388  
Fax: (575) 397-0397  
Email: [kathy@bbcinternational.com](mailto:kathy@bbcinternational.com)

**Patterson, Heather, EMNRD**

---

**From:** Kathy Purvis <kathy@bbcinternational.com>  
**Sent:** Monday, December 21, 2015 1:02 PM  
**To:** Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD; stucker@blm.gov  
**Cc:** Casey\_Summers@oxy.com; dusty\_wilson@oxy.com; cbrunson@bbcinternational.com; kswinney@bbcinternational.com; jgilkey@bbcinternational.com; Jennifer\_duarte@oxy.com; frank\_barnett@oxy.com  
**Subject:** Cedar Canyon 28 Federal #6

This is to inform you that Oxy Permian had a leak at the Cedar Canyon 28 Federal #6 (new drill pad) on the evening of December 20, 2015. Oxy spilled 215 bbls of oil due to a manhole cover being left untightened on the rental frac tank. The preliminary report shows the leak measuring approximately 200' x 200' on location. Fluid recovery is in progress. The release is located in the southwest of Section 28, T24S, R29E of Eddy County, NM. BBC International will delineate/remediate the location at a later date and an initial C-141 will follow. Driving directions: From Malaga, go East on Duarte Rd, turn right on McDonald Rd and go 4.5 miles to the last location on the right before the river crossing. API number and GPS coordinates are not available at this time.

*Kathy Purvis*

BBC International, Inc.

1324 W. Marland

Hobbs, NM 88240

Phone: (575) 397-6388

Fax: (575) 397-0397

Email: [kathy@bbcinternational.com](mailto:kathy@bbcinternational.com)