. ·

Additional data for EC transaction #57174 that would not fit on the form

32. Additional remarks, continued

11/03/2007 RAN MIT TEST TO 420# FOR 30 MINUTES - OK. CLEAN LOCATION, RDMO.

RETURN WELL TO INJECTION.

ATTACHED: WORKOVER PROCEDURE

(CHK PN 891189)

