
DATE	25/07	SUSPENSE	BIDOKS	1162-8/0	7 NSL	RAPP NO.	R07332	14/602
· .		NI	EW MEXICO OIL (- Engin 1220 South St. Franc	eering Bureau -	ON DIVISION	H	BC Open Cambio 5737	ating, INC 31#1
	······	A	DMINISTRATI	VE APPLIC	ATION CH	ECKLIST	٢	
T	THIS CHECKLIS	ST IS MANE		RATIVE APPLICATIONS			ES AND REGULA	rions
Appli	[DHC] []	n-Standa -Downho PC-Pool [W	ard Location] [NSP-No ble Commingling] [C Commingling] [OLS FX-Waterflood Expans [SWD-Salt Water Dis ed Enhanced Oil Recov	TB-Lease Commir - Off-Lease Storag ion] [PMX-Press sposal] [IPI-Injec	gling] [PLC-P e] [OLM-Off-L sure Maintenanc stion Pressure In	ool/Lease Co ease Measur e Expansion icrease]	mmingling] ement]]	
[1] .			ICATION - Check Th ocation - Spacing Unit NSL NSP			1	· · ·	
			e Only for [B] or [C] ommingling - Storage] DHC [] CTB	- Measurement	C 🗌 OLS	OLM		
	[(C] Ir	ijection - Disposal - Pre WFX DMX		hanced Oil Reco IPI 🔲 EOR	very PPR		
	[]	D] O	ther: Specify	· · · · · · · · · · · · · · · · · · ·				
[2] -		CATION	REQUIRED TO: - (Working, Royalty o					
	[H	3] [] Offset Operators, L	easeholders or Surf	ace Owner	•		• .
	[(c) [] Application is One	Which Requires Pu	blished Legal No	otice	. • *	· ·
· .	. [[D] [] Notification and/or (U.S. Bureau of Land Managern	Concurrent Approv ent - Commissioner of Public	al by BLM or SI Lands, State Land Office	.0		
	· [E	E] [] For all of the above,	Proof of Notificati	on or Publication	n is Attached,	and/or,	
	[F]] Waivers are Attache	d				· ·
[3]			RATE AND COMPLI		ION REQUIRE	D TO PROC	CESS THE T	YPE .
	al is accura	ite and c	N: I hereby certify tha omplete to the best of a information and noti	my knowledge. Ta	lso understand th	at no action ⁻	for administra will be taken c	tive on this

Note: Statement must be completed by an individual with managerial and/or supervisory capacity.

Print or Type Name	Signature	 Title	Date
· · ·	· .	e-mail Address	

BC OPERATING, INC.

P.O. Box 50820 Midland, Texas 79710 2007 NOV 28



November 27, 2007

Oil Conservation Division 1220 South St. Francis Dr Santa Fe, New Mexico 87505

Attn: Will Jones

RE: Cambio 31 #1; Lea County; API # 30-025-36480

Dear Mr. Jones,

BC Operating is requesting a non-standard location for the above mentioned well. We re-entered this well permitting it in the Edison: Morrow, North (Gas) Pool. The Morrow was unsuccessful and we plugged back to the Townsend Permo Upper Penn (59847) Pool. This pool is 40 acre spacing and per the statewide rules, we can only be 330' from the quarter-quarter of the section and our location is 1230' FNL making us only 90' from the south quarter-quarter.

I have enclosed a quarter mile radius map showing that there are not other offset wells.

Please contact me at 432.684.9696 x 216 if you should have any questions.

Sincerely,

an Botkin

Pam Botkin **Engineering Tech**

Cc: District Office - Donna Mull Well file

District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410

1220 S. St. Francis Dr., Santa Fe, NM 87505

District IV

State of New Mexico Energy, Minerals & Natural Resources Department OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505

2

Form C-102 Revised October 12, 2005 Submit to Appropriate District Office State Lease - 4 Copies Fee Lease - 3 Copies


✓ AMENDED REPORT

WELL LOCATION AND ACREAGE DEDICATION PLAT

1	r		² Pool Code			³ Pool Name				
3			59847 Townsend Permo Up				^j pper Penn			
⁴ Property (Code	⁵ Property Name						6,	⁶ Well Number	
36465		Cambio 31						1		
⁷ OGRID No.		⁸ Operator Name							⁹ Elevation	
160825		BC Operating						4015		
¹⁰ Surface Location										
UL or let no.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County	
, D	18	155	35E		1230	North	1054	West	Lea	
¹¹ Bottom Hole Location If Different From Surface										
UL or lot no.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County	
¹² Dedicated Acres ¹³ Joint or Infill ¹⁴ Consolidation Code ¹⁵ Order No.										
40										
L									···	

No allowable will be assigned to this completion until all interests have been consolidated or a non-standard unit has been approved by the division.

17				
16				¹⁷ OPERATOR CERTIFICATION
				I hereby certify that the information contained herein is true and complete
		· · · · · · · · · · · · · · · · · · ·		to the best of my knowledge and belief, and that this organization either
				owns a working interest or unleased mineral interest in the land including
				the proposed bottom hole location or has a right to drill this well at this
				location pursuant to a contract with an owner of such a mineral or working
Í				interest, or to a voluntary pooling agreement or a compulsory pooling
				orderneretofore entered by the division.
				Pan Botkin 1/27/07
				Signature Date
				Pam Botkin
				Printed Name
				·
	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·	
				¹⁸ SURVEYOR CERTIFICATION
				I hereby certify that the well location shown on this
				plat was plotted from field notes of actual surveys
	• · · · · ·			made by me or under my supervision, and that the
				· _
	• .			same is true and correct to the best of my belief.
				Date of Survey
				Signature and Seal of Professional Surveyor:
		,		
				Certificate Number



Brooks, David K., EMNRD

From: Pam Botkin [pbotkin@usaonline.net]

Sent: Wednesday, December 05, 2007 8:56 AM

To: Brooks, David K., EMNRD

Cc: Jaron Simon

Subject: Cambio 31 #1 Non-standard Location

December 5, 2007

Dear Mr. Brooks,

After speaking with you this morning, you needed to know about the ownership of the 40 acres to south of our Cambio well.

BC Operating owns 320 acres in the north $\frac{1}{2}$ of Sec 31, T155, R35E of Lea County. This would include the 40 acres that the Cambio well is in and the 40 acres to the south of the Cambio 31 #1 well.

I was looking over the C-102 that I sent to you and noticed that I mistakenly stated that the well was in Section 18, it is in Section 31 of T155,R35E. I apologize for any confusion this may have caused.

We have shut-in this well pending approval of the Non-standard location and your prompt attention will be greatly appreciated. If you have any other questions or concerns please let me know.

Sincerely, Pam Botkin Engineering Tech

Pam Botkín

BC Operating 432.684-9696 (Ext 216)

This inbound email has been scanned by the MessageLabs Email Security System.