

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-02531
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <u>SWD</u>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator HAL J. RASMUSSEN OPERATING, INC.		6. State Oil & Gas Lease No. B-6717
3. Address of Operator 550 W. TEXAS, SUITE 200, MIDLAND, TEXAS 79701		7. Lease Name or Unit Agreement Name: AMERADA STATE
4. Well Location Unit Letter <u>G</u> : <u>2310</u> feet from the <u>NORTH</u> line and <u>1650</u> feet from the <u>EAST</u> line Section <u>13</u> Township <u>21S</u> Range <u>34E</u> NMPM LEA County		7. Well No. <u>3</u>
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3651 GL		8. Pool name or Wildcat <u>WILSON YATES 7 RVRS ASSOC.</u> <u>SWD</u>

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐


12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

4 1/2" Casing has been cut and pulled from 279'

Propose to P&A as follows:

1. CIBP set @ 3650'
2. TEST CASING TO 500 PSI.

HEARING



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE Agent DATE 10/31/01

Type or print name Michael P. Jobe

Telephone No. 915-687-1664

(This space for State use)

APPROVED BY _____ TITLE _____ ORIGINAL SIGNED BY GARY W. WINK DATE NOV 19 2001
NATURAL SCIENCE MANAGER - 2