

Submit 3 Copies To Appropriate District Office  
 District I  
 1625 N. French Dr., Hobbs, NM 88240  
 District II  
 1301 W. Grand Ave., Artesia, NM 88210  
 District III  
 1000 Rio Brazos Rd., Aztec, NM 87410  
 District IV  
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
 Energy, Minerals and Natural Resources

Form C-103  
 Revised March 25, 1999

OIL CONSERVATION DIVISION  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

WELL API NO. 30-025-02577
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-11610
7. Lease Name or Unit Agreement Name:  WILSON STATE
7. Well No. 2
8. Pool name or Wildcat WILSON YATES 7 RVRs ASSOC. SWD
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3662 DF

**SUNDRY NOTICES AND REPORTS ON WELLS**  
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
 Oil Well  Gas Well  Other -SWD

2. Name of Operator  
 HAL J. RASMUSSEN OPERATING, INC.

3. Address of Operator  
 550 W. TEXAS, SUITE 200, MIDLAND, TEXAS 79701

4. Well Location  
 Unit Letter J : 2310 feet from the SOUTH line and 2310 feet from the EAST line  
 Section 23 Township 21S Range 34E NMPM LEA County

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

<b>NOTICE OF INTENTION TO:</b> PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input checked="" type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>		<b>SUBSEQUENT REPORT OF:</b> REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>	
--	--	---	--

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach well logs to proposed completion or recompilation.

Propose to P&A as follows:

1. Set CIBP @ 3550 + dump bail 35' cement plug (Bottom)-TAG
2. 25 sx cement plug 1560' - 1700' Tag( Top Salt @1745')
3. 100 sx cement 266'- 366' Perf @ 366' and Sqz & Tag (Surface Shoe)
4. 10 sx surface plug w/ regulation marker

HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED BEFORE EXAMINER  
 OIL CONSERVATION DIVISION  
 EXHIBIT NO. 76  
 CASE NO: 12758-A

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Michael P. Jobe TITLE Agent DATE 10/01/01

Type or print name Michael P. Jobe Telephone No. 915-687-1664  
 (This space for State use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE 10/1/01  
 Conditions of approval, if any: \_\_\_\_\_

*dm*

Hal J. Rasmussen Operating, Inc.


Lease WILSON STATE

Well # 2

Location: J-23-21S-34E

Formation @ TD: 7 RVRS

Formation @ PBTD: 7 RVRS



Surface plug  
10 sx

16" @ 216' w/ 250 sx cmt (Circ)

Plug #3 266' - 366' Perf and Sqz. w/ 100 sx

TOC: 1100 Deter. By: Calc

Plug #2 1560' - 1700' 25 sx

T. Salt: 1745

Plug #1 CIBP @ 3550' w/35' (Proposed)

7" @ 3612' w/ 350 sx cmt

T.S

Plug	Type	Sacks Cmnt	Depth	
			from	to
Plug #1	CIBP w/35'		3550	
Plug #2	Casing	25 sx	1560	1700
Plug #3	Shoe Perf & Sqz	100 sx	266	366
Plug #4	Surface	10 sx		
Plug #5				
Plug #6				

TD: 3815  
PBTD: 3748

3815