



RECEIVED 000

2015 MAR 15 P 1:26

Andy Wetherell
Land Representative
San Juan Basin

Midcontinent Business Unit
Chevron U.S.A. Inc.
1400 Smith Street
Houston, TX 77002
Tel 713-372-9914
andy.w@chevron.com

March 8, 2016

Certified Mail

Commissioner of Public Lands
State of New Mexico
P. O. Box 1148
Santa Fe, NM 87504-1148

2:87
c: 2 33

New Mexico Oil Conservation Division
1220 South Saint Francis
Santa Fe, NM 87505-4000

RE: Submittal of Rincon Unit 2016 Plan of Development
Recap of 2015 Activities and Production
Rincon Unit-Rio Arriba County, New Mexico


Gentlemen:

Enclosed you will find a copy of the proposed 2016 Plan of Development and the 2015 Review of Operations and Production Activities for the Rincon Unit, submitted by Chevron Midcontinent L. P., the Unit Operator. We ask for your approval of our Plan of Development for 2016. Any changes to this Plan for 2016 will be made by Amendments to the Plan as they become necessary.

Copies of the 2016 Plan of Development and the 2015 Review of Operations have been sent to, BLM, the Commissioner of Public Lands for the State of New Mexico and the New Mexico Oil Conservation Division. We have also provided copies of this material to all of the Working Interest Owners in the Rincon Unit.

If during your review of this material you should have any questions, please feel free to contact Simon Martin, PE by telephone at +1 713-372-3821 or email at SimonMartin@Chevron.com. You may also contact me at +1 713-372-9914, by letter or email as indicated on the letterhead above.

Sincerely,


Andy Wetherell, CPL
Land Representative

RINCON UNIT REVIEW OF OPERATIONS - 2015
--

<u>No. Wellbores as of 12/31/15</u>	<u>All Formations</u>
Drilling	0
Drilled & Waiting on Completion	0
Producing	345
Shut-in	2
Abandoned	25
Injection	0
<u>December 2015 Production</u>	
Oil - Barrels	1,216
Gas - MCF @14.73 psi	564,876
Water - Barrels	1,437
Gas Injection - MCF @14.73 psi	0
<u>Production for Year 2015</u>	
Oil - Barrels	18,647
Gas - MCF @14.73 psi	6,516,563
Water - Barrels	17,764
Gas Injection - MCF @14.73 psi	0
<u>Cumulative Production thru 12/31/15</u>	
Oil - Barrels	2,108,609
Gas - MCF @14.73 psi	498,544,572
Water - Barrels	927,826
Gas Injection - MCF @14.73 psi	0

CHEVRON MIDCONTINENT, L.P.
RINCON UNIT WELL SUMMARY 12/31/2015

By Formation/Completion

Basin Dakota	Prod Wells	Not Prod	TOTAL
Grand Count	178	5	183
Duals	7	0	7
DH Commingle	138	0	138
Surf Commingle	0	0	0
Triple Completion	7	0	7
Stand Alone	27	0	27
TA	0	2	2
P&A	0	3	3
Basin Fruitland Coal	Prod Wells	Not Prod	TOTAL
Grand Count	38	1	39
Duals	0	0	0
DH Commingle	0	0	0
Surf Commingle	0	0	0
Triple Completion	0	0	0
Stand Alone	38	0	38
TA	0	1	1
P&A	0	0	0
Blanco Mesaverde	Prod Wells	Not Prod	TOTAL
Grand Count	186	3	189
Duals	11	0	11
DH Commingle	141	0	141
Surf Commingle	0	0	0
Triple Completion	7	0	7
Stand Alone	27	0	27
TA	0	0	0
P&A	0	3	3
Blanco Pictured Cliffs	Prod Wells	Not Prod	TOTAL
Grand Count	101	23	124
Duals	13	0	13
DH Commingle	5	0	5
Surf Commingle	0	0	0
Triple Completion	2	0	2
Stand Alone	81	0	81
TA	0	0	0
P&A	0	23	23
Largo Gallup/Tocito	Prod Wells	Not Prod	TOTAL
Grand Count	12	0	12
Duals	3	0	3
DH Commingle	4	0	4
Surf Commingle	0	0	0
Triple Completion	5	0	5
Stand Alone	0	0	0
TA	0	0	0
P&A	0	0	0
Otero Chacra	Prod Wells	Not Prod	TOTAL
Grand Count	9	1	10
Duals	2	0	2
DH Commingle	5	0	5
Surf Commingle	0	0	0
Triple Completion	0	0	0
Stand Alone	2	1	3
TA	0	0	0
P&A	0	0	0

Rincon Unit Totals	Prod Wells	Not Prod	TOTAL
Grand Count Zones	524	33	557
Duals	36	0	36
DH Commingle	293	0	293
Surf Commingle	0	0	0
Triple Completion	21	0	21
Stand Alone	175	1	176
TA	0	3	3
P&A	0	29	29
Total Wellbores	345	27	372

2015
Annual Production Volumes

	OIL, BBL	GAS, MCF	WATER, BBL
Dakota	8,721	3,073,371	7,858
Fruitland Coal	-	258,688	-
Mesaverde	9,259	2,208,629	9,335
Pictured Cliffs	50	801,834	287
Gallup/Tocito	617	131,215	276
Chacra	-	42,826	8
Rincon Total	18,647	6,516,563	17,764

GLR= 349.4697807 MCF/BBL

Chevron Midcontinent, L.P.
Rincon Unit
Rio Arriba County, New Mexico

2015 Review of Operations

New Wells Spud in 2015

Well	Pool	UL	Sec	Twp/Rng
None				

New Wells Completed in 2015

Well	Pool	UL	Sec	Twp/Rng
None				

Workovers - Cleanouts, repairs, down-hole commingling, acidizings, & zone adds

Type	Well	Pool	UL	Sec	Twp/Rng
Replace Tubing / Cleanout / Bypass Plunger	Rincon Unit Well #57E	Blanco Mesa Verde / Largo Gallup / Basin Dakota	O	1	26 N 7 W
Repair Bradenhead (Compliance)	Rincon Unit Well #82	Blanco Mesa Verde	M	23	27 N 6 W
Repair Bradenhead (Compliance)	Rincon Unit Well #83	Blanco Mesa Verde	B	23	27 N 6 W

Plugging & Abandonments

Well	Pool	UL	Sec	Twp/Rng
None				

Temporary Abandonments

Well	Pool	UL	Sec	Twp/Rng
None				

Facility Projects

Well
Tank Replacements
Separator Replacements

Plunger Lift Controller Upgrades

Well	Pool	UL	Sec	Twp/Rng
Rincon Unit Well #1E	Blanco Mesaverde / Basin Dakota	G	30	27 N 6 W
Rincon Unit Well #11	Blanco Mesaverde / Basin Dakota	K	6	26 N 6 W
Rincon Unit Well #11E	Blanco Mesaverde / Basin Dakota / Blanco Tocito	J	6	26 N 6 W
Rincon Unit Well #57	Blanco Mesaverde / Basin Dakota	A	1	26 N 7 W
Rincon Unit Well #97A	Blanco Mesaverde	P	18	27 N 6 W
Rincon Unit Well #134R	Blanco Mesaverde / Basin Dakota / Basin Mancos	A	12	26 N 7 W
Rincon Unit Well #136	Blanco Mesaverde / Basin Dakota	A	23	27 N 7 W
Rincon Unit Well #136E	Blanco Mesaverde / Basin Dakota	D	23	27 N 7 W
Rincon Unit Well #136P	Blanco Mesaverde / Basin Dakota	F	23	27 N 7 W
Rincon Unit Well #137	Blanco Mesaverde / Basin Dakota	K	24	27 N 7 W
Rincon Unit Well #138	Blanco Mesaverde / Basin Dakota	A	25	27 N 7 W
Rincon Unit Well #149M	Blanco Mesaverde / Basin Dakota	F	30	27 N 6 W
Rincon Unit Well #151	Basin Dakota	B	14	27 N 7 W
Rincon Unit Well #157	Basin Dakota	N	18	27 N 6 W
Rincon Unit Well #159	Basin Dakota	G	18	27 N 6 W
Rincon Unit Well #164	Basin Dakota / Largo Gallup	L	2	26 N 7 W
Rincon Unit Well #166P	Blanco Mesaverde / Basin Dakota	D	32	27 N 6 W
Rincon Unit Well #168E	Basin Dakota / Largo Gallup / Blanco Mesaverde	I	38	27 N 7 W
Rincon Unit Well #172	Basin Dakota	B	26	27 N 7 W
Rincon Unit Well #174M	Blanco Mesaverde / Basin Dakota	F	19	27 N 6 W
Rincon Unit Well #174R	Blanco Mesaverde / Basin Dakota	D	19	27 N 6 W
Rincon Unit Well #178	Blanco Mesaverde / Basin Dakota	K	23	27 N 7 W
Rincon Unit Well #184M	Blanco Mesaverde / Basin Dakota	P	15	27 N 7 W
Rincon Unit Well #184P	Blanco Mesaverde / Basin Dakota	I	15	27 N 7 W
Rincon Unit Well #185E	Blanco Mesaverde / Basin Dakota	J	22	27 N 7 W
Rincon Unit Well #193M	Blanco Mesaverde / Basin Dakota	D	35	27 N 7 W
Rincon Unit Well #201	Basin Dakota / Largo Gallup / Blanco Mesaverde	G	2	26 N 7 W
Rincon Unit Well #201E	Basin Dakota / Largo Gallup / Blanco Mesaverde	J	2	26 N 7 W
Rincon Unit Well #202	Blanco Mesaverde / Basin Dakota	A	27	27 N 7 W
Rincon Unit Well #202M	Blanco Mesaverde / Basin Dakota	I	27	27 N 7 W
Rincon Unit Well #223A	Blanco Mesaverde / Blanco South Pictured Cliffs / Otero Chacra	N	34	27 N 7 W
Rincon Unit Well #229	Basin Dakota	I	34	27 N 7 W
Rincon Unit Well #229M	Blanco Mesaverde / Basin Dakota	B	34	27 N 7 W
Rincon Unit Well #231	Blanco Mesaverde / Basin Dakota	M	12	26 N 7 W
Rincon Unit Well #302	Blanco Mesaverde / Basin Dakota	C	11	26 N 7 W
Rincon Unit Well #303	Blanco Mesaverde / Basin Dakota	E	33	27 N 7 W
Rincon Unit Well #303M	Blanco Mesaverde / Basin Dakota	H	33	27 N 7 W
Rincon Unit Well #306M	Blanco Mesaverde / Basin Dakota	F	34	27 N 7 W
Rincon Unit Well #412	Blanco Mesaverde / Basin Dakota	G	26	27 N 7 W
Rincon Unit Well #503	Basin Dakota / Blanco Mesaverde	H	13	27 N 7 W
Rincon Unit Well #505	Basin Dakota / Blanco Mesaverde	G	15	27 N 7 W

Wellhead Compressor Installs

Well	Pool	UL	Sec	Twp/Rng
None				

Chevron Midcontinent, L.P.
Rincon Unit
Rio Arriba County, New Mexico

2016 Plan of Development

PLANNED WELLS TO BE DRILLED IN 2016

Well	Pool	UL	Sec	Twp/Rng
None				

POSSIBLE CONVERSION / DEEPENING TO SALTWATER DISPOSAL WELL (dependent on economic review & funding)

Well	Pool	UL	Sec	Twp/Rng
Rincon Unit Well #84	Blanco Mesaverde	A	26	27 N 7 W
Rincon Unit Well #182E	Basin Dakota / Gallup	J	26	27 N 6 W

Chevron Midcontinent, L.P.
Rincon Unit
Rio Arriba County, New Mexico

2016 Plan of Operations

Potential Workovers - Cleanouts, repairs, commingling, acidizing & zone adds dependent on permit approval and funding

Well	Pool	UL	Sec	Twp	/	Rng
Rincon Unit Well #182R	Basin Dakota / Blanco Mesaverde	B	26	27	N	6 W
Rincon Unit Well #172	Basin Dakota	B	26	27	N	7 W
Rincon Unit Well #192E	Basin Dakota / Largo Gallup / Blanco Mesaverde	D	1	26	N	7 W
Rincon Unit Well #126R	Basin Dakota / Blanco Mesaverde	L	27	27	N	6 W
Rincon Unit Well #126M	Basin Dakota / Blanco Mesaverde	P	27	27	N	6 W
Rincon Unit Well #158Q	Basin Dakota / Blanco Mesaverde	O	22	27	N	6 W
Rincon Unit Well #133	Basin Dakota	K	14	27	N	7 W
Rincon Unit Well #173M	Basin Dakota / Blanco Mesaverde	J	23	27	N	6 W
Rincon Unit Well #108P	Basin Dakota / Blanco Mesaverde	H	19	27	N	6 W
Rincon Unit Well #182P	Basin Dakota / Blanco Mesaverde	P	26	27	N	6 W
Rincon Unit Well #182	Basin Dakota	G	26	27	N	6 W
Rincon Unit Well #188M	Basin Dakota / Blanco Mesaverde	L	33	27	N	7 W
Rincon Unit Well #166E	Basin Dakota / Blanco Mesaverde / Blanco South Pictured Cliffs	F	32	27	N	6 W
Rincon Unit Well #201	Basin Dakota / Blanco Mesaverde	G	2	26	N	7 W
Rincon Unit Well #192	Basin Dakota	K	1	27	N	6 W
Rincon Unit Well #176	Basin Dakota / Blanco Mesaverde	A	31	27	N	6 W
Rincon Unit Well #183E	Basin Dakota / Blanco Mesaverde	J	31	27	N	6 W
Rincon Unit Well #130M	Basin Dakota / Blanco Mesaverde	I	32	27	N	6 W
Rincon Unit Well #31	Blanco Mesaverde	P	36	27	N	7 W
Rincon Unit Well #82A	Blanco Mesaverde	C	23	27	N	6 W
Rincon Unit Well #138	Basin Dakota / Blanco Mesaverde	A	33	27	N	7 W
Rincon Unit Well #137E	Basin Dakota / Largo Gallup / Blanco Mesaverde	J	24	27	N	7 W
Rincon Unit Well #155	Basin Dakota	M	17	27	N	6 W
Rincon Unit Well #161M	Basin Dakota / Blanco Mesaverde	F	27	27	N	6 W
Rincon Unit Well #21	Blanco Mesaverde	L	16	27	N	6 W
Rincon Unit Well #21A	Blanco Mesaverde	D	16	27	N	6 W
Rincon Unit Well #126	Basin Dakota / Blanco Mesaverde	N	27	27	N	6 W
Rincon Unit Well #128	Basin Dakota / Blanco Mesaverde	L	28	27	N	6 W
Rincon Unit Well #156	Basin Dakota	M	16	27	N	6 W
Rincon Unit Well #165	Basin Dakota	G	27	27	N	6 W
Rincon Unit Well #101	Blanco Mesaverde	L	1	26	N	7 W
Rincon Unit Well #102	Blanco Mesaverde	M	11	26	N	7 W
Rincon Unit Well #183	Basin Dakota / Blanco Mesaverde	K	31	27	N	6 W
Rincon Unit Well #408	Basin Dakota / Blanco Mesaverde	P	21	27	N	6 W
Rincon Unit Well #403	Basin Dakota / Blanco Mesaverde	P	26	27	N	6 W
Rincon Unit Well #229	Basin Dakota	I	34	27	N	7 W
Rincon Unit Well #129M	Basin Dakota / Blanco Mesaverde	P	29	27	N	6 W
Rincon Unit Well #130	Basin Dakota / Blanco Mesaverde	A	32	27	N	6 W
Rincon Unit Well #146	Basin Dakota	G	23	27	N	6 W
Rincon Unit Well #156P	Basin Dakota	O	16	27	N	6 W
Rincon Unit Well #157	Basin Dakota	N	18	27	N	6 W
Rincon Unit Well #159R	Basin Dakota	B	18	27	N	6 W
Rincon Unit Well #164R	Basin Dakota / Blanco Mesaverde	K	2	26	N	7 W
Rincon Unit Well #166P	Basin Dakota / Blanco Mesaverde	D	32	27	N	6 W
Rincon Unit Well #168R	Basin Dakota / Blanco Mesaverde	M	32	27	N	6 W
Rincon Unit Well #168R	Basin Dakota / Blanco Mesaverde	O	36	27	N	7 W
Rincon Unit Well #177	Basin Dakota	L	13	27	N	7 W
Rincon Unit Well #179	Basin Dakota	G	16	27	N	6 W
Rincon Unit Well #180	Basin Dakota	G	21	27	N	6 W
Rincon Unit Well #181	Basin Dakota	G	22	27	N	6 W
Rincon Unit Well #183R	Basin Dakota / Blanco Mesaverde	M	31	27	N	6 W
Rincon Unit Well #184	Basin Dakota	A	15	27	N	7 W
Rincon Unit Well #187	Basin Dakota	A	35	27	N	7 W
Rincon Unit Well #201M	Basin Dakota / Blanco Mesaverde	A	2	26	N	7 W
Rincon Unit Well #415	Basin Dakota / Blanco Mesaverde	I	1	26	N	7 W
Rincon Unit Well #57	Basin Dakota / Blanco Mesaverde	A	1	26	N	7 W

Potential Artificial Lift Upgrades

Rincon Unit Well #78	Blanco Mesaverde	G	14	27	N	7 W
Rincon Unit Well #79A	Basin Dakota / Blanco Mesaverde	D	17	27	N	6 W
Rincon Unit Well #84	Blanco Mesaverde	A	26	27	N	7 W
Rincon Unit Well #85	Blanco Mesaverde / Blanco South Pictured Cliffs	H	15	27	N	7 W
Rincon Unit Well #88A	Blanco Mesaverde	J	13	27	N	7 W
Rincon Unit Well #97	Blanco Mesaverde / Blanco South Pictured Cliffs	L	18	27	N	6 W
Rincon Unit Well #97A	Blanco Mesaverde	P	18	27	N	6 W
Rincon Unit Well #108E	Basin Dakota / Otero Chacra	O	19	27	N	6 W
Rincon Unit Well #123	Blanco Mesaverde	M	13	27	N	7 W
Rincon Unit Well #131E	Blanco Mesaverde / Basin Dakota / Blanco South Pictured Cliffs	C	36	27	N	7 W
Rincon Unit Well #133	Basin Dakota	K	14	27	N	7 W
Rincon Unit Well #138E	Basin Dakota / Blanco Mesaverde	F	25	27	N	7 W
Rincon Unit Well #139	Basin Dakota / Blanco Mesaverde	K	25	27	N	7 W
Rincon Unit Well #149	Basin Dakota / Blanco Mesaverde	N	30	27	N	6 W
Rincon Unit Well #155	Basin Dakota	M	17	27	N	6 W
Rincon Unit Well #155R	Basin Dakota / Blanco Mesaverde	L	17	27	N	6 W
Rincon Unit Well #159P	Basin Dakota / Blanco Mesaverde	D	18	27	N	6 W
Rincon Unit Well #167	Basin Dakota	B	13	27	N	7 W
Rincon Unit Well #168	Blanco Mesaverde / Basin Dakota	A	36	27	N	7 W
Rincon Unit Well #174	Basin Dakota	N	19	27	N	6 W

Rincon Unit Well #185R	Blanco Mesaverde / Basin Dakota	G	22	27	N	7	W
Rincon Unit Well #186M	Basin Dakota / Largo Gallup / Blanco Mesaverde	L	33	27	N	7	W
Rincon Unit Well #186R	Blanco Mesaverde / Basin Dakota	M	33	27	N	7	W
Rincon Unit Well #203M	Blanco Mesaverde / Basin Dakota	L	27	27	N	7	W
Rincon Unit Well #231E	Blanco Mesaverde / Basin Dakota / Blanco South Pictured Cliffs	D	12	26	N	7	W
Rincon Unit Well #300	Basin Fruitland Coal	G	6	26	N	6	W
Rincon Unit Well #413	Blanco Mesaverde / Basin Dakota	E	13	27	N	7	W

Potential Wellhead Compressor Installs

Rincon Unit Well #184M	Blanco Mesaverde / Basin Dakota	P	15	27	N	7	W
Rincon Unit Well #185	Blanco Mesaverde / Basin Dakota	A	22	27	N	7	W

Potential Plugging & Abandonments

Well	Pool	UL	Sec	Twp/Rng			
Rincon Unit Well #3	Blanco South Pictured Cliffs	P	6	26	N	6	W
Rincon Unit Well #5	Blanco South Pictured Cliffs	P	32	27	N	6	W
Rincon Unit Well #19	Basin Fruitland Coal	E	30	27	N	6	W
Rincon Unit Well #21	Blanco Mesaverde	L	16	27	N	6	W
Rincon Unit Well #25	Blanco South Pictured Cliffs	A	36	27	N	7	W
Rincon Unit Well #26	Blanco South Pictured Cliffs	L	32	27	N	7	W
Rincon Unit Well #27	Blanco South Pictured Cliffs	M	13	27	N	7	W
Rincon Unit Well #29	Blanco Mesaverde	A	22	27	N	6	W
Rincon Unit Well #33	Blanco Mesaverde	M	22	27	N	6	W
Rincon Unit Well #34	Blanco South Pictured Cliffs	K	28	27	N	7	W
Rincon Unit Well #38	Blanco South Pictured Cliffs	I	26	27	N	7	W
Rincon Unit Well #41	Blanco South Pictured Cliffs	A	35	27	N	7	W
Rincon Unit Well #45	Blanco South Pictured Cliffs	N	38	27	N	7	W
Rincon Unit Well #51	Blanco South Pictured Cliffs	L	6	26	N	6	W
Rincon Unit Well #52	Blanco South Pictured Cliffs	H	20	27	N	6	W
Rincon Unit Well #54	Blanco South Pictured Cliffs	G	14	27	N	7	W
Rincon Unit Well #55	Blanco South Pictured Cliffs	A	2	26	N	7	W
Rincon Unit Well #56	Blanco South Pictured Cliffs	J	2	26	N	7	W
Rincon Unit Well #61	Blanco South Pictured Cliffs	A	30	27	N	6	W
Rincon Unit Well #63	Blanco South Pictured Cliffs	D	23	27	N	7	W
Rincon Unit Well #64	Blanco South Pictured Cliffs	H	23	27	N	7	W
Rincon Unit Well #66	Blanco South Pictured Cliffs	H	22	27	N	7	W
Rincon Unit Well #68	Blanco South Pictured Cliffs	P	27	27	N	7	W
Rincon Unit Well #76	Blanco South Pictured Cliffs	H	34	27	N	7	W
Rincon Unit Well #86	Blanco South Pictured Cliffs	P	15	27	N	7	W
Rincon Unit Well #109	Blanco South Pictured Cliffs	D	19	27	N	6	W
Rincon Unit Well #113	Blanco Mesaverde	H	20	27	N	6	W
Rincon Unit Well #114	Blanco South Pictured Cliffs	K	20	27	N	6	W
Rincon Unit Well #141	Blanco South Pictured Cliffs	C	27	27	N	6	W
Rincon Unit Well #148	Blanco South Pictured Cliffs	D	23	27	N	6	W
Rincon Unit Well #155R	Blanco Mesaverde / Basin Dakota	L	17	27	N	6	W
Rincon Unit Well #160	Blanco South Pictured Cliffs	N	23	27	N	6	W
Rincon Unit Well #186	Blanco Mesaverde	O	33	27	N	7	W
Rincon Unit Well #199	Blanco South Pictured Cliffs	O	14	27	N	7	W
Rincon Unit Well #212	Otero Chacra	P	12	26	N	7	W
Rincon Unit Well #220	Otero Chacra	O	28	27	N	7	W
Rincon Unit Well #232	Otero Chacra	G	12	26	N	7	W
Rincon Unit Well #239	Basin Fruitland Coal	K	18	27	N	6	W
Rincon Unit Well #240	Basin Fruitland Coal	K	21	27	N	6	W
Rincon Unit Well #242	Basin Fruitland Coal	N	23	27	N	6	W
Rincon Unit Well #243	Basin Fruitland Coal	K	27	27	N	6	W
Rincon Unit Well #251	Basin Fruitland Coal	K	28	27	N	6	W
Rincon Unit Well #255	Basin Fruitland Coal	N	20	27	N	6	W
Rincon Unit Well #258	Basin Fruitland Coal	H	17	27	N	6	W
Rincon Unit Well #260	Basin Fruitland Coal	H	32	27	N	6	W
Rincon Unit Well #261	Basin Fruitland Coal	M	29	27	N	6	W
Rincon Unit Well #263	Basin Fruitland Coal	H	19	27	N	6	W
Rincon Unit Well #264	Basin Fruitland Coal	M	19	27	N	6	W
Rincon Unit Well #265	Basin Fruitland Coal	G	30	27	N	6	W
Rincon Unit Well #271	Basin Fruitland Coal	M	1	26	N	7	W
Rincon Unit Well #276	Basin Fruitland Coal	A	13	27	N	7	W
Rincon Unit Well #277	Basin Fruitland Coal	N	13	27	N	7	W
Rincon Unit Well #279	Basin Fruitland Coal	K	14	27	N	7	W
Rincon Unit Well #281	Basin Fruitland Coal	A	23	27	N	7	W
Rincon Unit Well #290	Basin Fruitland Coal	M	33	27	N	7	W

Potential Facility Projects

NMOCD required Below Grade Tank replacements
 Electrifications
 Rincon Central Oil / Water Storage Facility
 Rincon Lat 4 building upgrade
 Saltwater Disposal Well
 Lat 4 Compressor Isolation system
 Separator Replacement / Upgrades