

16-May-07

## Well Inspection History

API Number: **30-025-25904-00-00** Well Name & No.: **WALLEN BASS**  
Operator: **REUBIN COLLINS DBA RCJ ENTERPRISES,** District: **HOBBS** County Name: **LEA**  
Field: **WALLEN BASS** Legal: **S: 21 T: 20S R: 34E**  
Well Type: **OIL (PRODUCING)**

Insp. Dt.	Insp. Type	Insp. Purpose	Insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes
5/15/2007	Routine/Periodic	Enforcement Action Follow-u	iLWH0713556		102	Y	114
	Idle Well (Rule 201),,PER GAIL MACQUESTEN..NO CHANGE, OFF ELECTRIC..CORROSION ON POLISH ROD AND MOTOR SHEAVE..VALVES OPEN TO FLOWLINE						
3/15/2007	Compliance Verification	Enforcement Action Follow-u	iJCW0707451		105		
	Well is not pumping no electricity. Polish rod corroded and corroded sheave on motor.						
3/15/2007	Compliance Verification	Request/Complaint	iLWH0707450		102		
	WELL IS OFF ELECTRIC, VALVES OPEN TO FLOWLINE,,PUMPING UNIT HAS NOT BEEN ACTIVE FOR A LONG TIME..						
1/17/2007	Compliance Verification	Enforcement Action Follow-u	iLWH0701744		102		
	WELL HAS BEEN PUT BACK ON PRODUCTION PER REUBIN COLLINS						
5/24/2006	Routine/Periodic	Normal Routine Activity	iLWH0614445		102	Y	114
	Idle Well (Rule 201), NEEDS TO BE T/A, P/A OR PUT BACK IN USE. FIRST NOTICE						
2/1/2002	Routine/Periodic	Normal Routine Activity	iJDR02032361		113		
	A-OK. All Equipment and Location in Good Shape.						

**Total Inspections Performed: 6**