API Number: 30-015-34440-00-00 Well Name & No.: SHEARN BECKY FEDERAL Operator: C&D MANAGEMENT COMPANY DBA FREE District: ARTESIA County Name: EDDY Field: SHEARN BECKY FEDERAL Legal: S: 14 T: 17S R: 27E Well Type: OIL (PRODUCING) Insp. Dt. Insp. Type Insp. Purpose Insp. No. RmdyRqDt Insp. By Viol. SNC Failed Co 9/26/2007 Routine/Periodic Normal Routine Activity iREH0726941 214 No wellsign. Well is incapable of producing. Casing just above ground level with no wellhead. Sample sacks have been removed an covered. 2/14/2007 Routine/Periodic Normal Routine Activity iMLB07045380 211 Well is drilled. No flow line or production equipment. Well has open 8 5/8 casing set with collar above ground level. Pit with lining in di on North side of well. Sample sacks from drilling operations remain on site. No well sign present. Well was identified utilizing GPS sys 9/28/2006 Routine/Periodic Normal Routine Activity iPCH0627135 210	29-Apr-08	Well Inspection History							
Legal: S: 14 T: 17S R: 27E Well Type: OIL (PRODUCING) Insp. Dt. Insp. Type Insp. Purpose Insp. No. RmdyRqDt Insp. By Viol. SNC Failed Co 9/26/2007 Routine/Periodic Normal Routine Activity iREH0726941 214 No wellsign. Well is incapable of producing. Casing just above ground level with no wellhead. Sample sacks have been removed at covered. P/A marker next to open hole. Photos taken. 2/14/2007 Routine/Periodic Normal Routine Activity iMLB07045380 211 Well is drilled. No flow line or production equipment. Well has open 8 5/8 casing set with collar above ground level. Pit with lining in di on North side of well. Sample sacks from drilling operations remain on site. No well sign present. Well was identified utilizing GPS system	API Number:	30-015-34440-00-00	Well Name & No.:		SHEARN BECKY FEDERAL				
Well Type: OIL (PRODUCING) Insp. Dt. Insp. Type Insp. Purpose Insp. No. RmdyRqDt Insp. By Viol. SNC Failed Co 9/26/2007 Routine/Periodic Normal Routine Activity iREH0726941 214 No wellsign. Well is incapable of producing. Casing just above ground level with no wellhead. Sample sacks have been removed at covered. 2/14/2007 Routine/Periodic Normal Routine Activity iMLB07045380 211 Well is drilled. No flow line or production equipment. Well has open 8 5/8 casing set with collar above ground level. Pit with lining in di on North side of well. Sample sacks from drilling operations remain on site. No well sign present. Well was identified utilizing GPS system	Operator:	C&D MANAGEMEN	COMPANY DBA FREE	District:	ARTESIA	County Nar	me: EDDY		
Insp. Dt. Insp. Type Insp. Purpose Insp. No. RmdyRqDt Insp. By Viol. SNC Failed Co 0/26/2007 Routine/Periodic Normal Routine Activity iREH0726941 214 No wellsign. Well is incapable of producing. Casing just above ground level with no wellhead. Sample sacks have been removed an covered. 2/14/2007 Routine/Periodic Normal Routine Activity iMLB07045380 211 Well is drilled. No flow line or production equipment. Well has open 8 5/8 casing set with collar above ground level. Pit with lining in di on North side of well. Sample sacks from drilling operations remain on site. No well sign present.	Field:	SHEARN BECKY FE	DERAL	Legal:	S: 14 T: 17S R: 1	27E		•	
D/26/2007 Routine/Periodic Normal Routine Activity iREH0726941 214 No wellsign. Well is incapable of producing. Casing just above ground level with no wellhead. Sample sacks have been removed at covered. P/A marker next to open hole. Photos taken. 2/14/2007 Routine/Periodic Normal Routine Activity iMLB07045380 211 Well is drilled. No flow line or production equipment. Well has open 8 5/8 casing set with collar above ground level. Pit with lining in di on North side of well. Sample sacks from drilling operations remain on site. No well sign present. Well was identified utilizing GPS system	Well Type:	OIL (PRODUCING)	•						
No wellsign. Well is incapable of producing. Casing just above ground level with no wellhead. Sample sacks have been removed at covered. P/A marker next to open hole. Photos taken. 2/14/2007 Routine/Periodic Normal Routine Activity iMLB07045380 211 Well is drilled. No flow line or production equipment. Well has open 8 5/8 casing set with collar above ground level. Pit with lining in di on North side of well. Sample sacks from drilling operations remain on site. No well sign present. Well was identified utilizing GPS systematical set.	Insp. Dt. Ins	р. Туре	Insp. Purpose	insp. No.	RmdyRqDt	Insp. By	Viol. SNC	Failed Codes	
covered. P/A marker next to open hole. Photos taken. /14/2007 Routine/Periodic Normal Routine Activity iMLB07045380 211 Well is drilled. No flow line or production equipment. Well has open 8 5/8 casing set with collar above ground level. Pit with lining in di on North side of well. Sample sacks from drilling operations remain on site. No well sign present. Well was identified utilizing GPS system	/26/2007 Ro	utine/Periodic	Normal Routine Activity	iREH0726	941	214			
Well is drilled. No flow line or production equipment. Well has open 8 5/8 casing set with collar above ground level. Pit with lining in di on North side of well. Sample sacks from drilling operations remain on site. No well sign present. Well was identified utilizing GPS system.		÷ .		ove ground	level with no wellhead.	Sample sack	s have been i	removed and pit	
on North side of well. Sample sacks from drilling operations remain on site. No well sign present. Well was identified utilizing GPS sys	2/14/2007 Ro	utine/Periodic	Normal Routine Activity	iMLB0704	5380	211			
0/28/2006 Routine/Periodic Normal Routine Activity iPCH0627135 210	on	North side of well. Sample	sacks from drilling operations re	emain on si	te. No well sign present	. Well was ide			
	9/28/2006 Ro	utine/Periodic	Normal Routine Activity	iPCH0627	135	210 ·			

Total Inspections Performed: 3

Case 14055 De Novo C&D Management Company dba Freedom Ventures Company OCD Exhibit No. 17

ShEARN BECKY FEDERAL #1