Examiner Hearing –May29, 2008 Docket No. 17-08 Page 3 of 10

South Pearl Queen Unit #007	30-025-03316
West Pearl Queen Unit #103	30-025-03247
West Pearl Queen Unit #107	30-025-03231
West Pearl Queen Unit #108	30-025-03234
West Pearl Queen Unit #110	30-025-03254
West Pearl Queen Unit #112	30-025-03244
West Pearl Queen Unit #117	30-025-03241
West Pearl Queen Unit #118	30-025-03248
West Pearl Queen Unit #119	30-025-03240
West Pearl Queen Unit #120	30-025-03224
West Pearl Queen Unit #121	30-025-03225
West Pearl Queen Unit #122	30-025-03228
West Pearl Queen Unit #124	30-025-03229
West Pearl Queen Unit #125	30-025-03227
West Pearl Queen Unit #126	30-025-03226
West Pearl Queen Unit #127	30-025-03242
West Pearl Queen Unit #128	30-025-03249
West Pearl Queen Unit #129	30-025-03243
West Pearl Queen Unit #134	30-025-03262
West Pearl Queen Unit #135	30-025-03261
West Pearl Queen Unit #140	30-025-03283
West Pearl Queen Unit #143	30-025-03286
West Pearl Queen Unit #153	30-025-03265
West Pearl Queen Unit #154	30-025-03266
West Pearl Queen Unit #163	30-025-22870
West Pearl Queen Unit #164	30-025-23083
West Pearl Queen Unit #169	30-025-25365
West Pearl Queen Unit #191	30-025-30861
West Pearl Queen Unit #192	30-025-30867
West Pearl Queen Unit #195	30-025-31021
West Pearl Queen Unit #202	30-025-31125

3. CASE 14107: (Continued from the April 17, 2008 Examiner Hearing.)

Application of the New Mexico Oil Conservation Division for a Compliance Order against Xeric Oil & Gas Corporation ("Xeric"). The Applicant seeks an Order finding that Operator Xeric Oil & Gas Corporation ("Xeric") is in violation of Rule 19.15.2.50 NMAC and the terms of APD Permit No. 1237 with regard to the West Pearl Unit #301 well and requiring Operator Xeric to comply with both the terms of the referenced Rule and Permit, or alternatively authorizing the division to plug the well and forfeit any applicable/available security in the event that Xeric fails to comply, and assessing an appropriate civil penalty. The subject well is located approximately 16 miles Southwest of Hobbs in Lea County and is identified as follows:

West Pearl Queen Unit #301

30-025-36791

4. <u>CASE 14130</u>: Application of Energen Resources Corporation for Compulsory Pooling and Unorthodox Well Location, Rio Arriba and San Juan Counties, New Mexico. Applicant seeks an order pooling all mineral interests in the Fruitland Coal formation, (Basin-Fruitland Coal Gas Pool) underlying the W/2 of Section 22, Township 32 North, Range 6 West, NMPM, Rio Arriba and San Juan Counties, New Mexico, forming a standard 320-acre spacing and proration unit to be dedicated to the 32-5 Unit Well No. 115. The well will be directionally drilled from an unorthodox surface location 120 feet from the South line and 50 feet from the East line of Section 22 in Rio Arriba County, penetrating the Fruitland Coal formation at an unorthodox point 50 feet from the South line and 2630 feet from the West line of Section 22, to a standard bottom hole location 660 feet from the North and West lines of Section 22 in Township 32 North, Range 6 West, NMPM in San Juan County, New Mexico. Also to be considered will be the cost of drilling and completing said well and the allocation of the cost thereof as well as actual operating costs and charges for supervision, designation of Energen Resources Corporation as operator of the well and a charge for risk involved in drilling said well. The proposed well location is approximately 6 miles south of Arboles, Colorado.