



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Carlsbad Field Office
620 E. Greene St.
Carlsbad, New Mexico 88220-6292
www.blm.gov/nm



In Reply Refer To:
NMNM 08277
3160 (522)

CERTIFIED--RETURN RECEIPT REQUESTED
7006 0810 0000 8667 3442

OCT 07 2008

Mr. Dennis Langlitz
Jehovah Jireh Oil Co.
1425 South Country Club Circle
Carlsbad, NM 88220

RE: NMNM 08277, Saladar Wells
Section 33, T.20S., R.28E.
Eddy County, New Mexico

Dear Mr. Langlitz:

This is in response to your letter received by this office on September 25, 2008. The Bureau of Land Management (BLM) will participate in the scheduled hearing concerning the application for authority to inject into the wells described below.

<u>Well Name/No.</u>	<u>API No.</u>	<u>Surface Status</u>
Saladar No. 002	30-015-02450	Fee surface.
Saladar No. 004	30-015-02446	Federal surface
Saladar No. 006	30-015-02448	Federal surface
Saladar No. 007	30-015-10468	Federal surface
Saladar No. 008	30-015-02449	Federal surface
Saladar No. 012	30-015-24179	Federal surface

These wells inject into Federal minerals; like approval will be required from the BLM prior to injection.

If these wells are to be used for commercial water disposal, a Right-of-Way (ROW) with a \$25,000 bond will be required for each well.

BLM has numerous compliance issues that have not been addressed by the operator.

If you have any questions, please contact Jim Amos at 575-234-5909 or Wesley Ingram at 575-234-5982.

Sincerely,

/s/ Don Peterson

Don Peterson
AFM, Lands and Minerals

cc:
Certified - 7006 0810 0000 8667 3428
New Mexico Oil Conservation Division
1220 South St. Francis Drive
Santa Fe, NM 87505

RECEIVED
2008 OCT 10 PM 1 18