

MARTIN YATES, III  
1912 - 1985  
FRANK W. YATES  
1936 - 1986



105 SOUTH FOURTH STREET  
ARTESIA, NEW MEXICO 88210  
TELEPHONE (505) 748-1471

S. P. YATES  
CHAIRMAN OF THE BOARD  
JOHN A. YATES  
PRESIDENT  
PEYTON YATES  
EXECUTIVE VICE PRESIDENT  
RANDY G. PATTERSON  
SECRETARY  
DENNIS G. KINSEY  
TREASURER

March 25, 1996

Oil Conservation Division  
New Mexico Department of Energy  
Minerals and Natural Resources  
2040 South Pacheco Street  
Santa Fe, New Mexico 87505

Attention: Mr. David R. Catanach

Re: Case No. 11848  
Indian Basin Upper Pennsylvanian Associated Pool Rules - Order No. R-9922

Dear Mr. Catanach:

Enclosed are the following items submitted in response to your request at the referenced hearing on March 21, 1996, for information on drainage calculations:

1. Production curves and ultimate recovery analyses for each producing well in the pool.
2. A page entitled Production & Log Summary that provides a summary of the ultimate recoveries and a summary of log analyses for each well.
3. Two pages that shows how volumetric calculations were made.
4. A page that shows average well drainage with input parameters taken from Item 2 above.
5. A page that shows drainage calculations for the Hickory ALV Fed #1.

Please let me know if anything else is needed.

Sincerely,

Albert R. Stall  
Engineer

enclosures

→ cc: Mr. William F. Carr  
w/ enclosures