



- Wind Direction Indicators  
(wind sock or streamers)
- △ H2S Monitors  
(alarms at bell nipple and shale shaker)
- Briefing Areas
- Remote BOP Closing Unit
- Sign and Condition Flags

EXHIBIT "D"  
RIG LAY OUT PLAT

KUKUI OPERATING COMPANY  
GOODNIGHT "35" FEDERAL # 3  
UNIT "M" SECTION 35  
T23S-R29E EDDY CO. NM