1	STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT
2	OIL CONSERVATION DIVISION STATE LAND OFFICE BUILDING SANTA FE, NEW MEXICO
3	
4	24 April 1985
5	EXAMINER HEARING
6	
7	IN THE MATTER OF:
8	Application of Caulkins Oil Company CASE for downhole commingling, Rio Arriba 8573,8574
9	Coounty, New Mexico.
10	
11	
12	BEFORE: Michael E. Stogner, Examiner
13	
14	TRANSCRIPT OF HEARING
15	
16	APPEARANCES
17	
18	
19	For the Oil Conservation Maryann Lunderman Division: Attorney at Law Energy and Minerals Department
20	Energy and Minerals Department Energy and Minerals Division Santa Fe, New Mexico 87501
21	
22	For the Applicant: Karen Aubrey
23	Attorney at Law KELLAHIN & KELLAHIN P. O. Box 2265
24	Santa Fe, New Mexico 87501
25	

1		2	
2			
3	INDEX		
4			
5	CHARLES E. VERQUER		
6	Direct Examination by Ms. Aubrey	4	
7	Cross Examination by Mr. Stogner	12	
8			
9			
	ЕХНІВІТЅ		
10			
11	CASE 8573		
12	CASE 8573		
13	Caulkins Exhibit One, Information		
14	Caulkins Exhibit Two, List		
15	Caulkins Exhibit Three, Plat		
16	Caulkins Exhibit Four, Schematic, etc		
17	Caulkins Exhibit Five, Tabulation	4	
18	Caulkins Exhibit Six, Sundry Notices	4	
19			
20			
21	CASE 8574		
22			
23	Caulkins Exhibit One, Information		
24	Caulkins Exhibit Two, List	7	
	Caulkins Exhibit Three, Plat	7	
25	Caulkins Exhibit Four, Schematic, etc	7	

1		3	
2			
3	EXHIBITS CONT'D		
4			
5			
6	Caulkins Exhibit Five, Tabulation	8	
7	Caulkins Exhibit Six, Sundry Notices	8	
8			
j			
9	CASE 8575		
10			
11	Caulkins Exhibit One, Information		
12	Caulkins Exhibit Two, List	10	
13	Caulkins Exhibit Three, Plat	10	
14	Caulkins Exhibit Four, Schematic, etc	10	
15	Caulkins Exhibit Five, Tabulation	11	
16	Caulkins Exhibit Six, Sundry Notices	11	
17			
18			
19			
20			
21			
22			
23			
24			
25			

Q And that would be true for each of the eight wells involved in Case 8573.

A That is correct.

20

21

22

23

24

25

Q Finally, Mr. Verquer, Exhibit Number Six are copies of the sundry notices on the Federal leases involved in Case 85 -- I'm sorry, Case 8573.

A That is correct.

1		7
2	do you know what	the bottom hole pressure in each of the
3	zones are?	
4	A	We do not.
5	Q	With the installation of the Baker equip-
6	ment that you propo	se to install will you be able to prevent
	any cross flow fr	om between the three zones in these
7	wellbores?	
8	A W	e will prevent cross flow.
9	Q E	xhibit Number Two then shows the well lo-
10	cations?	
11	A	That does.
12	Q	And Exhibit Number Three is a plat for
13	each of the propose	d wells, is that correct?
	A	That is correct.
14	Q	And Exhibit Four once again shows the lo-
15	cation of the perf	orations in the wellbore and the proposed
16	location for the in	stallation of the Baker equipment.
17	A	That is correct.
18	Q	I believe you testified that in connec-
19	tion with these se	even wells you will be installing an addi-
20	tional check flow v	valve because of the addition of the third
21	zone.	
	A	That's correct.
22	Q	With regard to Exhibit Number Five, does
23	that show your pro	posed allocation formula for the produc-
24	tion from the three	zones?
25	A	That is correct.

Γ

That is correct. Α

23 24

Let me refer you now to Exhibit Number Six, which consists of sundry notices on the Federal leases, or the Federal wells involved in this case.

We do.

A

each

1 2 Q Do you know whether or not the zones fluids from these four zones are compatible with each 3 other? With the history of the offsetting wells, A 5 we believe they should be compatible, yes. 6 And is the ownership common in the four 0 7 zones in each of these two wells? 8 A They are. 9 0 Do you know what the bottom hole pressure in each of the four zones involved in Case 8575 is? 10 No. 11 Is it your opinion, Mr. Verquer, that the 12 installation of the equipment that you've described will 13 prevent any cross flow between the zones and should entitle 14 Caulkins to a waiver of the 50 percent requirement in Rule 15 302? 16 I -- it is. 17 Let me refer you to Exhibit Number Two in 18 Case 8475. Does that show the location of the wells invol-19 ved in this case? A That is correct. 20 And attached to -- I'm sorry, and Exhibit 0 21 Number Three is a plat for each of the wells? 22 A Showing the dedicated acreage of 23 one, yes.

24

25

And Exhibit Number Four once again con-0 tains the technical data on the equipment you intend to in-

And the Dakota zone, also?

Q

1	13
2	A Yes.
3	Q In your Exhibit One you show that both
4	wells will be recompleted to produce gas from the Chacra and
5	Mesaverde zones that wouldn't otherwise produce. So these
6	two wells are producing okay, let me back up.
7	Exhibit Number Two you show wells both
8	produce now from Pictured Cliffs and Basin Dakota zones, is
	that correct?
9	A That is correct.
10	Q Okay. So this 320-acre nonstandard pro-
11	ration unit would be for the Dakota only, right?
12	A 233-E had been drilled and completed in
13	the, I'm sorry, my I covered the covered it up down
	there in the corner in that nonstandard unit, the Chacra-
14	Mesaverde and the Dakota well, which is in the southwest
15	quarter of that section.
16	And Order No. R-7006 approved that 320-
17	acre nonstandard unit for the Mesaverde zone.
18	Q So that nonstandard proration unit with
19	this new order would allow the proration unit for the Blanco
20	Mesaverde. Basin Dakota was approved years ago, right?
21	A Years ago, yes, sir.
22	Q And the Pictured Cliffs and Chacra,
	they're on 160 acres. That would be standard.
23	A That would be standard at 160 acres.
24	Q And all the interests are common in 160
25	as well as the 320.

3

5

6

7

8

10

9

11

12

13 14

15

16

17

18 19

20

21

22

23

24 25

there any actual pressure data Q Are for

there was seepage at the well from the formation into wellbore, that could migrate to the Dakota without a check valve in that, and therefore soak it up there, which is not a good situation.

So we propose to put the check valve there to keep any cross flow from going into the Dakota.

Okay. How about -- what kind of pres-0 sures are you anticipating in the Pictured Cliffs and the Chacra in relationship to the Mesaverde and Basin Dakota?

This -- this Pictured Cliff has been the line since 1952. I would anticipate that the bottom hole pressure in the Pictured Cliff today is 320 pounds, and against that -- that is -- that is the reason for the cross flow equipment to keep -- keep any cross flow -- run equipment to prevent cross flow between zones.

Q But that wouldn't prevent the if they were quite a bit more, from cross flowing to zones. your upper zones, would it?

Those check valves, they call them a reverse flow check valve, they can only flow one way.

> I see. Q

And the way they flow is from the Α tion into the tubing. They don't flow from the -- so Dakota pressure can only get into the -- will only be on the inside of that tubing and it can't get out into the tion.

any of these formations in this area?

A I have some on other wells, yes. I have some wells that -- I don't have any that I've commingled in the Pictured Cliffs-Dakota where -- where it verified that we have less than 50 percent difference, but I don't anticipate that the pressure on that Pictured Cliff would be any higher than that 320 to 350 pounds at an absolute maximum, and the Mesaverde pressure will certainly be 1200.

Q Is there a similar commingling profile on any well within the vicinity where you've got these four zones commingling downhole?

A No, sir.

Q How about any three combination?

A Yes. I've got the Pictured Cliff, Chacra, and Mesaverde commingled in a well in Section 3. Let's see, one of these things -- that's not that close to it but it's in the general -- general area.

I have another one that is commingled in those three zones that is in Section 17. This is all in 26, 6.

Also I have one -- one well commingled four zones, Pictured Cliff, Chacra, Mesaverde, and Greenhorn, and it's in Section 13, 26 North, 7 West.

Q And what was the section, sir, I'm sorry?

A Section 13.

Q Same township and range?

A Now, that wellis just commingled. All

mingle the Pictured Cliffs and the Chacra and pull that in one tubing and then downhole the Blanco Mesaverde-Basin Dakota and commingle that production? Would that be possible?

A Yes, that could be -- you mean to produce the well that way?

Q Yes, have two zones commingled, dually

completed, with two more commingled zones?

A Yes, they're commingled now. I mean they're dual completed now; they could be done that way.

Probably have to change the size of the tubing. We have 2-3/8ths to TD on the lower zone.

Now pressure information could be taken another way.

Before this was ever commenced we could take a bottom hole pressure of both zones, which wouldn't require a rig to be on it, and when the wells are completed and tested in each zone. I could take a pressure test then and have bottom hole pressure for each zone, but that's after the fact.

Q What is your approximation, what is the pressure in the Basin Dakota at this present time? Is that 1200?

A Approximately 1200 pounds, yes, sir, the wells that are this old.

Q And how long have those been downhole commingled, these two zones?

A This Pictured Cliff-Chacra has not been downhole commingled. Which -- I'm sorry, maybe I missed it.

Q Well, I'm getting ahead of myself, I think.

I'm referring to the wells that we talked about in 8574, the Chacra and Mesaverde is commingled presently, right?

 $\texttt{C} \;\; \texttt{E} \;\; \texttt{R} \;\; \texttt{T} \;\; \texttt{I} \;\; \texttt{F} \;\; \texttt{I} \;\; \texttt{C} \;\; \texttt{A} \;\; \texttt{T} \;\; \texttt{E}$ 

**5** 

I, SALLY W. BOYD, C.S.R., DO HEREBY CERTIFY that the foregoing Transcript of Hearing before the Oil Conservation Division was reported by me; that the said transcript is a full, true, and correct record of the hearing, prepared by me to the best of my ability.

Souly W. Boyd COR

I do hereby certify that the foregoing is a complete record of the proceedings in the Examiner hearing of Case 105, 8573, 8574, 8575 heard by me on 24 Minutes 1985

Marha Starrer

Oll Conservation Division