




BEFORE EXAMINER CATANACH
OIL CONSERVATION DIVISION
M/W EXHIBIT NO. 55
CASE NO. 119960





1100

1200

1300



Hixon Development Company
Mandana State #2
990' FNL & 1680' FEL
Sec. 2, T25N-R12W
San Juan County, New Mexico

Induction Log
Performed by Birdwell
Dated: 9/9/77
NMOCD Case Nos. 9420 & 9421
July 6, 1988
Dugan Production Corp., et. al.
Exhibit No. 16

LOG NUMBER

1260'
1274'
Pictured Cliffs perforations

18' 8"



1000


Hixon Development Company
N.T.B. #1
790' ENL & 1450' FWL
Sec. 32, T26N-R12W
San Juan County, New Mexico


Induction Log
Performed by Birdwell
Dated: 3/7/79
NMOCD Case Nos. 9420 & 9421
July 6, 1988
Dugan Production Corp., et. al.
Exhibit No. 17

1100

1098'
to
1117'


Pictured Cliffs perforations





1000

1100



Hixon Development Company
N.T.B. #1

790' ENL & 1450' FWL
Sec. 32, T26N-R12W
San Juan County, New Mexico

Density-Neutron Log
Performed by Birdwell
Dated: 3/7/79

1098'
to
1117'

Pictured Cliffs perforations