GW-163

MONITORING REPORTS

DATE: 1996-2000



) EGEIV

MASERVATION DIVIS

10601 Lomas NE Suite 106 Albuquerque, NM 87112

505-237-8440

December 6, 2000

Mr. Wayne Price
Oil Conservation Division
NM Energy, Minerals, and Natural Resources Department
2040 South Pacheco
Santa Fe, NM 87505

RE: Notification of Release to Groundwater at

Two Former LG&E Sites, Now Operated by Conoco Inc.,

1) Apex Compressor Station, Lea County, New Mexico, and

2) PCA Junction, Lea County, New Mexico

GW-163

Dear Mr. Price:

On behalf of Conoco Inc. (Conoco), Maxim Technologies, Inc. (Maxim) is forwarding this letter to officially notify the New Mexico Oil Conservation Division (OCD) of hydrocarbon related impacts to groundwater at the two above referenced facilities. LG&E Marketing, a subsidiary of LG&E Energy of Hobbs, New Mexico, formerly operated these facilities.

On December 1, 2000, Conoco became the owner/operator of these LG&E assets in New Mexico. As part of the acquisition of these assets, Conoco initiated a due diligence phase, which consisted in part, of installing soil borings and temporary monitor wells at these facilities. As a result of this phase of the due diligence, two sites were determined to have hydrocarbon related impacts to groundwater. These sites are:

- 1) Apex Compressor Station, several miles west of Hobbs (north of the Hobbs Gas Plant) in Lea County, New Mexico, and the
- 2) PCA Junction Station, northeast of Carlsbad in Eddy County, New Mexico.

The Apex Compressor Station is composed of four compressors, a tank farm, incoming and outgoing pipelines with associated metering houses, and scrubbers. Subsurface investigation activities, consisting of drilling, sampling and laboratory analysis of soil and groundwater, were conducted on September 7 and 8, 2000. A total of six soil borings were installed, and groundwater was encountered between 60 and 61 feet below ground surface (bgs). Three groundwater samples were collected and analyzed for BTEX and TPH. One groundwater sample in the vicinity of the tank farm contained benzene at 48 micrograms per liter (ug/L).

The PCA Junction facility consists of two bermed condensate tanks, two methanol saddle tanks and associated gas piping. Three soil borings and temporary monitoring wells were

[&]quot;Providing Cost-Effective Solutions to Clients Nationwide"

Mr. Wayne Price December 6, 2000 Page 2

installed around the tank farm on September 27, 2000. Groundwater levels in the temporary wells ranged from 22 to 23 feet bgs. Three groundwater samples were collected and analyzed for BTEX and TPH. Two samples exhibited benzene impacts ranging from 340—1,700 ug/L, toluene from 370-4,700 ug/L, and xylenes from 380-2,300 ug/L.

Maxim is currently putting together work plans for the two sites to further investigate the extent and nature of the groundwater impacts. It is our intent to forward these work plans to you for review and comment prior to their implementation.

If you have any questions, please do not hesitate to call Clyde Yancey, Maxim at 505-237-8440 or John Skopak, Conoco at 281-293-5584.

Sincerely,

MAXIM TECHNOLOGIES, INC.

Clyde L. Yancey, P.G. Senior Project Manager

Copy to:

John E: Skopak, Conoco Inc./Remediation Technology

Joyce M. Miley, Conoco Inc./NG&GP

Marshall C. Honeyman, Conoco Inc./NG&GP

Mark A. Bishop, Conoco Inc./NG&GP

Wayne Price

From:

Wayne Price

To:

Chris Eustice

Cc:

Jerry Sexton; Gary Wink; Karen Sharp Llano Apex Comp. St. GW-163

Subject:

Date:

Friday, May 24, 1996 1:48PM

RE: Anti-freeze spill approx. 5 bbls.

Dear Chris,

Llano had a spill on 5/16/96.

Called Ed Sloman, Ed indicated Envir. Spill Control Co. responded to spill. All contaminated soil has been picked up and placed on plastic. They have sampled dirt pile and spill area and are waiting on results.

1216

B

OIL CONSERVATION

They have tentative plans to dispose of this material at one of the NMOCD disposal facilities.

They are planning on sending in a final report.

cc: Ed Sloman-Llano

393-2152 off

DISTRICTI

P.O.Box 1980, Hobbs, NM 88241-1980

P.O. Drawer DD, Artesia, NM 88211-0719

DISTRICT III

1000 Rio Brazos Rd, Aztec, NM 87410

State of New Mexico Energy, Minerais and Natural Resources Department

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

SUBMIT 2 COPIES TO APPROPRIATE DISTRIC OFFICE IN ACCORDANC WITH RULE 116 PRINTE: ON BACK SIDE OF FORM

OPERATOR	71	12/	11276	· (L	ana)	ADDRESS				TELEPHO
REPORT	FIRE	BREAK	11.91(TILL XE	LEAK	BLOWO	or i	OTHER*	 -	
OF OR	TIKE	DREAK	31		LLTIK	2200	•	OHER.		
YPE OF	DRLG	PROD	TANK	PIPE	GASO	OIL		OTHER*		
FACILITY	WELL	WELL	BTRY	LINE	PLNT	RFY		O I I L		
FACILITY N	AME:	· · · · · · · · · · · · · · · · · · ·	aper	y Co	mereza.	or &	lat	(8,0)		
LOCATION (OF FACILITY			f -		SEC.	TWI	P. R	GE.	COUNTY
Qu/Qu S∞. o						<u> </u>				
	AND DIRECT			N .	1 11 11	M1 ' D	WI	1 > 14	2 /	11/11
	ROMINENT I	<u>ANDMAR</u>	K.	1101	1 Horus	- Mino		·]2 //	i no	Haple
DATE AND I	~	/16/9	76	ý.		E AND HOU			2	
OF OCCURR WAS IMMEI		YES		NOT R		OF DISCOVE	KY			
NOLICE CIA		153	NO	QUIRE	1	ES. VHOM	B 2.	and C	1	
BY		1 ()		QUIKE	DAT			mus.		
WHOM	7 d	\mathcal{A}	lo ma	n,	1	HOUR 5	1167	96	Z_i	55 FM
TYPE OF			1	· /		NTITY /	1 2 12		JME RE-	, , , ,
	_ <i>[]</i>	7.	7500	1 - 1	OF		9/3/	COVE		n and
FLUID LOST	Γ U	1/1/	・チントメビ	' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' ' '	1 01. 1	<i></i>	· //-/1		ekeu /	1 100 1 2 1
	UIDS REACI	YES		O	QUANTITY	<i>D</i> 22 /	· ////	LE COVE	ERED /	/ which
DID ANY FL A WATERCO	UIDS REAC					wss /	· //->	, COVI	ekeu /	
DID ANY FL A WATERCY IF YES, DES	JUIDS REACI DURSE? CRIBE FULL	Yee	ND REMEI	OJAL ACTION	QUANTITY		. 11.			
A WATERCY IF YES, DES	JUIDS REACI DURSE? CRIBE FULL	Yee	ND REMEI	OJAL ACTION	QUANTITY					,
DID ANY FL A WATERCY IF YES, DES	JUIDS REACI DURSE? CRIBE FULL	Yee	NO REMEI	DIAL ACTION	TAKEN San	aue	An :	ral		2
DID ANY FL A WATERCY IF YES, DES DESCRIBE (CAUSE OF PI	ROBLEM A	NO REMEI	DIAL ACTION	TAKEN San	aue	An :	ral	ue	· · · · · · · · · · · · · · · · · · ·
DESCRIBE O	CAUSE OF PI	ROBLEM A S TED AND	NO REMEI	DIAL ACTION	TAKEN San	aue	An :	ral		
DESCRIBE O	CAUSE OF PI	ROBLEM A S TED AND	NO REMEI	DIAL ACTION	TAKEN San	aue	An :	ral	ue	
DESCRIBE O	CAUSE OF PICACLOS CAUSE OF PICACLOS AREA AFFECT MOST	ROBLEM A S TED AND	NO REMEI	DIAL ACTION Colen Locken Laction Tak	TAKEN San	au Cl	An :	ral	ue	· · · · · · · · · · · · · · · · · · ·
DESCRIPTION OF AREA	CAUSE OF PICACION CAUSE OF PICACION AREA AFFECT MOST	ROBLEM A LIVETED AND LEMING	NO REMEI	DIAL ACTION LOKE LACTION TAK LACTION TAK	TAKEN PI	auc CC) rig	encent	was	Luc Lu'a	y ———
DESCRIPTIO	CAUSE OF PICACION CAUSE OF PICACION AREA AFFECT ON FA	ROBLEM A COUNTED AND	NO REMEI	DIAL ACTION Colen Locken Laction Tak	TAKEN PI	au Cl	on At	was	ue	· · · · · · · · · · · · · · · · · · ·

I HEREBY CERTIFY THAT THE INFORMATION ABOVE IS TRUE AND COMPLETE TO THE BEST OF MY KNOWLEDGE AND BELIE