From: <u>Eads, Cristina, EMNRD</u>

To: "rtijerina@goodnightmidstream.com"

Cc: "rmann@slo.state.nm.us"; Mike EMNRD Bratcher (mike.bratcher@state.nm.us); Robert EMNRD Hamlet

(Robert.Hamlet@state.nm.us); Victoria EMNRD Venegas (Victoria.Venegas@state.nm.us)

Subject: NDHR1918658476 PIPER SWD @ FDHR1918658363

Date: Tuesday, April 28, 2020 11:20:00 AM

Attachments: CP-1195 Well Log.pdf

(C-141 Remediation Plan) NDHR1918658476.pdf

image002.png

NDHR1918658476 PIPER SWD @ FDHR1918658363

Mr. Tijerina,

The OCD has denied the submitted Remediation Plan C-141 for incident # nDHR1918658476 for the following reason:

- Depth to groundwater has been incorrectly assessed. Records from the Office of the State Engineer indicate depth to groundwater at or near the site is less than 50' below ground surface. Please see page 2 of the attached well log in this email. This well is located in the same position as the well labeled "Incorrectly Geolocated CP-01245-1" on Figure 2 of the report.
- Before considering approval of the requested variance, vertical delineation needs to be completed.

The Denied C-141 can be found in the online image file. Please review and make the required correction prior to resubmitting though the fee portal. If you have any questions or believe this denial is in error, please contact me prior to submitting an additional C-141.

Cristina Eads

Environmental Bureau

EMNRD – Oil Conservation Division

5200 Oakland Avenue NE, Suite 100

Albuquerque, New Mexico 87113

505.670-5601

.....

email: <u>Cristina.Eads@state.nm.us</u>



OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.