## State of New Mexico Form C-103 Submit 1 Copy To Appropriate District Office Revised July 18, 2013 Energy, Minerals and Natural Resources District I - (575) 393-6161 WELL API NO: 30-015-27592 1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283 OIL CONSERVATION DIVISION 811 S. First St., Artesia, NM 88210 5. Indicate Type of Lease 1220 South St. Francis Dr. District III - (505) 334-6178 STATE FEE 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 District IV - (505) 476-3460 6. State Oil & Gas Lease No. 1220 S. St. Francis Dr., Santa Fe, NM B-2071-28 87505 7. Lease Name or Unit Agreement Name: SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A Mewbourne WDW-1 DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH 8. Well Number: WDW-1 MEWBOURNE Gas Well Other: Injection Well PROPOSEA D. S. Well: Oil Well 2. Name of Operator: HOLLYFRONTIER NAVAJO REFINING LLC 9. OGRID Number: 15694 10. Pool name or Wildcat: Navajo Permo-3. Address of Operator: PO BOX 159, ARTESIA, NM 88211 PENN 96918 501 E MAIN ST. ARTESIA, NM 88210 4. Well Location Unit Letter: O: 660 feet from the SOUTH line and 2210 feet from the EAST line Section: 31 Township: 17S Range: 28E NMPM County: EDDY 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,678' GL 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: ALTERING CASING □ PERFORM REMEDIAL WORK □ REMEDIAL WORK PLUG AND ABANDON TEMPORARILY ABANDON **CHANGE PLANS** COMMENCE DRILLING OPNS.□ P AND A CASING/CEMENT JOB MULTIPLE COMPL PULL OR ALTER CASING П DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: OTHER: FALL OFF TEST

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

JULY 25, 2020: Day 1: Start constant injection rate into WDW-1 Mewbourne as well as the three (3) offset wells for at least 30 hours prior to shut-in of WDW-1 for Fall Off Testing. Wellhead pressure will not exceed 1400 psig. Plant personnel will record rate, volume and pressure during the constant rate injection period to ensure steady flow for analysis. Samples of the injection fluid will be collected every 10 hours and analyzed for pH and specific gravity.

JULY 26, 2020: Day 2: Continue constant injection rate into all 4 wells.

JULY 27, 2020: Day 3: While injection continues, run dual downhole memory gauges to test depth making flowing gradient stops every 1,000 feet. Collect pressure data at test depth for minimum of 1 hour while injecting at a constant rate. Shut WDW-1 in and start data collection for a minimum of 30 hours. WDW-2, WDW-3 and WDW-4 will continue injection.

JULY 28, 2020: Day 4: WDW-1 will remain shut-in while collecting pressure data.

JULY 29, 2020: Day 5: After a minimum of 30 hours of data collection, gauges from the well will be pulled making stops every 1,000 feet. After tools reach surface, a second run with sinker bars will tag bottom. Will conduct MIT for minimum of 30 minutes with calibrated pressure gauge.

Note: Will notify Artesia District of schedule for Witnessing.

Spud Date:		Rig Relea	ise Date:			
I hereby certify that	the information above is true and	complete to	the best of my knowledge and belief			
SIGNATURE Seuro P Dode Type or print name: Lewis R. Dade For State Use Only			TITLE: Environmental SpecialistDATE: 07/15/2020 E-mail address: Lewis.Dade@hollyfrontier.com_ PHONE:575-746-5281			
APPROVED BY	Carl J. Charrey	TITI F	Environmental Engineer	DATE	9/8/2020	

Conditions of Approval (if any): Follow Fall-Off Test Plan.

Achieve adequate steady-state injection rate and conditions to stress injection zone.